

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230fdc",
    "firstName": "Jyoti Pawar ",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_022-23707514",
    "workMobileNo": "0_DEFAULT_91-9987531329"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5500000",
    "discussWithPerson": "KAUSHUIK DATTA",
    "expectedFees": 2750,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "640c34384dda382753e651f2",
"role": "SITEENGINEER",
"firstName": "Prashant ",
"email": "kasarprashant121@gmail.com",
"lastName": "Kasar",
"mobileNo": "9892524464",
"designation": "",
"shortName": "PK",
"workWithDocumentMaker": "",
"profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
```

```
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": []
},
"clientType": {
"label": "BANK",
"value": "BANK"
},
"location": {
"latitude": "19.175442054368908",
"longitude": "73.23781490490093"
},
"geo": {
"type": "Point",
"coordinates": [
73.23781490490093,
19.175442054368908
]
},
"siteVisit": {
"siteVisitStatus": true,
"schedule": [],
"visitedDate": [
{
"status": "COMPLETED",
"dateTime": "2023-07-29",
"remark": "MANUAL_IN_TASK"
}
]
}
```

```
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-29",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manjarali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Badlapur (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Sadguru Heritage",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "1(Part)",
  "label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "22 & 22A",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "1 (Part)/22 and 1(Part)/22A",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421503",
  "label": false
}
```

```

},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {

```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kulgaon_Badlapur_Municipal_Council",
"label": "Kulgaon Badlapur Municipal Council"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Manjarli - Valivali Road",
"west": "Manjarli Village Road",
"south": "Bungalow",
"east": "Residential Building"
},
"asPerDocumentAgreement": {
"north": "Road",
"west": "Manjarli Gaonthan",
"south": "Road",
"east": "18 M. Road"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "12",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "4400",
"depreciatedBuildingRate": "2200"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "50400",
"landRate": "10480",
"igrImage": "cases/64b6bfd1f76ce54e5d43a330/igr_1690788088943_Image.png",
"squareMeterGuideLineRate": "50400.00",
"squareFeetGuideLineRate": "4682.00"
},
"igrFinalRate": {
"rate": "4386.00",
"squareFeetGuideLineRate": "4386.00",
"squareMeterGuideLineRate": "47206.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "5000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KBMC norms",
  "tenantName": "Anu Kawali",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "8",
```

```
"totalLifeBuilding": "60",
"estimatedAge": "52",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "646.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64b6bfd1f76ce54e5d43a330/
routeMap_1690788298350_Image.png",
    "routeLat": "19.175349",
    "routeLng": "73.237895",
    "stationName": "Badlapur",
    "routeDistance": "1.2 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ghwyhp",
      "name": "ghwyhp",
      "image": "cases/64b6bfd1f76ce54e5d43a330/
routeMap_1690788230288_Image.png"
    }
  ]
}
```

```
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2371600.00",
  "finalValue": "2371600.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2836865.00",
  "selectedBuildUpValue": "646.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64c72cf50950be569ff91c01",
      "name":
"externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
      "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
```

```
    "_id": "64c72d080950be569ff91c4b",
    "name":
"externallmg_1690774792089_WhatsApp_Image_20230729_at_13957_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792089_WhatsApp_Image_20230729_at_13957_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64c72d080950be569ff91c47",
    "name":
"externallmg_1690774792079_WhatsApp_Image_20230729_at_13809_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792079_WhatsApp_Image_20230729_at_13809_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c72d080950be569ff91c4a",
    "name":
"externallmg_1690774792086_WhatsApp_Image_20230729_at_13956_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792086_WhatsApp_Image_20230729_at_13956_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c72cf50950be569ff91c01",
    "name":
"externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64c72cf50950be569ff91bff",
    "name":
"externallmg_1690774773011_WhatsApp_Image_20230729_at_13958_PM_2.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773011_WhatsApp_Image_20230729_at_13958_PM_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "64c72d080950be569ff91c48",
    "name":
"externallmg_1690774792081_WhatsApp_Image_20230729_at_13810_PM_1.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792081_WhatsApp_Image_20230729_at_13810_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64c72d080950be569ff91c46",
    "name":
"externallmg_1690774792076_WhatsApp_Image_20230729_at_13809_PM_1.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792076_WhatsApp_Image_20230729_at_13809_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64c72d080950be569ff91c43",
    "name": "Living Room",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792068_WhatsApp_Image_20230729_at_13806_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64c72d080950be569ff91c44",
    "name": "Living Room",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792070_WhatsApp_Image_20230729_at_13808_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64c72d080950be569ff91c39",
    "name": "Bedroom",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792036_WhatsApp_Image_20230729_at_13801_PM_1.jpeg",
    "orientation": "landscape"
  },
]
```

```
{
  "status": false,
  "_id": "64c72d080950be569ff91c45",
  "name": "Terrace Area",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792072_WhatsApp_Image_20230729_at_13808_PM.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64c72d080950be569ff91c3b",
  "name": "Terrace Area",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792042_WhatsApp_Image_20230729_at_13802_PM.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64c72d080950be569ff91c41",
  "name": "Kitchen",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792063_WhatsApp_Image_20230729_at_13805_PM.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```



```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "539.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64b6bfd1f76ce54e5d43a330",
"ownerName": "Mr. Rajesh Gangaram Khamgaonkar & Mrs. Vaishali Rajesh
Khamgaonkar",
"ownerPhoneNo": "9969031893",
"appAddress": "sadguru Heritage co operative society Ltd\n203 A wing\nBadlapur ",
"remark": "All Documents in Mumbai id ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/04/2013",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Sadguru Group",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Rajesh Gangaram Khamgaonkar & Mrs. Vaishali Rajesh
Khamgaonkar"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "708386",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
document_1690786322149_DocScanner_Jul_18_2023_1433.pdf",
    "fileName": "document_1690786322149_DocScanner_Jul_18_2023_1433.pdf"
```

```
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/11/2011",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / BP / 2011 - 12 / 1855 - 254 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/64b6bfd1f76ce54e5d43a330/
document_1690786402221_1275044.pdf",
  "id": "852626",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Mon Jul 31 2023 12:23:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002655",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "425028",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 18 2023 22:07:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajesh Gangaram Khamgaonkar & Mrs. Vaishali Rajesh
Khamgaonkar",
    "phone": "9969031893",
    "ownershipShare": "",
    "email": "",
    "id": "841084"
  }
]
```

```
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "308304",
    "name": "Living Room",
    "length": "9.00",
    "length1": "9",
    "length2": "0",
    "width": "18.25",
    "width1": "18",
    "width2": "3",
    "totalArea": "164.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "164.25"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Terrace Area",
    "length": "9.00",
    "length1": "9",
    "length2": "0",
    "width": "5.00",
    "width1": "5",
    "width2": "00",
    "totalArea": "45.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "45.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Kitchen",
```

```
"length": "7.58",
"length1": "7",
"length2": "7",
"width": "8.42",
"width1": "8",
"width2": "5",
"totalArea": "63.83",
"images": [],
"extraAreas": [],
"finalArea": "63.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Balcony Area",
  "length": "",
  "length1": "7",
  "length2": "7",
  "width": "",
  "width1": "3",
  "width2": "6",
  "totalArea": "26.54",
  "images": [],
  "finalArea": "26.54",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "22.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.67"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "1.17",
  "length1": "1",
  "length2": "2",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "4.28",
  "images": [],
  "extraAreas": [],
  "finalArea": "4.28"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "12.00",
  "width1": "12",
  "width2": "0",
  "totalArea": "108.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "108.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Terrace Area",
  "length": "9.00",
  "length1": "9",
```

```
"length2": "0",
"width": "8.00",
"width1": "8",
"width2": "0",
"totalArea": "72.00",
"images": [],
"extraAreas": [],
"finalArea": "72.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bathroom",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "4.83",
  "width1": "4",
  "width2": "10",
  "totalArea": "18.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.53"
}
],
```

```
"otherComposition": [
  {
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "6",
    "length": "2.50",
    "width1": "5",
    "width2": "00",
    "width": "5.00",
    "totalArea": "12.50",
    "percentageBeforeTotal": "12.50",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "12.5"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "922791",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "539",
    "squareMeterArea": "50.07",
    "docFinalBuiltUp": "646.8",
    "docFinalBuiltUpSquareMeter": "60.084",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "20",
    "docFinalSaleable": "776.16",
    "docFinalSaleableSquareMeter": "72.1008"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64c75d2f0950be569ff9844e",
    "id": "1",
    "property": "Residential Flat",
    "area": "660",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "2400000",
    "expectedRate": "3636.36",
    "builtUpExpectedRate": "2400000",
    "image": "cases/64b6bfd1f76ce54e5d43a330/
indicator_1690787119357_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64c75d470950be569ff9845e",
    "id": "2",
    "property": "Residential Flat",
    "area": "660",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "2600000",
    "expectedRate": "3939.39",
    "builtUpExpectedRate": "2600000",
    "image": "cases/64b6bfd1f76ce54e5d43a330/
indicator_1690787143753_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64c75d5d0950be569ff9846f",
    "id": "3",
    "property": "Residential Flat",
    "area": "655",
```



```
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "2500000",
"expectedRate": "3816.79",
"builtUpExpectedRate": "2500000",
"image": "cases/64b6bfd1f76ce54e5d43a330/
indicator_1690787165492_Image.png"
},
{
  "printlnReport": true,
  "_id": "64c75d7b0950be569ff9849d",
  "id": "4",
  "property": "Residential Flat",
  "area": "607",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "2550000",
  "expectedRate": "4200.99",
  "builtUpExpectedRate": "2550000",
  "image": "cases/64b6bfd1f76ce54e5d43a330/
indicator_1690787195340_Image.png"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72cf50950be569ff91bfe",
    "name":
"externallmg_1690774773004_WhatsApp_Image_20230729_at_13958_PM_1.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773004_WhatsApp_Image_20230729_at_13958_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72cf50950be569ff91bff",
```

```
    "name":
"externallmg_1690774773011_WhatsApp_Image_20230729_at_13958_PM_2.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773011_WhatsApp_Image_20230729_at_13958_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72cf50950be569ff91c00",
  "name":
"externallmg_1690774773019_WhatsApp_Image_20230729_at_13958_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773019_WhatsApp_Image_20230729_at_13958_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72cf50950be569ff91c01",
  "name":
"externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773026_WhatsApp_Image_20230729_at_13959_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72cf50950be569ff91c02",
  "name":
"externallmg_1690774773031_WhatsApp_Image_20230730_at_111839_AM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773031_WhatsApp_Image_20230730_at_111839_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72cf50950be569ff91c03",
  "name":
"externallmg_1690774773033_WhatsApp_Image_20230730_at_111840_AM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774773033_WhatsApp_Image_20230730_at_111840_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c39",
  "name":
"externallmg_1690774792036_WhatsApp_Image_20230729_at_13801_PM_1.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792036_WhatsApp_Image_20230729_at_13801_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c3a",
  "name":
"externallmg_1690774792039_WhatsApp_Image_20230729_at_13801_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792039_WhatsApp_Image_20230729_at_13801_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c3b",
  "name":
"externallmg_1690774792042_WhatsApp_Image_20230729_at_13802_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792042_WhatsApp_Image_20230729_at_13802_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c3c",
  "name":
"externallmg_1690774792048_WhatsApp_Image_20230729_at_13803_PM_1.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792048_WhatsApp_Image_20230729_at_13803_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c3d",
  "name":
"externallmg_1690774792051_WhatsApp_Image_20230729_at_13803_PM_2.jpeg",
```

```
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792051_WhatsApp_Image_20230729_at_13803_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c3e",
    "name":
"externallmg_1690774792054_WhatsApp_Image_20230729_at_13803_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792054_WhatsApp_Image_20230729_at_13803_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c3f",
    "name":
"externallmg_1690774792058_WhatsApp_Image_20230729_at_13804_PM_1.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792058_WhatsApp_Image_20230729_at_13804_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c40",
    "name":
"externallmg_1690774792060_WhatsApp_Image_20230729_at_13804_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792060_WhatsApp_Image_20230729_at_13804_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c41",
    "name":
"externallmg_1690774792063_WhatsApp_Image_20230729_at_13805_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792063_WhatsApp_Image_20230729_at_13805_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c72d080950be569ff91c42",
  "name":
"externallmg_1690774792066_WhatsApp_Image_20230729_at_13806_PM_1.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792066_WhatsApp_Image_20230729_at_13806_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c43",
  "name":
"externallmg_1690774792068_WhatsApp_Image_20230729_at_13806_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792068_WhatsApp_Image_20230729_at_13806_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c44",
  "name":
"externallmg_1690774792070_WhatsApp_Image_20230729_at_13808_PM_1.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792070_WhatsApp_Image_20230729_at_13808_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c45",
  "name":
"externallmg_1690774792072_WhatsApp_Image_20230729_at_13808_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792072_WhatsApp_Image_20230729_at_13808_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c72d080950be569ff91c46",
  "name":
"externallmg_1690774792076_WhatsApp_Image_20230729_at_13809_PM_1.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792076_WhatsApp_Image_20230729_at_13809_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c47",
    "name":
"externallmg_1690774792079_WhatsApp_Image_20230729_at_13809_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792079_WhatsApp_Image_20230729_at_13809_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c48",
    "name":
"externallmg_1690774792081_WhatsApp_Image_20230729_at_13810_PM_1.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792081_WhatsApp_Image_20230729_at_13810_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c49",
    "name":
"externallmg_1690774792083_WhatsApp_Image_20230729_at_13810_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792083_WhatsApp_Image_20230729_at_13810_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c4a",
    "name":
"externallmg_1690774792086_WhatsApp_Image_20230729_at_13956_PM.jpeg",
    "path": "cases/64b6bfd1f76ce54e5d43a330/
externallmg_1690774792086_WhatsApp_Image_20230729_at_13956_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c72d080950be569ff91c4b",
```

```
"name":
"externalImg_1690774792089_WhatsApp_Image_20230729_at_13957_PM.jpeg",
  "path": "cases/64b6bfd1f76ce54e5d43a330/
externalImg_1690774792089_WhatsApp_Image_20230729_at_13957_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-07-18T16:37:37.159Z",
"updatedAt": "2023-08-11T07:09:14.081Z",
"__v": 0,
"invoiceId": "64b6bfd1f76ce54e5d43a336",
"fullAddress": "Residential Flat No. 203, 2nd Floor, Wing - A, Sadguru Heritage,
Village - Manjarali, Gut No. 1 (Part)/22 and 1(Part)/22A, Taluka - Ambarnath, District -
Thane, Badlapur (West), 421503, State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Rajesh Gangaram Khamgaonkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9969031893",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Terrace Area +
Balcony Area + 2 Passage + WC + Bathroom",
"carpetTotal": "406.29",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "12.50",
"builtupPercentage": "20",
"finalBuiltupArea": "644.52",
"finalCarpetArea": "537.10",
"finalSalableArea": "773.42",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 488.00\nOpen Terrace Area in Sq. Ft.
= 51.00\nTotal Carpet Area in Sq. Ft. = 539.00\n(Area as per Agreement for Sale)",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 539.00",
```

"buildingServicesRate": "2500",  
 "flatRate": "4700",  
 "landOtherRate": "2200",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00",  
 "reportGeneratedDate": "Fri Aug 11 2023 12:14:42 GMT+0530 (India Standard Time)",  
 "siteVisitDate": "2023-07-29",  
 "proposePurchasers": []

Name	Length	Width	Total
Composition :			
Living Room	9'0"	18'3"	164.25
Terrace Area	9'0"	5'00"	45.00
Kitchen	7'7"	8'5"	63.83
Balcony Area	7'7"	3'6"	26.54
Passage	2'10"	8'00"	22.67
Passage	1'2"	3'8"	4.28
Bedroom	9'0"	12'0"	108.00
Terrace Area	9'0"	8'0"	72.00
WC	3'0"	4'00"	12.00
Bathroom	3'10"	4'10"	18.53
Other Composition :			
Cupboard	2'6"	5'00"	12.50