

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "15000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 7500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
```

```
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62ea09ea4e679b264caf07d7",
    "role": "SITEENGINEER",
    "firstName": "Suraj",
    "email": "suraj@vastukala.org",
    "lastName": "Zore",
    "mobileNo": "8652448654",
    "designation": "",
    "shortName": "SZ",
    "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
    "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
```

```
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-1930",
        "label": "Chartered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "60af7d4d2ffdf65bcd658643",
    "PANNo": "AESPC7493M",
    "role": "VALUER",
    "firstName": "Vidhi",
    "fatherName": "Manoj",
    "email": "vids_singh@yahoo.com",
    "lastName": "Chalikwar",
    "mobileNo": "9820549087",
    "designation": "Valuer",
    "registrationNo": [
      {
        "title": {
          "value": "Chartered_Valuer",
          "label": "Chartered Valuer"
        },
        "_id": "60eeb39af3dd69653a58168d",
        "number": "CAT-I-A-1930"
      }
    ],
    "shortName": "VC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
\\profilePhoto_1622113613002_Vidhi C.jpeg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.116237657710275",
  "longitude": "72.90493446580383"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.90493446580383,
    19.116237657710275
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-31",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kanjur",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "30",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "T4, Oak Runwal Forests",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhandup (West)",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Runwal Forests Tower 1, 2, 3 & 4 Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Lal Bahadur Shastri Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```

```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Mangatram Petrol Pump",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "CTS No. 596, 596/1-6, 597, 597/1-7, 598, 598/1-3, 599A, 599A/1-81, 601,
602, 602/1-9, 603, 604, 605, 605/1-17, 606, 606/1-83, 607, 607/1-31, 607A, 607D",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3002",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "Pin - 400 078",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
}
```

```
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Jai Hind Oil Company",
    "west": "LBS Road",
    "south": "Gundecha Altura Complex",
    "east": "Railway Track"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  }
}
```

```
    },
    "extraDetailOfProperty": ""
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "depreciatedCostOfConstruction": "",
    "depreciatedBuildingRate": ""
  },
  "igrRate": {
    "propertyName": "Kanjur Village",
    "rate": "151330",
    "landRate": "67220",
    "igrImage": "cases/64ba6bdca87c525d5c03e6f7/igr_1690871420867_Image.png",
    "squareMeterGuideLineRate": "174030.00",
    "squareFeetGuideLineRate": "16168.00"
  },
  "igrFinalRate": {
    "rate": "151330",
    "squareMeterGuideLineRate": "174030.00",
    "squareFeetGuideLineRate": "16168.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Tenant_Occupied",
      "label": "Tenant Occupied"
    },
    "monthlyRent": "42,000",
    "assessmentNo": "Details not available",
    "taxPaidHolderName": "Details not available",
    "taxAmount": "Details not available",
    "electricityServiceConnectionNo": "Details not available",
    "meterCardHolderName": "Details not available",
    "undividedAreaOfLandAsPerSaleDeed": "Details not available",
    "floorSpaceIndex": "As per MCGM norms",
    "tenantName": "Suman Kumar",
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "2",
"totalLifeBuilding": "60",
"estimatedAge": "58",
"noOfBasement": "3",
"noOfPodium": "1",
"noOfAmenityFloors": "",
"noOfFloors": "38",
"flatFloorNo": "30",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "727.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64ba6bdca87c525d5c03e6f7/
routeMap_1690877533229_Image.png",
```

```
"routeLat": "19.137333",
"routeLng": "72.931778",
"stationName": "Bhandup",
"routeDistance": "1.5 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "rdmv4",
    "name": "rdmv4",
    "image": "cases/64ba6bdca87c525d5c03e6f7/
routeMap_1690877442932_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```



```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "17847000.00",
"bookValue": "0",
"finalValue": "17847000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "11755753.00",
  "selectedBuildUpValue": "727.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64c7bdd1a5c3051014f5a1a9",
      "name": "externalimg_r_1690811843206_1690811631419_image_1.jpg",
      "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811843206_1690811631419_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64c7bdd1a5c3051014f5a1aa",
      "name": "externalimg_r_1690811850955_1690811631419_image_6.jpg",
      "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811850955_1690811631419_image_6.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64c7bdd1a5c3051014f5a1ab",
      "name": "externalimg_r_1690811847504_1690811631419_image_4.jpg",
      "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811847504_1690811631419_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64c7bdd1a5c3051014f5a1ac",
      "name": "externalimg_r_1690811848372_1690811631419_image_5.jpg",
      "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811848372_1690811631419_image_5.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "64c7bdd1a5c3051014f5a1a6",
    "name": "externallmg_r_1690811842891_1690811631419_image_0.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811842891_1690811631419_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a7",
    "name": "externallmg_r_1690811844482_1690811631419_image_2.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811844482_1690811631419_image_2.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19a",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811803731_1690811586743_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19b",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811802922_1690811586743_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19c",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811803060_1690811586743_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19e",
    "name": "Living Room",
```

```
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811804130_1690811586743_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19f",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811803800_1690811586743_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a0",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811806112_1690811586743_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a1",
    "name": "Living Room",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811806526_1690811586743_image_7.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26929",
    "max": "27988"
  },
  "builtUpRateRange": {
    "min": "24481",
    "max": "25444"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```



```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "661.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64ba6bdca87c525d5c03e6f7",
"ownerName": "Mrs. Vikas Bhaguji Said & Mrs. Kanchan Vikas Said",
"ownerPhoneNo": "9867907727",
"appAddress": "Flat no. T4 3002, 30th Floor, Oak Runwal Forests, LBS Marg,
Bhandup West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "19/01/2019",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Wheelabrator Alloy Castings Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mrs. Vikas Bhaguji Said & Mrs. Kanchan Vikas Said"
    },
    "isHardCopy": false,
```

```
"displayStatus": true,
"fileName": "document_1690876144610_document_1689938834331_Racpc_Ghatk
opar_Vikas_Said.pdf",
"path": "cases/64ba6bdca87c525d5c03e6f7/document_1690876144610_document_
1689938834331_Racpc_Ghatkopar_Vikas_Said.pdf",
"id": "249940",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Aug 01 2023 13:19:04 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae129faa6d152c1801b47d",
"label": "RERA Certificate"
},
"inputs": {
"documentDate": "09/09/2021",
"number": {
"value": "Registration_No",
"label": "Registration No"
},
"Registration_No": "P51800000818"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690876199388_P51800000818.pdf",
"path": "cases/64ba6bdca87c525d5c03e6f7/
document_1690876199388_P51800000818.pdf",
"id": "654061",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Aug 01 2023 13:19:59 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae1247aa6d152c1801b2ea",
"label": "Commencement Certificate"
},
"inputs": {
"documentDate": "27/05/2019",
"nameOfApprovingAuthority": {
"value": "Municipal_Corporation_Of_Greater_Mumbai",
"label": "Municipal Corporation Of Greater Mumbai"
},
"number": {
"value": "No",
"label": "No"
}
},
}
```

```
    "No": "CHE / ES / 1458 / S / 337 (New) / FCC / 2 / Amend"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690876333527_8_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "path": "cases/64ba6bdca87c525d5c03e6f7/document_1690876333527_8_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "id": "607764",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Aug 01 2023 13:22:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "31/05/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CHE / ES / 1458 / S / 337 (New) / OCC / 3 / New"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690876461871_2274608_OC_signed.pdf",
  "path": "cases/64ba6bdca87c525d5c03e6f7/document_1690876461871_2274608_OC_signed.pdf",
  "id": "600721",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Aug 01 2023 13:24:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "26/07/2023",
    "nameOfApprovingAuthority": {
```

```
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CHE / ES / 1458 / S / 337 (New)"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690876502072_Drawing.pdf",
"path": "cases/64ba6bdca87c525d5c03e6f7/
document_1690876502072_Drawing.pdf",
"id": "358775",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Aug 01 2023 13:25:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1257aa6d152c1801b335",
    "label": "Society Registration Certificate"
  },
  "inputs": {
    "documentDate": "29/07/2021",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MUM-2 / WS / HSG / TC / 11296 / 2021-2022 / 2021"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690876544080_2_Status_of_Formation_of_Legal_Entity_Society_Co_Op_etc.pdf",
"path": "cases/64ba6bdca87c525d5c03e6f7/document_1690876544080_2_Status_of_Formation_of_Legal_Entity_Society_Co_Op_etc.pdf",
"id": "400386",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Aug 01 2023 13:25:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
}
```

```
"inputs": {
  "documentDate": "08/03/2021",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690876835487_Possess.pdf",
"path": "cases/64ba6bdca87c525d5c03e6f7/
document_1690876835487_Possess.pdf",
"id": "936567",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Aug 01 2023 13:30:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002714",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "760369",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 21 2023 16:58:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vikas Bhaguji Said & Mrs. Kanchan Vikas Said",
    "phone": "9867907727",
    "ownershipShare": "",
    "email": "",
    "id": "629039"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
```

```
"length": "17.42",
"length1": "17",
"length2": "5",
"width": "9.75",
"width1": "9",
"width2": "9",
"totalArea": "169.81",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64c8b5dfa5c3051014f60c44",
    "name": "Living Entrance",
    "extraAreaType": "Add",
    "length": "4.83",
    "length1": "4",
    "length2": "10",
    "width": "4.75",
    "width1": "4",
    "width2": "9",
    "totalArea": "22.96"
  }
],
"finalArea": "192.77"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "54.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.76"
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "18.42",
  "width1": "18",
  "width2": "5",
  "totalArea": "58.32",
  "images": [],
  "extraAreas": [],
  "finalArea": "58.32"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Store Room",
  "length": "5.42",
  "length1": "5",
  "length2": "5",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "23.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.33",
  "length1": "11",
  "length2": "4",
```

```
"width": "9.75",
"width1": "9",
"width2": "9",
"totalArea": "110.50",
"images": [],
"extraAreas": [],
"finalArea": "110.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "121.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "121.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "33.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.94"
},
{
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "33.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.86"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "61.41",
    "totalAreaDocument": "661.00",
    "docBultupPercentage": "10",
    "docFinalBultUp": "727.10",
    "docFinalBultUpSquareMeter": "67.55",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "750792"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64c8a715a5c3051014f5e015",
```

```
"property": "Runwal Forest, Bhandup West",
"area": "661",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "16th",
"source": "https://www.99acres.com/",
"expectedPrice": "17800000",
"expectedRate": "26928.90",
"builtUpExpectedRate": "24480.81",
"image": "cases/64ba6bdca87c525d5c03e6f7/
indicator_1690871161269_Image.png",
"squareMeter": "61.41",
"id": "955975"
},
{
  "printlnReport": true,
  "_id": "64c8a715a5c3051014f5e016",
  "property": "Runwal Forest, Bhandup West",
  "area": "631",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "17000000",
  "expectedRate": "26941.36",
  "builtUpExpectedRate": "24492.15",
  "image": "cases/64ba6bdca87c525d5c03e6f7/
indicator_1690871216451_Image.png",
  "squareMeter": "58.62",
  "id": "214087"
},
{
  "printlnReport": true,
  "_id": "64c8a715a5c3051014f5e017",
  "property": "Runwal Forest, Bhandup West",
  "area": "661",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "15th",
  "source": "magic_bricks",
  "expectedPrice": "18500000",
```

```
    "expectedRate": "27987.90",
    "builtUpExpectedRate": "25443.54",
    "image": "cases/64ba6bdca87c525d5c03e6f7/
indicator_1690871266237_Image.png",
    "squareMeter": "61.41",
    "id": "211199"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19a",
    "name": "externalImg_r_1690811803731_1690811586743_image_3.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811803731_1690811586743_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19b",
    "name": "externalImg_r_1690811802922_1690811586743_image_1.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811802922_1690811586743_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19c",
    "name": "externalImg_r_1690811803060_1690811586743_image_2.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811803060_1690811586743_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19d",
    "name": "externalImg_r_1690811802774_1690811586743_image_0.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811802774_1690811586743_image_0.jpg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19e",
    "name": "externallmg_r_1690811804130_1690811586743_image_5.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811804130_1690811586743_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a19f",
    "name": "externallmg_r_1690811803800_1690811586743_image_4.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811803800_1690811586743_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a0",
    "name": "externallmg_r_1690811806112_1690811586743_image_6.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811806112_1690811586743_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a1",
    "name": "externallmg_r_1690811806526_1690811586743_image_7.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811806526_1690811586743_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a2",
    "name": "externallmg_r_1690811808290_1690811586743_image_10.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811808290_1690811586743_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c7bdd1a5c3051014f5a1a3",
  "name": "externalimg_r_1690811807615_1690811586743_image_9.jpg",
  "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811807615_1690811586743_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7bdd1a5c3051014f5a1a4",
  "name": "externalimg_r_1690811806838_1690811586743_image_8.jpg",
  "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811806838_1690811586743_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7bdd1a5c3051014f5a1a5",
  "name": "externalimg_r_1690811808817_1690811586743_image_12.jpg",
  "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811808817_1690811586743_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7bdd1a5c3051014f5a1a6",
  "name": "externalimg_r_1690811842891_1690811631419_image_0.jpg",
  "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811842891_1690811631419_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7bdd1a5c3051014f5a1a7",
  "name": "externalimg_r_1690811844482_1690811631419_image_2.jpg",
  "path": "cases/64ba6bdca87c525d5c03e6f7/
externalimg_r_1690811844482_1690811631419_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "64c7bdd1a5c3051014f5a1a8",
    "name": "externallmg_r_1690811846113_1690811631419_image_3.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811846113_1690811631419_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1a9",
    "name": "externallmg_r_1690811843206_1690811631419_image_1.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811843206_1690811631419_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1aa",
    "name": "externallmg_r_1690811850955_1690811631419_image_6.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811850955_1690811631419_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1ab",
    "name": "externallmg_r_1690811847504_1690811631419_image_4.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811847504_1690811631419_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1ac",
    "name": "externallmg_r_1690811848372_1690811631419_image_5.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externallmg_r_1690811848372_1690811631419_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1ad",
```

```
    "name": "externalImg_r_1690811766499_1690811560938_image_2.png",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811766499_1690811560938_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1ae",
    "name": "externalImg_r_1690811766276_1690811560938_image_1.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811766276_1690811560938_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64c7bdd1a5c3051014f5a1af",
    "name": "externalImg_r_1690811766039_1690811560938_image_0.jpg",
    "path": "cases/64ba6bdca87c525d5c03e6f7/
externalImg_r_1690811766039_1690811560938_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-21T11:28:28.302Z",
"updatedAt": "2023-08-01T09:49:56.416Z",
"__v": 0,
"invoiceId": "64ba6bdca87c525d5c03e704",
"fullAddress": "Residential Flat No. 3002, 30th Floor, Building No T4, Oak Runwal
Forests, Runwal Forests Tower 1, 2, 3 & 4 Co-op. Hsg. Soc. Ltd., Near Mangatram
Petrol Pump, Lal Bahadur Shastri Marg, Village - Kanjur, Taluka - Kurla, District -
Mumbai, Bhandup (West), Pin - 400 078, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Suman Kumar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenent",
"siteVisitContactNo": "6397149883",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
```

"finalAsPerArea": "Agreement For Sale",  
 "finalBuiltUpPercentage": "10",  
 "finalCarpetConvertToBuiltUpPer": "10",  
 "finalMeasurementType": "Sq. Ft.",  
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 661.00",  
 "flatRate": "27000.00",  
 "landOtherRate": "24000",  
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + Store  
 Room + 2 Toilet",  
 "carpetTotal": "629.94",  
 "otherCarpetTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "692.93",  
 "finalCarpetArea": "629.94",  
 "finalSalableArea": "762.23",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "",  
 "finalSaleablePercentage": "",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00",  
 "siteVisitDate": "2023-07-31"

Name	Length	Width	Total
Composition :			
Living Room	17'5"	9'9"	169.81
Kitchen	6'11"	7'11"	54.76
Passage	3'2"	18'5"	58.32
Store Room	5'5"	4'5"	23.92
Bedroom	11'4"	9'9"	110.50
Bedroom	12'6"	9'9"	121.87
Toilet	4'4"	7'10"	33.94
Toilet	7'8"	4'5"	33.86



Other  
Composition :

---