

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb41"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423130c",
    "firstName": "Sanjaykumar SHrivastav",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9969207619"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
```

```
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank Of India",
  "displayName": "Bank Of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb41",
  "branchCode": "000082",
  "type": "BRANCH",
  "name": "Thane Main Branch",
  "email": "Thane.NaviMumbai@bankofindia.co.in\t",
  "mobileNo": "02225332942",
  "alternateMobileNo": null,
  "address": "Bank Of India BUilding 1st floor Shivajipath opp M H High School Thane
(WEst) 400601\r\n",
  "ledgerName": null,
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64abdb2806d6ec174986d16b",
    "role": "PICKUPPERSON",
    "firstName": "Sahadu",
    "email": "thoratsahadu8679@gmail.com",
    "lastName": "Thorat",
```

```
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fd2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.201806",
  "longitude": "73.088583"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.088583,
    19.201806
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-02",
      "remark": "Ok "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"area": "790",
"rate": "6813",
"yearOfConstruction": "2018",
"compositionOfBuilding": "Stilt + 7 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nandivli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Avighna Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Sarvoday Park",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "45",
"label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "4/B",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```



```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64c0d26e9d3a3e4ed9c16239",
"ownerName": "Mr. Jayesh Keshav Gavade",
"ownerPhoneNo": "9819237399",
"fullAddress": "Residential Flat No. 402, 4th Floor, Wing - B, Avighna Heights,
Sarvoday Park, Village - Nandivli, Taluka - Kalyan, District - Thane, State -
Maharashtra, India",
"remark": "Ok ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/10/2016",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Shree Mangal Constructions",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Jayesh Keshav Gavade"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1690358354248_boi_main_br_Jayesh_gawde.pdf",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
document_1690358354248_boi_main_br_Jayesh_gawde.pdf",
    "id": "188319",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Wed Jul 26 2023 13:29:20 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]
```



```
    },
    "No": "---"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691146365317_OC.pdf",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/document_1691146365317_OC.pdf",
  "id": "707761",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Aug 04 2023 16:22:45 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002788",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "740387",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jul 26 2023 13:29:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Jayesh Keshav Gavade",
    "phone": "9819237399",
    "ownershipShare": "",
    "email": "",
    "id": "271022"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca41160faf29427ac9b4df",
    "name": "externalImg_r_1690976493888_1690976280450_image_2.png",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/externalImg_r_1690976493888_1690976280450_image_2.png",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e0",
  "name": "externallmg_r_1690976495124_1690976280450_image_3.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976495124_1690976280450_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e1",
  "name": "externallmg_r_1690976491812_1690976280450_image_1.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976491812_1690976280450_image_1.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e2",
  "name": "externallmg_r_1690976489708_1690976280450_image_0.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976489708_1690976280450_image_0.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e3",
  "name": "externallmg_r_1690976497417_1690976280450_image_4.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976497417_1690976280450_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e4",
  "name": "externallmg_r_1690976499268_1690976280450_image_5.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976499268_1690976280450_image_5.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e5",
  "name": "externallmg_r_1690976501001_1690976280450_image_6.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976501001_1690976280450_image_6.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e6",
  "name": "externallmg_r_1690976502662_1690976280450_image_7.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976502662_1690976280450_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e7",
  "name": "externallmg_r_1690976503708_1690976280450_image_8.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976503708_1690976280450_image_8.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e8",
  "name": "externallmg_r_1690976506304_1690976280450_image_9.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976506304_1690976280450_image_9.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4e9",
  "name": "externallmg_r_1690976507670_1690976280450_image_10.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976507670_1690976280450_image_10.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4ea",
  "name": "externallmg_r_1690976508581_1690976280450_image_11.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976508581_1690976280450_image_11.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4eb",
  "name": "externallmg_r_1690976509841_1690976280450_image_12.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976509841_1690976280450_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4ec",
  "name": "externallmg_r_1690976510774_1690976280450_image_13.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976510774_1690976280450_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4ed",
  "name": "externallmg_r_1690976515965_1690976280450_image_15.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976515965_1690976280450_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca41160faf29427ac9b4ee",
  "name": "externallmg_r_1690976511973_1690976280450_image_14.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976511973_1690976280450_image_14.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca41160faf29427ac9b4ef",
    "name": "externallmg_r_1690976518814_1690976280450_image_16.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976518814_1690976280450_image_16.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca41160faf29427ac9b4f0",
    "name": "externallmg_r_1690976521111_1690976280450_image_17.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976521111_1690976280450_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca41160faf29427ac9b4f1",
    "name": "externallmg_r_1690976524902_1690976280450_image_18.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976524902_1690976280450_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4f2",
    "name": "externallmg_r_1690976454286_1690976241711_image_2.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976454286_1690976241711_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4f3",
    "name": "externallmg_r_1690976450826_1690976241711_image_0.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976450826_1690976241711_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "64ca41160faf29427ac9b4f4",
  "name": "externallmg_r_1690976460581_1690976241711_image_4.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976460581_1690976241711_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64ca41160faf29427ac9b4f5",
  "name": "externallmg_r_1690976464361_1690976241711_image_5.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976464361_1690976241711_image_5.jpg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64ca41160faf29427ac9b4f6",
  "name": "externallmg_r_1690976466319_1690976241711_image_6.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976466319_1690976241711_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64ca41160faf29427ac9b4f7",
  "name": "externallmg_r_1690976468887_1690976241711_image_7.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976468887_1690976241711_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64ca41160faf29427ac9b4f8",
  "name": "externallmg_r_1690976473430_1690976241711_image_9.jpg",
  "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976473430_1690976241711_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "64ca41160faf29427ac9b4f9",
    "name": "externallmg_r_1690976472210_1690976241711_image_8.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976472210_1690976241711_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4fa",
    "name": "externallmg_r_1690976475851_1690976241711_image_11.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976475851_1690976241711_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4fb",
    "name": "externallmg_r_1690976474336_1690976241711_image_10.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976474336_1690976241711_image_10.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4fc",
    "name": "externallmg_r_1690976476940_1690976241711_image_12.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976476940_1690976241711_image_12.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4fd",
    "name": "externallmg_r_1690976478672_1690976241711_image_13.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externallmg_r_1690976478672_1690976241711_image_13.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4fe",
```

```
    "name": "externalImg_r_1690976479948_1690976241711_image_14.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalImg_r_1690976479948_1690976241711_image_14.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b4ff",
    "name": "externalImg_r_1690976481694_1690976241711_image_15.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalImg_r_1690976481694_1690976241711_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b500",
    "name": "externalImg_r_1690976483462_1690976241711_image_16.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalImg_r_1690976483462_1690976241711_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b501",
    "name": "externalImg_r_1690976484412_1690976241711_image_17.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalImg_r_1690976484412_1690976241711_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ca41160faf29427ac9b502",
    "name": "externalImg_r_1690976486617_1690976241711_image_18.jpg",
    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalImg_r_1690976486617_1690976241711_image_18.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Jayesh Keshav Gavade.doc",
    "filename": "1691146335832_Jayesh_Keshav_Gavade.doc",
```



```

    "path": "cases/64c0d26e9d3a3e4ed9c16239/
externalDocuments/1691146335832_Jayesh_Keshav_Gavade.doc",
    "size": "5422592",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Fri Aug 04 2023 16:22:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"createdAt": "2023-07-26T07:59:42.742Z",
"updatedAt": "2023-08-04T10:52:45.508Z",
"__v": 0,
"invoiceId": "64c0d26e9d3a3e4ed9c16247",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Jayesh Keshav Gavade",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819237399",
"siteVisitDate": "2023-08-02"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			