

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "just_dial",
    "label": "Just Dial"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "64c8a781a5c3051014f5e151",
    "type": "PRIVATE_CLIENT",
    "name": "Laxminarayan B Sharma",
    "displayName": "Laxminarayan B Sharma",
    "initial": "L"
  },
  "branch": ""
}
```

```
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "FRONTDESK",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "shortName": "JB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f949ce45132d6a6bddbcc3",
    "role": "SITEENGINEER",
    "firstName": "Tushar ",
    "email": "tusharbhuwad90@gmail.com",
    "lastName": "Bhuwad",
    "mobileNo": "9082053889",
    "designation": "",
    "shortName": "TSB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    }
  ]
}
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.10444886918001",
  "longitude": "72.84161426441776"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-01T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-01T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-01T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-01T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-01T09:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": []
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Harivijay",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bhagat Singh Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```

```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```



```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vile Parle West",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64c8a79aa5c3051014f5e15b",
"ownerName": "Laxminarayan B Sharma",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8209747869",
"contactPersonName": "Bharat Sharma",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Laxminarayan B Sharma",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "313669"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fdcf2",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 501, 5th Floor, Wing - A, Harivijay, Bhagat Singh
Road, Village - Vile Parle, Vile Parle West, Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1690871636102_HARIVIJAY_AGREEMT.pdf",
    "path": "cases/64c8a79aa5c3051014f5e15b/
document_1690871636102_HARIVIJAY_AGREEMT.pdf",
    "id": "142732",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Aug 01 2023 12:04:41 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
```



```
    "displayStatus": false,
    "fileName": "document_1690871675945_SKMBT_C22023072815360.pdf",
    "path": "cases/64c8a79aa5c3051014f5e15b/
document_1690871675945_SKMBT_C22023072815360.pdf",
    "id": "301526",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Tue Aug 01 2023 12:04:41 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "002873",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "226428",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Aug 01 2023 12:05:06 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca105d3bd5b9059271e0cd",
    "name": "externalImg_r_1690964060840_IMG20230802103452.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalImg_r_1690964060840_IMG20230802103452.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca105d3bd5b9059271e0ce",
    "name": "externalImg_r_1690964060919_IMG20230802103508.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalImg_r_1690964060919_IMG20230802103508.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e109",
  "name": "externallmg_r_1690964102237_IMG20230801153318.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102237_IMG20230801153318.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e10a",
  "name": "externallmg_r_1690964102250_IMG20230801153434.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102250_IMG20230801153434.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e10b",
  "name": "externallmg_r_1690964102231_IMG20230801152335.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102231_IMG20230801152335.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e10c",
  "name": "externallmg_r_1690964102246_IMG20230801153430.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102246_IMG20230801153430.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e10d",
  "name": "externallmg_r_1690964102253_IMG20230801153439.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102253_IMG20230801153439.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10863bd5b9059271e10e",
      "name": "externalimg_r_1690964102256_IMG20230801153455.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964102256_IMG20230801153455.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10863bd5b9059271e10f",
      "name": "externalimg_r_1690964102259_IMG20230801153545.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964102259_IMG20230801153545.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10863bd5b9059271e110",
      "name": "externalimg_r_1690964102263_IMG20230801155337.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964102263_IMG20230801155337.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10863bd5b9059271e111",
      "name": "externalimg_r_1690964102266_IMG20230801155736.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964102266_IMG20230801155736.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10863bd5b9059271e112",
      "name": "externalimg_r_1690964102270_IMG20230801155824.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964102270_IMG20230801155824.jpg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e113",
  "name": "externallmg_r_1690964102273_IMG20230801155834.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102273_IMG20230801155834.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e114",
  "name": "externallmg_r_1690964102279_IMG20230801160050.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102279_IMG20230801160050.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e115",
  "name": "externallmg_r_1690964102276_IMG20230801160043.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102276_IMG20230801160043.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e116",
  "name": "externallmg_r_1690964102282_IMG20230801160121.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102282_IMG20230801160121.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10863bd5b9059271e117",
  "name": "externallmg_r_1690964102286_IMG20230801160158.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964102286_IMG20230801160158.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e190",
    "name": "externallmg_r_1690964155435_IMG20230801153312.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964155435_IMG20230801153312.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e191",
    "name": "externallmg_r_1690964155482_IMG20230801153413.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964155482_IMG20230801153413.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e192",
    "name": "externallmg_r_1690964155439_IMG20230801153324.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964155439_IMG20230801153324.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e193",
    "name": "externallmg_r_1690964155433_IMG20230801152617.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964155433_IMG20230801152617.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e194",
    "name": "externallmg_r_1690964155485_IMG20230801153419.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964155485_IMG20230801153419.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64ca10bb3bd5b9059271e195",
    "name": "externalimg_r_1690964155488_IMG20230801153438.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155488_IMG20230801153438.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e196",
    "name": "externalimg_r_1690964155491_IMG20230801153449.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155491_IMG20230801153449.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e197",
    "name": "externalimg_r_1690964155494_IMG20230801153501.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155494_IMG20230801153501.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e198",
    "name": "externalimg_r_1690964155497_IMG20230801153510.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155497_IMG20230801153510.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e199",
    "name": "externalimg_r_1690964155500_IMG20230801153513.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155500_IMG20230801153513.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64ca10bb3bd5b9059271e19a",
    "name": "externalimg_r_1690964155506_IMG20230801153518.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155506_IMG20230801153518.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e19b",
    "name": "externalimg_r_1690964155510_IMG20230801153524.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155510_IMG20230801153524.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e19c",
    "name": "externalimg_r_1690964155513_IMG20230801153527.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155513_IMG20230801153527.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e19d",
    "name": "externalimg_r_1690964155517_IMG20230801153533.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155517_IMG20230801153533.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e19e",
    "name": "externalimg_r_1690964155520_IMG20230801155308.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155520_IMG20230801155308.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e19f",
```

```
    "name": "externalimg_r_1690964155522_IMG20230801155333.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155522_IMG20230801155333.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e1a0",
    "name": "externalimg_r_1690964155525_IMG20230801155349.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155525_IMG20230801155349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e1a1",
    "name": "externalimg_r_1690964155527_IMG20230801155352.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155527_IMG20230801155352.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e1a2",
    "name": "externalimg_r_1690964155588_IMG20230801155728.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155588_IMG20230801155728.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10bb3bd5b9059271e1a3",
    "name": "externalimg_r_1690964155598_IMG20230801155828.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964155598_IMG20230801155828.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22a",
    "name": "externalimg_r_1690964209539_IMG20230801155333.jpg",
```



```
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209539_IMG20230801155333.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22b",
    "name": "externallmg_r_1690964209542_IMG20230801155349.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209542_IMG20230801155349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22c",
    "name": "externallmg_r_1690964209550_IMG20230801155728.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209550_IMG20230801155728.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22d",
    "name": "externallmg_r_1690964209546_IMG20230801155352.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209546_IMG20230801155352.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22e",
    "name": "externallmg_r_1690964209556_IMG20230801155828.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209556_IMG20230801155828.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca10f13bd5b9059271e22f",
    "name": "externallmg_r_1690964209559_IMG20230801155859.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209559_IMG20230801155859.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e230",
  "name": "externallmg_r_1690964209563_IMG20230801155900.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209563_IMG20230801155900.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e231",
  "name": "externallmg_r_1690964209566_IMG20230801155904.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209566_IMG20230801155904.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e232",
  "name": "externallmg_r_1690964209569_IMG20230801155907.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209569_IMG20230801155907.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e233",
  "name": "externallmg_r_1690964209575_IMG20230801155932.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209575_IMG20230801155932.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e234",
  "name": "externallmg_r_1690964209580_IMG20230801155936.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209580_IMG20230801155936.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10f13bd5b9059271e235",
      "name": "externalimg_r_1690964209572_IMG20230801155931.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964209572_IMG20230801155931.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10f13bd5b9059271e236",
      "name": "externalimg_r_1690964209583_IMG20230801160042.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964209583_IMG20230801160042.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10f13bd5b9059271e237",
      "name": "externalimg_r_1690964209586_IMG20230801160047.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964209586_IMG20230801160047.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10f13bd5b9059271e238",
      "name": "externalimg_r_1690964209590_IMG20230801160049.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964209590_IMG20230801160049.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ca10f13bd5b9059271e239",
      "name": "externalimg_r_1690964209593_IMG20230801160058.jpg",
      "path": "cases/64c8a79aa5c3051014f5e15b/
externalimg_r_1690964209593_IMG20230801160058.jpg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e23a",
  "name": "externallmg_r_1690964209596_IMG20230801160119.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209596_IMG20230801160119.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e23b",
  "name": "externallmg_r_1690964209599_IMG20230801160122.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209599_IMG20230801160122.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e23c",
  "name": "externallmg_r_1690964209602_IMG20230801160134.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209602_IMG20230801160134.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca10f13bd5b9059271e23d",
  "name": "externallmg_r_1690964209605_IMG20230801160149.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964209605_IMG20230801160149.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e285",
  "name": "externallmg_1690964223889_Screenshot_2023080115452761_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/externallmg_1690964223889_Screens
hot_2023080115452761_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e286",
  "name": "externallmg_r_1690964223898_IMG20230801152623.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964223898_IMG20230801152623.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e287",
  "name": "externallmg_r_1690964223893_IMG20230801152523.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964223893_IMG20230801152523.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e288",
  "name": "externallmg_r_1690964223905_IMG20230801153538.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964223905_IMG20230801153538.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e289",
  "name": "externallmg_r_1690964223903_IMG20230801153531.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964223903_IMG20230801153531.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ca11003bd5b9059271e28a",
  "name": "externallmg_r_1690964223907_IMG20230801155833.jpg",
  "path": "cases/64c8a79aa5c3051014f5e15b/
externallmg_r_1690964223907_IMG20230801155833.jpg",
  "orientation": "portrait"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ca11003bd5b9059271e28b",
    "name": "externalImg_r_1690964223910_IMG20230801160044.jpg",
    "path": "cases/64c8a79aa5c3051014f5e15b/
externalImg_r_1690964223910_IMG20230801160044.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-01T06:35:06.396Z",
"updatedAt": "2023-08-02T08:17:04.047Z",
"__v": 0,
"invoiceId": "64c8a79aa5c3051014f5e161",
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			