

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb59"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231331",
    "firstName": "Namrata Ghone",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9769152981"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
    "city": "Nashik"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb59",
  "branchCode": "000352",
  "type": "BRANCH",
  "name": "RACPC Nashik ",
  "email": "sbi.10518@sbi.co.in",
  "mobileNo": "02532501640",
  "alternateMobileNo": "",
  "address": "1st Floor,Patel Plaza ,N.D.Patel Road,Opp BSNL,Landmark Seawoods
Navratna Hotel Nashik-422001",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "643a91f233d16f6b1237a4ee",
    "role": "SITEENGINEER",
    "firstName": "Pankaj",
    "email": "pankajpachore510@gmail.com",
    "lastName": "Pachore",
    "mobileNo": "7709956078",
    "shortName": "PA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/643a91f233d16f6b1237a4ee/
profilePhoto_1689049435398_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
```

```
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19°57'34.9\"N",
  "longitude": "73°49'40.9\"E"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
}
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Deolali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Siddhivinayak",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near K.J. Maheta High School Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Nashik Pune Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Ashtavinayak Residency Co.Op.Hsg.Soc.Ltd.Nashik ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "17/C/5+6+17/A/2 17/B+17/C/4",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "12",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": true,
"name": "Mouza",
"key": "mouza",
"value": "Nashik",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422 401",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```



```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "NEW",
"_id": "64c8e404a5c3051014f676c1",
"ownerName": "Harshal Subhash Chaudhari",
"ownerPhoneNo": "9890612272",
"fullAddress": "Flat No. 12, 3rd Floor, Siddhivinayak, Ashtavinayak Residency
Co.Op.Hsg.Soc.Ltd.Nashik , Near K.J. Maheta High School Road, Nashik Pune Road,
Village - Deolali, Mouza Nashik, Taluka - Nashik, District - Nashik, Nashik, 422 401,
State - Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "from": {
      "value": "Owner",
      "label": "Owner"
    },
    "Owner": "Harshal Subhash Chaudhari",
    "to": {
      "value": "buyer",
      "label": "buyer"
    },
    "buyer": "Harshal Subhash Chaudhari"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690887086276_Agreement_to_Sale_1.pdf",
  "path": "cases/64c8e404a5c3051014f676c1/
document_1690887086276_Agreement_to_Sale_1.pdf",
  "id": "700141",
  "uploadedBy": "643a91f233d16f6b1237a4ee",
  "createdAt": "Tue Aug 01 2023 16:22:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "Nashik Road/18570/3322 dated 29.07.2017"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690887133816_Type_C_Building_Plan.pdf",
  "path": "cases/64c8e404a5c3051014f676c1/
document_1690887133816_Type_C_Building_Plan.pdf",
  "id": "665480",
  "uploadedBy": "643a91f233d16f6b1237a4ee",
  "createdAt": "Tue Aug 01 2023 16:22:28 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002876",
"createdBy": "643a91f233d16f6b1237a4ee",
"caseHistory": [
  {
    "id": "668335",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 01 2023 16:22:52 GMT+0530 (India Standard Time)"
  }
],
"owners": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67a96",
    "name":
"externallmg_1690887266660_ce7605dea5274437868624258b7184c0.jpg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266660_ce7605dea5274437868624258b7184c0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67a97",
```



```
"name":
"externalImg_1690887266673_WhatsApp_Image_20230801_at_122129_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externalImg_1690887266673_WhatsApp_Image_20230801_at_122129_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a98",
  "name":
"externalImg_1690887266688_WhatsApp_Image_20230801_at_122130_PM_1.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externalImg_1690887266688_WhatsApp_Image_20230801_at_122130_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a99",
  "name":
"externalImg_1690887266705_WhatsApp_Image_20230801_at_122130_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externalImg_1690887266705_WhatsApp_Image_20230801_at_122130_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9a",
  "name":
"externalImg_1690887266710_WhatsApp_Image_20230801_at_122131_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externalImg_1690887266710_WhatsApp_Image_20230801_at_122131_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9b",
  "name":
"externalImg_1690887266729_WhatsApp_Image_20230801_at_122132_PM_1.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externalImg_1690887266729_WhatsApp_Image_20230801_at_122132_PM_1.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9c",
  "name":
"externallmg_1690887266738_WhatsApp_Image_20230801_at_122132_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266738_WhatsApp_Image_20230801_at_122132_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9d",
  "name":
"externallmg_1690887266754_WhatsApp_Image_20230801_at_122133_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266754_WhatsApp_Image_20230801_at_122133_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9e",
  "name":
"externallmg_1690887266772_WhatsApp_Image_20230801_at_122134_PM_1.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266772_WhatsApp_Image_20230801_at_122134_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67a9f",
  "name":
"externallmg_1690887266782_WhatsApp_Image_20230801_at_122134_PM.jpeg",
  "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266782_WhatsApp_Image_20230801_at_122134_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c8e462a5c3051014f67aa0",
  "name":
"externallmg_1690887266792_WhatsApp_Image_20230801_at_122135_PM.jpeg",
```

```
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266792_WhatsApp_Image_20230801_at_122135_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa1",
    "name":
"externallmg_1690887266798_WhatsApp_Image_20230801_at_122136_PM_1.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266798_WhatsApp_Image_20230801_at_122136_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa2",
    "name":
"externallmg_1690887266807_WhatsApp_Image_20230801_at_122136_PM.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266807_WhatsApp_Image_20230801_at_122136_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa3",
    "name":
"externallmg_1690887266812_WhatsApp_Image_20230801_at_122137_PM.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266812_WhatsApp_Image_20230801_at_122137_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa4",
    "name":
"externallmg_1690887266817_WhatsApp_Image_20230801_at_122138_PM.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266817_WhatsApp_Image_20230801_at_122138_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "64c8e462a5c3051014f67aa5",
    "name":
"externallmg_1690887266824_WhatsApp_Image_20230801_at_122139_PM_1.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266824_WhatsApp_Image_20230801_at_122139_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa6",
    "name":
"externallmg_1690887266830_WhatsApp_Image_20230801_at_122139_PM.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266830_WhatsApp_Image_20230801_at_122139_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c8e462a5c3051014f67aa7",
    "name":
"externallmg_1690887266839_WhatsApp_Image_20230801_at_122140_PM.jpeg",
    "path": "cases/64c8e404a5c3051014f676c1/
externallmg_1690887266839_WhatsApp_Image_20230801_at_122140_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-01T10:52:52.781Z",
"updatedAt": "2023-08-01T10:54:26.954Z",
"__v": 0,
"invoiceId": "64c8e405a5c3051014f676d0",
"updatedBy": "636a1ad14d42487767af3f91"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			