

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231032",
    "firstName": "Namrata ",
    "email": "racpc.sion@sbi.co.in",
    "mobileNo": "",
    "workMobileNo": "8879237774",
    "lastName": "Salvi"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8000000",
    "discussWithPerson": "Namrata ",
    "expectedFees": 4000,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
```

```
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.04498768965623",
  "longitude": "72.84321622966434"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84321622966434,
    19.04498768965623
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
```

```
{
  "status": "COMPLETED",
  "dateTime": "2023-08-03",
  "remark": "No road acces to this bldg. Pls check tha photos. "
},
{
  "status": "COMPLETED",
  "dateTime": "2023-08-03",
  "remark": "No road acces to this bldg. Pls check tha photos. "
},
{
  "status": "COMPLETED",
  "dateTime": "2023-08-03",
  "remark": "No road acces to this bldg. Pls check tha photos. "
}
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Mahim Division",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dadar (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "162",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prafullaban Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "D. L. Vaidya Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Mirandawadi",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "168, TPS IV",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "205",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 028",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
    "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
```

```
"label": "Joint Ownership"
},
"populationClassList": {
  "label": "Middle Class",
  "value": "MiddleClass"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Bhartiya Kamgar Sena",
  "west": "Internal Road & Matoshree Heights",
  "south": "Ahilya Niwas",
  "east": "Sairaj Dham CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "39286",
  "depreciatedBuildingRate": "2086"
},
"igrRate": {
  "propertyName": "Mahim Division",
  "rate": "268290",
  "landRate": "112910",
  "igrImage": "cases/64ca42d10faf29427ac9b926/igr_1691147163879_Image.png",
  "squareMeterGuideLineRate": "268290.00",
```

```
"squareFeetGuideLineRate": "24925.00"
},
"igrFinalRate": {
  "rate": "22471.00",
  "squareFeetGuideLineRate": "22471.00",
  "squareMeterGuideLineRate": "241875.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "29,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Electricity Bill Consumer No.618-659-006*7",
  "meterCardHolderName": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
```

```
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
}
```

```
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "6",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "360.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64ca42d10faf29427ac9b926/
routeMap_1691213894362_Image.png",
    "routeLat": "19.022806",
    "routeLng": "72.840306",
    "stationName": "Dadar",
    "routeDistance": "850 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
}
```



```
"locationMapImg": [
  {
    "id": "sjuy2h",
    "name": "sjuy2h",
    "image": "cases/64ca42d10faf29427ac9b926/
routeMap_1691213823271_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "14142960.00",
  "bookValue": "0",
  "finalValue": "14142960.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8089560.00",
  "selectedBuildUpValue": "360.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64cba92b2ccdc2701668a82c",
      "name": "externalImg_1691068632029_1691068423996_image_17.jpeg",
      "path": "cases/64ca42d10faf29427ac9b926/
externalImg_1691068632029_1691068423996_image_17.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a816",
    "name": "externallmg_1691068670713_1691068462224_image_12.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670713_1691068462224_image_12.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a815",
    "name": "externallmg_1691068670701_1691068462224_image_11.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670701_1691068462224_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a819",
    "name": "externallmg_1691068671388_1691068462224_image_15.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671388_1691068462224_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a818",
    "name": "externallmg_1691068671345_1691068462224_image_14.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671345_1691068462224_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a82c",
    "name": "externallmg_1691068632029_1691068423996_image_17.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068632029_1691068423996_image_17.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a80a",
    "name": "Living Room",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068668960_1691068462224_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a80f",
    "name": "Living Room",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669983_1691068462224_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a80e",
    "name": "Living Room",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669951_1691068462224_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a810",
    "name": "Living Room",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670147_1691068462224_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cba92b2ccdc2701668a812",
    "name": "Living Room",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670189_1691068462224_image_8.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "35088",
"max": "41990"
},
"builtUpRateRange": {
  "min": "35088",
  "max": "41990"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "360.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64ca42d10faf29427ac9b926",
"ownerName": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav",
"ownerPhoneNo": "9082943837",
"appAddress": "Flat no. 205, 2nd Floor, Praffulaban CHS, Village - Mahim, Dadar West
",
"remark": "No road acces to this bldg. Pls check tha photos. ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },

```

```
"inputs": {
  "documentDate": "19/06/2018",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Rajmani R. Mishra",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1691212236198_document_1690976931664_Racpc_Sion_
Rajesh_Yadav.pdf",
"path": "cases/64ca42d10faf29427ac9b926/document_1691212236198_document_
1690976931664_Racpc_Sion_Rajesh_Yadav.pdf",
"id": "945754",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Sat Aug 05 2023 10:40:36 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "31/01/2006",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "-"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691212781183_OC.pdf",
  "path": "cases/64ca42d10faf29427ac9b926/document_1691212781183_OC.pdf",
  "id": "655173",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
```

```
"createdAt": "Sat Aug 05 2023 10:49:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "22/09/2018",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "27"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691212847860_Share_Cer.pdf",
  "path": "cases/64ca42d10faf29427ac9b926/
document_1691212847860_Share_Cer.pdf",
  "id": "921619",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Aug 05 2023 10:50:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "07/07/2023",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "618-659-006*7"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691212938861_Electr.pdf",
    "path": "cases/64ca42d10faf29427ac9b926/document_1691212938861_Electr.pdf",
    "id": "262844",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Sat Aug 05 2023 10:52:18 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002897",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "277868",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 02 2023 17:19:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajesh Timmal Yadav & Mrs. Geeta Rajesh Yadav",
    "phone": "9082943837",
    "ownershipShare": "",
    "email": "",
    "id": "414257"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "859791",
    "name": "Living Room",
    "length": "9.83",
    "length1": "9",
    "length2": "10",
    "width": "9.33",
    "width1": "9",
    "width2": "4",
    "totalArea": "91.78",
    "images": []
  }
]
```

```
"extraAreas": [],
"finalArea": "91.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "81.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "91.84",
  "images": [],
  "extraAreas": [],
  "finalArea": "91.84"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
```

```
"length": "4.67",
"length1": "4",
"length2": "8",
"width": "3.08",
"width1": "3",
"width2": "1",
"totalArea": "14.39",
"images": [],
"extraAreas": [],
"finalArea": "14.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "17.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.11"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "793846",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "360",
    "squareMeterArea": "33.44",
```

```

    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64ccdbbc6161ec774b1d29e5",
    "property": "D. L. Vaidya Marg, Dadar West",
    "area": "225",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "https://www.99acres.com/",
    "expectedPrice": "9000000",
    "expectedRate": "40000.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64ca42d10faf29427ac9b926/
indicator_1691145661366_Image.png",
    "squareMeter": "20.90",
    "id": "618235"
  },
  {
    "printlnReport": true,
    "_id": "64ccdbbc6161ec774b1d29e6",
    "property": "Sita Smruti, dadar West",
    "area": "650",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "27000000",
    "expectedRate": "41538.46",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64ca42d10faf29427ac9b926/
indicator_1691145786294_Image.png",
    "squareMeter": "60.39",

```

```
"id": "852202"
},
{
  "printlnReport": true,
  "_id": "64ccdbbc6161ec774b1d29e7",
  "property": "Shree Sadan, Dadar West",
  "area": "513",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "18000000",
  "expectedRate": "35087.72",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64ca42d10faf29427ac9b926/
indicator_1691145888179_Image.png",
  "squareMeter": "47.66",
  "id": "489365"
},
{
  "printlnReport": true,
  "_id": "64ccdbbc6161ec774b1d29e8",
  "property": "Matoshree Apartment, Dadar West",
  "area": "774",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "6",
  "source": "magic_bricks",
  "expectedPrice": "32500000",
  "expectedRate": "41989.66",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64ca42d10faf29427ac9b926/
indicator_1691146131641_Image.png",
  "squareMeter": "71.91",
  "id": "273974"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80a",
```



```
    "name": "externallmg_1691068668960_1691068462224_image_0.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068668960_1691068462224_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80b",
    "name": "externallmg_1691068669660_1691068462224_image_1.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669660_1691068462224_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80c",
    "name": "externallmg_1691068669748_1691068462224_image_2.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669748_1691068462224_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80d",
    "name": "externallmg_1691068669921_1691068462224_image_3.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669921_1691068462224_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80e",
    "name": "externallmg_1691068669951_1691068462224_image_4.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669951_1691068462224_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a80f",
    "name": "externallmg_1691068669983_1691068462224_image_5.jpeg",
```

```
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068669983_1691068462224_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a810",
    "name": "externallmg_1691068670147_1691068462224_image_6.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670147_1691068462224_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a811",
    "name": "externallmg_1691068670162_1691068462224_image_7.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670162_1691068462224_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a812",
    "name": "externallmg_1691068670189_1691068462224_image_8.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670189_1691068462224_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a813",
    "name": "externallmg_1691068670220_1691068462224_image_9.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670220_1691068462224_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a814",
    "name": "externallmg_1691068670661_1691068462224_image_10.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670661_1691068462224_image_10.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cba92b2ccdc2701668a815",
  "name": "externallmg_1691068670701_1691068462224_image_11.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670701_1691068462224_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cba92b2ccdc2701668a816",
  "name": "externallmg_1691068670713_1691068462224_image_12.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068670713_1691068462224_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cba92b2ccdc2701668a817",
  "name": "externallmg_1691068671118_1691068462224_image_13.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671118_1691068462224_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cba92b2ccdc2701668a818",
  "name": "externallmg_1691068671345_1691068462224_image_14.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671345_1691068462224_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cba92b2ccdc2701668a819",
  "name": "externallmg_1691068671388_1691068462224_image_15.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671388_1691068462224_image_15.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cba92b2ccdc2701668a81a",
    "name": "externallmg_1691068671419_1691068462224_image_16.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068671419_1691068462224_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a81b",
    "name": "externallmg_1691068630716_1691068423996_image_0.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068630716_1691068423996_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a81c",
    "name": "externallmg_1691068630955_1691068423996_image_1.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068630955_1691068423996_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a81d",
    "name": "externallmg_1691068631027_1691068423996_image_2.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631027_1691068423996_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a81e",
    "name": "externallmg_1691068631047_1691068423996_image_3.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631047_1691068423996_image_3.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64cba92b2ccdc2701668a81f",
  "name": "externallmg_1691068631119_1691068423996_image_4.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631119_1691068423996_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64cba92b2ccdc2701668a820",
  "name": "externallmg_1691068631124_1691068423996_image_5.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631124_1691068423996_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64cba92b2ccdc2701668a821",
  "name": "externallmg_1691068631221_1691068423996_image_6.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631221_1691068423996_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64cba92b2ccdc2701668a822",
  "name": "externallmg_1691068631224_1691068423996_image_7.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631224_1691068423996_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64cba92b2ccdc2701668a823",
  "name": "externallmg_1691068631320_1691068423996_image_8.jpeg",
  "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631320_1691068423996_image_8.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a824",
    "name": "externallmg_1691068631326_1691068423996_image_9.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631326_1691068423996_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a825",
    "name": "externallmg_1691068631419_1691068423996_image_10.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631419_1691068423996_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a826",
    "name": "externallmg_1691068631621_1691068423996_image_11.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631621_1691068423996_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a827",
    "name": "externallmg_1691068631625_1691068423996_image_12.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631625_1691068423996_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a828",
    "name": "externallmg_1691068631628_1691068423996_image_13.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externallmg_1691068631628_1691068423996_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "64cba92b2ccdc2701668a829",
    "name": "externalimg_1691068631826_1691068423996_image_14.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externalimg_1691068631826_1691068423996_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a82a",
    "name": "externalimg_1691068631922_1691068423996_image_15.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externalimg_1691068631922_1691068423996_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a82b",
    "name": "externalimg_1691068632025_1691068423996_image_16.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externalimg_1691068632025_1691068423996_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a82c",
    "name": "externalimg_1691068632029_1691068423996_image_17.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externalimg_1691068632029_1691068423996_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64cba92b2ccdc2701668a82d",
    "name": "externalimg_1691068632125_1691068423996_image_18.jpeg",
    "path": "cases/64ca42d10faf29427ac9b926/
externalimg_1691068632125_1691068423996_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-02T11:49:37.920Z",
```

```
"updatedAt": "2023-08-05T06:06:16.417Z",
"__v": 0,
"invoiceId": "64ca42d20faf29427ac9b939",
"fullAddress": "Residential Flat No. 205, 2nd Floor, Prafullaban Co-op. Hsg. Soc. Ltd.,
Mirandawadi, Plot No. 162, D. L. Vaidya Road, Village - Mahim Division, District -
Mumbai, Dadar (West), PIN - 400 028, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Rajesh Yadav ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9082943837",
"buildingServicesRate": "2800.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 360.00",
"flatRate": "40000.00",
"landOtherRate": "37200",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom",
"carpetTotal": "296.90",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "356.28",
"finalCarpetArea": "296.90",
"finalSalableArea": "391.91",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 300.00\n(Area as per Agreement
for sale)\n",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"siteVisitDate": "2023-08-03"
}
```



<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	9'10"	9'4"	91.78
Kitchen	7'8"	10'8"	81.78
Bedroom	9'7"	9'7"	91.84
WC	4'8"	3'1"	14.39
Bathroom	4'8"	3'8"	17.11
Other Composition :			