

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2174000",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": 1087,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State -
Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
```

```
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.19157185279909",
  "longitude": "72.8570677509242"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8570677509242,
    19.19157185279909
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-03T06:30:00.000Z",
```

```
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-08-03T17:16:26.026Z",
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": "person meet at site-Mr Naresh Patel -096192 67715\n",
  "rateMin": "17000",
  "lumpsumValue": "4500000-5000000",
  "rateMax": "18000",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kurar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Malad (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Borivali",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "58",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Adcon Residency Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Pushpa Park, Road No. 4, Behind Classic Hotel",
  "label": false
},
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "169/169-A, 169/1 to 10",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "603",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 097",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid door with safety door",
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering with POP Finished",
    "value": "Cement_Plastering_with_POP_Finished"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road & Under Construction Building",
    "south": "Sai Palace CHSL",
    "east": "Road No. 4",
    "west": "Pushpa Park Road No. 3"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
```

```
"rate": "102510",
"landRate": "42270",
"igrImage": "cases/64cb3c7a0faf29427aca1e8c/igr_1691232910602_Image.png",
"squareMeterGuideLineRate": "107636.00",
"squareFeetGuideLineRate": "10000.00"
},
"igrFinalRate": {
  "rate": "9696.00",
  "squareFeetGuideLineRate": "9696.00",
  "squareMeterGuideLineRate": "104367.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": "11,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "label": "6\" Thk. Brick Masonery",
  "value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2019",
  "fullDate": "1/1/2019"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"materialUsedList": {
```

```
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"maintenanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
}
```

```
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "4",
"totalLifeBuilding": "60",
"estimatedAge": "56",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "252.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64cb3c7a0faf29427aca1e8c/
routeMap_1691386983296_Image.png",
    "routeLat": "19.191378",
    "routeLng": "72.857029",
    "stationName": "Malad",
    "routeDistance": "1.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  }
},
```



```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "cmtb5d",
    "name": "cmtb5d",
    "image": "cases/64cb3c7a0faf29427aca1e8c/
routeMap_1691386867196_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4410000.00",
  "bookValue": "0",
  "finalValue": "4410000.00"
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2443392.00",
"selectedBuildUpValue": "252.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "64cbde982ccdc2701668b1f4",
"name": "externalImg_1691082317347_image.jpeg",
```

```
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082317347_image.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1f6",
    "name": "externallmg_1691082319842_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082319842_image.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1f2",
    "name": "externallmg_1691082314738_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082314738_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1f3",
    "name": "externallmg_1691082315869_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082315869_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1fa",
    "name": "externallmg_1691082364607_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364607_image.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1f7",
```

```
    "name": "externallmg_1691082363657_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082363657_image.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b201",
    "name": "Living Room",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082367132_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b202",
    "name": "Living Room",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082367667_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1fd",
    "name": "Living Room",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082365592_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64cbde982ccdc2701668b1fb",
    "name": "Living Room",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364892_image.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20444",
    "max": "22703"
  }
},
```

```
"builtUpRateRange": {
  "min": "17038",
  "max": "18919"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```



```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "210.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64cb3c7a0faf29427aca1e8c",
"ownerName": "Jayshree Naresh Patel",
"ownerPhoneNo": "9619267715",
"appAddress": "Flat no.603 ,6 th floor,Bldg - Adcon Residency Co-op HSG Soc
Ltd,Pushpa park road no.4 , Behind Classic Hotel, Villege kurar Malad East ",
"remark": "contact presen- Naresh Patel (index- 2 mey 1 st owner ka Neam hey &
agreement Jayshree Naresh Patel Neam hey documents pure hey sir)",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "documentDate": "01/08/2023",
```

```
"from": {
  "value": "Vendor",
  "label": "Vendor"
},
"Vendor": "Mr. Bankim Prabodh Randeria",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Mrs. Jayshree Naresh Patel & Mr. Naresh Shankarbhai Patel"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1691385660141_Agreement.pdf",
"path": "cases/64cb3c7a0faf29427aca1e8c/
document_1691385660141_Agreement.pdf",
"id": "839415",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Aug 07 2023 10:51:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/02/2018",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / A-343 / BP (WS) / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691385763072_2147109_FurtherCC_signed.pdf",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
document_1691385763072_2147109_FurtherCC_signed.pdf",
  "id": "340897",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Aug 07 2023 10:52:43 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b337",
    "label": "Full Occupation Certificate"
  },
  "inputs": {
    "documentDate": "18/02/2019",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / A-343 / BP (WS) / AP - BCC / Amend 2"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691385865742_2206878_OC_signed.pdf",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
document_1691385865742_2206878_OC_signed.pdf",
  "id": "507633",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Aug 07 2023 10:54:25 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002905",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "670186",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Aug 03 2023 11:04:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Jayshree Naresh Patel",
    "phone": "9619267715",
    "email": "",
    "ownershipShare": "",
    "id": "607376"
  },
  {

```

```
"name": "Mr. Naresh Shankarbhai Patel",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "697972"
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "495343",
"name": "Living Room",
"length": "12.67",
"length1": "12",
"length2": "8",
"width": "8.75",
"width1": "8",
"width2": "9",
"totalArea": "110.83",
"images": [],
"extraAreas": [],
"finalArea": "110.83"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "7.83",
"length1": "7",
"length2": "10",
"width": "7.67",
"width1": "7",
"width2": "8",
"totalArea": "60.06",
"images": [],
"extraAreas": [],
"finalArea": "60.06"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Passage",
"length": "4.25",
"length1": "4",
"length2": "3",
"width": "2.42",
"width1": "2",
"width2": "5",
"totalArea": "10.27",
"images": [],
"extraAreas": [],
"finalArea": "10.27"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "12.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "3.75",
```

```
"width1": "3",
"width2": "9",
"totalArea": "13.44",
"images": [],
"extraAreas": [],
"finalArea": "13.44"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "230314",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "210",
  "squareMeterArea": "19.51",
  "docFinalBuiltUp": "252",
  "docFinalBuiltUpSquareMeter": "23.412000000000003",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64ce2a95dc9f3034f3ffaf18",
  "property": "Residential Flat",
  "area": "340",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6000000",
  "expectedRate": "17647.06",
```

```
    "builtUpExpectedRate": "0.00",
    "image": "cases/64cb3c7a0faf29427aca1e8c/
indicator_1691232683491_Image.png",
    "squareMeter": "31.59",
    "id": "876072"
  },
  {
    "printlnReport": true,
    "_id": "64ce2a95dc9f3034f3ffaf19",
    "property": "Residential Flat",
    "area": "225",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "4600000",
    "expectedRate": "20444.44",
    "builtUpExpectedRate": "17037.04",
    "image": "cases/64cb3c7a0faf29427aca1e8c/
indicator_1691232707334_Image.png",
    "squareMeter": "20.90",
    "id": "533527"
  },
  {
    "printlnReport": true,
    "_id": "64ce2a95dc9f3034f3ffaf1a",
    "property": "Residential Flat",
    "area": "370",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "7000000",
    "expectedRate": "18918.92",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64cb3c7a0faf29427aca1e8c/
indicator_1691232743660_Image.png",
    "squareMeter": "34.37",
    "id": "931437"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64cbde982ccdc2701668b1f1",
  "name": "externalimg_1691082313083_image.jpeg",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
externalimg_1691082313083_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cbde982ccdc2701668b1f2",
  "name": "externalimg_1691082314738_image.jpeg",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
externalimg_1691082314738_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cbde982ccdc2701668b1f3",
  "name": "externalimg_1691082315869_image.jpeg",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
externalimg_1691082315869_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cbde982ccdc2701668b1f4",
  "name": "externalimg_1691082317347_image.jpeg",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
externalimg_1691082317347_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cbde982ccdc2701668b1f5",
  "name": "externalimg_1691082318582_image.jpeg",
  "path": "cases/64cb3c7a0faf29427aca1e8c/
externalimg_1691082318582_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "64cbde982ccdc2701668b1f6",
    "name": "externallmg_1691082319842_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082319842_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1f7",
    "name": "externallmg_1691082363657_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082363657_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1f8",
    "name": "externallmg_1691082364037_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364037_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1f9",
    "name": "externallmg_1691082364327_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364327_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1fa",
    "name": "externallmg_1691082364607_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364607_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1fb",
```

```
    "name": "externallmg_1691082364892_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082364892_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1fc",
    "name": "externallmg_1691082365142_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082365142_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1fd",
    "name": "externallmg_1691082365592_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082365592_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1fe",
    "name": "externallmg_1691082365972_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082365972_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b1ff",
    "name": "externallmg_1691082366332_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externallmg_1691082366332_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b200",
    "name": "externallmg_1691082366596_image.jpeg",
```

```
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externalImg_1691082366596_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b201",
    "name": "externalImg_1691082367132_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externalImg_1691082367132_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbde982ccdc2701668b202",
    "name": "externalImg_1691082367667_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externalImg_1691082367667_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbe1972ccdc2701668b3ee",
    "name": "externalImg_1691083150697_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externalImg_1691083150697_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cbe1972ccdc2701668b3ef",
    "name": "externalImg_1691083151123_image.jpeg",
    "path": "cases/64cb3c7a0faf29427aca1e8c/
externalImg_1691083151123_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-03T05:34:50.167Z",
"updatedAt": "2023-08-07T06:46:50.480Z",
"__v": 0,
"invoiceId": "64cb3c7a0faf29427aca1e95",
```

"fullAddress": "Residential Flat No. 603, 6th Floor, Adcon Residency Co-op. Hsg. Soc. Ltd., Pushpa Park, Road No. 4, Behind Classic Hotel, Plot No. 58, Village - Kurar, Taluka - Borivali, District - Mumbai Suburban, Malad (East), PIN - 400 097, State - Maharashtra, India",

"updatedBy": "60eeaeddf3dd69653a581316",

"addressForMap": "",

"caseReferredBy": "60af6ae22ffdf65bcd65861d",

"contactPersonName": "Jayshree Naresh Patel",

"email": "",

"isExternal": "false",

"isUrgent": "false",

"ownershipShare": "",

"purchaseValueAsPerDocument": "",

"relationWithOwner": "self",

"siteVisitContactNo": "9619267715",

"briefDescOfProperty": "Living Room + Kitchen + Passage + WC + Bathroom",

"carpetTotal": "206.85",

"finalMeasurementType": "Sq. Ft.",

"otherCarpetTotal": "0.00",

"siteVisitDate": "2023-08-03",

"buildingServicesRate": "2700",

"finalAreaType": "Carpet Area",

"finalAsPerArea": "Agreement for sale",

"finalBuiltUpPercentage": "20",

"finalCarpetConvertToBuiltUpPer": "20",

"finalValuationAreaString": "Carpet Area in Sq. Ft. = 210.00",

"flatRate": "21000",

"landOtherRate": "18300",

"builtupPercentage": "10",

"extendOfSiteRemark": "",

"finalBuiltupArea": "227.53",

"finalCarpetArea": "206.85",

"finalSalableArea": "250.29",

"salablePercentage": "10",

"siteMeasurementRemark": "",

"toBeAdded": "",

"finalSaleablePercentage": "0",

"otherCompositionBuiltUpTotal": "0.00",

"otherCompositionCarpetTotal": "0.00",

"otherCompositionSaleableTotal": "0.00"

}

Name

Length

Width

Total

Composition :

Living Room	12'8"	8'9"	110.83
Kitchen	7'10"	7'8"	60.06
Passage	4'3"	2'5"	10.27
WC	3'6"	3'6"	12.25
Bathroom	3'7"	3'9"	13.44
Other Composition :			