Deepak jain

Inspection report of Residential/ Commercial/ Industrial properties

Name of Bank: cosmoc Date of inspection:5-8-2023

| Tame | of Dalik. Cosinoc | Date of hispection .5-6-2025 |
|-----------|---|--|
| | Name of the Applicant | Pranali wamane |
| 1. | Type of property: | Residental flat |
| 2. | Address of the property | Flat no1011,10 th floor ,1b ,,morarji mill mahada |
| | | sankul ,vishveshwar nagar road,near , ,goregaon east |
| 3. | Nearest Railway station | 550 m away from goregaon station |
| 4. | Name of the road access to | vishveshwar nagar road |
| | the property | |
| 5. | Landmark / vicinity : | Near udipi hotel |
| 6. | Boundaries of the building | North: hetali blessing chsl |
| | | south : road |
| | | east:a wing/road |
| | | west: road |
| 7. | Locality | Type : Residential / Commercial / Industrial / Mix |
| | | Class of people : Lower class/Middle class/ |
| | | Upper Middle class/ Higher class |
| | | Opper whome class/ ringiler class |
| | | Site is: Normal/ above road/ below road |
| 8. | Permitted Land Use | <u>Residential</u> / <u>C</u> ommercial/Industrial/Mix |
| 9. | Actual Land Use | Residential/Commercial/Industrial/Mix |
| 10. | Availability of other | School |
| | amenities in the | Market |
| | surrounding | College |
| | | Temple |
| 11. | Surrounding development | <u>Developed</u> /Well Developed |
| 12. | Occupant | Kamlesh soni /4 years/tenant |
| 13. | Building details | Type of Structure: : (RCC/Load Beaing) |
| | | No. of Floors: gropund+21st floor |
| | | No of wings:2 |
| | | No. of flats/units on each floor:12 flat |
| 14. | No. of lifts with capacity & Status | 3 no with 8 person capacity |
| 15. | Underground & Overhead | 1 no. Overhead Tank & |
| | tanks | 1 no. Under ground Tank |
| 16. | Year of Construction | 2011 |
| 17. | Age of the building | 12 years |
| 18. | Estimated future life of the building | 48 years |
| 19. | Building elevation | Good |
| 20. | Condition of the building: | Good |
| 21. | Finishing | Luster paint / cement |
| 22. | Amenities | Parking, |
| <i></i> . | 111111111111111111111111111111111111111 | i aiking , |

| 23. | Flooring in open spaces and staircase | Open Space Garden tiles & Kotastone staircase |
|-----|---------------------------------------|---|
| 24. | Doors & Windows | Wooden door/safty door |
| 25. | Compound wall & no. of | 8 ft height of compound wall & 2 nos. of MS |
| | gates | Gates & security |
| 26. | No. of rooms | 1 bhk(converted) |
| 27. | View from the different | building |
| | rooms of the property | |
| 28. | Internal finishing | Flooring in different rooms: vitrified Kitchen Platform: granite/stainless steel Electrical: OPEN/CONCEALED Plumbing: OPEN / CONCEALED |
| 29. | Balcony | |
| 31 | Carpet area as per Measurement : | 221sq feet |
| 32 | Nearest Bus stop | Peru baug |
| 33 | Nearest Hospital | Bmc hopsital |
| 34 | Condition of Road | 30 fit good wide road |
| 35 | Rate per sq ft. | |
| 36 | Person Met at Site | Mrs pranali wamne |
| 37 | Coordinate | 19.166861232434794, 72.85371204438917 |
| 38 | Name on society board | Dhondu dhantal uttekar |
| 39 | Name on door | Na |

REMARK

1:the said property 1 rk but converted into 1 bhk. east :open sky west:flat no 1012

north:lobby/flat no 1010 south :open sky