

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b96a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230e7a",
    "firstName": "Pramod Meshram",
    "email": "rlf.aurangabad@bankofbaroda.com",
    "mobileNo": "2060280",
    "workMobileNo": "9922579393"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "64b7cbabd0368073e3fa8872",
    "name": "Aurangabad Branch",
    "shortName": "Aur",
    "email": "aurangabad@vastukala.org",
    "address": "Parimal Housing Society, N 3, Cidco, Aurangabad, Maharashtra 431003",
    "city": "Aurangabad"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b96a",
  "branchCode": "000013",
  "type": "BRANCH",
  "name": "Specializes Mortgage Store Aurangabad",
  "email": "rif.aurangabad@bankofbaroda.com",
  "mobileNo": "02402060280",
  "alternateMobileNo": "02402336190",
  "address": "'Krishna Tower', Plot No. 104, Sahakar Nagar, Shahnour Miya Darga
Road, Aurangabad - 431001",
  "ledgerName": "BOB RLF Aurangabad",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "FRONTDESK",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "shortName": "JB",
```

```

    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fd2c2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "Rajesh",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "Ghadi",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ]
    }
  ]
}

```

```
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.11319249691622",
  "longitude": "73.00107296222056"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-08",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "11000000.00",
  "lumpsumValue": "11300000.00",
  "rateMax": "11300000.00",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Rohinjan",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "15",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",

```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Satyam Trinity Towers",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
```

```
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1506",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
```

```
"label": "Proposed Vitrified tiles flooring",
"value": "Proposed_Vitrified_tiles_flooring"
},
"doors": {
  "label": "Proposed Teak wood door frame with flush doors",
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
},
"windows": {
  "label": "Proposed Powder coated aluminium sliding windows",
  "value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring
with Concealed.",
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_w
iring_with_Concealed."
},
"finishing": {
  "label": "Proposed Cement Plastering",
  "value": "Proposed_Cement_Plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Higher Middle Class",
    "value": "HigherMiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "ADIRAJ",
    "south": "SWAPNAPURTI ",
    "east": "open",
    "west": "OPEN"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
```

```
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "I Class",
    "value": "I_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
    "fullDate": "1/1/2025"
  },
  "propertyTypeList": {
    "value": "Residential",
```

```
"label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": "",
"noOfPodium": "02",
"noOfAmenityFloors": "03",
"noOfFloors": "024",
"noOfDwellingUnitsInBuilding": "06",
"noOfLifts": "03"
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "4",
    "percentage": "5.16",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "1",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "1",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "1",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "1",
  "percentage": "0.11",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "1",
  "percentage": "0.08",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "1",
  "percentage": "0.08",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "1",
  "percentage": "0.32",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "1",
  "percentage": "0.05",
```

```
"isHideFloor": false,
"status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "1",
  "percentage": "0.05",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "1",
  "percentage": "0.16",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "3",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "31.16",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": false,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64cdef04dc9f3034f3ff107d",
"ownerName": "Chalo Anthony Paliakkara ",
"ownerPhoneNo": "8806663151",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8806663151",
"contactPersonName": "Chalo Anthony Paliakkara ",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Chalo Anthony Paliakkara ",
    "phone": "8806663151",
    "ownershipShare": "",
    "email": "",
    "id": "985748"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fdfc2",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 1506, 15th Floor, Wing - B, Satyam Trinity Towers,
Village - Rohinjan, Navi Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691217641523_Chacko_Anthony_Paliakkara.pdf",
    "path": "cases/64cdef04dc9f3034f3ff107d/
document_1691217641523_Chacko_Anthony_Paliakkara.pdf",
    "id": "353287",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Sat Aug 05 2023 12:10:44 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "002961",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
```

```
"id": "493556",
"title": "Create Case",
"description": "Create Case",
"datetime": "Sat Aug 05 2023 12:11:08 GMT+0530 (India Standard Time)"
}
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173c9",
  "name": "externalImg_1691462532048_1691462326668_image_0.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externalImg_1691462532048_1691462326668_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173ca",
  "name": "externalImg_1691462532424_1691462326668_image_1.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externalImg_1691462532424_1691462326668_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173cb",
  "name": "externalImg_1691462534783_1691462326668_image_2.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externalImg_1691462534783_1691462326668_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173cc",
  "name": "externalImg_1691462534828_1691462326668_image_3.jpeg",
```

```
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462534828_1691462326668_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d1ab89dc9f3034f30173cd",
    "name": "externallmg_1691462534898_1691462326668_image_4.jpeg",
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462534898_1691462326668_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d1ab89dc9f3034f30173ce",
    "name": "externallmg_1691462535033_1691462326668_image_5.jpeg",
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462535033_1691462326668_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d1ab89dc9f3034f30173cf",
    "name": "externallmg_1691462535138_1691462326668_image_6.jpeg",
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462535138_1691462326668_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64d1ab89dc9f3034f30173d0",
    "name": "externallmg_1691462504115_1691462296218_image_0.jpeg",
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462504115_1691462296218_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64d1ab89dc9f3034f30173d1",
    "name": "externallmg_1691462504529_1691462296218_image_1.jpeg",
    "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462504529_1691462296218_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173d2",
  "name": "externallmg_1691462507137_1691462296218_image_2.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462507137_1691462296218_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173d3",
  "name": "externallmg_1691462507214_1691462296218_image_3.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462507214_1691462296218_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173d4",
  "name": "externallmg_1691462507284_1691462296218_image_4.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462507284_1691462296218_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173d5",
  "name": "externallmg_1691462507384_1691462296218_image_5.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462507384_1691462296218_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64d1ab89dc9f3034f30173d6",
  "name": "externallmg_1691462507469_1691462296218_image_6.jpeg",
  "path": "cases/64cdef04dc9f3034f3ff107d/
externallmg_1691462507469_1691462296218_image_6.jpeg",
  "orientation": "landscape"
}
```

```
}
],
"externalDocuments": [],
"createdAt": "2023-08-05T06:41:08.752Z",
"updatedAt": "2023-08-08T02:49:58.999Z",
"__v": 0,
"invoiceId": "64cdef04dc9f3034f3ff1081",
"addressForMap": "",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			