

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "firstName": "r. Mohanty",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1180"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  }
}
```

```
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
    "email": "rushipingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
```

```
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "20°01'41.5\"N",
"longitude": "73°50'11.2\"E"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft."
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},

```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Adgaon-2",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "79",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gauri Row Houses",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": true,
"name": "Landmark",
"key": "landmark",
"value": "Near Nishant Garden",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```

```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Row House No. 02",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "561/ 2/ 1",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```



```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "NEW",
"_id": "64d222f087258203eaae3d2b",
"ownerName": "Nitu Ramprakash Tyagi ",
"ownerPhoneNo": "8550960268",
"fullAddress": "Cost Vetting No. Row House No. 02, Basement Floor, Gauri Row
Houses, Near Nishant Garden, Plot No. 79, Village - Adgaon-2, Gut No. 561/ 2/ 1,
Taluka - Nashik, District - Nashik, Nashik, 422007, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae127eaa6d152c1801b3ed",
      "label": "Vetting Estimate"
    }
  },

```

```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691492915305_20230804_01_14_35342ScanFile.pdf",
    "path": "cases/64d222f087258203eaae3d2b/
document_1691492915305_20230804_01_14_35342ScanFile.pdf",
    "id": "969989",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Aug 08 2023 16:41:18 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003011",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "515260",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 08 2023 16:41:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fe5",
    "name":
"externalImg_1691493246085_WhatsApp_Image_20230804_at_45443_PM_2.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externalImg_1691493246085_WhatsApp_Image_20230804_at_45443_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fe6",
    "name":
"externalImg_1691493246126_WhatsApp_Image_20230804_at_45443_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externalImg_1691493246126_WhatsApp_Image_20230804_at_45443_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fe7",
    "name":
"externallmg_1691493246176_WhatsApp_Image_20230804_at_45444_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246176_WhatsApp_Image_20230804_at_45444_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fe8",
    "name":
"externallmg_1691493246202_WhatsApp_Image_20230804_at_45444_PM_2.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246202_WhatsApp_Image_20230804_at_45444_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fe9",
    "name":
"externallmg_1691493246218_WhatsApp_Image_20230804_at_45444_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246218_WhatsApp_Image_20230804_at_45444_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fea",
    "name":
"externallmg_1691493246256_WhatsApp_Image_20230804_at_45445_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246256_WhatsApp_Image_20230804_at_45445_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3feb",
```



```
    "name":
"externallmg_1691493246269_WhatsApp_Image_20230804_at_45445_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246269_WhatsApp_Image_20230804_at_45445_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fec",
    "name":
"externallmg_1691493246308_WhatsApp_Image_20230804_at_45446_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246308_WhatsApp_Image_20230804_at_45446_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fed",
    "name":
"externallmg_1691493246334_WhatsApp_Image_20230804_at_45446_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246334_WhatsApp_Image_20230804_at_45446_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fee",
    "name":
"externallmg_1691493246361_WhatsApp_Image_20230804_at_45447_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246361_WhatsApp_Image_20230804_at_45447_PM_1.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2237e87258203eaae3fef",
    "name":
"externallmg_1691493246445_WhatsApp_Image_20230804_at_45447_PM_2.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246445_WhatsApp_Image_20230804_at_45447_PM_2.jpeg",
    "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2237e87258203eaae3ff0",
  "name":
"externallmg_1691493246490_WhatsApp_Image_20230804_at_45447_PM.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246490_WhatsApp_Image_20230804_at_45447_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2237e87258203eaae3ff1",
  "name":
"externallmg_1691493246568_WhatsApp_Image_20230804_at_45448_PM.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493246568_WhatsApp_Image_20230804_at_45448_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae402a",
  "name":
"externallmg_1691493256616_WhatsApp_Image_20230804_at_45437_PM_1.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256616_WhatsApp_Image_20230804_at_45437_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae402b",
  "name":
"externallmg_1691493256697_WhatsApp_Image_20230804_at_45437_PM.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256697_WhatsApp_Image_20230804_at_45437_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae402c",
  "name":
"externallmg_1691493256768_WhatsApp_Image_20230804_at_45438_PM_1.jpeg",
```

```
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256768_WhatsApp_Image_20230804_at_45438_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae402d",
    "name":
"externallmg_1691493256839_WhatsApp_Image_20230804_at_45438_PM_2.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256839_WhatsApp_Image_20230804_at_45438_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae402e",
    "name":
"externallmg_1691493256904_WhatsApp_Image_20230804_at_45438_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256904_WhatsApp_Image_20230804_at_45438_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae402f",
    "name":
"externallmg_1691493256971_WhatsApp_Image_20230804_at_45439_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493256971_WhatsApp_Image_20230804_at_45439_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae4030",
    "name":
"externallmg_1691493257025_WhatsApp_Image_20230804_at_45439_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257025_WhatsApp_Image_20230804_at_45439_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64d2238987258203eaae4031",
  "name":
"externallmg_1691493257050_WhatsApp_Image_20230804_at_45440_PM_1.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257050_WhatsApp_Image_20230804_at_45440_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae4032",
  "name":
"externallmg_1691493257064_WhatsApp_Image_20230804_at_45440_PM_2.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257064_WhatsApp_Image_20230804_at_45440_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae4033",
  "name":
"externallmg_1691493257094_WhatsApp_Image_20230804_at_45440_PM.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257094_WhatsApp_Image_20230804_at_45440_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae4034",
  "name":
"externallmg_1691493257160_WhatsApp_Image_20230804_at_45441_PM_1.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257160_WhatsApp_Image_20230804_at_45441_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d2238987258203eaae4035",
  "name":
"externallmg_1691493257228_WhatsApp_Image_20230804_at_45441_PM.jpeg",
  "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257228_WhatsApp_Image_20230804_at_45441_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae4036",
    "name":
"externallmg_1691493257256_WhatsApp_Image_20230804_at_45442_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257256_WhatsApp_Image_20230804_at_45442_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae4037",
    "name":
"externallmg_1691493257271_WhatsApp_Image_20230804_at_45442_PM_2.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257271_WhatsApp_Image_20230804_at_45442_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae4038",
    "name":
"externallmg_1691493257296_WhatsApp_Image_20230804_at_45442_PM.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257296_WhatsApp_Image_20230804_at_45442_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d2238987258203eaae4039",
    "name":
"externallmg_1691493257323_WhatsApp_Image_20230804_at_45443_PM_1.jpeg",
    "path": "cases/64d222f087258203eaae3d2b/
externallmg_1691493257323_WhatsApp_Image_20230804_at_45443_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-08T11:11:44.813Z",
"updatedAt": "2023-08-08T11:14:17.490Z",
```

```
"__v": 0,  
"invoiceId": "64d222f187258203eaae3d3f",  
"updatedBy": "63f9ed37ce84bf289ba991ac"  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			