

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "firstName": "Sagar",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1180"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, "
```

```
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
    "email": "rushipingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
```

```
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "20°33'54.5\"N",
"longitude": "74°30'50.7\"E"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft."
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},

```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malegaon Camp",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Malegaon",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3+4",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hemka Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Loknete Vyankatrao Hire Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": true,
"name": "Landmark",
"key": "landmark",
"value": "Opp. Borade Hospital,",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "13/3 &13/4",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```

```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "423 105",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```



```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "NEW",
"_id": "64d229c187258203eaae53fd",
"ownerName": "Lalit Mohanlal Kankariya.",
"ownerPhoneNo": "9422270715",
"fullAddress": "Cost Vetting No. 2, 2nd Floor, Hemka Apartment, Opp. Borade
Hospital,, Plot No. 3+4, New/Current Survey No. 13/3 &13/4, Loknete Vyankatrao Hire
Marg,, Village - Malegaon Camp, Taluka - Malegaon, District - Nashik, Nashik, 423 105,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae127eaa6d152c1801b3ed",
      "label": "Vetting Estimate"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691494812125_LMK_valuation.pdf",
    "path": "cases/64d229c187258203eaae53fd/
document_1691494812125_LMK_valuation.pdf",
    "id": "771796",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Aug 08 2023 17:10:23 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003012",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "811425",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 08 2023 17:10:49 GMT+0530 (India Standard Time)"
  }
],
"owners": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b27",
    "name":
"externalImg_1691495767705_WhatsApp_Image_20230607_at_94421_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externalImg_1691495767705_WhatsApp_Image_20230607_at_94421_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b28",
    "name":
"externalImg_1691495767992_WhatsApp_Image_20230607_at_94422_AM.jpeg",
```

```
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495767992_WhatsApp_Image_20230607_at_94422_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b29",
    "name":
"externallmg_1691495768391_WhatsApp_Image_20230607_at_94423_AM_1.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495768391_WhatsApp_Image_20230607_at_94423_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b2a",
    "name":
"externallmg_1691495768761_WhatsApp_Image_20230607_at_94423_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495768761_WhatsApp_Image_20230607_at_94423_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b2b",
    "name":
"externallmg_1691495769099_WhatsApp_Image_20230607_at_94424_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495769099_WhatsApp_Image_20230607_at_94424_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b2c",
    "name":
"externallmg_1691495769413_WhatsApp_Image_20230607_at_94427_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495769413_WhatsApp_Image_20230607_at_94427_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "64d22d5b87258203eaae6b2d",
  "name":
"externallmg_1691495769879_WhatsApp_Image_20230607_at_94428_AM.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495769879_WhatsApp_Image_20230607_at_94428_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d5b87258203eaae6b2e",
  "name":
"externallmg_1691495770085_WhatsApp_Image_20230607_at_94429_AM_1.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495770085_WhatsApp_Image_20230607_at_94429_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d5b87258203eaae6b2f",
  "name":
"externallmg_1691495770294_WhatsApp_Image_20230607_at_94429_AM_2.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495770294_WhatsApp_Image_20230607_at_94429_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d5b87258203eaae6b30",
  "name":
"externallmg_1691495770484_WhatsApp_Image_20230607_at_94430_AM.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495770484_WhatsApp_Image_20230607_at_94430_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d5b87258203eaae6b31",
  "name":
"externallmg_1691495770690_WhatsApp_Image_20230607_at_94431_AM_1.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495770690_WhatsApp_Image_20230607_at_94431_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b32",
    "name":
"externallmg_1691495770847_WhatsApp_Image_20230607_at_94431_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495770847_WhatsApp_Image_20230607_at_94431_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b33",
    "name":
"externallmg_1691495771053_WhatsApp_Image_20230607_at_94434_AM_1.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495771053_WhatsApp_Image_20230607_at_94434_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b34",
    "name":
"externallmg_1691495771261_WhatsApp_Image_20230607_at_94434_AM_2.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495771261_WhatsApp_Image_20230607_at_94434_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b35",
    "name":
"externallmg_1691495771431_WhatsApp_Image_20230607_at_94434_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495771431_WhatsApp_Image_20230607_at_94434_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d5b87258203eaae6b36",
```

```
    "name":
"externallmg_1691495771640_WhatsApp_Image_20230607_at_94435_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495771640_WhatsApp_Image_20230607_at_94435_AM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d6787258203eaae6b66",
    "name":
"externallmg_1691495781737_WhatsApp_Image_20230607_at_94436_AM_1.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495781737_WhatsApp_Image_20230607_at_94436_AM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d6787258203eaae6b67",
    "name":
"externallmg_1691495781847_WhatsApp_Image_20230607_at_94436_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495781847_WhatsApp_Image_20230607_at_94436_AM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d6787258203eaae6b68",
    "name":
"externallmg_1691495781930_WhatsApp_Image_20230607_at_94437_AM_1.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495781930_WhatsApp_Image_20230607_at_94437_AM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d6787258203eaae6b69",
    "name":
"externallmg_1691495782014_WhatsApp_Image_20230607_at_94437_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782014_WhatsApp_Image_20230607_at_94437_AM.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d6787258203eaae6b6a",
  "name":
"externallmg_1691495782163_WhatsApp_Image_20230607_at_94438_AM_1.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782163_WhatsApp_Image_20230607_at_94438_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d6787258203eaae6b6b",
  "name":
"externallmg_1691495782259_WhatsApp_Image_20230607_at_94438_AM.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782259_WhatsApp_Image_20230607_at_94438_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d6787258203eaae6b6c",
  "name":
"externallmg_1691495782357_WhatsApp_Image_20230607_at_94439_AM.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782357_WhatsApp_Image_20230607_at_94439_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d6787258203eaae6b6d",
  "name":
"externallmg_1691495782507_WhatsApp_Image_20230607_at_94440_AM.jpeg",
  "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782507_WhatsApp_Image_20230607_at_94440_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d22d6787258203eaae6b6e",
  "name":
"externallmg_1691495782669_WhatsApp_Image_20230607_at_94441_AM_1.jpeg",
```

```

    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782669_WhatsApp_Image_20230607_at_94441_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d22d6787258203eaae6b6f",
    "name":
"externallmg_1691495782872_WhatsApp_Image_20230607_at_94441_AM.jpeg",
    "path": "cases/64d229c187258203eaae53fd/
externallmg_1691495782872_WhatsApp_Image_20230607_at_94441_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-08T11:40:49.582Z",
"updatedAt": "2023-08-08T11:56:23.115Z",
"__v": 0,
"invoiceId": "64d229c187258203eaae540c",
"updatedBy": "63f9ed37ce84bf289ba991ac"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			