

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b949"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f50",
    "firstName": "Vishwas Mane",
    "email": "0_default_vishwas.mane@janasevabank.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8779298387"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3925000",
    "discussWithPerson": "Vishwas Mane",
    "expectedFees": 1962.5,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
  }
}
```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b949",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "Borivli (West) Branch",
  "email": "jssbl@mtnl.net.in",
  "mobileNo": "28332893",
  "alternateMobileNo": "",
  "address": "Aravali Business Centre(Phhol Mahal) Ramdas Surtale Marg Off
SOdawala Lane Boriwali (West) Mumbai 4000092",
  "ledgerName": "Janseva Sahakari Bank Borivali (W)",
  "fax": "28998842",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
```

```
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.258022502359783",
  "longitude": "72.85668433179357"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85668433179357,
    19.258022502359783
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-09T09:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-08-11",
    "remark": "MANUAL_IN_TASK"
  }
]
```

```
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Magathane",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "1",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Borivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ashutosh Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sadguru Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Devipada, Sant Gora Kumbhar Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```



```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "217,217/1 to 58 & 218, 218/1 to 32 of Village Magathane",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 066",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
```

```

    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  }
}

```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Gora Kumbhar Road",
  "west": "Ariana Residency",
  "south": "Vrundavan CHSL",
  "east": "SRA Building"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": "Details not available"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "17000",
  "depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Magathane, Borivali",
  "rate": "156390",
  "landRate": "69980",
  "igrImage": "cases/64d3641887258203eaafeac2/igr_1691824793052_Image.png",
  "squareMeterGuideLineRate": "125112.00",
  "squareFeetGuideLineRate": "11623.00"
},
"igrFinalRate": {
  "rate": "10599.00",
  "squareFeetGuideLineRate": "10599.00",
  "squareMeterGuideLineRate": "114086.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Seller_Occupied",
  "label": "Seller Occupied"
},
"monthlyRent": "10,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per SRA norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "40",
"ageOfBuilding": "20",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
```

```
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "270.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64d3641887258203eaafeac2/
routeMap_1691754660342_Image.png",
    "routeLat": "19.223904",
    "routeLng": "72.867358",
    "stationName": "Borivali",
    "routeDistance": "1.9 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "xvscri",
      "name": "xvscri",
      "image": "cases/64d3641887258203eaafeac2/
routeMap_1691754332549_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```



```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4590000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4590000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
"rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2861730.00",
  "selectedBuildUpValue": "270.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64d5b0e58807d30b0ab295b1",
      "name":
"externallmg_1691726053213_IMG_20230810_160204_copy_900x1200.jpg",
      "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053213_IMG_20230810_160204_copy_900x1200.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64d5b0d68807d30b0ab2952b",
      "name": "Living Room",
```

```
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037867_IMG_20230810_155523_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952d",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037880_IMG_20230810_155532_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b3",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053241_IMG_20230810_155510_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64d5b0e58807d30b0ab295ab",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053141_IMG_20230810_160001_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64d5b0d68807d30b0ab29531",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037914_IMG_20230810_155851_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b1",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053213_IMG_20230810_160204_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "64d5b0e58807d30b0ab295af",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053185_IMG_20230810_160142_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d5b0e58807d30b0ab295ad",
    "name": "Living Room",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053159_IMG_20230810_160123_copy_900x1200.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20000",
    "max": "22222"
  },
  "builtUpRateRange": {
    "min": "18182",
    "max": "18519"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "270.00",
```



```
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64d3641887258203eaafeac2",
"ownerName": "Bhimrao Shivaji Shinde",
"ownerPhoneNo": "8652345590",
"appAddress": "Flat no.403,4 th floor, Floor, C -wing Ashutosh Building,Bldg no- 1 ,
Sadguru Nagar,Devipada Borivali East-400066",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "25/07/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Kanhaiyalal Manaji Mistry",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Bhimrao Shivaji Shinde, Mrs. Mandakini Bhimrao Shinde & Mr.
Aakash Bhimrao Shinde"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "774578",
    "path": "cases/64d3641887258203eaafeac2/
document_1691575249317_BhimraoSShindhe.pdf",
    "fileName": "document_1691575249317_BhimraoSShindhe.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "16/06/2017",
```

```
"nameOfApprovingAuthority": {
  "value": "Slum_Rehabilitation_Authority_(SRA)",
  "label": "Slum Rehabilitation Authority (SRA)"
},
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "CE / 9585 / BP (WS) / AR"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1691753497340_229718.pdf",
"path": "cases/64d3641887258203eaafeac2/
document_1691753497340_229718.pdf",
"id": "320754",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Aug 11 2023 17:01:37 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003045",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "571596",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 09 2023 15:32:00 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Bhimrao Shivaji Shinde",
    "phone": "8652345590",
    "email": "",
    "ownershipShare": "",
    "id": "868508"
  },
  {
    "name": "Mrs. Mandakini Bhimrao Shinde",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "495736"
  },
  {

```

```
"name": "Mr. Aakash Bhimrao Shinde",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "360297"
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "855463",
"name": "Living Room",
"length": "11.75",
"length1": "11",
"length2": "9",
"width": "9.42",
"width1": "9",
"width2": "5",
"totalArea": "110.65",
"images": [],
"extraAreas": [],
"finalArea": "110.65"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "7.42",
"length1": "7",
"length2": "5",
"width": "7.75",
"width1": "7",
"width2": "9",
"totalArea": "57.48",
"images": [],
"extraAreas": [],
"finalArea": "57.48"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Toilet",
"length": "5.58",
"length1": "5",
"length2": "7",
"width": "4.67",
"width1": "4",
"width2": "8",
"totalArea": "26.06",
"images": [],
"extraAreas": [],
"finalArea": "26.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "2.17",
  "length1": "2",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "6.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "6.86"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "735020",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "270",
  "squareMeterArea": "25.08",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64d7255b3cb8cf13cb84ad0f",
    "property": "Devipada, Borivli East",
    "area": "450",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "8200000",
    "expectedRate": "18222.22",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64d3641887258203eaafeac2/
indicator_1691820265871_Image.png",
    "squareMeter": "41.81",
    "id": "711946"
  },
  {
    "printlnReport": true,
    "_id": "64d7255b3cb8cf13cb84ad10",
    "property": "Devipada Road, Borivali East",
    "area": "450",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "4th Floor",
    "source": "magic_bricks",
```

```
    "expectedPrice": "10000000.00",
    "expectedRate": "22222.22",
    "builtUpExpectedRate": "18518.52",
    "image": "cases/64d3641887258203eaafeac2/
indicator_1691820495959_Image.jpeg",
    "squareMeter": "41.81",
    "id": "699114"
  },
  {
    "printlnReport": true,
    "_id": "64d7255b3cb8cf13cb84ad11",
    "property": "Sadguru Nagar, Devipada Road, Borivali East",
    "area": "440",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "8000000",
    "expectedRate": "18181.82",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64d3641887258203eaafeac2/
indicator_1691820594555_Image.jpeg",
    "squareMeter": "40.88",
    "id": "535312"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab29528",
    "name":
"externallmg_1691726037826_IMG_20230810_155504_copy_900x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037826_IMG_20230810_155504_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab29529",
    "name":
"externallmg_1691726037848_IMG_20230810_155506_copy_900x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037848_IMG_20230810_155506_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952a",
    "name":
"externallmg_1691726037860_IMG_20230810_155519_copy_1600x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037860_IMG_20230810_155519_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952b",
    "name":
"externallmg_1691726037867_IMG_20230810_155523_copy_1600x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037867_IMG_20230810_155523_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952c",
    "name":
"externallmg_1691726037872_IMG_20230810_155527_copy_1600x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037872_IMG_20230810_155527_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952d",
    "name":
"externallmg_1691726037880_IMG_20230810_155532_copy_1600x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037880_IMG_20230810_155532_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0d68807d30b0ab2952e",
```

```
    "name":
"externallmg_1691726037885_IMG_20230810_155540_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037885_IMG_20230810_155540_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0d68807d30b0ab2952f",
  "name":
"externallmg_1691726037894_IMG_20230810_155842_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037894_IMG_20230810_155842_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0d68807d30b0ab29530",
  "name":
"externallmg_1691726037904_IMG_20230810_155846_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037904_IMG_20230810_155846_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0d68807d30b0ab29531",
  "name":
"externallmg_1691726037914_IMG_20230810_155851_copy_901x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726037914_IMG_20230810_155851_copy_901x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295aa",
  "name":
"externallmg_1691726053130_IMG_20230810_155957_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053130_IMG_20230810_155957_copy_1600x1200.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295ab",
  "name":
"externallmg_1691726053141_IMG_20230810_160001_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053141_IMG_20230810_160001_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295ac",
  "name":
"externallmg_1691726053149_IMG_20230810_160009_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053149_IMG_20230810_160009_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295ad",
  "name":
"externallmg_1691726053159_IMG_20230810_160123_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053159_IMG_20230810_160123_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295ae",
  "name":
"externallmg_1691726053173_IMG_20230810_160129_copy_901x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053173_IMG_20230810_160129_copy_901x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295af",
  "name":
"externallmg_1691726053185_IMG_20230810_160142_copy_900x1200.jpg",
```

```
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053185_IMG_20230810_160142_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b0",
    "name":
"externallmg_1691726053198_IMG_20230810_160143_copy_900x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053198_IMG_20230810_160143_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b1",
    "name":
"externallmg_1691726053213_IMG_20230810_160204_copy_900x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053213_IMG_20230810_160204_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b2",
    "name":
"externallmg_1691726053228_IMG_20230810_195357_copy_900x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053228_IMG_20230810_195357_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d5b0e58807d30b0ab295b3",
    "name":
"externallmg_1691726053241_IMG_20230810_155510_copy_1600x1200.jpg",
    "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053241_IMG_20230810_155510_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64d5b0e58807d30b0ab295b4",
  "name":
"externallmg_1691726053247_IMG_20230810_155512_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053247_IMG_20230810_155512_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295b5",
  "name":
"externallmg_1691726053251_IMG_20230810_155534_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053251_IMG_20230810_155534_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295b6",
  "name":
"externallmg_1691726053256_IMG_20230810_155538_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053256_IMG_20230810_155538_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295b7",
  "name":
"externallmg_1691726053265_IMG_20230810_155840_copy_900x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053265_IMG_20230810_155840_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295b8",
  "name":
"externallmg_1691726053276_IMG_20230810_160215_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053276_IMG_20230810_160215_copy_1600x1200.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295b9",
  "name":
  "externallmg_1691726053286_IMG_20230810_160216_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053286_IMG_20230810_160216_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295ba",
  "name":
  "externallmg_1691726053296_IMG_20230810_195407_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053296_IMG_20230810_195407_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d5b0e58807d30b0ab295bb",
  "name":
  "externallmg_1691726053302_IMG_20230810_195410_copy_1600x1200.jpg",
  "path": "cases/64d3641887258203eaafeac2/
externallmg_1691726053302_IMG_20230810_195410_copy_1600x1200.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"createdAt": "2023-08-09T10:02:00.430Z",
"updatedAt": "2023-08-12T11:16:08.786Z",
"__v": 0,
"invoiceId": "64d3641887258203eaafeace",
"fullAddress": "Residential Flat No. 403, 4th Floor, Building No 1, Wing - C, Ashutosh
Co-Op. Hsg. Soc. Ltd., Sadguru Nagar, Devipada, Sant Gora Kumbhar Marg, Village -
Magathane, Taluka - Borivali, District - Mumbai Suburban, Borivali (East), PIN - 400
066, State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Bhimrao Shivaji Shinde",
```

```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8652345590",
"briefDescOfProperty": "Living Room + Kitchen + Toilet + Passage",
"carpetTotal": "201.05",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "221.16",
"finalCarpetArea": "201.05",
"finalSalableArea": "243.27",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 270.00",
"buildingServicesRate": "2800",
"flatRate": "17000",
"landOtherRate": "14200",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Sat Aug 12 2023 16:25:43 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-08-11",
"proposePurchasers": [],
"processingDocuments": []
}

```

Name	Length	Width	Total
Composition :			
Living Room	11'9"	9'5"	110.65
Kitchen	7'5"	7'9"	57.48
Toilet	5'7"	4'8"	26.06

Passage	2'2"	3'2"	6.86
---------	------	------	------

---

Other  
Composition :

---