

```
{
  "typeOfReport": {
    "label": "Residential Bungalow ",
    "value": "Residential_Bungalow_"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb59"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231331",
    "firstName": "Namrata Ghone",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9769152981"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Namrata Ghone",
    "expectedFees": 1500,
    "quotedAmount": "1770"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
    "city": "Nashik"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb59",
  "branchCode": "000352",
  "type": "BRANCH",
  "name": "RACPC Nashik ",
  "email": "sbi.10518@sbi.co.in",
  "mobileNo": "02532501640",
  "alternateMobileNo": "",
  "address": "1st Floor,Patel Plaza ,N.D.Patel Road,Opp BSNL,Landmark Seawoods
Navratna Hotel Nashik-422001",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "shortName": "Sachin",
```

```
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
    "email": "rushipingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "designation": "",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "20.034646063770502",
  "longitude": "73.86596894964717"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.86596894964717,
    20.034646063770502
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Adgaon ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  }
}
```

```
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
```

```
"key": "street1",
"value": "Adgaon Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shiv Mandir ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "760/1,",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```

```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
```



```
"area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
```

```
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64d46eb787258203eab09aa7",
```

```
"ownerName": "Santosh yashwant Borade",
"ownerPhoneNo": "9423286646",
"appAddress": "bungalow near shiv mandir adgaon ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64d46eb787258203eab09aa7/
document_1691643410220_Kaagaz_20230809_130450815662.pdf",
    "fileName": "document_1691643410220_Kaagaz_20230809_130450815662.pdf",
    "displayStatus": false,
    "id": "259055",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Thu Aug 10 2023 10:29:05 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Vetting Documents",
      "value": "60ae128aaa6d152c1801b41f"
    },
    "isHardCopy": false,
    "path": "cases/64d46eb787258203eab09aa7/
document_1691643465919_Kaagaz_20230809_130750982859.pdf",
    "fileName": "document_1691643465919_Kaagaz_20230809_130750982859.pdf",
    "displayStatus": false,
    "id": "286005",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Thu Aug 10 2023 10:29:05 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Approved Building Plan",
      "value": "60ae1277aa6d152c1801b3cc"
    },
    "isHardCopy": false,
    "path": "cases/64d46eb787258203eab09aa7/
document_1691643484539_APPROVED_PLAN___borade.pdf",
    "fileName": "document_1691643484539_APPROVED_PLAN___borade.pdf",
    "displayStatus": false,
    "id": "141389",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Thu Aug 10 2023 10:29:05 GMT+0530 (India Standard Time)"
  }
]
```

```
    },
    {
      "documentType": {
        "label": "Commencement Certificate",
        "value": "60ae1247aa6d152c1801b2ea"
      },
      "isHardCopy": false,
      "path": "cases/64d46eb787258203eab09aa7/
document_1691643510480_APPROVED_CERTIFICATE.pdf",
      "fileName": "document_1691643510480_APPROVED_CERTIFICATE.pdf",
      "displayStatus": false,
      "id": "443800",
      "uploadedBy": "636a29b64d42487767af43ea",
      "createdAt": "Thu Aug 10 2023 10:29:05 GMT+0530 (India Standard Time)"
    }
  ],
  "caseNumber": "003063",
  "createdBy": "636a29b64d42487767af43ea",
  "caseHistory": [
    {
      "id": "856148",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Thu Aug 10 2023 10:29:35 GMT+0530 (India Standard Time)"
    }
  ],
  "owners": [
    {
      "name": "Santosh yashwant Borade",
      "phone": "9423286646",
      "ownershipShare": "",
      "email": "",
      "id": "866235"
    }
  ],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
  "indicatorArr": [],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
    }
  ]
}
```



```
    "_id": "64d4744e87258203eab0b10c",
    "name":
"externallmg_1691645004895_WhatsApp_Image_20230809_at_60859_PM.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645004895_WhatsApp_Image_20230809_at_60859_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b10d",
    "name":
"externallmg_1691645004987_WhatsApp_Image_20230809_at_60900_PM_1.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645004987_WhatsApp_Image_20230809_at_60900_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b10e",
    "name":
"externallmg_1691645005231_WhatsApp_Image_20230809_at_60900_PM_2.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645005231_WhatsApp_Image_20230809_at_60900_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b10f",
    "name":
"externallmg_1691645005369_WhatsApp_Image_20230809_at_60900_PM.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645005369_WhatsApp_Image_20230809_at_60900_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b110",
    "name":
"externallmg_1691645005571_WhatsApp_Image_20230809_at_60901_PM_1.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645005571_WhatsApp_Image_20230809_at_60901_PM_1.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d4744e87258203eab0b111",
  "name":
"externallmg_1691645005709_WhatsApp_Image_20230809_at_60901_PM.jpeg",
  "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645005709_WhatsApp_Image_20230809_at_60901_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d4744e87258203eab0b112",
  "name":
"externallmg_1691645005849_WhatsApp_Image_20230809_at_60902_PM_1.jpeg",
  "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645005849_WhatsApp_Image_20230809_at_60902_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d4744e87258203eab0b113",
  "name":
"externallmg_1691645006011_WhatsApp_Image_20230809_at_60902_PM.jpeg",
  "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006011_WhatsApp_Image_20230809_at_60902_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d4744e87258203eab0b114",
  "name":
"externallmg_1691645006140_WhatsApp_Image_20230809_at_60903_PM_1.jpeg",
  "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006140_WhatsApp_Image_20230809_at_60903_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d4744e87258203eab0b115",
  "name":
"externallmg_1691645006318_WhatsApp_Image_20230809_at_60903_PM.jpeg",
```

```
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006318_WhatsApp_Image_20230809_at_60903_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b116",
    "name":
"externallmg_1691645006468_WhatsApp_Image_20230809_at_60904_PM_1.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006468_WhatsApp_Image_20230809_at_60904_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b117",
    "name":
"externallmg_1691645006581_WhatsApp_Image_20230809_at_60904_PM_2.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006581_WhatsApp_Image_20230809_at_60904_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d4744e87258203eab0b118",
    "name":
"externallmg_1691645006715_WhatsApp_Image_20230809_at_60904_PM.jpeg",
    "path": "cases/64d46eb787258203eab09aa7/
externallmg_1691645006715_WhatsApp_Image_20230809_at_60904_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-10T04:59:35.730Z",
"updatedAt": "2023-08-10T05:23:26.977Z",
"__v": 0,
"invoiceId": "64d46eb887258203eab09ac2",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"fullAddress": " Residential Bungalow No. Basement Floor, Near Shiv Mandir , CTS
No. 760/1,, Adgaon Road, Village - Adgaon , Taluka - Nashik, District - Nashik, Nashik,
422003, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "",
```

"contactPersonName": "Santosh yashwant Borade",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9423286646"

}

Name	Length	Width	Total
Composition :			
Other Composition :			