

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.032006753909947",
  "longitude": "73.05942553095443"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.05942553095443,
    19.032006753909947
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-11T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-11T09:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-12",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kharghar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Panvel",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "36",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sukh Sakhu Sadan Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "04",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Belpada",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 210",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
```

```

    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shantivan CHSL",
    "west": "Mahadev Bua Gharat Garden",
    "south": "Wing - A & Belpada Road",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "11.00 Mtr. Wide Road",
    "west": "Plot No. 37",
    "south": "15.00 Mtr. Wide Road & Plot No. 42-A",
    "east": "15.00 Mtr. Wide Road"
  },
  "extraDetailOfProperty": "Details is not available"
},
"compositeRate": {
  "remark": "As per Agreement Built up area is 547.00 Sq. Ft. As per our physical measurement actual Carpet area is 335.00 Sq. ft. The loading between measured Carpet Area to agreement built up area is 64%. For the purpose of valuation we have considered the actual measured Carpet Area. ",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",

```

```
"depreciatedCostOfConstruction": "13562.5",
"depreciatedBuildingRate": "1862.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "112300",
  "landRate": "42300",
  "igrImage": "cases/64d6027f8807d30b0ab3519c/igr_1691835745210_Image.png",
  "squareMeterGuideLineRate": "89840.00",
  "squareFeetGuideLineRate": "8346.00"
},
"igrFinalRate": {
  "rate": "7596.00",
  "squareFeetGuideLineRate": "7596.00",
  "squareMeterGuideLineRate": "81758.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "11,500.00",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "Details is not available",
  "meterCardHolderName": "Details is not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Information_Not_Available",
    "label": "Information Not Available"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2006",
    "fullDate": "1/1/2006"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
```

```
"label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "17",
"totalLifeBuilding": "60",
"estimatedAge": "43",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "547.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64d6027f8807d30b0ab3519c/
routeMap_1691999932881_Image.png",
    "routeLat": "19.031966",
    "routeLng": "73.060837",
    "stationName": "Kharghar",
    "routeDistance": "800 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "eqlh0d",
    "name": "eqlh0d",
    "image": "cases/64d6027f8807d30b0ab3519c/
routeMap_1691999841409_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "4543605.00",
"finalValue": "4543605.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3050326.00",
"selectedBuildUpValue": "401.57",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64d9a20f72fe95784711d75d",
      "name": "externallmg_1691984399181_IMG_20230812_14853.jpg",
      "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399181_IMG_20230812_14853.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64d9a20f72fe95784711d764",
      "name": "Living Room",
      "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399199_IMG_20230812_19597.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64d9a20f72fe95784711d766",
      "name": "Living Room",
      "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399206_IMG_20230812_20584.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64d9a20f72fe95784711d763",
      "name": "Living Room",
      "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399198_IMG_20230812_18910.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64d9a20f72fe95784711d75c",
      "name": "Living Room",
      "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399178_IMG_20230812_14330.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d9a20f72fe95784711d75e",
    "name": "Living Room",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399184_IMG_20230812_15243.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d9a22172fe95784711d793",
    "name": "Living Room",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417367_IMG_20230812_22385.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d9a20f72fe95784711d75b",
    "name": "Living Room",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399176_IMG_20230812_2012.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64d9a22172fe95784711d791",
    "name": "Living Room",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417361_IMG_20230812_21835.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9273",
    "max": "12917"
  },
  "builtUpRateRange": {
    "min": "8523",
    "max": "10764"
  }
},
}
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```



```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "334.64",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64d6027f8807d30b0ab3519c",
"ownerName": "Mr. Vikasrao Prabhakar Pharne",
"ownerPhoneNo": "9029295411",
"appAddress": "Flat no. B-402, 4th Floor, Sukh Sakhu Sadan CHS, Plot no. 36, Sector
no. 04, Village-Belpada, Kharghar ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
    "documentDate": "28/07/2023",
    "from": {
      "value": "Seller",
      "label": "Seller"
    }
  },
  "Seller": "Mr. Gurunath Manohar Mayekar ",
  "to": {
```

```
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Vikasrao Prabhakar Pharne & Mrs. Priyanka Vikasrao Pharne"
},
"isHardCopy": false,
"displayStatus": true,
"id": "148575",
"path": "cases/64d6027f8807d30b0ab3519c/
document_1691746901654_Racpc_GHatkopar_Vilasrao_Pharne.pdf",
"fileName": "document_1691746901654_Racpc_GHatkopar_Vilasrao_Pharne.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "23/08/2006",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / BP / ATPO / 1168"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "898462",
  "path": "cases/64d6027f8807d30b0ab3519c/
document_1691998873072_1154830.pdf",
  "fileName": "document_1691998873072_1154830.pdf"
}
],
"caseNumber": "003097",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "176538",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 11 2023 15:12:23 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Vikasrao Prabhakar Pharne",
    "phone": "9029295411",
    "email": "",
    "ownershipShare": "",
    "id": "566500"
  },
  {
    "name": "Mrs. Priyanka Vikasrao Pharne",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "653566"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "838995",
    "name": "Living Room",
    "length": "13.67",
    "length1": "13",
    "length2": "8",
    "width": "8.83",
    "width1": "8",
    "width2": "10",
    "totalArea": "120.72",
    "images": [],
    "extraAreas": [],
    "finalArea": "120.72"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "3.50",
```

```
"length1": "3",
"length2": "6",
"width": "4.17",
"width1": "4",
"width2": "2",
"totalArea": "14.58",
"images": [],
"extraAreas": [],
"finalArea": "14.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.33",
  "length1": "3",
  "length2": "4",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "12.22",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "14.03",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.03"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "9.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "44.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
```

```
"width": "9.67",
"width1": "9",
"width2": "8",
"totalArea": "83.78",
"images": [],
"extraAreas": [],
"finalArea": "83.78"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "8",
  "width2": "10",
  "width": "8.83",
  "totalArea": "17.67",
  "percentageBeforeTotal": "17.67",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "17.67"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
}
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length1": "2",
"length2": "00",
"length": "2.00",
"width1": "8",
"width2": "6",
"width": "8.50",
"totalArea": "17.00",
"percentageBeforeTotal": "17.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "17"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "101460",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "547",
  "squareMeterArea": "50.82",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
```

```
  "_id": "64d75d8372fe9578471194eb",
  "property": "Flat",
  "area": "440",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "4500000",
  "expectedRate": "10227.27",
  "builtUpExpectedRate": "8522.73",
  "image": "cases/64d6027f8807d30b0ab3519c/
indicator_1691835610206_Image.png",
  "squareMeter": "40.88",
  "id": "600747"
},
{
  "printlnReport": true,
  "_id": "64d75d8372fe9578471194ec",
  "property": "Flat",
  "area": "550",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "5100000",
  "expectedRate": "9272.73",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64d6027f8807d30b0ab3519c/
indicator_1691835643762_Image.png",
  "squareMeter": "51.10",
  "id": "375872"
},
{
  "printlnReport": true,
  "_id": "64d75d8372fe9578471194ed",
  "property": "Flat",
  "area": "480",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "6200000",
  "expectedRate": "12916.67",
```



```
    "builtUpExpectedRate": "10763.89",
    "image": "cases/64d6027f8807d30b0ab3519c/
indicator_1691835686381_Image.png",
    "squareMeter": "44.59",
    "id": "451685"
  },
  {
    "printlnReport": true,
    "_id": "64da0414ccaf1e7b7f6272a1",
    "id": "4",
    "property": "Flat",
    "area": "550",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "1",
    "source": "https://www.99acres.com/",
    "expectedPrice": "6700000",
    "expectedRate": "12181.82",
    "builtUpExpectedRate": "6700000",
    "image": "cases/64d6027f8807d30b0ab3519c/
indicator_1692009486367_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d75a",
    "name": "externalImg_1691984399173_IMG_20230812_166.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externalImg_1691984399173_IMG_20230812_166.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d75b",
    "name": "externalImg_1691984399176_IMG_20230812_2012.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externalImg_1691984399176_IMG_20230812_2012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64d9a20f72fe95784711d75c",
    "name": "externallmg_1691984399178_IMG_20230812_14330.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399178_IMG_20230812_14330.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d75d",
    "name": "externallmg_1691984399181_IMG_20230812_14853.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399181_IMG_20230812_14853.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d75e",
    "name": "externallmg_1691984399184_IMG_20230812_15243.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399184_IMG_20230812_15243.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d75f",
    "name": "externallmg_1691984399187_IMG_20230812_15623.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399187_IMG_20230812_15623.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d760",
    "name": "externallmg_1691984399193_IMG_20230812_16512.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399193_IMG_20230812_16512.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64d9a20f72fe95784711d761",
    "name": "externallmg_1691984399194_IMG_20230812_17219.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399194_IMG_20230812_17219.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d762",
    "name": "externallmg_1691984399196_IMG_20230812_17754.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399196_IMG_20230812_17754.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d763",
    "name": "externallmg_1691984399198_IMG_20230812_18910.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399198_IMG_20230812_18910.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d764",
    "name": "externallmg_1691984399199_IMG_20230812_19597.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399199_IMG_20230812_19597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d765",
    "name": "externallmg_1691984399200_IMG_20230812_20325.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399200_IMG_20230812_20325.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d766",
```

```
    "name": "externallmg_1691984399206_IMG_20230812_20584.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399206_IMG_20230812_20584.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d767",
    "name": "externallmg_1691984399208_IMG_20230812_21134.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399208_IMG_20230812_21134.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a20f72fe95784711d768",
    "name": "externallmg_1691984399209_IMG_20230812_21445.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984399209_IMG_20230812_21445.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d791",
    "name": "externallmg_1691984417361_IMG_20230812_21835.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417361_IMG_20230812_21835.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d792",
    "name": "externallmg_1691984417364_IMG_20230812_22107.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417364_IMG_20230812_22107.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d793",
    "name": "externallmg_1691984417367_IMG_20230812_22385.jpg",
```

```
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417367_IMG_20230812_22385.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d794",
    "name": "externallmg_1691984417369_IMG_20230812_22697.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417369_IMG_20230812_22697.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d795",
    "name": "externallmg_1691984417375_IMG_20230812_184624.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417375_IMG_20230812_184624.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d796",
    "name": "externallmg_1691984417405_IMG_20230812_191519.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externallmg_1691984417405_IMG_20230812_191519.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d797",
    "name": "externallmg_1691984417464_Screenshot_2023081214071285_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/externallmg_1691984417464_Screens
hot_2023081214071285_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d798",
    "name": "externallmg_r_1691984417440_IMG20230812191654.jpg",
```

```
    "path": "cases/64d6027f8807d30b0ab3519c/
externalImg_r_1691984417440_IMG20230812191654.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d9a22172fe95784711d799",
    "name": "externalImg_r_1691984417413_IMG20230812191649.jpg",
    "path": "cases/64d6027f8807d30b0ab3519c/
externalImg_r_1691984417413_IMG20230812191649.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-11T09:42:23.816Z",
"updatedAt": "2023-08-14T11:19:30.279Z",
"__v": 0,
"invoiceId": "64d602808807d30b0ab351b6",
"fullAddress": "Residential Flat No. B/402, 4th Floor, Sukh Sakhu Sadan Co-Op. Hsg.
Soc. Ltd., Plot No. 36, Sector 04, Belpada, Village - Kharghar, Taluka - Panvel, District -
Raigad, Navi Mumbai, PIN - 410 210, State - Maharashtra, Country - India",
"updatedBy": "60af41852ffdf65bcd6585d4",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Vikasrao Prabhakar Pharne",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9029295411",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "actual site measurement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 334.64",
"flatRate": "14200",
"landOtherRate": "11700",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + Bathroom
+ WC",
"carpetTotal": "299.97",
"otherCarpetTotal": "34.67",
```

```

"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "34.67",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "401.57",
"finalCarpetArea": "334.64",
"finalSalableArea": "441.72",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 300.00\nBalcony Area in Sq. Ft.
= 35.00",
"finalSaleablePercentage": "10",
"reportGeneratedDate": "Mon Aug 14 2023 16:10:14 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-08-12",
"processingDocuments": []
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'8"	8'10"	120.72
Passage	3'6"	4'2"	14.58
Passage	3'4"	3'8"	12.22
Bathroom	3'7"	3'11"	14.03
WC	2'8"	3'8"	9.78
Kitchen	7'11"	5'8"	44.86
Bedroom	8'8"	9'8"	83.78
Other Composition :			
Balcony	2'00"	8'10"	17.67
Balcony	2'00"	8'6"	17.00