

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "firstName": "Pushpa",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3500000",
    "discussWithPerson": "Pushpa",
    "expectedFees": 1750,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
```

```
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "20.017305750058053",
  "longitude": "73.83365063267128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.83365063267128,
    20.017305750058053
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Parksyde Homes",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Bali Mandir",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "I, Phase 3",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
```

```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "257/1 to 12",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422006",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
}
```



```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64d71a913cb8cf13cb8484d5",
"ownerName": "Mr.Kripa Sindhu Saha & Mrs. Namrata Pradhan",
"ownerPhoneNo": "9096080883",
"appAddress": "Flat No. 301, (Wing I)Parksyde Homes hanuman Nagar ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Deed of Apartment",
      "value": "60ae1269aa6d152c1801b389"
    },
    "isHardCopy": false,
    "path": "cases/64d71a913cb8cf13cb8484d5/document_1691818575167_DEED_OF_APPARTMENT_OF_KRIPA_SINDHU_SAHA_.pdf",
    "fileName": "document_1691818575167_DEED_OF_APPARTMENT_OF_KRIPA_SINDHU_SAHA_.pdf",
    "displayStatus": false,
    "id": "620935",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Sat Aug 12 2023 11:06:54 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003108",
"createdBy": "636a29b64d42487767af43ea",
"caseHistory": [
  {
    "id": "869533",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 12 2023 11:07:21 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr.Kripa Sindhu Saha & Mrs. Namrata Pradhan",
    "phone": "9096080883",
    "ownershipShare": "",
    "email": "",
    "id": "752872"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b23e",
    "name":
"externallmg_1691821670032_WhatsApp_Image_20230811_at_120651_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670032_WhatsApp_Image_20230811_at_120651_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b23f",
    "name":
"externallmg_1691821670122_WhatsApp_Image_20230811_at_120652_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670122_WhatsApp_Image_20230811_at_120652_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b240",
    "name":
"externallmg_1691821670175_WhatsApp_Image_20230811_at_120652_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670175_WhatsApp_Image_20230811_at_120652_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b241",
    "name":
"externallmg_1691821670227_WhatsApp_Image_20230811_at_120653_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670227_WhatsApp_Image_20230811_at_120653_PM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b242",
    "name":
"externallmg_1691821670305_WhatsApp_Image_20230811_at_120654_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670305_WhatsApp_Image_20230811_at_120654_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b243",
    "name":
"externallmg_1691821670380_WhatsApp_Image_20230811_at_120654_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670380_WhatsApp_Image_20230811_at_120654_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b244",
    "name":
"externallmg_1691821670418_WhatsApp_Image_20230811_at_120655_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670418_WhatsApp_Image_20230811_at_120655_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b245",
    "name":
"externallmg_1691821670470_WhatsApp_Image_20230811_at_120655_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670470_WhatsApp_Image_20230811_at_120655_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726673cb8cf13cb84b246",
```

```
    "name":
"externallmg_1691821670509_WhatsApp_Image_20230811_at_120656_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670509_WhatsApp_Image_20230811_at_120656_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b247",
  "name":
"externallmg_1691821670547_WhatsApp_Image_20230811_at_120657_PM_1.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670547_WhatsApp_Image_20230811_at_120657_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b248",
  "name":
"externallmg_1691821670612_WhatsApp_Image_20230811_at_120657_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670612_WhatsApp_Image_20230811_at_120657_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b249",
  "name":
"externallmg_1691821670676_WhatsApp_Image_20230811_at_120658_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670676_WhatsApp_Image_20230811_at_120658_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b24a",
  "name":
"externallmg_1691821670726_WhatsApp_Image_20230811_at_120659_PM_1.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670726_WhatsApp_Image_20230811_at_120659_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b24b",
  "name":
"externallmg_1691821670778_WhatsApp_Image_20230811_at_120659_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670778_WhatsApp_Image_20230811_at_120659_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b24c",
  "name":
"externallmg_1691821670857_WhatsApp_Image_20230811_at_120700_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670857_WhatsApp_Image_20230811_at_120700_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726673cb8cf13cb84b24d",
  "name":
"externallmg_1691821670930_WhatsApp_Image_20230811_at_120701_PM_1.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821670930_WhatsApp_Image_20230811_at_120701_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726733cb8cf13cb84b28c",
  "name":
"externallmg_1691821682078_WhatsApp_Image_20230811_at_120701_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682078_WhatsApp_Image_20230811_at_120701_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726733cb8cf13cb84b28d",
  "name":
"externallmg_1691821682169_WhatsApp_Image_20230811_at_120702_PM_1.jpeg",
```

```
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682169_WhatsApp_Image_20230811_at_120702_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b28e",
    "name":
"externallmg_1691821682247_WhatsApp_Image_20230811_at_120702_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682247_WhatsApp_Image_20230811_at_120702_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b28f",
    "name":
"externallmg_1691821682288_WhatsApp_Image_20230811_at_120703_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682288_WhatsApp_Image_20230811_at_120703_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b290",
    "name":
"externallmg_1691821682338_WhatsApp_Image_20230811_at_120704_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682338_WhatsApp_Image_20230811_at_120704_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b291",
    "name":
"externallmg_1691821682403_WhatsApp_Image_20230811_at_120704_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682403_WhatsApp_Image_20230811_at_120704_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64d726733cb8cf13cb84b292",
    "name":
"externallmg_1691821682465_WhatsApp_Image_20230811_at_120705_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682465_WhatsApp_Image_20230811_at_120705_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b293",
    "name":
"externallmg_1691821682491_WhatsApp_Image_20230811_at_120706_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682491_WhatsApp_Image_20230811_at_120706_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b294",
    "name":
"externallmg_1691821682529_WhatsApp_Image_20230811_at_120706_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682529_WhatsApp_Image_20230811_at_120706_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b295",
    "name":
"externallmg_1691821682581_WhatsApp_Image_20230811_at_120707_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682581_WhatsApp_Image_20230811_at_120707_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b296",
    "name":
"externallmg_1691821682608_WhatsApp_Image_20230811_at_120707_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682608_WhatsApp_Image_20230811_at_120707_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b297",
    "name":
"externallmg_1691821682658_WhatsApp_Image_20230811_at_120708_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682658_WhatsApp_Image_20230811_at_120708_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b298",
    "name":
"externallmg_1691821682709_WhatsApp_Image_20230811_at_120709_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682709_WhatsApp_Image_20230811_at_120709_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b299",
    "name":
"externallmg_1691821682735_WhatsApp_Image_20230811_at_120709_PM.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682735_WhatsApp_Image_20230811_at_120709_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b29a",
    "name":
"externallmg_1691821682816_WhatsApp_Image_20230811_at_120710_PM_1.jpeg",
    "path": "cases/64d71a913cb8cf13cb8484d5/
externallmg_1691821682816_WhatsApp_Image_20230811_at_120710_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d726733cb8cf13cb84b29b",
```

```

"name":
"externalImg_1691821682852_WhatsApp_Image_20230811_at_120710_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externalImg_1691821682852_WhatsApp_Image_20230811_at_120710_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d726983cb8cf13cb84b2d4",
  "name":
"externalImg_1691821719825_WhatsApp_Image_20230811_at_120711_PM.jpeg",
  "path": "cases/64d71a913cb8cf13cb8484d5/
externalImg_1691821719825_WhatsApp_Image_20230811_at_120711_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-12T05:37:21.263Z",
"updatedAt": "2023-08-12T06:28:40.040Z",
"__v": 0,
"invoiceId": "64d71a913cb8cf13cb8484de",
"fullAddress": " Flat No. 301, Basement Floor, Wing - I, Phase 3, Parksyde Homes,
Near Bali Mandir, Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, 422006,
State - Maharashtra, India",
"updatedBy": "636a29b64d42487767af43ea",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr.Kripa Sindhu Saha & Mrs. Namrata Pradhan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9096080883"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
