

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8000000",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 4000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },
]
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.11524518867144",
  "longitude": "72.9343601779113"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.9343601779113,
```

```
19.11524518867144
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-14",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-14",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Hariyali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "49",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai Suburban",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swastik Emerald",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Tagore NAgar",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Tagore Nagar Matruchhaya Co-op. Hsg. Soc. LTd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "347/33 to 40 & 347(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "802",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400083",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vikhroli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Adityaraj Gold Building No. 50",
    "west": "Ramakant Deshmukh Marg",
    "south": "Residential Building",
    "east": "Eastern Express Highway"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "16000.00",
  "depreciatedBuildingRate": "2700"
},
"igrRate": {
```

```
"propertyName": "Residential Flat",
"rate": "135960",
"landRate": "58490",
"igrImage": "cases/64d9d0536f80f132fecedf21/igr_1692016195490_Image.png",
"squareMeterGuideLineRate": "142758.00",
"squareFeetGuideLineRate": "13263.00"
},
"igrFinalRate": {
  "rate": "135960",
  "squareMeterGuideLineRate": "142758.00",
  "squareFeetGuideLineRate": "13263.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "23,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2022",
"fullDate": "1/1/2022"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "RCC_Framed_Structure",
"label": "RCC Framed Structure"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "581.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64d9d0536f80f132fecedf21/
routeMap_1692162212482_Image.png",
  "routeLat": "19.115110",
  "routeLng": "72.934536",
  "stationName": "Vikhroli",
  "routeDistance": "950 M."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
}
```



```
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "jho2w",
    "name": "jho2w",
    "image": "cases/64d9d0536f80f132fecedf21/
routeMap_1692162145422_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "9296000.00",
  "finalValue": "9296000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
```

```
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7705803.00",
  "selectedBuildUpValue": "581.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ec",
    "name": "externallmg_1692012846858_1692012643551_image_3.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012846858_1692012643551_image_3.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f0",
    "name": "externallmg_1692012852509_1692012643551_image_7.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012852509_1692012643551_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ea",
    "name": "externallmg_1692012842760_1692012643551_image_1.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012842760_1692012643551_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4eb",
    "name": "externallmg_1692012844538_1692012643551_image_2.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012844538_1692012643551_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ed",
    "name": "externallmg_1692012849165_1692012643551_image_4.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012849165_1692012643551_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ec",
```

```
    "name": "externallmg_1692012846858_1692012643551_image_3.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012846858_1692012643551_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4e9",
    "name": "externallmg_1692012841424_1692012643551_image_0.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012841424_1692012643551_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f2",
    "name": "Living Room",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012854822_1692012643551_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f7",
    "name": "Bedroom",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012892374_1692012695903_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f8",
    "name": "Bedroom",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012892829_1692012695903_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f4",
    "name": "Kitchen",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012889644_1692012695903_image_1.jpeg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17717",
    "max": "25047"
  },
  "builtUpRateRange": {
    "min": "14764",
    "max": "20873"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "581.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64d9d0536f80f132fecedf21",
"ownerName": "Mrs. Supriya Subhash Salgaonkar, Mr. Saiprit Subhash Salgaonkar &
Mr. Subhash Ganpat Salgaonkar",
"ownerPhoneNo": "7738944455",
"appAddress": "Flat no.802, 8 th floor,,Swastik Emerald Bldg
no.49,Matruchhaya,CHSL,Tagore Nagar Vikhroli East- 400083",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "10/08/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Chandrakant Mahipat Rane",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Supriya Subhash Salgaonkar, Mr. Saiprit Subhash Salgaonkar
& Mr. Subhash Ganpat Salgaonkar"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "729805",
    "path": "cases/64d9d0536f80f132fecedf21/document_1691996158384_SupriyaSubb
asgSalgaonkar_SBI_Racpc_Andheri_East.pdf",
    "fileName": "document_1691996158384_SupriyaSubbasgSalgaonkar_SBI_Racpc_
Andheri_East.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "13/07/2022",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "MH / EE / BP Cell / GM / MHADA - 8 / 054 / 2022"
    }
  },
]
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1692161287953_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"path": "cases/64d9d0536f80f132fecedf21/document_1692161287953_1_Occupanc
y_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotte
d_development.pdf",
"id": "694580",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Aug 16 2023 10:18:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "26/12/2018",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MH / EE / (BP) / GM / MHADA - 8 / 054 / 2018"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692161332978_2_Commencement_Certificates__NA_Or
der_for_plotted_development.pdf",
  "path": "cases/64d9d0536f80f132fecedf21/document_1692161332978_2_Commenc
ement_Certificates__NA_Order_for_plotted_development.pdf",
  "id": "475089",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Aug 16 2023 10:18:53 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003130",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "725640",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Mon Aug 14 2023 12:27:23 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mrs. Supriya Subhash Salgaonkar, Mr. Saiprit Subhash Salgaonkar & Mr.
Subhash Ganpat Salgaonkar",
"phone": "7738944455",
"ownershipShare": "",
"email": "",
"id": "859143"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "188780",
"name": "Living Room",
"length": "14.00",
"length1": "14",
"length2": "0",
"width": "9.75",
"width1": "9",
"width2": "9",
"totalArea": "136.50",
"images": [],
"extraAreas": [],
"finalArea": "136.50"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "10.00",
"length1": "10",
"length2": "0",
"width": "8.42",
"width1": "8",
```

```
"width2": "5",
"totalArea": "84.17",
"images": [],
"extraAreas": [],
"finalArea": "84.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "90.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "90.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "107.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "107.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "5",
    "name": "Toilet",
    "length": "",
    "length1": "7",
    "length2": "0",
    "width": "",
    "width1": "4",
    "width2": "3",
    "totalArea": "29.75",
    "images": [],
    "finalArea": "29.75",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "5",
    "name": "Toilet",
    "length": "6.00",
    "length1": "6",
    "length2": "0",
    "width": "3.75",
    "width1": "3",
    "width2": "9",
    "totalArea": "22.50",
    "images": [],
    "extraAreas": [],
    "finalArea": "22.50"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
```

```
"squareMeterArea": "53.98",
"totalAreaDocument": "581",
"docBultupPercentage": "",
"docFinalBultUp": "0.00",
"docFinalBultUpSquareMeter": "0.00",
"docSaleablePercentage": "20",
"docFinalSaleable": "697.20",
"docFinalSaleableSquareMeter": "64.77",
"id": "121816"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64da1e72ccaf1e7b7f62f0f0",
  "property": "Residential Flat",
  "area": "535",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "12000000",
  "expectedRate": "22429.91",
  "builtUpExpectedRate": "18691.59",
  "image": "cases/64d9d0536f80f132fecedf21/indicator_1692015994352_Image.png",
  "squareMeter": "49.70",
  "id": "885793"
},
{
  "printlnReport": true,
  "_id": "64da1e72ccaf1e7b7f62f0f1",
  "property": "Residential Flat",
  "area": "507",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "11200000",
  "expectedRate": "22090.73",
  "builtUpExpectedRate": "18408.94",
  "image": "cases/64d9d0536f80f132fecedf21/indicator_1692016060298_Image.png",
  "squareMeter": "47.10",
  "id": "517494"
}
```

```
},
{
  "printlnReport": true,
  "_id": "64da1e72ccaf1e7b7f62f0f2",
  "property": "Residential Flat",
  "area": "527",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "13200000",
  "expectedRate": "25047.44",
  "builtUpExpectedRate": "20872.87",
  "image": "cases/64d9d0536f80f132fecedf21/indicator_1692016086319_Image.png",
  "squareMeter": "48.96",
  "id": "981397"
},
{
  "printlnReport": true,
  "_id": "64da1e72ccaf1e7b7f62f0f3",
  "property": "Residential Flat",
  "area": "507",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "12000000",
  "expectedRate": "23668.64",
  "builtUpExpectedRate": "19723.87",
  "image": "cases/64d9d0536f80f132fecedf21/indicator_1692016112778_Image.png",
  "squareMeter": "47.10",
  "id": "231746"
},
{
  "printlnReport": true,
  "_id": "64dc6c54ccaf1e7b7f6370af",
  "id": "5",
  "property": "Residential Flat",
  "area": "428",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": ""
}
```



```
"source": "Index_no.2",
"expectedPrice": "8207533",
"expectedRate": "19176.48",
"builtUpExpectedRate": "15980.40",
"image": "cases/64d9d0536f80f132fecedf21/indicator_1692167252102_Image.png"
}
],
"externallimages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da1162ccaf1e7b7f62c4e9",
"name": "externallmg_1692012841424_1692012643551_image_0.jpeg",
"path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012841424_1692012643551_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da1162ccaf1e7b7f62c4ea",
"name": "externallmg_1692012842760_1692012643551_image_1.jpeg",
"path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012842760_1692012643551_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da1162ccaf1e7b7f62c4eb",
"name": "externallmg_1692012844538_1692012643551_image_2.jpeg",
"path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012844538_1692012643551_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da1162ccaf1e7b7f62c4ec",
"name": "externallmg_1692012846858_1692012643551_image_3.jpeg",
"path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012846858_1692012643551_image_3.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ed",
    "name": "externallmg_1692012849165_1692012643551_image_4.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012849165_1692012643551_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ee",
    "name": "externallmg_1692012851155_1692012643551_image_5.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012851155_1692012643551_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4ef",
    "name": "externallmg_1692012851685_1692012643551_image_6.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012851685_1692012643551_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f0",
    "name": "externallmg_1692012852509_1692012643551_image_7.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012852509_1692012643551_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f1",
    "name": "externallmg_1692012854270_1692012643551_image_8.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012854270_1692012643551_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64da1162ccaf1e7b7f62c4f2",
    "name": "externallmg_1692012854822_1692012643551_image_9.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012854822_1692012643551_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f3",
    "name": "externallmg_1692012888707_1692012695903_image_0.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012888707_1692012695903_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f4",
    "name": "externallmg_1692012889644_1692012695903_image_1.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012889644_1692012695903_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f5",
    "name": "externallmg_1692012890289_1692012695903_image_2.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012890289_1692012695903_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f6",
    "name": "externallmg_1692012891955_1692012695903_image_3.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externallmg_1692012891955_1692012695903_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f7",
```

```
    "name": "externalImg_1692012892374_1692012695903_image_4.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externalImg_1692012892374_1692012695903_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f8",
    "name": "externalImg_1692012892829_1692012695903_image_5.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externalImg_1692012892829_1692012695903_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4f9",
    "name": "externalImg_1692012894587_1692012695903_image_6.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externalImg_1692012894587_1692012695903_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4fa",
    "name": "externalImg_1692012808865_1692012614067_image_0.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externalImg_1692012808865_1692012614067_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64da1162ccaf1e7b7f62c4fb",
    "name": "externalImg_1692012810365_1692012614067_image_1.jpeg",
    "path": "cases/64d9d0536f80f132fecedf21/
externalImg_1692012810365_1692012614067_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "externalImg_1692012808865_1692012614067_image_0.jpeg",
```

```
  "filename":
"1692163490169_externallmg_1692012808865_1692012614067_image_0.jpeg",
  "path": "cases/64d9d0536f80f132fecedf21/processingDocuments/1692163490169_
externallmg_1692012808865_1692012614067_image_0.jpeg",
  "size": "1093291",
  "createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1692012810365_1692012614067_image_1.jpeg",
  "filename":
"1692163490200_externallmg_1692012810365_1692012614067_image_1.jpeg",
  "path": "cases/64d9d0536f80f132fecedf21/processingDocuments/1692163490200_
externallmg_1692012810365_1692012614067_image_1.jpeg",
  "size": "354939",
  "createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1692163490212_IGR01.pdf",
  "path": "cases/64d9d0536f80f132fecedf21/
processingDocuments/1692163490212_IGR01.pdf",
  "size": "100797",
  "createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1692163490215_IGR02.pdf",
  "path": "cases/64d9d0536f80f132fecedf21/
processingDocuments/1692163490215_IGR02.pdf",
  "size": "100968",
  "createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1692163490217_IGR03.pdf",
  "path": "cases/64d9d0536f80f132fecedf21/
processingDocuments/1692163490217_IGR03.pdf",
  "size": "100558",
  "createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
```

```
"originalname": "IGR-04.pdf",
"filename": "1692163490220_IGR04.pdf",
"path": "cases/64d9d0536f80f132fecedf21/
processingDocuments/1692163490220_IGR04.pdf",
"size": "100736",
"createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=Supriya.xlsx",
"filename": "1692163490222_Summary_NewSupriya.xlsx",
"path": "cases/64d9d0536f80f132fecedf21/
processingDocuments/1692163490222_Summary_NewSupriya.xlsx",
"size": "2709651",
"createdAt": "Wed Aug 16 2023 10:54:50 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"createdAt": "2023-08-14T06:57:23.164Z",
"updatedAt": "2023-08-16T06:27:56.738Z",
"__v": 0,
"invoiceId": "64d9d0536f80f132fecedf2c",
"fullAddress": "Residential Flat No. 802, 8th Floor, Building No 49, Swastik Emerald,
Tagore Nagar Matruchhaya Co-op. Hsg. Soc. LTd., Tagore NAgar, Village - Hariyali,
Vikhroli (East), Mumbai Suburban, 400083, State - Maharashtra, India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Maan Aviani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"siteVisitContactNo": "9664755047",
"buildingServicesRate": "2700",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 581.00",
"flatRate": "16000",
"landOtherRate": "13300",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
```

"carpetTotal": "447.92",  
 "otherCarpetTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "517.46",  
 "finalCarpetArea": "470.42",  
 "finalSalableArea": "569.21",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "",  
 "finalSaleablePercentage": "",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00",  
 "siteVisitDate": "2023-08-14"

Name	Length	Width	Total
Composition :			
Living Room	14'0"	9'9"	136.50
Kitchen	10'0"	8'5"	84.17
Bedroom	9'0"	10'0"	90.00
Bedroom	10'9"	10'00"	107.50
Toilet	7'0"	4'3"	29.75
Toilet	6'0"	3'9"	22.50
Other Composition :			