

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },
]
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.11560420200044",
  "longitude": "72.93468242097899"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.93468242097899,
```

```
19.11560420200044
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-14",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Hariyali ",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "50",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai Suburban",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Adityaraj Gold",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Tagore Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Tagore Nagar Manoranjan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "347(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "405",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400083",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vikhroli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MHADA",
  "label": "MHADA"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Aditya Fortune",
  "west": "Ramakant Deshmukh Marg",
  "south": "Swastik Emerald",
  "east": "Eastern Express Highway"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "135960",
  "landRate": "58490",
  "igrImage": "cases/64d9d28c6f80f132fecee423/igr_1692016727218_Image.png",
  "squareMeterGuideLineRate": "135960.00",
  "squareFeetGuideLineRate": "12631.00"
```

```
},
"igrFinalRate": {
  "rate": "135960",
  "squareMeterGuideLineRate": "135960.00",
  "squareFeetGuideLineRate": "12631.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "22,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  }
}
```

```
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
```

```
"label": "Average"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
}
```

```
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "60",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "550.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64d9d28c6f80f132fecee423/
routeMap_1692165679729_Image.png",
    "routeLat": "19.115445",
    "routeLng": "72.934606",
    "stationName": "Vikhroli",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
```



```
{
  "id": "rlc61n",
  "name": "rlc61n",
  "image": "cases/64d9d28c6f80f132fecee423/
routeMap_1692165617218_Image.png"
}
],
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8800000.00",
  "finalValue": "8800000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6947050.00",
  "selectedBuildUpValue": "550.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64da10e6ccaf1e7b7f62c3f8",
      "name": "externallmg_1692012739431_1692012535965_image_3.jpeg",
      "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012739431_1692012535965_image_3.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f9",
    "name": "externallmg_1692012741349_1692012535965_image_4.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012741349_1692012535965_image_4.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3e5",
    "name": "externallmg_1692012620474_1692012425354_image_1.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012620474_1692012425354_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fa",
    "name": "externallmg_1692012743926_1692012535965_image_5.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012743926_1692012535965_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f8",
    "name": "externallmg_1692012739431_1692012535965_image_3.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012739431_1692012535965_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f5",
    "name": "externallmg_1692012729148_1692012535965_image_0.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012729148_1692012535965_image_0.jpeg",
    "orientation": "portrait"
  }
],
```

```
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3e8",
    "name": "externallmg_1692012622393_1692012425354_image_4.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012622393_1692012425354_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3e4",
    "name": "externallmg_1692012619509_1692012425354_image_0.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012619509_1692012425354_image_0.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3ea",
    "name": "Living Room",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012623513_1692012425354_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f0",
    "name": "Bedroom",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012701554_1692012506254_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f2",
    "name": "Bedroom",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012704461_1692012506254_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "64da10e6ccaf1e7b7f62c3ef",
    "name": "Kitchen",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012700973_1692012506254_image_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14352",
    "max": "21481"
  },
  "builtUpRateRange": {
    "min": "14352",
    "max": "17902"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```



```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "550.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64d9d28c6f80f132fecee423",
"ownerName": "Mrs. Shobha Rama Dhangar & Mr. Om Bablu Kadar",
```

```
"ownerPhoneNo": "7738944455",
"appAddress": "Flat no.405 4 th floor, Adityraj Gold Bldg no-50,T.N.Manorajan CHSL
Tagore Nagar Vikhroli East- 400083",
"remark": "",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "inputs": {
    "documentDate": "10/08/2023",
    "from": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Vijay Anant Katekar",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mrs. Shobha Rama Dhangar & Mr. Om Bablu Kadar"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "646034",
  "path": "cases/64d9d28c6f80f132fecee423/
document_1691996666502_ShobhaRamaDhangar_SBI_Racpc_Andheri_East.pdf",
  "fileName":
"document_1691996666502_ShobhaRamaDhangar_SBI_Racpc_Andheri_East.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "08/06/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "MH / EE / (B.P.) / GM / MHADA - 8 / 297 / 2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692165150342_OC.pdf",
  "path": "cases/64d9d28c6f80f132fecee423/document_1692165150342_OC.pdf",
  "id": "549282",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Aug 16 2023 11:22:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003131",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "790745",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 14 2023 12:36:52 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Shobha Rama Dhangar & Mr. Om Bablu Kadar",
    "phone": "7738944455",
    "ownershipShare": "",
    "email": "",
    "id": "897923"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "363444",
    "name": "Living Room",
    "length": "15.42",
    "length1": "15",
    "length2": "5",
    "width": "9.58",
    "width1": "9",
    "width2": "7",
```

```
"totalArea": "147.74",
"images": [],
"extraAreas": [],
"finalArea": "147.74"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "0",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "70.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "",
  "length1": "10",
  "length2": "7",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "31.75",
  "images": [],
  "finalArea": "31.75",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "3",
"name": "Bedroom",
"length": "10.00",
"length1": "10",
"length2": "0",
"width": "9.58",
"width1": "9",
"width2": "7",
"totalArea": "95.83",
"images": [],
"extraAreas": [],
"finalArea": "95.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "29.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "8.83",
  "width1": "8",
  "width2": "10",
  "totalArea": "99.37",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "99.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.50",
  "length1": "5",
  "length2": "6",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "24.29",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.29"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "51.10",
    "totalAreaDocument": "550",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "20",
    "docFinalSaleable": "660.00",
    "docFinalSaleableSquareMeter": "61.32",
    "id": "372132"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64da205dcaff1e7b7f62f9f7",
    "property": "Residential Flat",
    "area": "575",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "12100000",
    "expectedRate": "21043.48",
    "builtUpExpectedRate": "17536.23",
    "image": "cases/64d9d28c6f80f132fecee423/indicator_1692016634172_Image.png",
    "squareMeter": "53.42",
    "id": "617499"
  },
  {
    "printlnReport": true,
    "_id": "64da205dcaff1e7b7f62f9f8",
    "property": "Residential Flat",
    "area": "540",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "11600000",
    "expectedRate": "21481.48",
    "builtUpExpectedRate": "17901.23",
    "image": "cases/64d9d28c6f80f132fecee423/indicator_1692016663751_Image.png",
    "squareMeter": "50.17",
    "id": "886292"
  },
  {
    "printlnReport": true,
    "_id": "64dc99bdcaff1e7b7f64271c",
    "id": "4",
    "property": "Residential Flat",
    "area": "589",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
```

```
"floor": "",
"source": "Index_no.2",
"expectedPrice": "8600000",
"expectedRate": "14601.02",
"builtUpExpectedRate": "8600000",
"image": "cases/64d9d28c6f80f132fecee423/indicator_1692178877267_Image.png"
},
],
"externallImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da10e6ccaf1e7b7f62c3e4",
"name": "externallmg_1692012619509_1692012425354_image_0.jpeg",
"path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012619509_1692012425354_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da10e6ccaf1e7b7f62c3e5",
"name": "externallmg_1692012620474_1692012425354_image_1.jpeg",
"path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012620474_1692012425354_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da10e6ccaf1e7b7f62c3e6",
"name": "externallmg_1692012621428_1692012425354_image_2.jpeg",
"path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012621428_1692012425354_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64da10e6ccaf1e7b7f62c3e7",
"name": "externallmg_1692012622144_1692012425354_image_3.jpeg",
"path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012622144_1692012425354_image_3.jpeg",
"orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3e8",
    "name": "externallmg_1692012622393_1692012425354_image_4.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012622393_1692012425354_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3e9",
    "name": "externallmg_1692012622968_1692012425354_image_5.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012622968_1692012425354_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3ea",
    "name": "externallmg_1692012623513_1692012425354_image_6.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012623513_1692012425354_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3eb",
    "name": "externallmg_1692012624830_1692012425354_image_7.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012624830_1692012425354_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3ec",
    "name": "externallmg_1692012625613_1692012425355_image_8.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012625613_1692012425355_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64da10e6ccaf1e7b7f62c3ed",
  "name": "externallmg_1692012627428_1692012425355_image_9.jpeg",
  "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012627428_1692012425355_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64da10e6ccaf1e7b7f62c3ee",
  "name": "externallmg_1692012700583_1692012506254_image_0.jpeg",
  "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012700583_1692012506254_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64da10e6ccaf1e7b7f62c3ef",
  "name": "externallmg_1692012700973_1692012506254_image_1.jpeg",
  "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012700973_1692012506254_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64da10e6ccaf1e7b7f62c3f0",
  "name": "externallmg_1692012701554_1692012506254_image_2.jpeg",
  "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012701554_1692012506254_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64da10e6ccaf1e7b7f62c3f1",
  "name": "externallmg_1692012702402_1692012506254_image_3.jpeg",
  "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012702402_1692012506254_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "64da10e6ccaf1e7b7f62c3f2",
    "name": "externallmg_1692012704461_1692012506254_image_4.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012704461_1692012506254_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f3",
    "name": "externallmg_1692012706262_1692012506254_image_5.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012706262_1692012506254_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f4",
    "name": "externallmg_1692012706856_1692012506254_image_6.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012706856_1692012506254_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f5",
    "name": "externallmg_1692012729148_1692012535965_image_0.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012729148_1692012535965_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f6",
    "name": "externallmg_1692012732701_1692012535965_image_1.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012732701_1692012535965_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f7",
```

```
    "name": "externallmg_1692012735641_1692012535965_image_2.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012735641_1692012535965_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f8",
    "name": "externallmg_1692012739431_1692012535965_image_3.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012739431_1692012535965_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3f9",
    "name": "externallmg_1692012741349_1692012535965_image_4.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012741349_1692012535965_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fa",
    "name": "externallmg_1692012743926_1692012535965_image_5.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012743926_1692012535965_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fb",
    "name": "externallmg_1692012745136_1692012535965_image_6.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012745136_1692012535965_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fc",
    "name": "externallmg_1692012745866_1692012535965_image_7.jpeg",
```

```
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012745866_1692012535965_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fd",
    "name": "externallmg_1692012746216_1692012535965_image_8.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012746216_1692012535965_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3fe",
    "name": "externallmg_1692012582075_1692012390184_image_0.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012582075_1692012390184_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64da10e6ccaf1e7b7f62c3ff",
    "name": "externallmg_1692012583879_1692012390184_image_1.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/
externallmg_1692012583879_1692012390184_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "externallmg_1692012582075_1692012390184_image_0.jpeg",
    "filename":
"1692165844090_externallmg_1692012582075_1692012390184_image_0.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/processingDocuments/1692165844090_
externallmg_1692012582075_1692012390184_image_0.jpeg",
    "size": "1027990",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1692012583879_1692012390184_image_1.jpeg",
```

```
    "filename":
"1692165844120_externallmg_1692012583879_1692012390184_image_1.jpeg",
    "path": "cases/64d9d28c6f80f132fecee423/processingDocuments/1692165844120_
externallmg_1692012583879_1692012390184_image_1.jpeg",
    "size": "356011",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1692165844131_IGR01.pdf",
    "path": "cases/64d9d28c6f80f132fecee423/
processingDocuments/1692165844131_IGR01.pdf",
    "size": "100619",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1692165844133_IGR02.pdf",
    "path": "cases/64d9d28c6f80f132fecee423/
processingDocuments/1692165844133_IGR02.pdf",
    "size": "100542",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1692165844137_IGR03.pdf",
    "path": "cases/64d9d28c6f80f132fecee423/
processingDocuments/1692165844137_IGR03.pdf",
    "size": "100635",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=Shobha.xlsx",
    "filename": "1692165844140_Summary_NewShobha.xlsx",
    "path": "cases/64d9d28c6f80f132fecee423/
processingDocuments/1692165844140_Summary_NewShobha.xlsx",
    "size": "1683980",
    "createdAt": "Wed Aug 16 2023 11:34:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"createdAt": "2023-08-14T07:06:52.244Z",
```

```
"updatedAt": "2023-08-16T09:49:28.078Z",
"__v": 0,
"invoiceId": "64d9d28c6f80f132fecee430",
"fullAddress": "Residential Flat No. 405, 4th Floor, Building No 50, Adityaraj Gold,
Tagore Nagar Manoranjan Co-op. Hsg. Soc. Ltd., Tagore Nagar, Village - Hariyali ,
Municipality Ward No. S Ward, Vikhroli (East), Taluka - Kurla, District - Mumbai
Suburban, Mumbai Suburban, 400083, State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Maan Aviani ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Agent",
"siteVisitContactNo": "9664755047",
"siteVisitDate": "2023-08-14",
"buildingServicesRate": "2700",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 550.00",
"flatRate": "16000",
"landOtherRate": "13300",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "498.15000000000003",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "547.97",
"finalCarpetArea": "498.15",
"finalSalableArea": "602.76",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}
```

Name	Length	Width	Total
Composition :			
Living Room	15'5"	9'7"	147.74
Kitchen	10'0"	7'0"	70.00
Passage	10'7"	3'0"	31.75
Bedroom	10'0"	9'7"	95.83
Toilet	7'0"	4'2"	29.17
Bedroom	11'3"	8'10"	99.37
Toilet	5'6"	4'5"	24.29
Other Composition :			