

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
```

```
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.04712851669106",
  "longitude": "72.91532973558225"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91532973558225,
    19.04712851669106
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-18T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-18T11:30:00.000Z",
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-08-18T11:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-08-18T11:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-08-18T11:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-08-19",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Deonar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Samast",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Behind Lakme Company",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Govandi Station Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "328",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 088",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Govandi (East), Mumbai ",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Morya SRA Building ",
    "west": "Raheja D Road  ",
    "south": "Open Plot  ",
    "east": "Raheja Acropolis  "
  },
  "asPerDocumentAgreement": {
    "north": "CTS No. 390, Road  ",
    "west": "Prop. 13.40 DP. Road, CTS No. 402",
    "south": "CTS No. 395, 398",
    "east": "CTS No. 390"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": ""
```

```
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "207880.00",
  "landRate": "92080",
  "igrImage": "cases/64df50b3268ab30edd75d260/igr_1692683785955_Image.png",
  "squareMeterGuideLineRate": "239062.00",
  "squareFeetGuideLineRate": "22210.00"
},
"igrFinalRate": {
  "rate": "207880.00",
  "squareMeterGuideLineRate": "239062.00",
  "squareFeetGuideLineRate": "22210.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "42000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with one car parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Average",
"label": "Average"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Yes",
"label": "Yes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
}
```

```
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "796.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64df50b3268ab30edd75d260/
routeMap_1692684362198_Image.png",
    "routeLat": "19.047894",
    "routeLng": "72.916269",
    "stationName": "Govandi",
    "routeDistance": "1.1 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
```

```
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "y0rd8n",
    "name": "y0rd8n",
    "image": "cases/64df50b3268ab30edd75d260/
routeMap_1692684379625_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "20272000.00",
```



```
"finalValue": "20272000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "17688044.00",
  "selectedBuildUpValue": "796.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64e42fb7ae896715ef80b57d",
      "name":
"externallmg_1692676023271_WhatsApp_Image_20230822_at_81149_AM_1.jpeg",
      "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023271_WhatsApp_Image_20230822_at_81149_AM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64e42fb7ae896715ef80b57a",
      "name":
"externallmg_1692676023255_WhatsApp_Image_20230822_at_81148_AM_1.jpeg",
      "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023255_WhatsApp_Image_20230822_at_81148_AM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64e42fb7ae896715ef80b57b",
      "name":
"externallmg_1692676023261_WhatsApp_Image_20230822_at_81148_AM_2.jpeg",
      "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023261_WhatsApp_Image_20230822_at_81148_AM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64e47d69daae6a1c980e3adf",
      "name": "Living Room",
      "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912627_WhatsApp_Image_20230822_at_14709_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "status": false,
    "_id": "64e47d69daae6a1c980e3adc",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912621_WhatsApp_Image_20230822_at_14708_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e47d69daae6a1c980e3ade",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912625_WhatsApp_Image_20230822_at_14709_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e47d69daae6a1c980e3adb",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912617_WhatsApp_Image_20230822_at_14707_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad9",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912613_WhatsApp_Image_20230822_at_14706_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad3",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912600_WhatsApp_Image_20230822_at_14704_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad6",
    "name": "Living Room",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912605_WhatsApp_Image_20230822_at_14705_PM.jpeg",
    "orientation": "portrait"
  }
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "27624",
    "max": "30345"
  },
  "builtUpRateRange": {
    "min": "25114",
    "max": "27587"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "724.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64df50b3268ab30edd75d260",
"ownerName": "Ms. Kirtan Tirath Singh.",
"ownerPhoneNo": "8097138369",
"appAddress": "Flat no. 2102, 21th Floor, Sai Samast, Govandi Station Road, Village -
Deonar, Govandi ",
"remark": "",
"documents": [
  {
    "documentType": {
```



```
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"inputs": {
  "documentDate": "11/07/2023",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Concrete Builders",
  "to": {
    "value": "The_Allottees",
    "label": "The Allottees"
  },
  "The_Allottees": "Ms. Kirtan Tirath Singh"
},
"isHardCopy": false,
"displayStatus": false,
"id": "500985",
"path": "cases/64df50b3268ab30edd75d260/
document_1692356735596_Racpc_Sion_Kirtan_Singh.pdf",
"fileName": "document_1692356735596_Racpc_Sion_Kirtan_Singh.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 2275 / ME / STGL / AP "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692682991043_227175.pdf",
  "path": "cases/64df50b3268ab30edd75d260/
document_1692682991043_227175.pdf",
  "id": "856387",
```

```
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Tue Aug 22 2023 12:47:11 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/05/2020",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800017405"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692683069346_120749.pdf",
  "path": "cases/64df50b3268ab30edd75d260/
document_1692683069346_120749.pdf",
  "id": "661272",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Tue Aug 22 2023 12:47:11 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003189",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "410138",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 18 2023 16:36:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Kirtan Tirath Singh.",
    "phone": "8097138369",
    "ownershipShare": "",
    "email": "",
    "id": "443287"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "432878",
    "name": "Living Room",
    "length": "15.58",
    "length1": "15",
    "length2": "7",
    "width": "10.67",
    "width1": "10",
    "width2": "8",
    "totalArea": "166.22",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "64e481e7daae6a1c980e55f4",
        "name": "other",
        "extraAreaType": "Add",
        "length": "10.08",
        "length1": "10",
        "length2": "1",
        "width": "7.42",
        "width1": "7",
        "width2": "5",
        "totalArea": "74.78"
      }
    ]
  },
  {
    "finalArea": "241"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "7.67",
    "length1": "7",
```

```
"length2": "8",
"width": "10.25",
"width1": "10",
"width2": "3",
"totalArea": "78.58",
"images": [],
"extraAreas": [],
"finalArea": "78.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilets",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "27.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilets",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "26.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.25"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "5",
"name": "Bedroom",
"length": "",
"length1": "10",
"length2": "2",
"width": "",
"width1": "13",
"width2": "7",
"totalArea": "138.10",
"images": [],
"finalArea": "156.51999999999998",
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64e48274daae6a1c980e5df4",
    "name": "other",
    "extraAreaType": "Add",
    "length": "3.25",
    "length1": "3",
    "length2": "3",
    "width": "5.67",
    "width1": "5",
    "width2": "8",
    "totalArea": "18.42"
  }
]
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "10.83",
  "width1": "10",
```

```
"width2": "10",
"totalArea": "134.51",
"images": [],
"extraAreas": [],
"finalArea": "134.51"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Passage",
    "label": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "8",
  "length2": "6",
  "length": "8.50",
  "width1": "3",
  "width2": "3",
  "width": "3.25",
  "totalArea": "27.62",
  "percentageBeforeTotal": "27.62",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "27.62"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```

    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "67.26",
    "totalAreaDocument": "724.00",
    "docBuiltpPercentage": "10",
    "docFinalBUILTUp": "796.40",
    "docFinalBUILTUpSquareMeter": "73.99",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "471541"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64e44e0fae896715ef813a52",
    "property": "Concrete Sai Samast, Chembur, Mumbai ",
    "area": "724.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "20000000.00",
    "expectedRate": "27624.31",
    "builtUpExpectedRate": "25113.01",
    "image": "cases/64df50b3268ab30edd75d260/indicator_1692683252045_Image.png",
    "squareMeter": "67.26",
    "id": "399948"
  },
  {
    "printlnReport": true,
    "_id": "64e44e0fae896715ef813a53",
    "property": "2 BHK FLAT for sale in Aastha I, Deonar, Mumbai ",
    "area": "690.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "19500000.00",
    "expectedRate": "28260.87",
    "builtUpExpectedRate": "25691.70",
  }
]

```

```
    "image": "cases/64df50b3268ab30edd75d260/
indicator_1692683516553_Image.png",
    "squareMeter": "64.10",
    "id": "103067"
  },
  {
    "printlnReport": true,
    "_id": "64e44e0fae896715ef813a54",
    "property": "2 BHK FLAT for sale in Sai Samast, Deonar, Chembur, Mumbai",
    "area": "725",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "22000000.00",
    "expectedRate": "30344.83",
    "builtUpExpectedRate": "27586.21",
    "image": "cases/64df50b3268ab30edd75d260/
indicator_1692683624270_Image.png",
    "squareMeter": "67.35",
    "id": "639433"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b579",
    "name":
"externallmg_1692676023249_WhatsApp_Image_20230822_at_81147_AM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023249_WhatsApp_Image_20230822_at_81147_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57a",
    "name":
"externallmg_1692676023255_WhatsApp_Image_20230822_at_81148_AM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023255_WhatsApp_Image_20230822_at_81148_AM_1.jpeg",
    "orientation": "portrait"
  },
  {

```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57b",
    "name":
"externallmg_1692676023261_WhatsApp_Image_20230822_at_81148_AM_2.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023261_WhatsApp_Image_20230822_at_81148_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57c",
    "name":
"externallmg_1692676023267_WhatsApp_Image_20230822_at_81148_AM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023267_WhatsApp_Image_20230822_at_81148_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57d",
    "name":
"externallmg_1692676023271_WhatsApp_Image_20230822_at_81149_AM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023271_WhatsApp_Image_20230822_at_81149_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57e",
    "name":
"externallmg_1692676023276_WhatsApp_Image_20230822_at_81149_AM_2.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023276_WhatsApp_Image_20230822_at_81149_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e42fb7ae896715ef80b57f",
    "name":
"externallmg_1692676023278_WhatsApp_Image_20230822_at_81149_AM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692676023278_WhatsApp_Image_20230822_at_81149_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad2",
    "name":
"externallmg_1692695912598_WhatsApp_Image_20230822_at_14703_PM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912598_WhatsApp_Image_20230822_at_14703_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad3",
    "name":
"externallmg_1692695912600_WhatsApp_Image_20230822_at_14704_PM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912600_WhatsApp_Image_20230822_at_14704_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad4",
    "name":
"externallmg_1692695912601_WhatsApp_Image_20230822_at_14704_PM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912601_WhatsApp_Image_20230822_at_14704_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad5",
    "name":
"externallmg_1692695912603_WhatsApp_Image_20230822_at_14705_PM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912603_WhatsApp_Image_20230822_at_14705_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad6",
```

```
    "name":
"externallmg_1692695912605_WhatsApp_Image_20230822_at_14705_PM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912605_WhatsApp_Image_20230822_at_14705_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad7",
    "name":
"externallmg_1692695912607_WhatsApp_Image_20230822_at_14706_PM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912607_WhatsApp_Image_20230822_at_14706_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad8",
    "name":
"externallmg_1692695912610_WhatsApp_Image_20230822_at_14706_PM_2.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912610_WhatsApp_Image_20230822_at_14706_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ad9",
    "name":
"externallmg_1692695912613_WhatsApp_Image_20230822_at_14706_PM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912613_WhatsApp_Image_20230822_at_14706_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ada",
    "name":
"externallmg_1692695912616_WhatsApp_Image_20230822_at_14707_PM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912616_WhatsApp_Image_20230822_at_14707_PM_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e47d69daae6a1c980e3adb",
  "name":
"externallmg_1692695912617_WhatsApp_Image_20230822_at_14707_PM.jpeg",
  "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912617_WhatsApp_Image_20230822_at_14707_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e47d69daae6a1c980e3adc",
  "name":
"externallmg_1692695912621_WhatsApp_Image_20230822_at_14708_PM_1.jpeg",
  "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912621_WhatsApp_Image_20230822_at_14708_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e47d69daae6a1c980e3add",
  "name":
"externallmg_1692695912623_WhatsApp_Image_20230822_at_14708_PM.jpeg",
  "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912623_WhatsApp_Image_20230822_at_14708_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e47d69daae6a1c980e3ade",
  "name":
"externallmg_1692695912625_WhatsApp_Image_20230822_at_14709_PM_1.jpeg",
  "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912625_WhatsApp_Image_20230822_at_14709_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e47d69daae6a1c980e3adf",
  "name":
"externallmg_1692695912627_WhatsApp_Image_20230822_at_14709_PM.jpeg",
```

```
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912627_WhatsApp_Image_20230822_at_14709_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ae0",
    "name":
"externallmg_1692695912629_WhatsApp_Image_20230822_at_14710_PM_1.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912629_WhatsApp_Image_20230822_at_14710_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e47d69daae6a1c980e3ae1",
    "name":
"externallmg_1692695912630_WhatsApp_Image_20230822_at_14710_PM.jpeg",
    "path": "cases/64df50b3268ab30edd75d260/
externallmg_1692695912630_WhatsApp_Image_20230822_at_14710_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-18T11:06:27.857Z",
"updatedAt": "2023-08-22T10:17:49.857Z",
"__v": 0,
"invoiceId": "64df50b4268ab30edd75d276",
"updatedBy": "60f915d3f3dd69653a592199",
"fullAddress": "Residential Flat No. 2102, 21st Floor, Sai Samast, Behind Lakme
Company, Govandi Station Road, Village - Deonar, Govandi (East), Mumbai , Taluka -
Kurla , District - Mumbai Suburban, 400 088, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Ms. Rupa Sharma (Sales Person)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7039003030",
"buildingServicesRate": "3000.00",
```

```

"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 724.00",
"flatRate": "28000.00",
"landOtherRate": "25000",
"builtupPercentage": "10",
"carpetTotal": "664.29",
"extendOfSiteRemark": "",
"finalBuiltupArea": "761.10",
"finalCarpetArea": "691.91",
"finalSalableArea": "837.21",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "All the above areas are within +/- 10% of the Agreement
for Sale Area. The above calculations and detail measurements taken by us prove that
the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area.",
"toBeAdded": "",
"finalSaleablePercentage": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilets",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "27.62",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Tue Aug 22 2023 15:26:40 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-08-19"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'7"	10'8"	166.22
Kitchen	7'8"	10'3"	78.58
Toilets	4'2"	6'7"	27.43
Toilets	7'0"	3'9"	26.25
Bedroom	10'2"	13'7"	138.10
Bedroom	12'5"	10'10"	134.51

Other
Composition :

Passage	8'6"	3'3"	27.62
---------	------	------	-------
