

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "firstName": "Priti",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
```

```
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.160236338505758 ",
  "longitude": "73.11662252899255"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11662252899255,
```

```
19.160236338505758
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-20",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Khoni",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "17",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Casa Clara",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Kalyan Shill Road",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "J",
```



```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Palava-Clara",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1702",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64e04e2b89269b6523778898",
"ownerName": "Mrs. Shilpa Jadhav",
"ownerPhoneNo": "9223495060",
"fullAddress": "Residential Flat No. 1702, 17th Floor, Wing - J, Casa Clara, Palava-
Clara, Kalyan Shill Road, Village - Khoni, Taluka - Kalyan, District - Thane, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "22/06/2017",
      "from": {
        "value": "Company",
        "label": "Company"
      },
      "Company": "Palava Dwellers Pvt. Ltd",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      }
    }
  }
],
```

```
    "purchaser": "Mrs. Shilpa Jadhav"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692448339211_Jondhale_palava.pdf",
  "path": "cases/64e04e2b89269b6523778898/
document_1692448339211_Jondhale_palava.pdf",
  "id": "829316",
  "uploadedBy": "6430f74691d7c62df11f3f15",
  "createdAt": "Sat Aug 19 2023 18:02:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "14/03/2018",
    "nameOfApprovingAuthority": {
      "value": "Town_Planner_",
      "label": "Town Planner "
    },
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "Ekatmik Nagar Vasahat / Atarli, Khoni & other / SS Thane / 471 "
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692702149762_1_Commencement_Certificates___NA_Order_for_plotted_development__20230822T113506981.pdf",
  "path": "cases/64e04e2b89269b6523778898/document_1692702149762_1_Commencement_Certificates___NA_Order_for_plotted_development__20230822T113506981.pdf",
  "id": "169833",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Aug 22 2023 16:34:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/03/2020",
```

```
"nameOfApprovingAuthority": {
  "value": "Town_Planner_",
  "label": "Town Planner "
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "BP / ANVP / Atarli, Khoni & other / SS Thane / 807 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1692702213880_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development_19.pdf",
"path": "cases/64e04e2b89269b6523778898/document_1692702213880_1_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development_19.pdf",
"id": "292909",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Aug 22 2023 16:34:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700000420"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1692702277714_P51700000420.pdf",
"path": "cases/64e04e2b89269b6523778898/
document_1692702277714_P51700000420.pdf",
"id": "984834",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Aug 22 2023 16:34:38 GMT+0530 (India Standard Time)"
```

```
}
],
"caseNumber": "003203",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "898383",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 19 2023 10:37:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Shilpa Jadhav",
    "phone": "9223495060",
    "ownershipShare": "",
    "email": "",
    "id": "684145"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac12",
    "name": "externalImg_1692535492976_1692535364374_image_0.jpeg",
    "path": "cases/64e04e2b89269b6523778898/externalImg_1692535492976_1692535364374_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac13",
    "name": "externalImg_1692535493650_1692535364374_image_1.jpeg",
    "path": "cases/64e04e2b89269b6523778898/externalImg_1692535493650_1692535364374_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac14",
  "name": "externallmg_1692535494121_1692535364374_image_2.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535494121_1692535364374_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac15",
  "name": "externallmg_1692535494859_1692535364374_image_3.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535494859_1692535364374_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac16",
  "name": "externallmg_1692535495247_1692535364374_image_4.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535495247_1692535364374_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac17",
  "name": "externallmg_1692535495788_1692535364374_image_5.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535495788_1692535364374_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac18",
  "name": "externallmg_1692535496336_1692535364374_image_6.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535496336_1692535364374_image_6.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac19",
    "name": "externallmg_1692535496901_1692535364374_image_7.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535496901_1692535364374_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac1a",
    "name": "externallmg_1692535497506_1692535364374_image_8.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535497506_1692535364374_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac1b",
    "name": "externallmg_1692535585690_1692535450345_image_0.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535585690_1692535450345_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac1c",
    "name": "externallmg_1692535586154_1692535450345_image_1.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535586154_1692535450345_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac1d",
    "name": "externallmg_1692535586519_1692535450345_image_2.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535586519_1692535450345_image_2.jpeg",
    "orientation": "portrait"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac1e",
  "name": "externallmg_1692535587144_1692535450345_image_3.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535587144_1692535450345_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac1f",
  "name": "externallmg_1692535587527_1692535450345_image_4.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535587527_1692535450345_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac20",
  "name": "externallmg_1692535587766_1692535450345_image_5.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535587766_1692535450345_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac21",
  "name": "externallmg_1692535588314_1692535450345_image_6.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535588314_1692535450345_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e20b3fae896715ef7eac22",
  "name": "externallmg_1692535588726_1692535450345_image_7.jpeg",
  "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535588726_1692535450345_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac23",
    "name": "externallmg_1692535589075_1692535450345_image_8.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535589075_1692535450345_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac24",
    "name": "externallmg_1692535589406_1692535450345_image_9.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535589406_1692535450345_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac25",
    "name": "externallmg_1692535589829_1692535450345_image_10.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535589829_1692535450345_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac26",
    "name": "externallmg_1692535590302_1692535450345_image_11.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535590302_1692535450345_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e20b3fae896715ef7eac27",
    "name": "externallmg_1692535591009_1692535450345_image_12.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externallmg_1692535591009_1692535450345_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "64e20b3fae896715ef7eac28",
    "name": "externalImg_1692535591351_1692535450345_image_13.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externalImg_1692535591351_1692535450345_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64e20b3fae896715ef7eac29",
    "name": "externalImg_1692535455667_1692535328582_image_0.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externalImg_1692535455667_1692535328582_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64e20b3fae896715ef7eac2a",
    "name": "externalImg_1692535455795_1692535328582_image_1.jpeg",
    "path": "cases/64e04e2b89269b6523778898/
externalImg_1692535455795_1692535328582_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-19T05:07:55.938Z",
"updatedAt": "2023-08-22T11:04:38.022Z",
"__v": 0,
"invoiceId": "64e04e2c89269b65237788c7",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Shilpa Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9223495060"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			