

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "6403359b80a50a302f6acd52",
    "firstName": "Suraj Barge",
    "lastName": "Barge",
    "mobileNo": "",
    "workMobileNo": "9920273024",
    "email": "suresh.barge@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Suraj Barge",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.171551394321153",
  "longitude": "73.07034129553367"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07034129553367,
```

```
19.171551394321153
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-19T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-19T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-19T07:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nilje",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Golflinks Viento Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan - Shil Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "13/1 pt, 15/0, 16/0, 181/1 pt, 182/2 pt & other's",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 204",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
```

```
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mumbai_Metropolitan_Region_Development_Authority",
    "label": "Mumbai Metropolitan Region Development Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "Yes",
    "label": "Yes"
  },
  "asPerActualAgreement": {
    "north": "Wing - B",
    "west": "Internal Road",
    "south": "Road",
    "east": "Utopia A Wing"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "11676",
  "depreciatedBuildingRate": "2376"
},
```

```
"igrRate": {
  "propertyName": "Residential ",
  "rate": "67600",
  "landRate": "20500",
  "igrImage": "cases/64e0692c89269b652377fead/igr_1692704292569_Image.png",
  "squareMeterGuideLineRate": "67600.00",
  "squareFeetGuideLineRate": "6280.00"
},
"igrFinalRate": {
  "rate": "5930.00",
  "squareFeetGuideLineRate": "5930.00",
  "squareMeterGuideLineRate": "63832.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "38000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MMRDA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Along with One Car Parking space No. G0048",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
```

```
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
"area": "1915.20",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
},
"routeMapImg": "cases/64e0692c89269b652377fead/
routeMap_1692766899982_Image.png",
"routeLat": "19.166842",
"routeLng": "73.072770",
"stationName": "Nilje",
"routeDistance": "2.5 Km"
},
"finalLatLng": {
"coordinates": [
null,
null
]
},
]
```



```
"type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "0mbm1d",
    "name": "0mbm1d",
    "image": "cases/64e0692c89269b652377fead/
routeMap_1692766906036_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18634896.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
```

```
"bookValue": "0",
"finalValue": "18634896.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11357136.00",
  "selectedBuildUpValue": "1915.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "64e46a2bdaae6a1c980df596",
  "name":
"externallmg_1692690987211_WhatsApp_Image_20230822_at_11357_PM_2.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987211_WhatsApp_Image_20230822_at_11357_PM_2.jpeg",
  "orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df594",
    "name":
"externallmg_1692690987206_WhatsApp_Image_20230822_at_11358_PM.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987206_WhatsApp_Image_20230822_at_11358_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df595",
    "name":
"externallmg_1692690987209_WhatsApp_Image_20230822_at_11357_PM_1.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987209_WhatsApp_Image_20230822_at_11357_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64e46a1edaae6a1c980df530",
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690974063_WhatsApp_Image_20230822_at_11357_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e46a1edaae6a1c980df531",
```

```
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690974066_WhatsApp_Image_20230822_at_11357_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58e",
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987189_WhatsApp_Image_20230822_at_11357_PM_17.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58d",
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987186_WhatsApp_Image_20230822_at_11357_PM_16.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df59b",
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987223_WhatsApp_Image_20230822_at_11357_PM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e46a2bdaae6a1c980df59c",
    "name": "Living Room",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987224_WhatsApp_Image_20230822_at_11357_PM_8.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11089",
    "max": "12579"
  },
  "builtUpRateRange": {
    "min": "9241",
```

```
"max": "10483"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
```



```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1596.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64e0692c89269b652377fead",
"ownerName": "Mr. Jitendra Ashok Chavan",
"ownerPhoneNo": "8605222707",
"appAddress": "Flat no. 301, 3rd Floor, Wing - A, Golfink Viento CHS, Village - Nilje,
Kalyan Dombivali ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "28/06/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      }
    }
  }
]
```

```
    },
    "Transferor": "Mr. Sunil S. Dangi & Mrs. Rekha Sunil Dangi",
    "to": {
      "value": "transferee",
      "label": "transferee"
    },
    "transferee": "Mr. Jitendra Ashok Chavan & Mrs. Yogini Jitendra Chavan"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "443807",
  "path": "cases/64e0692c89269b652377fead/
document_1692428546971_67841.pdf",
  "fileName": "document_1692428546971_67841.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "14/12/2015",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SROT / MCP - 03 / L.D.P.L. / OC - 1 / C1 - 14 / 902 - 2015"
},
  "isHardCopy": false,
  "displayStatus": true,
  "id": "440864",
  "path": "cases/64e0692c89269b652377fead/
document_1692703682597_161089.pdf",
  "fileName": "document_1692703682597_161089.pdf"
}
],
"caseNumber": "003210",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "339708",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Sat Aug 19 2023 12:33:08 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Jitendra Ashok Chavan",
"phone": "8605222707",
"ownershipShare": "",
"email": "",
"id": "770569"
},
{
"name": "Mrs. Yogini Jitendra Chavan",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "467126"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "660819",
"name": "Living Room",
"length": "13.67",
"length1": "13",
"length2": "8",
"width": "14.08",
"width1": "14",
"width2": "1",
"totalArea": "192.47",
"images": [],
"extraAreas": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
},
"_id": "64e4a7f5daae6a1c980f2b61",
"name": "other",
```

```
"extraAreaType": "Add",
"length": "10.67",
"length1": "10",
"length2": "8",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "106.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "64e4ac04daae6a1c980f3918",
  "name": "Other",
  "extraAreaType": "Add",
  "length": "16.33",
  "length1": "16",
  "length2": "4",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "57.17"
}
],
"finalArea": "356.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "14.00",
  "width1": "14",
  "width2": "0",
  "totalArea": "119.00",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "64e4ac57daae6a1c980f3969",
  "name": "other",
  "extraAreaType": "Add",
  "length": "2.58",
  "length1": "2",
  "length2": "7",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "13.99"
}
],
"finalArea": "132.99"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "16.42",
  "length1": "16",
  "length2": "5",
  "width": "12.25",
  "width1": "12",
  "width2": "3",
  "totalArea": "201.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "201.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "14.17",
```

```
"width1": "14",
"width2": "2",
"totalArea": "148.75",
"images": [],
"extraAreas": [],
"finalArea": "148.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "0",
  "width": "16.25",
  "width1": "16",
  "width2": "3",
  "totalArea": "162.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "162.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "8.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "2.50",
  "width1": "2",
  "width2": "6",
  "totalArea": "16.04",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.04"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "2.58",
  "width1": "2",
  "width2": "7",
  "totalArea": "11.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
```





```
"id": "11",
"name": "Toilet",
"length": "4.17",
"length1": "4",
"length2": "2",
"width": "7.17",
"width1": "7",
"width2": "2",
"totalArea": "29.86",
"images": [],
"extraAreas": [],
"finalArea": "29.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "2.33",
  "length1": "2",
  "length2": "4",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "10.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Toilet",
  "length": "1.58",
  "length1": "1",
  "length2": "7",
  "width": "2.50",
  "width1": "2",
  "width2": "6",
  "totalArea": "3.96",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "3.96"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Passage",
  "length": "5.50",
  "length1": "5",
  "length2": "6",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "46.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "46.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "15",
  "name": "Passage",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "15.58",
  "width1": "15",
  "width2": "7",
  "totalArea": "54.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.54"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },

```

```
"name": {
  "value": "Cupboard",
  "label": "Cupboard"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length1": "3",
"length2": "4",
"length": "3.33",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "6.67",
"percentageBeforeTotal": "6.67",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "6.67"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "11",
  "length2": "0",
  "length": "11.00",
  "width1": "8",
  "width2": "8",
  "width": "8.67",
  "totalArea": "95.33",
  "percentageBeforeTotal": "95.33",
  "images": [],
  "extraAreas": [],
```

```
"percentage": "100",
"finalArea": "95.33"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "4",
  "length2": "0",
  "length": "4.00",
  "width1": "22",
  "width2": "2",
  "width": "22.17",
  "totalArea": "88.67",
  "percentageBeforeTotal": "88.67",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "88.67"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "4",
  "length2": "5",
```

```
"length": "4.42",
"width1": "3",
"width2": "1",
"width": "3.08",
"totalArea": "13.62",
"percentageBeforeTotal": "13.62",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "13.62"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "148.27",
  "totalAreaDocument": "1596.00",
  "docBuiltupPercentage": "20",
  "docFinalBuiltUp": "1915.20",
  "docFinalBuiltUpSquareMeter": "177.93",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "808238"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64e49e70daae6a1c980efc32",
  "property": "2BHK flat for sale in Lodha Golflinks, Dombivli East",
  "area": "992.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "11000000.00",
"expectedRate": "11088.71",
"builtUpExpectedRate": "9240.59",
"image": "cases/64e0692c89269b652377fead/
indicator_1692704083582_Image.png",
"squareMeter": "92.16",
"id": "660048"
},
{
"printlnReport": true,
"_id": "64e49e70daae6a1c980efc33",
"property": "2 BHK Flat Lodha Golfinks, Khidkali, Thane",
"area": "1599.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Housing.Com",
"expectedPrice": "18100000.00",
"expectedRate": "11319.57",
"builtUpExpectedRate": "9432.98",
"image": "cases/64e0692c89269b652377fead/
indicator_1692704204865_Image.png",
"squareMeter": "148.55",
"id": "122543"
},
{
"printlnReport": true,
"_id": "64e49e70daae6a1c980efc34",
"property": "3 BHK flat for sale in Lodha Golfinks, Dombivli East",
"area": "1590",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "square_yards",
"expectedPrice": "20000000.00",
"expectedRate": "12578.62",
"builtUpExpectedRate": "10482.18",
"image": "cases/64e0692c89269b652377fead/
indicator_1692704245393_Image.png",
"squareMeter": "147.72",
"id": "115965"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a1edaae6a1c980df530",
    "name":
"externalImg_1692690974063_WhatsApp_Image_20230822_at_11357_PM_11.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externalImg_1692690974063_WhatsApp_Image_20230822_at_11357_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a1edaae6a1c980df531",
    "name":
"externalImg_1692690974066_WhatsApp_Image_20230822_at_11357_PM_12.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externalImg_1692690974066_WhatsApp_Image_20230822_at_11357_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a1edaae6a1c980df532",
    "name":
"externalImg_1692690974070_WhatsApp_Image_20230822_at_11357_PM_13.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externalImg_1692690974070_WhatsApp_Image_20230822_at_11357_PM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a1edaae6a1c980df533",
    "name":
"externalImg_1692690974072_WhatsApp_Image_20230822_at_11357_PM_14.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externalImg_1692690974072_WhatsApp_Image_20230822_at_11357_PM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58c",
    "name":
"externalImg_1692690987183_WhatsApp_Image_20230822_at_11357_PM_15.jpeg",
```

```
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987183_WhatsApp_Image_20230822_at_11357_PM_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58d",
    "name":
"externallmg_1692690987186_WhatsApp_Image_20230822_at_11357_PM_16.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987186_WhatsApp_Image_20230822_at_11357_PM_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58e",
    "name":
"externallmg_1692690987189_WhatsApp_Image_20230822_at_11357_PM_17.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987189_WhatsApp_Image_20230822_at_11357_PM_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df58f",
    "name":
"externallmg_1692690987190_WhatsApp_Image_20230822_at_11357_PM_18.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987190_WhatsApp_Image_20230822_at_11357_PM_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df590",
    "name":
"externallmg_1692690987194_WhatsApp_Image_20230822_at_11357_PM_19.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987194_WhatsApp_Image_20230822_at_11357_PM_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "64e46a2bdaae6a1c980df591",
  "name":
"externallmg_1692690987196_WhatsApp_Image_20230822_at_11358_PM_1.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987196_WhatsApp_Image_20230822_at_11358_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df592",
  "name":
"externallmg_1692690987200_WhatsApp_Image_20230822_at_11358_PM_2.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987200_WhatsApp_Image_20230822_at_11358_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df593",
  "name":
"externallmg_1692690987203_WhatsApp_Image_20230822_at_11358_PM_3.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987203_WhatsApp_Image_20230822_at_11358_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df594",
  "name":
"externallmg_1692690987206_WhatsApp_Image_20230822_at_11358_PM.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987206_WhatsApp_Image_20230822_at_11358_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df595",
  "name":
"externallmg_1692690987209_WhatsApp_Image_20230822_at_11357_PM_1.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987209_WhatsApp_Image_20230822_at_11357_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df596",
    "name":
"externallmg_1692690987211_WhatsApp_Image_20230822_at_11357_PM_2.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987211_WhatsApp_Image_20230822_at_11357_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df597",
    "name":
"externallmg_1692690987214_WhatsApp_Image_20230822_at_11357_PM_3.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987214_WhatsApp_Image_20230822_at_11357_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df598",
    "name":
"externallmg_1692690987217_WhatsApp_Image_20230822_at_11357_PM_4.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987217_WhatsApp_Image_20230822_at_11357_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df599",
    "name":
"externallmg_1692690987219_WhatsApp_Image_20230822_at_11357_PM_5.jpeg",
    "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987219_WhatsApp_Image_20230822_at_11357_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e46a2bdaae6a1c980df59a",
```

```
"name":
"externallmg_1692690987220_WhatsApp_Image_20230822_at_11357_PM_6.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987220_WhatsApp_Image_20230822_at_11357_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df59b",
  "name":
"externallmg_1692690987223_WhatsApp_Image_20230822_at_11357_PM_7.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987223_WhatsApp_Image_20230822_at_11357_PM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df59c",
  "name":
"externallmg_1692690987224_WhatsApp_Image_20230822_at_11357_PM_8.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987224_WhatsApp_Image_20230822_at_11357_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df59d",
  "name":
"externallmg_1692690987226_WhatsApp_Image_20230822_at_11357_PM_9.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987226_WhatsApp_Image_20230822_at_11357_PM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df59e",
  "name":
"externallmg_1692690987228_WhatsApp_Image_20230822_at_11357_PM_10.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987228_WhatsApp_Image_20230822_at_11357_PM_10.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e46a2bdaae6a1c980df59f",
  "name":
"externallmg_1692690987229_WhatsApp_Image_20230822_at_11357_PM.jpeg",
  "path": "cases/64e0692c89269b652377fead/
externallmg_1692690987229_WhatsApp_Image_20230822_at_11357_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-19T07:03:08.218Z",
"updatedAt": "2023-08-23T05:45:44.043Z",
"__v": 0,
"invoiceId": "64e0692c89269b652377feb9",
"fullAddress": "Residential Flat No. 301, 3rd Floor, Wing - A, Golflinks Viento Co-Op.
Hsg. Soc. Ltd., Kalyan - Shil Road, Village - Nilje, Dombivli (East), Taluka - Kalyan,
District - Thane, PIN Code - 421 204, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Jitendra Chavan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8605222707",
"buildingServicesRate": "2700.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1596.00",
"flatRate": "12000.00",
"landOtherRate": "9300",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 5 Passage + 6 Toilet",
"carpetTotal": "1110.40",
"otherCarpetTotal": "204.29",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "204.29",
"otherCompositionSaleableTotal": "0.00",
```

"builtupPercentage": "20",  
 "finalBuiltupArea": "1772.63",  
 "finalCarpetArea": "1477.19",  
 "finalSalableArea": "1949.89",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "\n",  
 "siteMeasurementRemark": "All the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.",  
 "finalSaleablePercentage": ""  
 }

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	13'8"	14'1"	192.47
Kitchen	8'6"	14'0"	119.00
Bedroom	16'5"	12'3"	201.10
Bedroom	10'6"	14'2"	148.75
Bedroom	10'0"	16'3"	162.50
Passage	2'5"	3'4"	8.06
Passage	6'5"	2'6"	16.04
Passage	4'6"	2'7"	11.62
Toilet	8'5"	5'5"	45.59
Toilet	4'1"	3'7"	14.63
Toilet	7'1"	4'2"	29.51
Toilet	4'2"	7'2"	29.86
Toilet	2'4"	4'7"	10.69
Toilet	1'7"	2'6"	3.96
Passage	5'6"	8'6"	46.75
Passage	3'6"	15'7"	54.54

Other  
Composition :

Cupboard	3'4"	2'00"	6.67
Balcony	11'0"	8'8"	95.33
Balcony	4'0"	22'2"	88.67
Balcony	4'5"	3'1"	13.62