

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "632ee4c4e2561b46f656d584"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7a01e363ef22db2f2417",
    "firstName": "testadgaon",
    "lastName": "adgaon",
    "mobileNo": "",
    "email": "adgaon@vastukala.org",
    "workMobileNo": "0000000000"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
```

```
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "632ee4c4e2561b46f656d584",
  "name": "RACPC Adgaon,",
  "branchCode": "14",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "me@me.sbi",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RACPC Adgaon, Nashik Branch,Nshik, Maharashtra State –
Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": "",
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": ""
},
"checker": "",
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "19.9565794272576",
"longitude": "73.77136315571458"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "30,31 & 40,41",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Morya Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dnyaneshwar Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Wasan Nagar Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Police Headquater Ground",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```

```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "897/ 1/ B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422009",
```



```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e1c10fae896715ef7ea136",
"ownerName": "Mukesh Prasad Gupta ",
"ownerPhoneNo": "7903048057",
"fullAddress": "Residential Flat No. 3, 1st Floor, Morya Heights, Near Police
Headquater Ground, Plot No. 30,31 & 40,41, Dnyaneshwar Nagar, Wasan Nagar Road,
Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, 422009, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      }
    }
  },
  {
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1692516491921_Mukesh_Gupta_NotaryCC_OC.pdf",
    "path": "cases/64e1c10fae896715ef7ea136/
document_1692516491921_Mukesh_Gupta_NotaryCC_OC.pdf",
    "id": "556511",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sun Aug 20 2023 12:59:55 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae1277aa6d152c1801b3cc",
  "label": "Approved Building Plan"
},
"inputs": {
  "nameOfApprovingAuthority": {
    "value": "Nashik_Municipal_Corporation",
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "CD/167"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1692516524671_Mukesh_Gupta_Plan.pdf",
"path": "cases/64e1c10fae896715ef7ea136/
document_1692516524671_Mukesh_Gupta_Plan.pdf",
"id": "751701",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Sun Aug 20 2023 12:59:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a7",
    "label": "Title Search Report"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692516548407_Mukesh_Gupta_TSR.pdf",
  "path": "cases/64e1c10fae896715ef7ea136/
document_1692516548407_Mukesh_Gupta_TSR.pdf",
  "id": "546843",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sun Aug 20 2023 12:59:55 GMT+0530 (India Standard Time)"
}
],
```



```
"caseNumber": "003240",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "756940",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Aug 20 2023 13:00:23 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mukesh Prasad Gupta ",
    "phone": "7903048057",
    "ownershipShare": "",
    "email": "",
    "id": "756551"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea3ff",
    "name":
"externallmg_1692516719279_WhatsApp_Image_20230818_at_12502_PM_1.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719279_WhatsApp_Image_20230818_at_12502_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea400",
    "name":
"externallmg_1692516719354_WhatsApp_Image_20230818_at_12502_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719354_WhatsApp_Image_20230818_at_12502_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea401",
    "name":
"externallmg_1692516719421_WhatsApp_Image_20230818_at_12503_PM_1.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719421_WhatsApp_Image_20230818_at_12503_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea402",
    "name":
"externallmg_1692516719459_WhatsApp_Image_20230818_at_12503_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719459_WhatsApp_Image_20230818_at_12503_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea403",
    "name":
"externallmg_1692516719537_WhatsApp_Image_20230818_at_12504_PM_1.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719537_WhatsApp_Image_20230818_at_12504_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea404",
    "name":
"externallmg_1692516719577_WhatsApp_Image_20230818_at_12504_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719577_WhatsApp_Image_20230818_at_12504_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea405",
```

```
    "name":
"externallmg_1692516719617_WhatsApp_Image_20230818_at_12505_PM_1.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719617_WhatsApp_Image_20230818_at_12505_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea406",
  "name":
"externallmg_1692516719711_WhatsApp_Image_20230818_at_12505_PM_2.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719711_WhatsApp_Image_20230818_at_12505_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea407",
  "name":
"externallmg_1692516719750_WhatsApp_Image_20230818_at_12505_PM.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719750_WhatsApp_Image_20230818_at_12505_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea408",
  "name":
"externallmg_1692516719790_WhatsApp_Image_20230818_at_12506_PM_1.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719790_WhatsApp_Image_20230818_at_12506_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea409",
  "name":
"externallmg_1692516719844_WhatsApp_Image_20230818_at_12506_PM_2.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719844_WhatsApp_Image_20230818_at_12506_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea40a",
  "name":
"externallmg_1692516719872_WhatsApp_Image_20230818_at_12506_PM.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719872_WhatsApp_Image_20230818_at_12506_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea40b",
  "name":
"externallmg_1692516719924_WhatsApp_Image_20230818_at_12507_PM_1.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719924_WhatsApp_Image_20230818_at_12507_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea40c",
  "name":
"externallmg_1692516719978_WhatsApp_Image_20230818_at_12507_PM.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516719978_WhatsApp_Image_20230818_at_12507_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea40d",
  "name":
"externallmg_1692516720016_WhatsApp_Image_20230818_at_12508_PM_1.jpeg",
  "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720016_WhatsApp_Image_20230818_at_12508_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e1c170ae896715ef7ea40e",
  "name":
"externallmg_1692516720042_WhatsApp_Image_20230818_at_12508_PM.jpeg",
```

```
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720042_WhatsApp_Image_20230818_at_12508_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea40f",
    "name":
"externallmg_1692516720082_WhatsApp_Image_20230818_at_12730_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720082_WhatsApp_Image_20230818_at_12730_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea410",
    "name":
"externallmg_1692516720120_WhatsApp_Image_20230818_at_12743_PM_1.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720120_WhatsApp_Image_20230818_at_12743_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea411",
    "name":
"externallmg_1692516720174_WhatsApp_Image_20230818_at_12743_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720174_WhatsApp_Image_20230818_at_12743_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e1c170ae896715ef7ea412",
    "name":
"externallmg_1692516720226_WhatsApp_Image_20230818_at_12744_PM.jpeg",
    "path": "cases/64e1c10fae896715ef7ea136/
externallmg_1692516720226_WhatsApp_Image_20230818_at_12744_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [],
"createdAt": "2023-08-20T07:30:23.864Z",
"updatedAt": "2023-08-20T07:32:00.402Z",
"__v": 0,
"invoiceId": "64e1c10fae896715ef7ea13c",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Mukesh Prasad Gupta ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7903048057"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			