

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4600000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 2300,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "627219d6afd7d55eddedd283",
  "role": "PICKUPPERSON",
  "firstName": "Mangesh ",
  "email": "mangeshpalande17@gmail.com",
  "lastName": "Palande",
  "mobileNo": "9833030550",
  "shortName": "MP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyan_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": "",
```

```
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.36705063113616",
  "longitude": "72.80045699222735"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.80045699222735,
    19.36705063113616
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-21T11:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-21T11:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dhovali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Palghar",
    "label": true
  },
}
```

```
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "\"Donde Heights\"",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2852/A",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "702",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": true,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "Vasai Road (West)",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  }
}
```

```
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "PowderCoatedAluminiumSliding",
  "label": "Powder Coated Aluminium Sliding"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "House / Bungalow",
    "west": "Maulana Azad Road",
    "south": "Paradise Building",
    "east": "Bungalow"
  },
}
```

```
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "Rs. 10,000.00 Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
```

```
"label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "937.76",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64e33fa6ae896715ef8010c7/
routeMap_1692777393519_Image.png",
  "routeLat": "19.344889",
  "routeLng": "72.803722",
  "stationName": "Vasai Road",
  "routeDistance": "6.7KM"
},
"finalLatLng": {
  "coordinates": [
```

```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "e2h2s",
    "name": "e2h2s",
    "image": "cases/64e33fa6ae896715ef8010c7/
routeMap_1692777187797_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "0.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "0.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0.00",
"selectedBuildUpValue": "937.76",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64e58ce8daae6a1c980f9196",
      "name":
"externallmg_1692765416314_WhatsApp_Image_20230822_at_85637_PM_2.jpeg",
      "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416314_WhatsApp_Image_20230822_at_85637_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64e58cd2daae6a1c980f90dd",
      "name":
"externallmg_1692765394799_WhatsApp_Image_20230822_at_85704_PM_1.jpeg",
      "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394799_WhatsApp_Image_20230822_at_85704_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64e58ce8daae6a1c980f9194",
      "name":
"externallmg_1692765416306_WhatsApp_Image_20230822_at_85636_PM.jpeg",
      "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416306_WhatsApp_Image_20230822_at_85636_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64e58ce8daae6a1c980f9191",
      "name":
"externallmg_1692765416294_WhatsApp_Image_20230822_at_85631_PM.jpeg",
      "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416294_WhatsApp_Image_20230822_at_85631_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64e58d01daae6a1c980f930b",
```

```
    "name":
"externallmg_1692765440990_WhatsApp_Image_20230822_at_85639_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765440990_WhatsApp_Image_20230822_at_85639_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64e58d01daae6a1c980f9317",
    "name": "Kitchen",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441017_WhatsApp_Image_20230822_at_85643_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e58d01daae6a1c980f931a",
    "name": "Kitchen",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441026_WhatsApp_Image_20230822_at_85701_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e58cd2daae6a1c980f90df",
    "name": "Bedroom",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394806_WhatsApp_Image_20230822_at_85704_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e58d01daae6a1c980f9315",
    "name": "Bedroom",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441016_WhatsApp_Image_20230822_at_85642_PM_2.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "852.51",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64e33fa6ae896715ef8010c7",
"ownerName": "Darshani Vishal Purandare",
"ownerPhoneNo": "9850187225",
"appAddress": "flat no 702 donde hights dhobli vasai w",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "inputs": {
      "documentDate": "05/08/2023",
      "amount": "46,00,000.00",
```

```
"from": {
  "value": "Developers",
  "label": "Developers"
},
"Developers": "M/s. Guruprabhu Realtors",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Mrs. Darshani Vishal Purandare"
},
"isHardCopy": false,
"displayStatus": true,
"id": "812380",
"path": "cases/64e33fa6ae896715ef8010c7/
document_1692614464475_Adobe_Scan_21_Aug_2023.pdf",
"fileName": "document_1692614464475_Adobe_Scan_21_Aug_2023.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "17/07/2023",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC/TP/OC/VP-5848-B/28/2023-24"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692857694196_Ocupancy_Certificate.pdf",
  "path": "cases/64e33fa6ae896715ef8010c7/
document_1692857694196_Ocupancy_Certificate.pdf",
  "id": "482492",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Thu Aug 24 2023 11:44:54 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003261",
```



```
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "417539",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 21 2023 16:12:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Darshani Vishal Purandare",
    "phone": "9850187225",
    "ownershipShare": "",
    "email": "",
    "id": "252832"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "897383",
    "name": "Living Room",
    "length": "16.00",
    "length1": "16",
    "length2": "00",
    "width": "12.00",
    "width1": "12",
    "width2": "00",
    "totalArea": "192.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "192.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Bedroom",
```

```
"length": "14.00",
"length1": "14",
"length2": "00",
"width": "10.33",
"width1": "10",
"width2": "4",
"totalArea": "144.67",
"images": [],
"extraAreas": [],
"finalArea": "144.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "132.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "132.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "15.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.00"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "",
  "length1": "16",
  "length2": "0",
  "width": "",
  "width1": "10",
  "width2": "2",
  "totalArea": "162.67",
  "images": [],
  "finalArea": "162.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "",
  "length1": "6",
  "length2": "5",
  "width": "",
  "width1": "4",
  "width2": "6",
  "totalArea": "28.87",
  "images": [],
  "finalArea": "28.87",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
```

```
"length2": "00",
"width": "2.33",
"width1": "2",
"width2": "4",
"totalArea": "4.67",
"images": [],
"extraAreas": [],
"finalArea": "4.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "27.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Flowered Area",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "12",
"name": "Flowered Area",
"length": "",
"length1": "10",
"length2": "4",
"width": "",
"width1": "2",
"width2": "0",
"totalArea": "20.67",
"images": [],
"finalArea": "20.67",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Dry Balcony",
  "length": "",
  "length1": "10",
  "length2": "2",
  "width": "",
  "width1": "2",
  "width2": "0",
  "totalArea": "20.33",
  "images": [],
  "finalArea": "20.33",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Flowered Area",
  "length": "",
  "length1": "12",
  "length2": "0",
  "width": "",
```

```
"width1": "2",
"width2": "0",
"totalArea": "24.00",
"images": [],
"finalArea": "24.00",
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "700046",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "852.51",
  "squareMeterArea": "79.2",
  "docFinalBuiltUp": "937.761",
  "docFinalBuiltUpSquareMeter": "87.12",
  "docBUILTUPPercentage": "10",
  "docSaleablePercentage": "20",
  "docFinalSaleable": "1125.3132",
  "docFinalSaleableSquareMeter": "104.54400000000001"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cd2daae6a1c980f90da",
  "name":
"externalImg_1692765394789_WhatsApp_Image_20230822_at_85702_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externalImg_1692765394789_WhatsApp_Image_20230822_at_85702_PM.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90db",
    "name":
"externallmg_1692765394790_WhatsApp_Image_20230822_at_85703_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394790_WhatsApp_Image_20230822_at_85703_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90dc",
    "name":
"externallmg_1692765394793_WhatsApp_Image_20230822_at_85703_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394793_WhatsApp_Image_20230822_at_85703_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90dd",
    "name":
"externallmg_1692765394799_WhatsApp_Image_20230822_at_85704_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394799_WhatsApp_Image_20230822_at_85704_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90de",
    "name":
"externallmg_1692765394803_WhatsApp_Image_20230822_at_85704_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394803_WhatsApp_Image_20230822_at_85704_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90df",
    "name":
"externallmg_1692765394806_WhatsApp_Image_20230822_at_85704_PM_3.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394806_WhatsApp_Image_20230822_at_85704_PM_3.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90e0",
    "name":
"externallmg_1692765394807_WhatsApp_Image_20230822_at_85704_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394807_WhatsApp_Image_20230822_at_85704_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90e1",
    "name":
"externallmg_1692765394810_WhatsApp_Image_20230822_at_85705_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394810_WhatsApp_Image_20230822_at_85705_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90e2",
    "name":
"externallmg_1692765394814_WhatsApp_Image_20230822_at_85705_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394814_WhatsApp_Image_20230822_at_85705_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90e3",
    "name":
"externallmg_1692765394815_WhatsApp_Image_20230822_at_85705_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394815_WhatsApp_Image_20230822_at_85705_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cd2daae6a1c980f90e4",
```



```
    "name":
"externallmg_1692765394817_WhatsApp_Image_20230822_at_85706_PM_1.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394817_WhatsApp_Image_20230822_at_85706_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cd2daae6a1c980f90e5",
  "name":
"externallmg_1692765394820_WhatsApp_Image_20230822_at_85706_PM_2.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394820_WhatsApp_Image_20230822_at_85706_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cd2daae6a1c980f90e6",
  "name":
"externallmg_1692765394822_WhatsApp_Image_20230822_at_85706_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394822_WhatsApp_Image_20230822_at_85706_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cd2daae6a1c980f90e7",
  "name":
"externallmg_1692765394823_WhatsApp_Image_20230822_at_85707_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394823_WhatsApp_Image_20230822_at_85707_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cd2daae6a1c980f90e8",
  "name":
"externallmg_1692765394824_WhatsApp_Image_20230822_at_85719_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765394824_WhatsApp_Image_20230822_at_85719_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f918e",
  "name":
"externallmg_1692765416285_WhatsApp_Image_20230822_at_85627_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416285_WhatsApp_Image_20230822_at_85627_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f918f",
  "name":
"externallmg_1692765416287_WhatsApp_Image_20230822_at_85629_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416287_WhatsApp_Image_20230822_at_85629_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f9190",
  "name":
"externallmg_1692765416289_WhatsApp_Image_20230822_at_85630_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416289_WhatsApp_Image_20230822_at_85630_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f9191",
  "name":
"externallmg_1692765416294_WhatsApp_Image_20230822_at_85631_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416294_WhatsApp_Image_20230822_at_85631_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f9192",
  "name":
"externallmg_1692765416297_WhatsApp_Image_20230822_at_85634_PM.jpeg",
```

```
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416297_WhatsApp_Image_20230822_at_85634_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58ce8daae6a1c980f9193",
    "name":
"externallmg_1692765416301_WhatsApp_Image_20230822_at_85636_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416301_WhatsApp_Image_20230822_at_85636_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58ce8daae6a1c980f9194",
    "name":
"externallmg_1692765416306_WhatsApp_Image_20230822_at_85636_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416306_WhatsApp_Image_20230822_at_85636_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58ce8daae6a1c980f9195",
    "name":
"externallmg_1692765416310_WhatsApp_Image_20230822_at_85637_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416310_WhatsApp_Image_20230822_at_85637_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58ce8daae6a1c980f9196",
    "name":
"externallmg_1692765416314_WhatsApp_Image_20230822_at_85637_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416314_WhatsApp_Image_20230822_at_85637_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64e58ce8daae6a1c980f9197",
  "name":
"externallmg_1692765416319_WhatsApp_Image_20230822_at_85637_PM_3.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416319_WhatsApp_Image_20230822_at_85637_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f9198",
  "name":
"externallmg_1692765416324_WhatsApp_Image_20230822_at_85637_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416324_WhatsApp_Image_20230822_at_85637_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f9199",
  "name":
"externallmg_1692765416327_WhatsApp_Image_20230822_at_85638_PM_1.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416327_WhatsApp_Image_20230822_at_85638_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f919a",
  "name":
"externallmg_1692765416330_WhatsApp_Image_20230822_at_85638_PM_2.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416330_WhatsApp_Image_20230822_at_85638_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58ce8daae6a1c980f919b",
  "name":
"externallmg_1692765416333_WhatsApp_Image_20230822_at_85638_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416333_WhatsApp_Image_20230822_at_85638_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58ce8daae6a1c980f919c",
    "name":
"externallmg_1692765416336_WhatsApp_Image_20230822_at_85639_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765416336_WhatsApp_Image_20230822_at_85639_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f930b",
    "name":
"externallmg_1692765440990_WhatsApp_Image_20230822_at_85639_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765440990_WhatsApp_Image_20230822_at_85639_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f930c",
    "name":
"externallmg_1692765440993_WhatsApp_Image_20230822_at_85639_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765440993_WhatsApp_Image_20230822_at_85639_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f930d",
    "name":
"externallmg_1692765440997_WhatsApp_Image_20230822_at_85640_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765440997_WhatsApp_Image_20230822_at_85640_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f930e",
```

```
    "name":
"externallmg_1692765440999_WhatsApp_Image_20230822_at_85640_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765440999_WhatsApp_Image_20230822_at_85640_PM_2.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f930f",
    "name":
"externallmg_1692765441002_WhatsApp_Image_20230822_at_85640_PM_3.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441002_WhatsApp_Image_20230822_at_85640_PM_3.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f9310",
    "name":
"externallmg_1692765441004_WhatsApp_Image_20230822_at_85640_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441004_WhatsApp_Image_20230822_at_85640_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f9311",
    "name":
"externallmg_1692765441005_WhatsApp_Image_20230822_at_85641_PM_1.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441005_WhatsApp_Image_20230822_at_85641_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f9312",
    "name":
"externallmg_1692765441007_WhatsApp_Image_20230822_at_85641_PM_2.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441007_WhatsApp_Image_20230822_at_85641_PM_2.jpeg",
    "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d01daae6a1c980f9313",
  "name":
"externallmg_1692765441009_WhatsApp_Image_20230822_at_85641_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441009_WhatsApp_Image_20230822_at_85641_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d01daae6a1c980f9314",
  "name":
"externallmg_1692765441013_WhatsApp_Image_20230822_at_85642_PM_1.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441013_WhatsApp_Image_20230822_at_85642_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d01daae6a1c980f9315",
  "name":
"externallmg_1692765441016_WhatsApp_Image_20230822_at_85642_PM_2.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441016_WhatsApp_Image_20230822_at_85642_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d01daae6a1c980f9316",
  "name":
"externallmg_1692765441016_WhatsApp_Image_20230822_at_85642_PM.jpeg",
  "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441016_WhatsApp_Image_20230822_at_85642_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d01daae6a1c980f9317",
  "name":
"externallmg_1692765441017_WhatsApp_Image_20230822_at_85643_PM_1.jpeg",
```

```
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441017_WhatsApp_Image_20230822_at_85643_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f9318",
    "name":
"externallmg_1692765441019_WhatsApp_Image_20230822_at_85643_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441019_WhatsApp_Image_20230822_at_85643_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f9319",
    "name":
"externallmg_1692765441025_WhatsApp_Image_20230822_at_85700_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441025_WhatsApp_Image_20230822_at_85700_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d01daae6a1c980f931a",
    "name":
"externallmg_1692765441026_WhatsApp_Image_20230822_at_85701_PM.jpeg",
    "path": "cases/64e33fa6ae896715ef8010c7/
externallmg_1692765441026_WhatsApp_Image_20230822_at_85701_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-21T10:42:46.036Z",
"updatedAt": "2023-08-24T06:17:29.743Z",
"__v": 0,
"invoiceId": "64e33fa6ae896715ef8010e0",
"updatedBy": "60f91b6f344e052188ffd1fc",
"fullAddress": "Residential Flat No. 702, 7th Floor, \"Donde Heights\", Village - Dhovali,
Vasai Road (West), Taluka - Vasai, District - Palghar, PIN - 401 201, State -
Maharashtra, India",
"addressForMap": "",
```


"caseReferredBy": "64acf498d9a15943959de54c",
 "contactPersonName": "Mr. Darshani V. Purandare",
 "email": "",
 "isExternal": "false",
 "isUrgent": "false",
 "ownershipShare": "",
 "purchaseValueAsPerDocument": "",
 "relationWithOwner": "self",
 "siteVisitContactNo": "9850187225",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet +
 3 Flowered Area + Dry Balcony",
 "carpetTotal": "796.3099999999998",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "875.94",
 "finalCarpetArea": "796.31",
 "finalSalableArea": "875.94",
 "salablePercentage": "0",
 "toBeAdded": "",
 "extendOfSiteRemark": "111",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 707.00\nFlowerbed Area in Sq.
 Ft. = 69.00\nDry Balcony Area in Sq. Ft. = 20.00\nCupboard Area in Sq. Ft. =
 5.00\nTotal Area in Sq. Ft. = 801.00\n(Area as per Site Measurement)",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement For Sale",
 "finalBuiltUpPercentage": "10",
 "finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "20",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 852.51"

Name	Length	Width	Total
Composition :			
Living Room	16'00"	12'00"	192.00
Bedroom	14'00"	10'4"	144.67
Bedroom	11'00"	12'00"	132.00
Passage	3'00"	5'00"	15.00
Kitchen	16'0"	10'2"	162.67
Toilet	6'5"	4'6"	28.87

Passage	2'00"	2'4"	4.67
Toilet	6'7"	4'2"	27.43
Flowered Area	12'00"	2'00"	24.00
Flowered Area	10'4"	2'0"	20.67
Dry Balcony	10'2"	2'0"	20.33
Flowered Area	12'0"	2'0"	24.00
Other Composition :			