

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a6b55cc325d356190e0942"
    },
    "type": "CREDITOFFICER",
    "_id": "64a6b55cc325d356190e0944",
    "firstName": "Umesh",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "5900"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a6b55cc325d356190e0942",
  "name": "Satpur Branch",
  "branchCode": "",
  "mobileNo": "7020235315",
  "alternateMobileNo": "",
  "email": "umesh.pagar@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1 st Floor, BSNL CTTC Building, Plot No. 45-47, D-Road, MIDC, Satpur,
Nashik - 422 007"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": "",
"maker": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": "",
"valuers": []
},
"clientType": {
```

```
"value": "BANK",
"label": "BANK"
},
"location": {
  "latitude": "20.008343160967136",
  "longitude": "73.74398734804774"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
```

```
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "30/31/1",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Revati Aanadvan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pipeline Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Anandvalli",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Revati Houses",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```

```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Revati Group",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```



```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422013",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e609bc1452884516b4f60f",
"ownerName": "Revati Aanadvan",
"ownerPhoneNo": "7776005228",
"fullAddress": " APF No. Basement Floor, Revati Aanadvan, Revati Group, Revati
Houses, Plot No. 30/31/1, Pipeline Road, Anandvalli, Taluka - Nashik, District - Nashik,
Nashik, 422013",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1692797226464_download.pdf",
    "path": "cases/64e609bc1452884516b4f60f/
document_1692797226464_download.pdf",
    "id": "322982",
    "uploadedBy": "63f9f4adce84bf289ba9956e",
    "createdAt": "Wed Aug 23 2023 18:59:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
```

```
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51600050817"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692797288738_89267.pdf",
  "path": "cases/64e609bc1452884516b4f60f/document_1692797288738_89267.pdf",
  "id": "997916",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Wed Aug 23 2023 18:59:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a7",
    "label": "Title Search Report"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692867444927_TSR.pdf",
  "path": "cases/64e609bc1452884516b4f60f/document_1692867444927_TSR.pdf",
  "id": "175345",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Aug 24 2023 14:27:27 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003341",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "182728",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 23 2023 18:59:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Revati Aanadvan",
    "phone": "7776005228",
```



```
    "ownershipShare": "",
    "email": "",
    "id": "320565"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787d9",
    "name":
"externalImg_1692938112729_WhatsApp_Image_20230823_at_22850_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externalImg_1692938112729_WhatsApp_Image_20230823_at_22850_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787da",
    "name":
"externalImg_1692938112781_WhatsApp_Image_20230823_at_22850_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externalImg_1692938112781_WhatsApp_Image_20230823_at_22850_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787db",
    "name":
"externalImg_1692938112848_WhatsApp_Image_20230823_at_22851_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externalImg_1692938112848_WhatsApp_Image_20230823_at_22851_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64e82f821452884516b787dc",
    "name":
"externallmg_1692938112931_WhatsApp_Image_20230823_at_22851_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938112931_WhatsApp_Image_20230823_at_22851_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787dd",
    "name":
"externallmg_1692938113019_WhatsApp_Image_20230823_at_22852_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113019_WhatsApp_Image_20230823_at_22852_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787de",
    "name":
"externallmg_1692938113102_WhatsApp_Image_20230823_at_22853_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113102_WhatsApp_Image_20230823_at_22853_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787df",
    "name":
"externallmg_1692938113164_WhatsApp_Image_20230823_at_22853_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113164_WhatsApp_Image_20230823_at_22853_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e0",
    "name":
"externallmg_1692938113229_WhatsApp_Image_20230823_at_22854_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113229_WhatsApp_Image_20230823_at_22854_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e1",
    "name":
"externallmg_1692938113321_WhatsApp_Image_20230823_at_22854_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113321_WhatsApp_Image_20230823_at_22854_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e2",
    "name":
"externallmg_1692938113404_WhatsApp_Image_20230823_at_22855_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113404_WhatsApp_Image_20230823_at_22855_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e3",
    "name":
"externallmg_1692938113507_WhatsApp_Image_20230823_at_22855_PM_2.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113507_WhatsApp_Image_20230823_at_22855_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e4",
    "name":
"externallmg_1692938113581_WhatsApp_Image_20230823_at_22855_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113581_WhatsApp_Image_20230823_at_22855_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e5",
```

```
    "name":
"externallmg_1692938113667_WhatsApp_Image_20230823_at_22856_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113667_WhatsApp_Image_20230823_at_22856_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e6",
    "name":
"externallmg_1692938113792_WhatsApp_Image_20230823_at_22856_PM_2.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113792_WhatsApp_Image_20230823_at_22856_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e7",
    "name":
"externallmg_1692938113893_WhatsApp_Image_20230823_at_22856_PM.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113893_WhatsApp_Image_20230823_at_22856_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f821452884516b787e8",
    "name":
"externallmg_1692938113957_WhatsApp_Image_20230823_at_22857_PM_1.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938113957_WhatsApp_Image_20230823_at_22857_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e82f8c1452884516b7884d",
    "name":
"externallmg_1692938123447_WhatsApp_Image_20230823_at_22857_PM_2.jpeg",
    "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938123447_WhatsApp_Image_20230823_at_22857_PM_2.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e82f8c1452884516b7884e",
  "name":
"externallmg_1692938123554_WhatsApp_Image_20230823_at_22857_PM_3.jpeg",
  "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938123554_WhatsApp_Image_20230823_at_22857_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e82f8c1452884516b7884f",
  "name":
"externallmg_1692938123735_WhatsApp_Image_20230823_at_22857_PM.jpeg",
  "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938123735_WhatsApp_Image_20230823_at_22857_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e82f8c1452884516b78850",
  "name":
"externallmg_1692938123849_WhatsApp_Image_20230823_at_22858_PM_1.jpeg",
  "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938123849_WhatsApp_Image_20230823_at_22858_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e82f8c1452884516b78851",
  "name":
"externallmg_1692938123902_WhatsApp_Image_20230823_at_22858_PM.jpeg",
  "path": "cases/64e609bc1452884516b4f60f/
externallmg_1692938123902_WhatsApp_Image_20230823_at_22858_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-23T13:29:32.681Z",
"updatedAt": "2023-08-25T04:35:24.032Z",
"__v": 0,
```

"invoiceId": "64e609bc1452884516b4f619",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Revati Aanadvan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7776005228"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
