

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f9f",
    "firstName": "Neha",
    "email": "0_default_cord.21117@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9892147204"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "720000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 360,
    "quotedAmount": "2950"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
```

```
"role": "PICKUPPERSON",
"firstName": "Ravindra",
"email": "ravindrakasare186@gmail.com",
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER + RATE VERFIER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
```

```

    "designation": "",
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {

```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.2105215197558",
  "longitude": "73.09104017301088"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09104017301088,
    19.2105215197558
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ayre Gaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sarvodaya Garden Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pandurangwadi, Near Jain Mandir",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Manpada Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "92",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1/3(pt)",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "701",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 201",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
```

```

    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. 2",
    "west": "Internal Road",
    "south": "Under Construction Building",
    "east": "Internal Road / Mahalarchaaya Building"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "The loading between measured Carpet area to Built up area mentioned in the Agreement is 28%. For the purpose of valuation we have considered the loading factor. ",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "8800",

```

```
"depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "67600",
  "landRate": "27500",
  "igrImage": "cases/64e9b8e41452884516bb5326/igr_1693303049071_Image.png",
  "squareMeterGuideLineRate": "70980.00",
  "squareFeetGuideLineRate": "6594.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "5948.00",
  "squareFeetGuideLineRate": "5948.00",
  "squareMeterGuideLineRate": "64023.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": " 16,000.00 ",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Customer No. 020012801824",
  "meterCardHolderName": "Mr. Chandrakant Chatur Katkade",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
    "fullDate": "1/1/2007"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
```

```
"label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "16",
"totalLifeBuilding": "60",
"estimatedAge": "44",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "850.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64e9b8e41452884516bb5326/
routeMap_1693228845311_Image.png",
  "routeLat": "19.210250",
  "routeLng": "73.091250",
  "stationName": "Dombivli",
  "routeDistance": "1.4 KM"
},
"finalLatLng": {
  "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "ytep58",
    "name": "ytep58",
    "image": "cases/64e9b8e41452884516bb5326/
routeMap_1693228695401_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "7480000.00",
"finalValue": "7480000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5055800.00",
```

```
"selectedBuildUpValue": "850.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64ec6beeeb1f822256d8a142",
      "name":
"externallmg_1693215726622_WhatsApp_Image_20230828_at_25727_PM_2.jpeg",
      "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215726622_WhatsApp_Image_20230828_at_25727_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64ec6c07eb1f822256d8a1a0",
      "name":
"externallmg_1693215751036_WhatsApp_Image_20230828_at_25728_PM_12.jpeg",
      "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751036_WhatsApp_Image_20230828_at_25728_PM_12.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64ec6c07eb1f822256d8a191",
      "name":
"externallmg_1693215751001_WhatsApp_Image_20230828_at_25727_PM_3.jpeg",
      "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751001_WhatsApp_Image_20230828_at_25727_PM_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64ec6beeeb1f822256d8a141",
      "name":
"externallmg_1693215726574_WhatsApp_Image_20230828_at_25727_PM_1.jpeg",
      "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215726574_WhatsApp_Image_20230828_at_25727_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  {

```

```
    "status": false,
    "_id": "64ec6c07eb1f822256d8a192",
    "name":
"externallmg_1693215751005_WhatsApp_Image_20230828_at_25727_PM_4.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751005_WhatsApp_Image_20230828_at_25727_PM_4.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64ec6c07eb1f822256d8a1a2",
    "name":
"externallmg_1693215751041_WhatsApp_Image_20230828_at_25728_PM.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751041_WhatsApp_Image_20230828_at_25728_PM.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64ec6c07eb1f822256d8a196",
    "name": "Living Room",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751016_WhatsApp_Image_20230828_at_25728_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ec6c07eb1f822256d8a198",
    "name": "Living Room",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751020_WhatsApp_Image_20230828_at_25728_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64ec6c07eb1f822256d8a19d",
    "name": "Living Room",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751031_WhatsApp_Image_20230828_at_25728_PM_9.jpeg",
    "orientation": "landscape"
  },
]
```

```
{
  "status": false,
  "_id": "64ec6c07eb1f822256d8a19e",
  "name": "Living Room",
  "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751033_WhatsApp_Image_20230828_at_25728_PM_10.jpeg",
  "orientation": "landscape"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7912",
    "max": "14364"
  },
  "builtUpRateRange": {
    "min": "6594",
    "max": "11971"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "850.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"_id": "64e9b8e41452884516bb5326",
"ownerName": "Mr. Devendra Natwarlal Mehta & Mrs. Kavita Devendra Mehta",
"ownerPhoneNo": "9324744932",
"appAddress": "flat no. 701 . uth floor Bldg no 3 Sarvodaya Gardenchs Ltd Ayre
Dombivli ",
"remark": "two number 9082954504",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "23/08/2023",
      "amount": "72,00,000.00",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Surekha Chandrakant Katkade & Mr. Chandrakant Chatur
Katkade",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Devendra Natwarlal Mehta & Mrs. Kavita Devendra Mehta"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "188904",
    "path": "cases/64e9b8e41452884516bb5326/
document_1693038697409_20230826103213.pdf",
    "fileName": "document_1693038697409_20230826103213.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "25/11/2005",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Municipal_Corporation",
        "label": "Kalyan Dombivli Municipal Corporation"
      },
      "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "KDMC / NRV / B.P. / D.V. / 446-143"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693293099933_Commencement_Certificate.pdf",
"path": "cases/64e9b8e41452884516bb5326/
document_1693293099933_Commencement_Certificate.pdf",
"id": "900317",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Aug 29 2023 12:41:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "30/11/2007",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "KDMC / NRV / CC / DV / 523"
},
"isHardCopy": false,
"displayStatus": true,
"id": "108595",
"path": "cases/64e9b8e41452884516bb5326/
document_1693293208782_Building_Completion_Certificate.pdf",
"fileName": "document_1693293208782_Building_Completion_Certificate.pdf"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "24/07/2023",
    "amount": "145",
```

```
"to": {
  "value": "Seller",
  "label": "Seller"
},
"Seller": "Mr. Chandrakant Chatur Katkade",
"number": {
  "value": "Consumer_No",
  "label": "Consumer No"
},
"Consumer_No": "020012801824"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693293468241_Electricity_Bill.pdf",
"path": "cases/64e9b8e41452884516bb5326/
document_1693293468241_Electricity_Bill.pdf",
"id": "546228",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Aug 29 2023 12:47:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "30/06/2019",
    "to": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Chandrakant C. Katkade & Mrs. Surekha C. Katkade",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "81"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1693293784247_Share_Certificate.pdf",
  "path": "cases/64e9b8e41452884516bb5326/
document_1693293784247_Share_Certificate.pdf",
  "id": "623228",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Tue Aug 29 2023 12:53:04 GMT+0530 (India Standard Time)"
}
```

```
}
],
"caseNumber": "003406",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "356780",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 26 2023 14:03:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Devendra Natwarlal Mehta & Mrs. Kavita Devendra Mehta",
    "phone": "9324744932",
    "ownershipShare": "",
    "email": "",
    "id": "990828"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "8",
    "name": "Bedroom",
    "length": "12.75",
    "length1": "12",
    "length2": "9",
    "width": "10.83",
    "width1": "10",
    "width2": "10",
    "totalArea": "138.12",
    "images": [],
    "finalArea": "138.12",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "1",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "118.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bathroom",
  "length": "",
  "length1": "5",
  "length2": "6",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "22.00",
```

```
"images": [],
"finalArea": "22.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "12.42",
  "width1": "12",
  "width2": "5",
  "totalArea": "40.35",
  "images": [],
  "finalArea": "40.35",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "",
  "length1": "8",
  "length2": "5",
  "width": "",
  "width1": "7",
  "width2": "6",
  "totalArea": "63.12",
  "images": [],
  "finalArea": "63.12",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
```

```
"name": "Living Room",
"length": "",
"length1": "17",
"length2": "0",
"width": "",
"width1": "10",
"width2": "0",
"totalArea": "170.00",
"images": [],
"finalArea": "170.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC & Bath",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "27.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.79"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
```



```
"length1": "7",
"length2": "6",
"length": "7.50",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "15.00",
"percentageBeforeTotal": "21.02",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64edc8deeb1f822256dacfb2",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "4.25",
    "length1": "4",
    "length2": "3",
    "width": "1.42",
    "width1": "1",
    "width2": "5",
    "totalArea": "6.02"
  }
],
"percentage": "100",
"finalArea": "21.02"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Niche",
    "label": "Niche"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "5",
  "length2": "6",
```

```
"length": "5.50",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "11.00",
"percentageBeforeTotal": "11.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "11"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Niche",
    "label": "Niche"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length1": "10",
  "length2": "00",
  "length": "10.00",
  "width1": "2",
  "width2": "0",
  "width": "2.00",
  "totalArea": "20.00",
  "percentageBeforeTotal": "20.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "20"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Niche",
    "label": "Niche"
  }
}
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "3",
    "length1": "9",
    "length2": "6",
    "length": "9.50",
    "width1": "2",
    "width2": "00",
    "width": "2.00",
    "totalArea": "19.00",
    "percentageBeforeTotal": "19.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "19"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "411653",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "850",
    "squareMeterArea": "78.97",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "20",
    "docFinalSaleable": "1020",
    "docFinalSaleableSquareMeter": "94.764"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": false,
  "_id": "64edc177eb1f822256dab4e9",
  "property": "Flat",
  "area": "550",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "4500000",
  "expectedRate": "8181.82",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64e9b8e41452884516bb5326/
indicator_1693302338658_Image.png",
  "squareMeter": "51.10",
  "id": "799742"
},
{
  "printlnReport": true,
  "_id": "64edc177eb1f822256dab4ea",
  "property": "Flat",
  "area": "637",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "9150000",
  "expectedRate": "14364.21",
  "builtUpExpectedRate": "11970.17",
  "image": "cases/64e9b8e41452884516bb5326/
indicator_1693302419945_Image.png",
  "squareMeter": "59.18",
  "id": "104553"
},
{
  "printlnReport": true,
  "_id": "64edc177eb1f822256dab4ec",
  "property": "Flat",
  "area": "680",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "1",
  "source": "magic_bricks",
```

```
    "expectedPrice": "7600000",
    "expectedRate": "11176.47",
    "builtUpExpectedRate": "9313.73",
    "image": "cases/64e9b8e41452884516bb5326/
indicator_1693302866895_Image.png",
    "squareMeter": "63.17",
    "id": "466457"
  },
  {
    "printlnReport": true,
    "_id": "64ede461eb1f822256db39c8",
    "id": "4",
    "property": "Flat",
    "area": "910",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "4",
    "source": "Index_no.2",
    "expectedPrice": "6000000",
    "expectedRate": "6593.41",
    "builtUpExpectedRate": "6000000",
    "image": "cases/64e9b8e41452884516bb5326/
indicator_1693312097251_Image.png"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6beeeb1f822256d8a140",
    "name":
"externallmg_1693215726531_WhatsApp_Image_20230828_at_25728_PM_14.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215726531_WhatsApp_Image_20230828_at_25728_PM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6beeeb1f822256d8a141",
    "name":
"externallmg_1693215726574_WhatsApp_Image_20230828_at_25727_PM_1.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215726574_WhatsApp_Image_20230828_at_25727_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6beeeb1f822256d8a142",
    "name":
"externallmg_1693215726622_WhatsApp_Image_20230828_at_25727_PM_2.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215726622_WhatsApp_Image_20230828_at_25727_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a191",
    "name":
"externallmg_1693215751001_WhatsApp_Image_20230828_at_25727_PM_3.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751001_WhatsApp_Image_20230828_at_25727_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a192",
    "name":
"externallmg_1693215751005_WhatsApp_Image_20230828_at_25727_PM_4.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751005_WhatsApp_Image_20230828_at_25727_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a193",
    "name":
"externallmg_1693215751008_WhatsApp_Image_20230828_at_25727_PM_5.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751008_WhatsApp_Image_20230828_at_25727_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a194",
```

```
    "name":
"externallmg_1693215751011_WhatsApp_Image_20230828_at_25727_PM.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751011_WhatsApp_Image_20230828_at_25727_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a195",
    "name":
"externallmg_1693215751014_WhatsApp_Image_20230828_at_25728_PM_1.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751014_WhatsApp_Image_20230828_at_25728_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a196",
    "name":
"externallmg_1693215751016_WhatsApp_Image_20230828_at_25728_PM_2.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751016_WhatsApp_Image_20230828_at_25728_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a197",
    "name":
"externallmg_1693215751018_WhatsApp_Image_20230828_at_25728_PM_3.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751018_WhatsApp_Image_20230828_at_25728_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a198",
    "name":
"externallmg_1693215751020_WhatsApp_Image_20230828_at_25728_PM_4.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751020_WhatsApp_Image_20230828_at_25728_PM_4.jpeg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec6c07eb1f822256d8a199",
  "name":
"externallmg_1693215751023_WhatsApp_Image_20230828_at_25728_PM_5.jpeg",
  "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751023_WhatsApp_Image_20230828_at_25728_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec6c07eb1f822256d8a19a",
  "name":
"externallmg_1693215751025_WhatsApp_Image_20230828_at_25728_PM_6.jpeg",
  "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751025_WhatsApp_Image_20230828_at_25728_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec6c07eb1f822256d8a19b",
  "name":
"externallmg_1693215751027_WhatsApp_Image_20230828_at_25728_PM_7.jpeg",
  "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751027_WhatsApp_Image_20230828_at_25728_PM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec6c07eb1f822256d8a19c",
  "name":
"externallmg_1693215751029_WhatsApp_Image_20230828_at_25728_PM_8.jpeg",
  "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751029_WhatsApp_Image_20230828_at_25728_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec6c07eb1f822256d8a19d",
  "name":
"externallmg_1693215751031_WhatsApp_Image_20230828_at_25728_PM_9.jpeg",
```



```
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751031_WhatsApp_Image_20230828_at_25728_PM_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a19e",
    "name":
"externallmg_1693215751033_WhatsApp_Image_20230828_at_25728_PM_10.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751033_WhatsApp_Image_20230828_at_25728_PM_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a19f",
    "name":
"externallmg_1693215751035_WhatsApp_Image_20230828_at_25728_PM_11.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751035_WhatsApp_Image_20230828_at_25728_PM_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a1a0",
    "name":
"externallmg_1693215751036_WhatsApp_Image_20230828_at_25728_PM_12.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751036_WhatsApp_Image_20230828_at_25728_PM_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec6c07eb1f822256d8a1a1",
    "name":
"externallmg_1693215751039_WhatsApp_Image_20230828_at_25728_PM_13.jpeg",
    "path": "cases/64e9b8e41452884516bb5326/
externallmg_1693215751039_WhatsApp_Image_20230828_at_25728_PM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64ec6c07eb1f822256d8a1a2",
  "name":
"externalImg_1693215751041_WhatsApp_Image_20230828_at_25728_PM.jpeg",
  "path": "cases/64e9b8e41452884516bb5326/
externalImg_1693215751041_WhatsApp_Image_20230828_at_25728_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-26T08:33:40.606Z",
"updatedAt": "2023-08-29T12:38:45.840Z",
"__v": 0,
"invoiceId": "64e9b8e41452884516bb532f",
"fullAddress": "Residential Flat No. 701, 7th Floor, Building No 3, Sarvodaya Garden
Co-Op. Hsg. Soc. Ltd., Pandurangwadi, Near Jain Mandir, Manpada Road, Village -
Ayre Gaon, Dombivli (East), Taluka - Kalyan, District - Thane, PIN - 421 201, State -
Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Chandrakant C. Katkade (Seller)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9870626582",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage + WC & Bath",
"carpetTotal": "592.13",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "71.02",
"builtupPercentage": "20",
"finalBuiltupArea": "795.78",
"finalCarpetArea": "663.15",
"finalSalableArea": "875.36",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 592.00\nCupboard Area in Sq.
Ft. = 21.00\nNitch Area in Sq. Ft. = 50.00\nTotal Area in Sq. Ft. = 663.00\n(Area as per
actual site measurement)\n",
"finalAreaType": "Built Up Area",
```

"finalAsPerArea": "Agreement For Sale",  
 "finalBuiltUpPercentage": "20",  
 "finalCarpetConvertToBuiltUpPer": "20",  
 "finalSaleablePercentage": "20",  
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 850.00",  
 "buildingServicesRate": "2500",  
 "flatRate": "9400",  
 "landOtherRate": "6900",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "71.02",  
 "otherCompositionSaleableTotal": "0.00",  
 "reportGeneratedDate": "Tue Aug 29 2023 17:24:51 GMT+0530 (India Standard Time)",  
 "siteVisitDate": "2023-08-28",  
 "remarks": []

Name	Length	Width	Total
Composition :			
Bedroom	12'9"	10'10"	138.12
Bedroom	12'6"	9'6"	118.75
WC	4'0"	3'0"	12.00
Bathroom	5'6"	4'0"	22.00
Passage	3'3"	12'5"	40.35
Kitchen	8'5"	7'6"	63.12
Living Room	17'0"	10'0"	170.00
WC & Bath	7'3"	3'10"	27.79
Other Composition :			
Cupboard	7'6"	2'00"	15.00
Niche	5'6"	2'00"	11.00
Niche	10'00"	2'0"	20.00
Niche	9'6"	2'00"	19.00