

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4585000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 2292.5,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.0149161350241",
  "longitude": "73.0177409437605"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0177409437605,
    19.0149161350241
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-26T09:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nerul",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C-10",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "17",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Navgharkul Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "48A",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Seawoods (West)",
```



```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Manpasand Housing Scheme",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "11",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 706",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "KotaStoneTileFlooring",
    "label": "Kota Stone Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  }
}
```

```

    },
    "fittings": {
      "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
      "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
    },
    "finishing": {
      "value": "Cement_Plastering_+_POP_Finish",
      "label": "Cement Plastering + POP Finish"
    }
  },
  "general": {
    "ownership": {
      "value": "Sole_Ownership",
      "label": "Sole Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "whetherCoveredUnderAnyState": {
      "value": "No",
      "label": "No"
    },
    "asPerActualAgreement": {
      "north": "Building No. B-4",
      "west": "Sant Dnyaneshwar Mauli Garden",
      "south": "Ayyappa Temple & Banubai Ganpat Tandel Marg",
      "east": "Ramesh Shankarao Hebbar Marg"
    },
    "asPerDocumentAgreement": {
      "north": "Details is not available\n",
      "west": "Details is not available",
      "south": "Details is not available",
      "east": "Details is not available"
    },
    "extraDetailOfProperty": ""
  },
}

```

```
"compositeRate": {
  "remark": "The loading between measured Carpet area to Built up area mentioned in
the Agreement is 28%. We have considered loading factor for purpose of valuation. ",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "14500",
  "depreciatedBuildingRate": "1600"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "112400",
  "landRate": "42800",
  "igrImage": "cases/64e9bae31452884516bb56c0/igr_1693292146881_Image.jpeg",
  "squareMeterGuideLineRate": "101160.00",
  "squareFeetGuideLineRate": "9398.00"
},
"igrFinalRate": {
  "rate": "8097.00",
  "squareMeterGuideLineRate": "87154.00",
  "squareFeetGuideLineRate": "8097.00",
  "depreciationPercentage": "76"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "14,000",
  "assessmentNo": " Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "Mr. Amar Patil \nOccupied Since - Last 7 months",
  "maintenanceOfFlat": "Normal"
```

```
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1999",
    "fullDate": "1/1/1999"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
```

```
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
},
"walls": {
"value": "1",
"label": "Yes"
},
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
},
"maintenancelssues": {
"value": "0",
"label": "No"
}
```

```
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_Possession_Receipt",
  "label": "As per Possession Receipt"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "24",
"totalLifeBuilding": "60",
"estimatedAge": "36",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "375.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64e9bae31452884516bb56c0/
routeMap_1693223403413_Image.png",
```



```
"routeLat": "19.014399",
"routeLng": "73.017429",
"stationName": "Seawood",
"routeDistance": "1.00 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "hyvy19",
    "name": "hyvy19",
    "image": "cases/64e9bae31452884516bb56c0/
routeMap_1693223261977_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5437500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "5437500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Aug 29 2023 13:22:35 GMT+0530 (India Standard Time)",
  "number": "2302301",
  "dayCount": "7",
  "monthCount": "447",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "3036375.00",
  "selectedBuildUpValue": "375.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64ec1858eb1f822256d7271b",
      "name": "externallmg_1693194327817_1693063261349.jpg",
      "path": "cases/64e9bae31452884516bb56c0/externallmg_1693194327817_1693063261349.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64ec1858eb1f822256d72727",
      "name": "Living Room",
      "path": "cases/64e9bae31452884516bb56c0/externallmg_1693194328288_1693063261480.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64ec1858eb1f822256d72723",
      "name": "Living Room",
      "path": "cases/64e9bae31452884516bb56c0/externallmg_1693194328152_1693063261593.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    "status": false,
    "_id": "64ec1858eb1f822256d7271f",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328050_1693063261502.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ec1858eb1f822256d72720",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328065_1693063261523.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ec1858eb1f822256d7271d",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327973_1693063261393.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ec1858eb1f822256d72719",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327696_1693063261305.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ec184beb1f822256d726b5",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194315638_1693063261260.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64ec1858eb1f822256d7271b",
    "name": "Living Room",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327817_1693063261349.jpg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "64ec1858eb1f822256d7271c",
      "name": "Living Room",
      "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327891_1693063261371.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16571",
    "max": "18182"
  },
  "builtUpRateRange": {
    "min": "13810",
    "max": "15600"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "375.00",
empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
isAdvanceInvoice": false,
status": true,
```

```
"caseStatus": "ATTACHSIGN",
"_id": "64e9bae31452884516bb56c0",
"ownerName": "Mr. Ashish Yashvant Thoravat",
"ownerPhoneNo": "9970747481",
"appAddress": "flat no c 10/ 2.11 2 nd floor NayaGharkul co. op so shg sector no 48A
Nerul ",
"remark": "ssl surendra k ",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "18/04/2018",
      "from": {
        "value": "The_Sellers",
        "label": "The Sellers"
      },
      "The_Sellers": "Mr. Anil Shankar Ghadge",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Dheeraj Jamidar Singh ",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "4740/2018"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1693217485204_Index_II.pdf",
    "path": "cases/64e9bae31452884516bb56c0/
document_1693217485204_Index_II.pdf",
    "id": "623819",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Mon Aug 28 2023 15:41:25 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
```

```
"documentDate": "26/08/2023",
"from": {
  "value": "Seller",
  "label": "Seller"
},
"Seller": "Mr. Dheeraj Jamidar Singh ",
"to": {
  "value": "Purchaser",
  "label": "Purchaser"
},
"Purchaser": "Mr. Ashish Yashvant Thoravat",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "14035 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693217605032_Ashish_Thoravat.pdf",
"path": "cases/64e9bae31452884516bb56c0/
document_1693217605032_Ashish_Thoravat.pdf",
"id": "926675",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Aug 28 2023 15:43:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "inputs": {
    "documentDate": "21/12/1999",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "remark": "in the name of Mr. Anil Shankar Ghadge"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693217695871_384473.pdf",
  "path": "cases/64e9bae31452884516bb56c0/
document_1693217695871_384473.pdf",
  "id": "687371",
  "uploadedBy": "62fe044a48a26047e6552796",
```

```
"createdAt": "Mon Aug 28 2023 15:44:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1244aa6d152c1801b2df",
    "label": "Transfer of Letter"
  },
  "inputs": {
    "documentDate": "23/03/2018",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "from": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Dheeraj Jamidar Singh ",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Ashish Yashvant Thoravat"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693217901254_317715.pdf",
  "path": "cases/64e9bae31452884516bb56c0/
document_1693217901254_317715.pdf",
  "id": "662619",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Aug 28 2023 15:48:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "20/01/1998",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "(Not mentioned)"
},
"isHardCopy": false,
"displayStatus": false,
"id": "849327",
"path": "cases/64e9bae31452884516bb56c0/
document_1693218414628_Adobe_Scan_Aug_28_2023.pdf",
"fileName": "document_1693218414628_Adobe_Scan_Aug_28_2023.pdf"
}
],
"caseNumber": "003407",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "796152",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 26 2023 14:12:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ashish Yashvant Thoravat",
    "phone": "9970747481",
    "ownershipShare": "",
    "email": "",
    "id": "460160"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "863113",
    "name": "Living Room",
    "length": "9.17",
    "length1": "9",
    "length2": "2",
    "width": "12.42",
    "width1": "12",
```

```
"width2": "5",
"totalArea": "113.82",
"images": [],
"extraAreas": [],
"finalArea": "113.82"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "WC",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "11.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "13.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "3",
  "name": "Passage",
  "length": "2.33",
  "length1": "2",
  "length2": "4",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "7.97",
  "images": [],
  "extraAreas": [],
  "finalArea": "7.97"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "46.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "46.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "18.89",
```

```
"images": [],
"extraAreas": [],
"finalArea": "18.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "79.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "79.51"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "695917",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "375",
    "squareMeterArea": "34.84",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
]
```



```
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64ed9681eb1f822256da29a4",
    "property": "Flat",
    "area": "220",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "4000000",
    "expectedRate": "18181.82",
    "builtUpExpectedRate": "15151.52",
    "image": "cases/64e9bae31452884516bb56c0/
indicator_1693291607875_Image.png",
    "squareMeter": "20.44",
    "id": "517101"
  },
  {
    "printlnReport": true,
    "_id": "64ed9681eb1f822256da29a5",
    "property": "Flat",
    "area": "250",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "3900000",
    "expectedRate": "15600.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64e9bae31452884516bb56c0/
indicator_1693291675779_Image.png",
    "squareMeter": "23.23",
    "id": "725487"
  },
  {
    "printlnReport": true,
    "_id": "64ed9681eb1f822256da29a6",
    "property": "Flat",
    "area": "350",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "2",
"source": "Navimumbaihouses.com",
"expectedPrice": "5800000",
"expectedRate": "16571.43",
"builtUpExpectedRate": "13809.52",
"image": "cases/64e9bae31452884516bb56c0/
indicator_1693291755164_Image.png",
"squareMeter": "32.52",
"id": "153296"
},
{
  "printlnReport": true,
  "_id": "64ed9681eb1f822256da29a7",
  "property": "Flat",
  "area": "390",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "2",
  "source": "Navimumbaihouses.com",
  "expectedPrice": "5900000",
  "expectedRate": "15128.21",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64e9bae31452884516bb56c0/
indicator_1693291843428_Image.png",
  "squareMeter": "36.23",
  "id": "292131"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec184beb1f822256d726b4",
    "name": "externalImg_1693194315618_1693063261240.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externalImg_1693194315618_1693063261240.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec184beb1f822256d726b5",
```

```
    "name": "externallmg_1693194315638_1693063261260.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194315638_1693063261260.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d72718",
    "name": "externallmg_1693194327605_1693063261281.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327605_1693063261281.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d72719",
    "name": "externallmg_1693194327696_1693063261305.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327696_1693063261305.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271a",
    "name": "externallmg_1693194327770_1693063261327.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327770_1693063261327.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271b",
    "name": "externallmg_1693194327817_1693063261349.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327817_1693063261349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271c",
    "name": "externallmg_1693194327891_1693063261371.jpg",
```

```
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327891_1693063261371.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271d",
    "name": "externallmg_1693194327973_1693063261393.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194327973_1693063261393.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271e",
    "name": "externallmg_1693194328013_1693063261415.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328013_1693063261415.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d7271f",
    "name": "externallmg_1693194328050_1693063261502.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328050_1693063261502.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d72720",
    "name": "externallmg_1693194328065_1693063261523.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328065_1693063261523.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1858eb1f822256d72721",
    "name": "externallmg_1693194328100_1693063261546.jpg",
    "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328100_1693063261546.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1858eb1f822256d72722",
  "name": "externallmg_1693194328135_1693063261569.jpg",
  "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328135_1693063261569.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1858eb1f822256d72723",
  "name": "externallmg_1693194328152_1693063261593.jpg",
  "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328152_1693063261593.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1858eb1f822256d72724",
  "name": "externallmg_1693194328178_1693063261635.jpg",
  "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328178_1693063261635.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1858eb1f822256d72725",
  "name": "externallmg_1693194328259_1693063261436.jpg",
  "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328259_1693063261436.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1858eb1f822256d72726",
  "name": "externallmg_1693194328270_1693063261458.jpg",
  "path": "cases/64e9bae31452884516bb56c0/
externallmg_1693194328270_1693063261458.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ec1858eb1f822256d72727",
      "name": "externalimg_1693194328288_1693063261480.jpg",
      "path": "cases/64e9bae31452884516bb56c0/
externalimg_1693194328288_1693063261480.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ec1858eb1f822256d72728",
      "name": "externalimg_1693194328309_1693063261615.jpg",
      "path": "cases/64e9bae31452884516bb56c0/
externalimg_1693194328309_1693063261615.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ec1858eb1f822256d72729",
      "name": "externalimg_r_1693194328245_1693063261219.jpg",
      "path": "cases/64e9bae31452884516bb56c0/
externalimg_r_1693194328245_1693063261219.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ec1858eb1f822256d7272a",
      "name": "externalimg_r_1693194328220_1693063261199.jpg",
      "path": "cases/64e9bae31452884516bb56c0/
externalimg_r_1693194328220_1693063261199.jpg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "createdAt": "2023-08-26T08:42:11.056Z",
  "updatedAt": "2023-08-29T09:08:39.140Z",
  "__v": 0,
  "invoiceId": "64e9bae31452884516bb56cb",
  "fullAddress": "Residential Flat No. 11, 2nd Floor, Building No C-10, Navgharkul Co-
Op. Hsg. Soc. Ltd., Manpasand Housing Scheme, Plot No. 17, Sector 48A, Seawoods
```

```
(West), Village - Nerul, Taluka - Thane, District - Thane, Navi Mumbai, PIN - 400 706,
State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Amar Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "9970747810",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom + 2
Passage",
"carpetTotal": "291.20",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "320.32",
"finalCarpetArea": "291.20",
"finalSalableArea": "352.35",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 375.00",
"buildingServicesRate": "2500",
"flatRate": "15400",
"landOtherRate": "12900",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Tue Aug 29 2023 13:11:42 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-08-26",
"remarks": []
}
```

Name	Length	Width	Total
Composition :			
Living Room	9'2"	12'5"	113.82
WC	3'9"	3'1"	11.56
Bathroom	3'5"	3'10"	13.10
Passage	2'4"	3'5"	7.97
Kitchen	6'3"	7'5"	46.35
Passage	7'1"	2'8"	18.89
Bedroom	8'11"	8'11"	79.51
Other Composition :			