

```
{
  "typeOfReport": {
    "value": "Residential_Bungalow_",
    "label": "Residential Bungalow "
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64130b50e6a52007fbaa7d90"
    },
    "type": "CREDITOFFICER",
    "_id": "64130b50e6a52007fbaa7d92",
    "firstName": "testgangapur",
    "lastName": "testgangapur",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3540"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64130b50e6a52007fbaa7d90",
  "name": "Gangapur Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "GangapurBranch@me.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHree Ganesh Avanie, Gangapur road, Nashik 422013, State
Maharashtra"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERIFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": ""
```

```
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.03942641017453",
  "longitude": "73.78929840991874"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Makhmalabad-2",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Upper Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "14",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dhanlaxmi Row Bungalow",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Shanti Nagar",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Siddhi Vinayak Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "42/5/B/ 14",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```

```
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e9ed461452884516bc526f",
"ownerName": "Dharma Rathod",
```

```
"ownerPhoneNo": "8999281606",
"fullAddress": "Residential Residential Bungalow No. Upper Ground Floor, Dhanlaxmi
Row Bungalow, Near Siddhi Vinayak Mandir, Plot No. 14, New/Current Survey No. 42/5/
B/ 14, Shanti Nagar, Village - Makhmalabad-2, Taluka - Nashik, District - Nashik,
Nashik, 422003, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Chandrikaben Rasikbhai Dashlani ",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "Dharma Chhaju Rathod "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1693052159989_notry_agreement_.pdf",
    "path": "cases/64e9ed461452884516bc526f/
document_1693052159989_notry_agreement_.pdf",
    "id": "906953",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Aug 26 2023 17:46:39 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      }
    },
    "isHardCopy": false,
    "displayStatus": false,
  }
]
```



```
    "fileName": "document_1693052188589_Sandip_zhodpe_document.pdf",
    "path": "cases/64e9ed461452884516bc526f/
document_1693052188589_Sandip_zhodpe_document.pdf",
    "id": "774177",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Aug 26 2023 17:46:39 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "Javak No. / NNV / C2 / 27697 "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1693052252763_93938.pdf",
    "path": "cases/64e9ed461452884516bc526f/
document_1693052252763_93938.pdf",
    "id": "392644",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Aug 26 2023 17:47:36 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003420",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "241611",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 26 2023 17:47:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Dharma Rathod",
```

```
    "phone": "8999281606",
    "ownershipShare": "",
    "email": "",
    "id": "592049"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56ef",
    "name":
"externallmg_1693052317345_WhatsApp_Image_20230317_at_93736_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317345_WhatsApp_Image_20230317_at_93736_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f0",
    "name":
"externallmg_1693052317766_WhatsApp_Image_20230317_at_93737_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317766_WhatsApp_Image_20230317_at_93737_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f1",
    "name":
"externallmg_1693052317850_WhatsApp_Image_20230317_at_93737_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317850_WhatsApp_Image_20230317_at_93737_AM.jpeg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f2",
    "name":
"externallmg_1693052317930_WhatsApp_Image_20230317_at_93738_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317930_WhatsApp_Image_20230317_at_93738_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f3",
    "name":
"externallmg_1693052317939_WhatsApp_Image_20230317_at_93738_AM_2.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317939_WhatsApp_Image_20230317_at_93738_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f4",
    "name":
"externallmg_1693052317976_WhatsApp_Image_20230317_at_93738_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052317976_WhatsApp_Image_20230317_at_93738_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f5",
    "name":
"externallmg_1693052319011_WhatsApp_Image_20230317_at_93739_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319011_WhatsApp_Image_20230317_at_93739_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f6",
    "name":
"externallmg_1693052319013_WhatsApp_Image_20230317_at_93739_AM_2.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319013_WhatsApp_Image_20230317_at_93739_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f7",
    "name":
"externallmg_1693052319016_WhatsApp_Image_20230317_at_93739_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319016_WhatsApp_Image_20230317_at_93739_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f8",
    "name":
"externallmg_1693052319017_WhatsApp_Image_20230317_at_93740_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319017_WhatsApp_Image_20230317_at_93740_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56f9",
    "name":
"externallmg_1693052319018_WhatsApp_Image_20230317_at_93740_AM_2.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319018_WhatsApp_Image_20230317_at_93740_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56fa",
    "name":
"externallmg_1693052319020_WhatsApp_Image_20230317_at_93740_AM_3.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319020_WhatsApp_Image_20230317_at_93740_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56fb",
```

```
    "name":
"externallmg_1693052319022_WhatsApp_Image_20230317_at_93740_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319022_WhatsApp_Image_20230317_at_93740_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56fc",
    "name":
"externallmg_1693052319025_WhatsApp_Image_20230317_at_93741_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319025_WhatsApp_Image_20230317_at_93741_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56fd",
    "name":
"externallmg_1693052319027_WhatsApp_Image_20230317_at_93741_AM.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319027_WhatsApp_Image_20230317_at_93741_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda01452884516bc56fe",
    "name":
"externallmg_1693052319062_WhatsApp_Image_20230317_at_93742_AM_1.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052319062_WhatsApp_Image_20230317_at_93742_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9eda81452884516bc5742",
    "name":
"externallmg_1693052327937_WhatsApp_Image_20230317_at_93742_AM_2.jpeg",
    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052327937_WhatsApp_Image_20230317_at_93742_AM_2.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9eda81452884516bc5743",
  "name":
"externallmg_1693052327991_WhatsApp_Image_20230317_at_93742_AM.jpeg",
  "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052327991_WhatsApp_Image_20230317_at_93742_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9eda81452884516bc5744",
  "name":
"externallmg_1693052328046_WhatsApp_Image_20230317_at_93743_AM_1.jpeg",
  "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052328046_WhatsApp_Image_20230317_at_93743_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9eda81452884516bc5745",
  "name":
"externallmg_1693052328114_WhatsApp_Image_20230317_at_93743_AM_2.jpeg",
  "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052328114_WhatsApp_Image_20230317_at_93743_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9eda81452884516bc5746",
  "name":
"externallmg_1693052328178_WhatsApp_Image_20230317_at_93743_AM.jpeg",
  "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052328178_WhatsApp_Image_20230317_at_93743_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9eda81452884516bc5747",
  "name":
"externallmg_1693052328244_WhatsApp_Image_20230826_at_51741_PM_1.jpeg",
```

```

    "path": "cases/64e9ed461452884516bc526f/
externallmg_1693052328244_WhatsApp_Image_20230826_at_51741_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-26T12:17:10.293Z",
"updatedAt": "2023-08-26T12:18:48.453Z",
"__v": 0,
"invoiceId": "64e9ed461452884516bc5283",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Dharma Rathod",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8999281606"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			