

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd93aace84bf289baab038",
    "firstName": "Pranjli ",
    "lastName": "Prabhu",
    "mobileNo": "",
    "workMobileNo": "9969957108",
    "email": "pranjli.prabhu@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Pranjli ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiroi Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
```

```
},
```

```
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
```

```
},
```

```
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
```

```
},
```

```
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.103707876664718",
  "longitude": "73.00090612606292"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.00090612606292,
```

```
19.103707876664718
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-29",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Koparkhairane, Navi Mumbai",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "21",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Jimmy Tower III",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "17",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Crystal Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 709",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Partly_Marble_Flooring_and_Partly_Ceramic_Flooring",
    "label": "Partly Marble Flooring and Partly Ceramic Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
    "west": "DVS Collage",
    "south": "Karan Krupa Society",
    "east": "Sector 17-18 Road"
  },
  "asPerDocumentAgreement": {
    "north": "2.45 Mtrs. Wide S.W. Drain",
    "west": "Open Space",
    "south": "9.00 M. W. Road",
    "east": "Plot No. 20 & 11"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "39",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "15908",
  "depreciatedBuildingRate": "1708"
},
"igrRate": {
  "propertyName": "Residential ",
```

```
"rate": "112200.00",
"landRate": "43200",
"igrImage": "cases/64ec83abeb1f822256d913e4/igr_1693305509200_Image.png",
"squareMeterGuideLineRate": "117810.00",
"squareFeetGuideLineRate": "10945.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "9143.00",
  "squareFeetGuideLineRate": "9143.00",
  "squareMeterGuideLineRate": "98411.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "28000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per NMMC norms",
  "tenantName": "Siddharth Rawat",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Covered Car Parking ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1997",
"fullDate": "1/1/1997"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "RCC_Framed_Structure",
"label": "RCC Framed Structure"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "0",
```

```
"label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "34",
"ageOfBuilding": "26",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "13",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "957.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64ec83abeb1f822256d913e4/
routeMap_1693306557076_Image.png",
    "routeLat": "19.103419",
    "routeLng": "73.000343",
    "stationName": "Kopar Khairane",
    "routeDistance": "1.9 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  }
}
```



```
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "qbip2a",
    "name": "qbip2a",
    "image": "cases/64ec83abeb1f822256d913e4/
routeMap_1693306489936_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "12694584.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",

```

```
"finalValue": "12694584.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Aug 29 2023 17:38:23 GMT+0530 (India Standard Time)",
  "number": "2302310",
  "dayCount": "16",
  "monthCount": "456",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8755337.00",
  "selectedBuildUpValue": "957.60",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64ed5614eb1f822256d980ff",
      "name": "externallmg_1693275645976_1693275525844_image_2.jpeg",
      "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275645976_1693275525844_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64ed5614eb1f822256d98100",
      "name": "externallmg_1693275646560_1693275525844_image_3.jpeg",
      "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275646560_1693275525844_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64ed5614eb1f822256d980fe",
      "name": "externallmg_1693275645441_1693275525844_image_1.jpeg",
      "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275645441_1693275525844_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "64ed5614eb1f822256d980f1",
      "name": "externallmg_1693275551704_1693275429556_image_4.jpeg",
      "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275551704_1693275429556_image_4.jpeg",
      "orientation": "landscape"
    }
  ],
  "compositionImages": [
    {
```

```
    "status": false,
    "_id": "64ed5614eb1f822256d980f6",
    "name": "Kitchen",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275592729_1693275470980_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ed5614eb1f822256d980fa",
    "name": "Kitchen",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275593669_1693275470980_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ed5614eb1f822256d980fb",
    "name": "Kitchen",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275594137_1693275470980_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ed5614eb1f822256d980ee",
    "name": "Kitchen",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275550954_1693275429556_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64ed5614eb1f822256d980f5",
    "name": "Kitchen",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275592028_1693275470980_image_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14865",
    "max": "17778"
  }
},
```

```
"builtUpRateRange": {
  "min": "12388",
  "max": "14815"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```



```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "798.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64ec83abeb1f822256d913e4",
"ownerName": "Mrs. Meenakshi Dabaria ",
"ownerPhoneNo": "8424050294",
"appAddress": "Flat no. 1101, 10th Floor, Jimmy Tower 3, Crystal City CHS, plot no.
21, sector - 17, Koparkhairane, Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "24/06/2022",
      "from": {
```

```
    "value": "Seller",
    "label": "Seller"
  },
  "Seller": "Mr. Jaspal Singh & Mrs. Sunita Kaur",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mrs. Meenakshi Dabaria & Mr. Birbal Dabaria",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "11407"
},
"isHardCopy": false,
"displayStatus": true,
"id": "473722",
"path": "cases/64ec83abeb1f822256d913e4/
document_1693222101212_Racpc_Sion_Minakshi_Dabaria.pdf",
"fileName": "document_1693222101212_Racpc_Sion_Minakshi_Dabaria.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "02/08/1997",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "NMMC / TPO / OC / 826"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693303969548_95692.pdf",
  "path": "cases/64ec83abeb1f822256d913e4/
document_1693303969548_95692.pdf",
  "id": "342693",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
```

```
"createdAt": "Tue Aug 29 2023 16:41:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "29/04/1995",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "NMMC / Div. 2 / TPO / SP No. 1398 "
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1693304036713_141916.pdf",
"path": "cases/64ec83abeb1f822256d913e4/
document_1693304036713_141916.pdf",
"id": "708808",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Tue Aug 29 2023 16:41:25 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003436",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "396779",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 28 2023 16:53:23 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Meenakshi Dabaria ",
    "phone": "8424050294",
    "ownershipShare": "",
    "email": "",
    "id": "458764"
```

```
},
{
  "name": "Mr. Birbal Dabaria",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "id": "569181"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Meter",
      "label": "Square Meter"
    },
    "id": "280428",
    "name": "Living Room",
    "length": "19.30",
    "length1": "19.3",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "193.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "193.00"
  },
  {
    "measurementType": {
      "value": "Square_Meter",
      "label": "Square Meter"
    },
    "id": "2",
    "name": "Kitchen",
    "length": "",
    "length1": "11",
    "length2": "0",
    "width": "",
    "width1": "7.8",
    "width2": "0",
    "totalArea": "85.80",
    "images": [],
    "finalArea": "85.80",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "2",
  "name": "Passage",
  "length": "11.60",
  "length1": "11.6",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "46.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "46.40"
},
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "130.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "130.00"
},
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.00",
```

```
"length1": "10",
"length2": "00",
"width": "15.80",
"width1": "15.8",
"width2": "00",
"totalArea": "158.00",
"images": [],
"extraAreas": [],
"finalArea": "158.00"
},
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.80",
  "length1": "6.8",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "27.20",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.20"
},
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "7",
  "name": "Toilet",
  "length": "",
  "length1": "7",
  "length2": "0",
  "width": "",
  "width1": "3.6",
  "width2": "0",
  "totalArea": "25.20",
  "images": [],
  "finalArea": "25.20",
  "extraAreas": []
},
```

```
{
  "measurementType": {
    "value": "Square_Meter",
    "label": "Square Meter"
  },
  "id": "7",
  "name": "Passage",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "10.60",
  "width1": "10.6",
  "width2": "00",
  "totalArea": "74.20",
  "images": [],
  "extraAreas": [],
  "finalArea": "74.20"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "74.14",
    "totalAreaDocument": "798.00",
    "docBultupPercentage": "20",
    "docFinalBultUp": "957.60",
    "docFinalBultUpSquareMeter": "88.96",
    "docSaleablePercentage": "19",
    "docFinalSaleable": "1139.54",
    "docFinalSaleableSquareMeter": "105.87",
    "id": "508535"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": true,
  "_id": "64edcac1eb1f822256dad98f",
  "property": "2BHK Flat for Sale in Jimmy Tower, Sector 18, Kopar Khairane, Navi
Mumbai",
  "area": "740.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "11000000.00",
  "expectedRate": "14864.86",
  "builtUpExpectedRate": "12387.39",
  "image": "cases/64ec83abeb1f822256d913e4/
indicator_1693304165091_Image.png",
  "squareMeter": "68.75",
  "id": "662602"
},
{
  "printlnReport": true,
  "_id": "64edcac1eb1f822256dad990",
  "property": "2 BHK Flat For Sale in Jimmy Tower, Crystal CHSL, Kopar Khairane,
Navi Mumbai",
  "area": "750.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "13000000.00",
  "expectedRate": "17333.33",
  "builtUpExpectedRate": "14444.44",
  "image": "cases/64ec83abeb1f822256d913e4/
indicator_1693304853134_Image.png",
  "squareMeter": "69.68",
  "id": "143158"
},
{
  "printlnReport": true,
  "_id": "64edcac1eb1f822256dad991",
  "property": "1 BHK Flat For Sale in Mudit Garden, Kopar Khairane, Navi Mumbai",
  "area": "450.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```



```
    "source": "magic_bricks",
    "expectedPrice": "8000000.00",
    "expectedRate": "17777.78",
    "builtUpExpectedRate": "14814.81",
    "image": "cases/64ec83abeb1f822256d913e4/
indicator_1693305218582_Image.png",
    "squareMeter": "41.81",
    "id": "136954"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980ed",
    "name": "externallmg_1693275550580_1693275429555_image_0.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275550580_1693275429555_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980ee",
    "name": "externallmg_1693275550954_1693275429556_image_1.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275550954_1693275429556_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980ef",
    "name": "externallmg_1693275551317_1693275429556_image_2.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275551317_1693275429556_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f0",
    "name": "externallmg_1693275551360_1693275429556_image_3.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275551360_1693275429556_image_3.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f1",
    "name": "externallmg_1693275551704_1693275429556_image_4.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275551704_1693275429556_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f2",
    "name": "externallmg_1693275551883_1693275429556_image_5.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275551883_1693275429556_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f3",
    "name": "externallmg_1693275552479_1693275429556_image_6.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275552479_1693275429556_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f4",
    "name": "externallmg_1693275591646_1693275470980_image_0.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275591646_1693275470980_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980f5",
    "name": "externallmg_1693275592028_1693275470980_image_1.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275592028_1693275470980_image_1.jpeg",
    "orientation": "portrait"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ed5614eb1f822256d980f6",
  "name": "externallmg_1693275592729_1693275470980_image_2.jpeg",
  "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275592729_1693275470980_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ed5614eb1f822256d980f7",
  "name": "externallmg_1693275592788_1693275470980_image_3.jpeg",
  "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275592788_1693275470980_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ed5614eb1f822256d980f8",
  "name": "externallmg_1693275593112_1693275470980_image_4.jpeg",
  "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275593112_1693275470980_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ed5614eb1f822256d980f9",
  "name": "externallmg_1693275593529_1693275470980_image_5.jpeg",
  "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275593529_1693275470980_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ed5614eb1f822256d980fa",
  "name": "externallmg_1693275593669_1693275470980_image_6.jpeg",
  "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275593669_1693275470980_image_6.jpeg",
  "orientation": "portrait"
},
{

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980fb",
    "name": "externallmg_1693275594137_1693275470980_image_7.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275594137_1693275470980_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980fc",
    "name": "externallmg_1693275594490_1693275470980_image_8.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275594490_1693275470980_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980fd",
    "name": "externallmg_1693275644825_1693275525844_image_0.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275644825_1693275525844_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980fe",
    "name": "externallmg_1693275645441_1693275525844_image_1.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275645441_1693275525844_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d980ff",
    "name": "externallmg_1693275645976_1693275525844_image_2.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275645976_1693275525844_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64ed5614eb1f822256d98100",
    "name": "externallmg_1693275646560_1693275525844_image_3.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275646560_1693275525844_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d98101",
    "name": "externallmg_1693275647205_1693275525844_image_4.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275647205_1693275525844_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d98102",
    "name": "externallmg_1693275647494_1693275525844_image_5.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275647494_1693275525844_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d98103",
    "name": "externallmg_1693275648053_1693275525844_image_6.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275648053_1693275525844_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ed5614eb1f822256d98104",
    "name": "externallmg_1693275648343_1693275525844_image_7.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externallmg_1693275648343_1693275525844_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64ed5614eb1f822256d98105",
    "name": "externalimg_1693275648712_1693275525844_image_8.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externalimg_1693275648712_1693275525844_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ed5614eb1f822256d98106",
    "name": "externalimg_1693275514081_1693275394950_image_0.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externalimg_1693275514081_1693275394950_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64ed5614eb1f822256d98107",
    "name": "externalimg_1693275514464_1693275394950_image_1.jpeg",
    "path": "cases/64ec83abeb1f822256d913e4/
externalimg_1693275514464_1693275394950_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-08-28T11:23:23.897Z",
"updatedAt": "2023-08-29T12:08:32.456Z",
"__v": 0,
"updatedBy": "627221f4afd7d55eddeddcb4",
"fullAddress": "Residential Flat No. 1001, 10th Floor, Jimmy Tower III, Crystal Co-Op.
Hsg. Soc. Ltd., Plot No. 21, Sector 17, Village - Koparkhairane, Navi Mumbai, Taluka -
Thane, District - Thane, PIN Code - 400 709, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Siddharth Rawat (Tenant)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "7020600709",
"buildingServicesRate": "2800.00",
```

```

"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 798.00",
"flatRate": "17000.00",
"landOtherRate": "14200",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"carpetTotal": "739.80",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "887.76",
"finalCarpetArea": "739.80",
"finalSalableArea": "1065.31",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.\n\n",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "19",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"siteVisitDate": "2023-08-28",
"reportGeneratedDate": "Tue Aug 29 2023 17:14:41 GMT+0530 (India Standard Time)"

```

Name	Length	Width	Total
Composition :			
Living Room	19.3'00"	10'00"	193.00
Kitchen	11'0"	7.8'0"	85.80
Passage	11.6'00"	4'00"	46.40
Bedroom	13'00"	10'00"	130.00
Bedroom	10'00"	15.8'00"	158.00
Toilet	6.8'00"	4'00"	27.20
Toilet	7'0"	3.6'0"	25.20

Passage	7'00"	10.6'00"	74.20
---------	-------	----------	-------

---

Other  
Composition :

---