

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "firstName": "Pushpa",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "2950"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "647ed1960ab64c23c9fcf71d",
  "role": "FRONTDESK",
  "firstName": "Rishidatt",
  "email": "rishiyadav44444@gamil.com",
```

```
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": ""
},
"checker": "",
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.967344188689218",
  "longitude": "73.76495385290528"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Pathardi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "02",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prathamesh Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Yogeshwar Road,",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Prashant Nagar",
  "label": false
},
"landmark": {
  "status": true,
```

```
"name": "Landmark",
"key": "landmark",
"value": "Near Kinderland School",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "320/ 3/ 1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-14",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```



```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64edbb68eb1f822256daa319",
"ownerName": "Prakash Borse",
"ownerPhoneNo": "9823609314",
"fullAddress": " Flat No. A-14, 4th Floor, Prathamesh Residency, Near Kinderland School, Plot No. 02, Yogeshwar Road,, Prashant Nagar, Village - Pathardi, Taluka - Nashik, District - Nashik, Nashik, 422010",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    }
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName": "document_1693301496598_prakash_borse_Draft.pdf",
    "path": "cases/64edbb68eb1f822256daa319/
document_1693301496598_prakash_borse_Draft.pdf",
    "id": "728834",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Aug 29 2023 15:02:59 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "CD/B5/199/1648"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1693301537213_Prakash_Borse.pdf",
    "path": "cases/64edbb68eb1f822256daa319/
document_1693301537213_Prakash_Borse.pdf",
    "id": "277876",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Aug 29 2023 15:02:59 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003455",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "606262",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 29 2023 15:03:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```



```
    "name": "Prakash Borse",
    "phone": "9823609314",
    "ownershipShare": "",
    "email": "",
    "id": "355509"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa668",
    "name":
"externallmg_1693301726184_WhatsApp_Image_20230828_at_63448_PM.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726184_WhatsApp_Image_20230828_at_63448_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa669",
    "name":
"externallmg_1693301726248_WhatsApp_Image_20230828_at_63449_PM_1.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726248_WhatsApp_Image_20230828_at_63449_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa66a",
    "name":
"externallmg_1693301726316_WhatsApp_Image_20230828_at_63449_PM.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726316_WhatsApp_Image_20230828_at_63449_PM.jpeg",
    "orientation": "landscape"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa66b",
  "name":
"externallmg_1693301726396_WhatsApp_Image_20230828_at_63450_PM_1.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726396_WhatsApp_Image_20230828_at_63450_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa66c",
  "name":
"externallmg_1693301726433_WhatsApp_Image_20230828_at_63450_PM_2.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726433_WhatsApp_Image_20230828_at_63450_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa66d",
  "name":
"externallmg_1693301726490_WhatsApp_Image_20230828_at_63450_PM.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726490_WhatsApp_Image_20230828_at_63450_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa66e",
  "name":
"externallmg_1693301726544_WhatsApp_Image_20230828_at_63451_PM.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726544_WhatsApp_Image_20230828_at_63451_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa66f",
  "name":
"externallmg_1693301726601_WhatsApp_Image_20230828_at_63452_PM.jpeg",
```

```
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726601_WhatsApp_Image_20230828_at_63452_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa670",
    "name":
"externallmg_1693301726668_WhatsApp_Image_20230828_at_63453_PM.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726668_WhatsApp_Image_20230828_at_63453_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa671",
    "name":
"externallmg_1693301726695_WhatsApp_Image_20230828_at_63454_PM_1.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726695_WhatsApp_Image_20230828_at_63454_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa672",
    "name":
"externallmg_1693301726777_WhatsApp_Image_20230828_at_63454_PM.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726777_WhatsApp_Image_20230828_at_63454_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edbbdfef1f822256daa673",
    "name":
"externallmg_1693301726805_WhatsApp_Image_20230828_at_63456_PM_1.jpeg",
    "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726805_WhatsApp_Image_20230828_at_63456_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64edbbdfef1f822256daa674",
  "name":
"externallmg_1693301726873_WhatsApp_Image_20230828_at_63456_PM.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726873_WhatsApp_Image_20230828_at_63456_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa675",
  "name":
"externallmg_1693301726941_WhatsApp_Image_20230828_at_63457_PM_1.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301726941_WhatsApp_Image_20230828_at_63457_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa676",
  "name":
"externallmg_1693301727008_WhatsApp_Image_20230828_at_63457_PM_2.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301727008_WhatsApp_Image_20230828_at_63457_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edbbdfef1f822256daa677",
  "name":
"externallmg_1693301727073_WhatsApp_Image_20230828_at_63457_PM.jpeg",
  "path": "cases/64edbb68eb1f822256daa319/
externallmg_1693301727073_WhatsApp_Image_20230828_at_63457_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-08-29T09:33:29.005Z",
"updatedAt": "2023-08-29T09:35:27.252Z",
"__v": 0,
"invoiceId": "64edbb69eb1f822256daa327",
```

```
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Prakash Borse",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9823609314"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			