

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Rent",
    "value": "Fair_Market_Rent"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230faa",
    "firstName": "Dineshkumar Mishra",
    "email": "0_default_dineshkumar.nishra@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9022373500"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2200000",
    "discussWithPerson": "Dineshkumar Mishra",
    "expectedFees": 1100,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
  }
}
```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.193180677851053",
  "longitude": "72.94782030534728"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94782030534728,
    19.193180677851053
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-01",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-31",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Panchpakhdi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Muktidham Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shree Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Wagle Estate",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
```



```
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "427(Part) to 435(Part) & 485",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "25",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```

    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN - 400 604",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},

```

```
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Anand CHSL",
    "west": "Internal Road",
    "south": "Shree Shaktidham CHSL",
    "east": "Laxmi Sadan"
  },
  "asPerDocumentAgreement": {
    "north": "Details is not available",
    "west": "Details is not available",
    "south": "Details is not available",
    "east": "Details is not available"
  },
  "extraDetailOfProperty": "Details is not available"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "52.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "11987.5",
  "depreciatedBuildingRate": "1187.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "101800",
```

```
"landRate": "46000",
"igrImage": "cases/64eddde3eb1f822256db1cb3/igr_1693543115774_Image.png",
"squareMeterGuideLineRate": "91620.00",
"squareFeetGuideLineRate": "8512.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "7028.00",
  "squareFeetGuideLineRate": "7028.00",
  "squareMeterGuideLineRate": "75653.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "17,000",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "Details is not available",
  "meterCardHolderName": "Details is not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "Miss. Sakshi Parab\nOccupied Since - Last 9 Months",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1988",
  "fullDate": "1/1/1988"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "Information_Not_Available",
"label": "Information Not Available"
}
```

```
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "35",
"totalLifeBuilding": "60",
"estimatedAge": "25",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "490.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64edde3eb1f822256db1cb3/
routeMap_1693571040021_Image.png",
    "routeLat": "19.191280",
    "routeLng": "72.947544",
    "stationName": "Thane",
    "routeDistance": "5.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```



```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "ec2sfe",
    "name": "ec2sfe",
    "image": "cases/64eddde3eb1f822256db1cb3/
routeMap_1693570957216_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5874120.00",
  "finalValue": "5874120.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
```

```
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3443720.00",
  "selectedBuildUpValue": "490.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "64f14396eb1f822256de7ddf",
  "name": "externalImg_r_1693533069388_1693532952711_image_1.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533069388_1693532952711_image_1.jpg",
  "orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64f14396eb1f822256de7de9",
    "name": "Living Room",
    "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533073608_1693532952711_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f14396eb1f822256de7de8",
    "name": "Living Room",
    "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533073441_1693532952711_image_11.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f14396eb1f822256de7de6",
    "name": "Living Room",
    "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533072741_1693532952711_image_8.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f14396eb1f822256de7de2",
    "name": "Living Room",
    "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533072231_1693532952711_image_6.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "64f14396eb1f822256de7ddd",
  "name": "Living Room",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533070343_1693532952711_image_2.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64f14396eb1f822256de7dde",
  "name": "Living Room",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533071003_1693532952711_image_3.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64f14396eb1f822256de7ddf",
  "name": "Living Room",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533069388_1693532952711_image_1.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64f14396eb1f822256de7de3",
  "name": "Living Room",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533071668_1693532952711_image_4.jpg",
  "orientation": "landscape"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "12500",
    "max": "18182"
  },
  "builtUpRateRange": {
    "min": "12500",
    "max": "15295"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "490.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64eddde3eb1f822256db1cb3",
"ownerName": "Mrs. Vishakha Vijay Tambat",
"ownerPhoneNo": "9004690441",
"appAddress": "\nFalt no 25 Muktidham co op society Ltd\nwagle estate thane",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "17/05/2000",
      "from": {
        "value": "The_Transferor",
        "label": "The Transferor"
      },
      "The_Transferor": "Smt. Sudha Ashok Rane ",
      "to": {
        "value": "The_Transferee",
        "label": "The Transferee"
      }
    }
  }
],
```

```
    "The_Transferee": "Mrs. Vishakha Vijay Tambat"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "621377",
  "path": "cases/64eddde3eb1f822256db1cb3/
document_1693310367464_Vishakha_v_Tambat_Nitin_sir.pdf",
  "fileName": "document_1693310367464_Vishakha_v_Tambat_Nitin_sir.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "01/06/1988",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "874 / "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693569180270_147828.pdf",
  "path": "cases/64eddde3eb1f822256db1cb3/
document_1693569180270_147828.pdf",
  "id": "982248",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Sep 01 2023 17:23:00 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003461",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "446828",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 29 2023 17:30:35 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mrs. Vishakha Vijay Tambat",
    "phone": "9004690441",
    "ownershipShare": "",
    "email": "",
    "id": "477638"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "756645",
    "name": "Living Room",
    "length": "15.17",
    "length1": "15",
    "length2": "2",
    "width": "9.58",
    "width1": "9",
    "width2": "7",
    "totalArea": "145.35",
    "images": [],
    "extraAreas": [],
    "finalArea": "145.35"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "2.75",
    "length1": "2",
    "length2": "9",
    "width": "3.33",
    "width1": "3",
    "width2": "4",
    "totalArea": "9.17",
    "images": [],
    "extraAreas": [],
  }
]
```

```
"finalArea": "9.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.25",
  "length1": "8",
  "length2": "3",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "88.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "88.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "104.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "104.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "8.25",
```

```
"length1": "8",
"length2": "3",
"width": "2.42",
"width1": "2",
"width2": "5",
"totalArea": "19.94",
"images": [],
"extraAreas": [],
"finalArea": "19.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "WC & Bath",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "11.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.10"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "648276",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "490",
    "squareMeterArea": "45.52",
    "docFinalBuiltUp": "0.00",
```

```
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64f16b13eb1f822256dea087",
    "property": "Flat",
    "area": "440",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "2",
    "source": "magic_bricks",
    "expectedPrice": "8000000",
    "expectedRate": "18181.82",
    "builtUpExpectedRate": "15151.52",
    "image": "cases/64eddde3eb1f822256db1cb3/
indicator_1693542753489_Image.png",
    "squareMeter": "40.88",
    "id": "462048"
  },
  {
    "printlnReport": true,
    "_id": "64f16b13eb1f822256dea088",
    "property": "Flat",
    "area": "596",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "8000000",
    "expectedRate": "13422.82",
    "builtUpExpectedRate": "0.00",
    "image": "cases/64eddde3eb1f822256db1cb3/
indicator_1693542817703_Image.png",
    "squareMeter": "55.37",
    "id": "292606"
  },
}
```

```
{
  "printlnReport": true,
  "_id": "64f16b13eb1f822256dea089",
  "property": "Flat",
  "area": "425",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "6500000",
  "expectedRate": "15294.12",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64eddde3eb1f822256db1cb3/
indicator_1693542889111_Image.png",
  "squareMeter": "39.48",
  "id": "213233"
},
{
  "printlnReport": true,
  "_id": "64f16b13eb1f822256dea08a",
  "property": "Flat",
  "area": "392",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "4900000",
  "expectedRate": "12500.00",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64eddde3eb1f822256db1cb3/
indicator_1693542944259_Image.png",
  "squareMeter": "36.42",
  "id": "455086"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f14396eb1f822256de7ddc",
    "name": "externalImg_r_1693533069199_1693532952711_image_0.jpg",
    "path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533069199_1693532952711_image_0.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7ddd",
  "name": "externallmg_r_1693533070343_1693532952711_image_2.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533070343_1693532952711_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7dde",
  "name": "externallmg_r_1693533071003_1693532952711_image_3.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533071003_1693532952711_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7ddf",
  "name": "externallmg_r_1693533069388_1693532952711_image_1.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533069388_1693532952711_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de0",
  "name": "externallmg_r_1693533072548_1693532952711_image_7.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533072548_1693532952711_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de1",
  "name": "externallmg_r_1693533072004_1693532952711_image_5.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533072004_1693532952711_image_5.jpg",
  "orientation": "portrait"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de2",
  "name": "externallmg_r_1693533072231_1693532952711_image_6.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533072231_1693532952711_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de3",
  "name": "externallmg_r_1693533071668_1693532952711_image_4.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533071668_1693532952711_image_4.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de4",
  "name": "externallmg_r_1693533073051_1693532952711_image_9.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533073051_1693532952711_image_9.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de5",
  "name": "externallmg_r_1693533073352_1693532952711_image_10.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533073352_1693532952711_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de6",
  "name": "externallmg_r_1693533072741_1693532952711_image_8.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533072741_1693532952711_image_8.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de7",
  "name": "externallmg_r_1693533073900_1693532952711_image_13.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533073900_1693532952711_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de8",
  "name": "externallmg_r_1693533073441_1693532952711_image_11.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533073441_1693532952711_image_11.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7de9",
  "name": "externallmg_r_1693533073608_1693532952711_image_12.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533073608_1693532952711_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f14396eb1f822256de7dea",
  "name": "externallmg_r_1693533074144_1693532952711_image_14.jpg",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533074144_1693532952711_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64f14396eb1f822256de7deb",
  "name": "externallmg_r_1693533053195_1693532924409_image_2.png",
  "path": "cases/64eddde3eb1f822256db1cb3/
externallmg_r_1693533053195_1693532924409_image_2.png",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "64f14396eb1f822256de7dec",
"name": "externalImg_r_1693533040225_1693532924409_image_0.jpg",
"path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533040225_1693532924409_image_0.jpg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "64f14396eb1f822256de7ded",
"name": "externalImg_r_1693533048462_1693532924409_image_1.jpg",
"path": "cases/64eddde3eb1f822256db1cb3/
externalImg_r_1693533048462_1693532924409_image_1.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-08-29T12:00:35.807Z",
"updatedAt": "2023-09-01T12:52:33.193Z",
"__v": 0,
"invoiceId": "64eddde4eb1f822256db1ccd",
"fullAddress": "Residential Flat No. 25, 1st Floor, Wing - B, Muktidham Co-Op. Hsg.
Soc. Ltd., Shree Nagar, Wagle Estate, Village - Panchpakhdi, Taluka - Thane, District -
Thane, Thane (West), PIN - 400 604, State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Miss. Sakshi Parab",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "9920040315",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 490.00",
```

"flatRate": "13300",  
 "landOtherRate": "10800",  
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC & Bath",  
 "carpetTotal": "379.06",  
 "otherCarpetTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "416.97",  
 "finalCarpetArea": "379.06",  
 "finalSalableArea": "458.66",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "finalSaleablePercentage": "0",  
 "extendOfSiteRemark": "",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00",  
 "siteMeasurementRemark": "",  
 "siteVisitDate": "2023-08-31",  
 "reportGeneratedDate": "Fri Sep 01 2023 18:18:16 GMT+0530 (India Standard Time)"

Name	Length	Width	Total
Composition :			
Living Room	15'2"	9'7"	145.35
Passage	2'9"	3'4"	9.17
Kitchen	8'3"	10'9"	88.69
Bedroom	10'9"	9'9"	104.81
Passage	8'3"	2'5"	19.94
WC & Bath	2'10"	3'11"	11.10
Other Composition :			