

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230fc1",
    "firstName": "Rajesh Waghela",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9833935397"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Rajesh Waghela",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": ""
}
```

```
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.217866325096907",
  "longitude": "72.82057157791131"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82057157791131,
    19.217866325096907
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-08-30T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-30T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-30T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-30T10:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-02",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Charkop",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "35",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Charkop Ravi Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "RSC - 24",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "MHADA Layout",
  "label": false
}
```



```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "41",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": " PIN - 400 067",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Vitrified_Tile_Flooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
}
```

```

"fixtures": {
  "value":
"Concealed_plumbing_with_C.P._fixtures._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fixtures. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
    "west": "Road",
    "south": "'B' Wing of Charkop Ravi CHSL",
    "east": "MHADA Society"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {

```

"remark": "As per Sale Plan attached in the Agreement cum Allotment Letter Flat was 2 Bedrooms + Living + Dinning + Study Room + Kitchen + 2 Toilets + Terrace. At the time of site inspection we observed that terrace area converted into Bedroom + Passage + Toilet. As per site composition of flat is 3 Bedrooms + Living + Dinning + Kitchen + 3 Toilets. Area of terrace is not mentioned in the agreement. For the purpose of valuation we have considered Carpet area of 722.00 Sq. Ft. as per Agreement cum Allotment Letter. ",

"depreciationPercentage": "16.5",  
"depreciationRatioOfBuilding": "",  
"salvageValue": "10",  
"depreciatedCostOfConstruction": "20754.5",  
"depreciatedBuildingRate": "2254.5"

},

"igrRate": {

"propertyName": "Flat",  
"rate": "138620",  
"landRate": "59310",  
"igrImage": "cases/64ef0951eb1f822256dcae94/igr\_1693918566190\_Image.png",  
"squareMeterGuideLineRate": "152482.00",  
"squareFeetGuideLineRate": "14166.00"

},

"igrFinalRate": {

"depreciationPercentage": "0",  
"rate": "13214.00",  
"squareFeetGuideLineRate": "13214.00",  
"squareMeterGuideLineRate": "142233.00"

},

"outgoingDetail": {

"areaStatusList": {  
"value": "Medium",  
"label": "Medium"

},

"propertyTypeOfUseList": {  
"value": "Residential\_Purpose",  
"label": "Residential Purpose"

},

"propertyOccupiedByList": {  
"value": "Owner\_Occupied",  
"label": "Owner Occupied"

},

"monthlyRent": "37,000.00",  
"assessmentNo": "Details not available",  
"taxPaidHolderName": "Details not available",  
"taxAmount": "Details not available",  
"electricityServiceConnectionNo": "Details not available",  
"meterCardHolderName": "Details not available",

```
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MHADA norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
    "fullDate": "1/1/2012"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
}
```

```
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "11",
"totalLifeBuilding": "60",
"estimatedAge": "49",
"noOfBasement": "",
"noOfPodium": "1",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "866.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
```



```
    "label": "Railway Station"
  },
  "routeMapImg": "cases/64ef0951eb1f822256dcae94/
routeMap_1693809269417_Image.png",
  "routeLat": "19.210944",
  "routeLng": "72.817389",
  "stationName": "Kandivali",
  "routeDistance": "4.9KM"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "63e5k8",
    "name": "63e5k8",
    "image": "cases/64ef0951eb1f822256dcae94/
routeMap_1693809122199_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "14985110.00",
"finalValue": "14985110.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11448610.00",
  "selectedBuildUpValue": "866.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64f56c01eb1f822256e1d305",
      "name": "externallmg_1693805569601_IMG_20230902_114712.jpg",
      "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569601_IMG_20230902_114712.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64f56c18eb1f822256e1d378",
      "name": "externallmg_1693805592146_IMG_20230902_114718.jpg",
      "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592146_IMG_20230902_114718.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64f56c01eb1f822256e1d303",
      "name": "externallmg_1693805569590_IMG_20230902_114708.jpg",
      "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569590_IMG_20230902_114708.jpg",
      "orientation": "portrait"
    }
  ],
  {
    "status": false,
```

```
    "_id": "64f56c01eb1f822256e1d304",
    "name": "externallmg_1693805569595_IMG_20230902_114710.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569595_IMG_20230902_114710.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64f56c18eb1f822256e1d381",
    "name": "externallmg_1693805592193_IMG_20230902_110855.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592193_IMG_20230902_110855.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f2",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569506_IMG_20230902_111915.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f8",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569537_IMG_20230902_111938.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f9",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569541_IMG_20230902_111943.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d2fc",
```

```
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569555_IMG_20230902_112006.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d2fd",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569559_IMG_20230902_112016.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c18eb1f822256e1d37a",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592157_terrace_area_corved_into_bed_room____2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f56c01eb1f822256e1d301",
    "name": "Living Room",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569583_IMG_20230902_114203.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "722.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64ef0951eb1f822256dcae94",
"ownerName": "Shri. Bhalku Parbatbhai Karangia & Shri. Shailesh Parbatbhai
Karangia",
"ownerPhoneNo": "9969768996",
"appAddress": "flat no 1402\ncharkopRavi co operative society Ltd\nkandivali w
\nMumbai 400 067\n",
"remark": "value confirm to \nMr Rajesh sir\n9321105314 \nTop op Loan\nAll
documents in Mumbai id ",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e5",
      "label": "Allotment Letter"
    },
    "inputs": {
      "documentDate": "15/12/2012",
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Charkop Ravi Co-Op. Hsg. Soc. Ltd",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      }
    }
  },

```

```
    "Allottee": "Shri. Bhalku Parbatbhai Karangia & Shri. Shailesh Parbatbhai Karangia"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "294677",
  "path": "cases/64ef0951eb1f822256dcae94/
document_1693801916208_Agreement_8.pdf",
  "fileName": "document_1693801916208_Agreement_8.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/04/2010",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CHE / A-4696 / BP (WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1693920008780_Commencement_Certificate.pdf",
  "path": "cases/64ef0951eb1f822256dcae94/
document_1693920008780_Commencement_Certificate.pdf",
  "id": "688082",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Tue Sep 05 2023 18:50:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/07/2020",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
  },
}
```

```
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "MH / EE / (B.P.) / GM ./ MHADA -76 / 501 / 2020"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693920136884_OccupationCertificate.pdf",
"path": "cases/64ef0951eb1f822256dcae94/
document_1693920136884_OccupationCertificate.pdf",
"id": "223000",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Sep 05 2023 18:52:17 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003477",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "208839",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 30 2023 14:48:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Bhalku Parbatbhai Karangia & Shri. Shailesh Parbatbhai Karangia",
    "phone": "9969768996",
    "ownershipShare": "",
    "email": "",
    "id": "392030"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "226694",
    "name": "Bedroom",
    "length": "8.92",
```

```
"length1": "8",
"length2": "11",
"width": "15.75",
"width1": "15",
"width2": "9",
"totalArea": "140.44",
"images": [],
"extraAreas": [],
"finalArea": "140.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Living Room",
  "length": "19.50",
  "length1": "19",
  "length2": "6",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "188.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "188.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Dining Area",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "25.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.62"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "23.64",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "16.67",
  "length1": "16",
  "length2": "8",
  "width": "10.33",
  "width1": "10",
  "width2": "4",
  "totalArea": "172.22",
  "images": [],
  "finalArea": "172.22",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
```

```
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "18.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "25.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.94"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "15.67",
  "width1": "15",
  "width2": "8",
  "totalArea": "147.53",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "64f582a8eb1f822256e21d0d",
      "name": "Bedroom",
      "extraAreaType": "Add",
      "length": "6.67",
      "length1": "6",
      "length2": "8",
      "width": "3.17",
      "width1": "3",
      "width2": "2",
      "totalArea": "21.11"
    }
  ],
  "finalArea": "168.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
```



```
"totalArea": "68.01",
"images": [],
"extraAreas": [],
"finalArea": "68.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Dry Balcony",
  "length": "",
  "length1": "3",
  "length2": "4",
  "width": "",
  "width1": "7",
  "width2": "4",
  "totalArea": "24.44",
  "images": [],
  "finalArea": "24.44",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "name": {
      "value": "Terrace",
      "label": "Terrace"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "12",
    "length2": "10",
    "length": "12.83",
    "width1": "15",
    "width2": "9",
    "width": "15.75",
    "totalArea": "202.12",
    "percentageBeforeTotal": "202.12",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
```

```
"finalArea": "202.12"
},
{
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "8",
  "length2": "4",
  "length": "8.33",
  "width1": "4",
  "width2": "7",
  "width": "4.58",
  "totalArea": "38.19",
  "percentageBeforeTotal": "38.19",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "38.19"
},
{
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "7",
  "length2": "2",
  "length": "7.17",
  "width1": "4",
  "width2": "2",
  "width": "4.17",
  "totalArea": "29.86",
  "percentageBeforeTotal": "29.86",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
```

```
"finalArea": "29.86"
},
{
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "10",
  "length2": "6",
  "length": "10.50",
  "width1": "2",
  "width2": "8",
  "width": "2.67",
  "totalArea": "28.00",
  "percentageBeforeTotal": "28.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "28"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1246aa6d152c1801b2e5",
      "label": "Allotment Letter"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "887086",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "722",
    "squareMeterArea": "67.08",
    "docFinalBuiltUp": "866.4",
    "docFinalBuiltUpSquareMeter": "80.496",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "20",
    "docFinalSaleable": "1039.68",
```

```
    "docFinalSaleableSquareMeter": "96.59519999999999"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64f7223deb1f822256e4da7a",
    "id": "1",
    "property": "Flat",
    "area": "1100",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "5",
    "source": "magic_bricks",
    "expectedPrice": "23500000",
    "expectedRate": "21363.64",
    "builtUpExpectedRate": "17803.03",
    "image": "cases/64ef0951eb1f822256dcae94/
indicator_1693917757217_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64f7229beb1f822256e4e0da",
    "id": "2",
    "property": "Flat",
    "area": "450",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "12",
    "source": "magic_bricks",
    "expectedPrice": "10000000",
    "expectedRate": "22222.22",
    "builtUpExpectedRate": "18518.52",
    "image": "cases/64ef0951eb1f822256dcae94/
indicator_1693917851257_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64f722efeb1f822256e4e205",
    "id": "3",
    "property": "Flat",
```

```
"area": "660",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "7",
"source": "magic_bricks",
"expectedPrice": "15000000",
"expectedRate": "22727.27",
"builtUpExpectedRate": "18939.39",
"image": "cases/64ef0951eb1f822256dcae94/
indicator_1693917935905_Image.png"
},
{
  "printlnReport": true,
  "_id": "64f7233feb1f822256e4e2df",
  "id": "4",
  "property": "Flat",
  "area": "456",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
  "source": "magic_bricks",
  "expectedPrice": "10500000",
  "expectedRate": "23026.32",
  "builtUpExpectedRate": "19188.60",
  "image": "cases/64ef0951eb1f822256dcae94/
indicator_1693918015386_Image.png"
},
{
  "printlnReport": true,
  "_id": "64f723c4eb1f822256e4e2ff",
  "id": "5",
  "property": "Flat",
  "area": "741.85",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "3",
  "source": "Index_no.2",
  "expectedPrice": "12200000",
  "expectedRate": "16445.37",
  "builtUpExpectedRate": "12200000",
```

```
    "image": "cases/64ef0951eb1f822256dcae94/
indicator_1693918148203_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f2",
    "name": "externallmg_1693805569506_IMG_20230902_111915.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569506_IMG_20230902_111915.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f3",
    "name": "externallmg_1693805569511_IMG_20230902_111917.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569511_IMG_20230902_111917.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f4",
    "name": "externallmg_1693805569516_IMG_20230902_111924.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569516_IMG_20230902_111924.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f5",
    "name": "externallmg_1693805569522_IMG_20230902_111925.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569522_IMG_20230902_111925.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f6",
    "name": "externallmg_1693805569528_IMG_20230902_111926.jpg",
```

```
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569528_IMG_20230902_111926.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f7",
    "name": "externallmg_1693805569534_IMG_20230902_111932.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569534_IMG_20230902_111932.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f8",
    "name": "externallmg_1693805569537_IMG_20230902_111938.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569537_IMG_20230902_111938.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2f9",
    "name": "externallmg_1693805569541_IMG_20230902_111943.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569541_IMG_20230902_111943.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2fa",
    "name": "externallmg_1693805569545_IMG_20230902_111949.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569545_IMG_20230902_111949.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c01eb1f822256e1d2fb",
    "name": "externallmg_1693805569550_IMG_20230902_111950.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569550_IMG_20230902_111950.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d2fc",
  "name": "externallmg_1693805569555_IMG_20230902_112006.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569555_IMG_20230902_112006.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d2fd",
  "name": "externallmg_1693805569559_IMG_20230902_112016.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569559_IMG_20230902_112016.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d2fe",
  "name": "externallmg_1693805569563_IMG_20230902_112018.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569563_IMG_20230902_112018.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d2ff",
  "name": "externallmg_1693805569571_IMG_20230902_112022.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569571_IMG_20230902_112022.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d300",
  "name": "externallmg_1693805569577_IMG_20230902_112023.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569577_IMG_20230902_112023.jpg",
  "orientation": "portrait"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d301",
  "name": "externallmg_1693805569583_IMG_20230902_114203.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569583_IMG_20230902_114203.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d302",
  "name": "externallmg_1693805569587_IMG_20230902_114209.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569587_IMG_20230902_114209.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d303",
  "name": "externallmg_1693805569590_IMG_20230902_114708.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569590_IMG_20230902_114708.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d304",
  "name": "externallmg_1693805569595_IMG_20230902_114710.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569595_IMG_20230902_114710.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c01eb1f822256e1d305",
  "name": "externallmg_1693805569601_IMG_20230902_114712.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805569601_IMG_20230902_114712.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d378",
  "name": "externallmg_1693805592146_IMG_20230902_114718.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592146_IMG_20230902_114718.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d379",
  "name":
"externallmg_1693805592153_terrace_area_corved_into_bed_room___1.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592153_terrace_area_corved_into_bed_room___1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37a",
  "name":
"externallmg_1693805592157_terrace_area_corved_into_bed_room___2.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592157_terrace_area_corved_into_bed_room___2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37b",
  "name":
"externallmg_1693805592163_terrace_area_corved_into_bed_room___3.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592163_terrace_area_corved_into_bed_room___3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37c",
  "name":
"externallmg_1693805592167_terrace_area_corved_into_bed_room___4.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592167_terrace_area_corved_into_bed_room___4.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37d",
  "name":
  "externallmg_1693805592174_terrace_area_corved_into_bed_room___5.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592174_terrace_area_corved_into_bed_room___5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37e",
  "name":
  "externallmg_1693805592178_terrace_area_corved_into_bed_room___6.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592178_terrace_area_corved_into_bed_room___6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d37f",
  "name":
  "externallmg_1693805592180_terrace_area_corved_into_bed_room___7.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592180_terrace_area_corved_into_bed_room___7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d380",
  "name": "externallmg_1693805592190_IMG_20230902_110852.jpg",
  "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592190_IMG_20230902_110852.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f56c18eb1f822256e1d381",
  "name": "externallmg_1693805592193_IMG_20230902_110855.jpg",
```

```
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592193_IMG_20230902_110855.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c18eb1f822256e1d382",
    "name": "externallmg_1693805592198_IMG_20230902_110859.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592198_IMG_20230902_110859.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c18eb1f822256e1d383",
    "name": "externallmg_1693805592201_IMG_20230902_110932.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_1693805592201_IMG_20230902_110932.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c18eb1f822256e1d384",
    "name": "externallmg_r_1693805592186_20230904_100639.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_r_1693805592186_20230904_100639.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f56c18eb1f822256e1d385",
    "name": "externallmg_r_1693805592183_20230903_230200.jpg",
    "path": "cases/64ef0951eb1f822256dcae94/
externallmg_r_1693805592183_20230903_230200.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet 1.xlsx",
    "filename": "1693917328007_Calculation_Sheet_1.xlsx",
```

```
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693917328007_Calculation_Sheet_1.xlsx",
    "size": "16124",
    "createdAt": "Tue Sep 05 2023 18:05:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1693917328008_igr1.pdf",
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693917328008_igr1.pdf",
    "size": "407613",
    "createdAt": "Tue Sep 05 2023 18:05:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "OccupationCertificate.pdf",
    "filename": "1693917328019_OccupationCertificate.pdf",
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693917328019_OccupationCertificate.pdf",
    "size": "164760",
    "createdAt": "Tue Sep 05 2023 18:05:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "plan.pdf",
    "filename": "1693917328025_plan.pdf",
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693917328025_plan.pdf",
    "size": "3342624",
    "createdAt": "Tue Sep 05 2023 18:05:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1693917328082_Summary_Sheet.xlsx",
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693917328082_Summary_Sheet.xlsx",
    "size": "2395821",
    "createdAt": "Tue Sep 05 2023 18:05:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Site Details.pdf",
    "filename": "1693921035109_Site_Details.pdf",
    "path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693921035109_Site_Details.pdf",
```

```
"size": "95110",
"createdAt": "Tue Sep 05 2023 19:07:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Previous Valuation Report.pdf",
"filename": "1693921086054_Previous_Valuation_Report.pdf",
"path": "cases/64ef0951eb1f822256dcae94/
processingDocuments/1693921086054_Previous_Valuation_Report.pdf",
"size": "553068",
"createdAt": "Tue Sep 05 2023 19:08:06 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "64f5690ceb1f822256e1ca6d",
"note": "Required Approved Plan & OC",
"taskId": "64ef1535eb1f822256dcd4b5",
"createdAt": "2023-09-04T05:20:12.147Z"
}
],
"createdAt": "2023-08-30T09:18:09.131Z",
"updatedAt": "2023-09-06T04:53:20.251Z",
"__v": 0,
"fullAddress": "Residential Flat No. 1402, 14th Floor, Wing - A, Charkop Ravi Co-Op.
Hsg. Soc. Ltd., Plot No. 35, RSC - 24, MHADA Layout, Village - Charkop, Taluka -
Borivali, District - Mumbai Suburban, PIN - 400 067, State - Maharashtra, India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Ms. Pioni S. Karangia ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```

"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Daughter of Shri. Shailesh Parbatbhai Karangia",
"siteVisitContactNo": "8828088334",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining Area + 2
Passage + 2 Toilet + Dry Balcony",
"carpetTotal": "883.87",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "298.17",
"builtupPercentage": "20",
"finalBuiltupArea": "1060.64",
"finalCarpetArea": "883.87",
"finalSalableArea": "1272.77",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 883.87\nTerrace Area in Sq. Ft. =
298.17\n(Area as per actual site measurement)",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Allotment Letter",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 722.00",
"buildingServicesRate": "2700",
"flatRate": "21200",
"landOtherRate": "18500",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Wed Sep 06 2023 09:54:18 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-09-02"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	8'11"	15'9"	140.44
Living Room	19'6"	9'8"	188.50
Dining Area	3'5"	7'6"	25.62
Passage	7'8"	3'1"	23.64

Bedroom	16'8"	10'4"	172.22
Toilet	7'00"	4'00"	28.00
Passage	4'3"	4'4"	18.42
Toilet	6'11"	3'9"	25.94
Bedroom	9'5"	15'8"	147.53
Kitchen	9'10"	6'11"	68.01
Dry Balcony	3'4"	7'4"	24.44
Other Composition :			
Terrace	12'10"	15'9"	202.12
Terrace	8'4"	4'7"	38.19
Terrace	7'2"	4'2"	29.86
Terrace	10'6"	2'8"	28.00