

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "64d1d989dc9f3034f301db35",
    "firstName": "Anagha",
    "lastName": "Ghanekar",
    "mobileNo": "",
    "workMobileNo": "9892850594",
    "email": "Anagha@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4350000",
    "discussWithPerson": "Anagha",
    "expectedFees": 2175,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60b7189d2ffdf65bcd65882b",
"role": "PICKUPPERSON",
"firstName": "Ravindra",
"email": "ravindrakasare186@gmail.com",
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627362b3afd7d55eddee1ee7",
"role": "SITEENGINEER",
"firstName": "Vicky ",
"email": "vicky@vastukala.org",
"lastName": "Bhor",
"mobileNo": "9004386288",
"designation": "",
"shortName": "VB",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": ""
}
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.99642342245686",
  "longitude": "73.10511316968547"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10511316968547,
    18.99642342245686
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-09-02T03:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Panvel",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Jindal Residency ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "C",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "745",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "409",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```

    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Panvel_Municipal_Corporation",
    "label": "Panvel Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - A & B",
    "west": "Open Plot",
    "south": "Open Plot ",
    "east": "Internal Road & Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details is not available",
    "west": "Details is not available",
    "south": "Details is not available",
    "east": "Details is not available"
  },
  "extraDetailOfProperty": "Details is not available"
},
"compositeRate": {
  "remark": "As per actual measurement Carpet area is 447.59 Sq. Ft. (including Dry Balcony Area + Terrace Area) is more than carpet area mentioned in the Agreement. We have considered the area mentioned in the documents. Hence to give proper weightage to the value of the property, higher rate considered",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",

```

```
"rate": "65300",
"landRate": "23900",
"igrImage": "cases/64f1f77eeb1f822256e029af/igr_1693824708853_Image.png",
"squareMeterGuideLineRate": "65300.00",
"squareFeetGuideLineRate": "6067.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "5874.00",
  "squareFeetGuideLineRate": "5874.00",
  "squareMeterGuideLineRate": "63230.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "11,500",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "Details is not available",
  "meterCardHolderName": "Details is not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per PMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "No",
"label": "No"
},
"carParking": "Stilt Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2020",
"fullDate": "1/1/2020"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
}
```

```
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
```

```
"label": "Information Not Available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "3",
"totalLifeBuilding": "60",
"estimatedAge": "57",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "9"
},
"finalPlinthArea": {
  "area": "320.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64f1f77eeb1f822256e029af/
routeMap_1693830346662_Image.png",
  "routeLat": "18.996004",
  "routeLng": "73.105106",
  "stationName": "Khandeshwar",
  "routeDistance": "4.00 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
}
```



```
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "2kzzal",
    "name": "2kzzal",
    "image": "cases/64f1f77eeb1f822256e029af/
routeMap_1693830244427_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5529000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
```

```
"finalValue": "5529000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1880267.00",
  "selectedBuildUpValue": "320.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "64f5a554eb1f822256e25fef",
    "name": "externalmg_1693820244187_IMG_20230904_36625.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalmg_1693820244187_IMG_20230904_36625.jpg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64f5a554eb1f822256e25fed",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externalmg_1693820244181_IMG_20230904_4271.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a554eb1f822256e25ff8",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externalmg_1693820244206_IMG_20230904_40128.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e2605c",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externalmg_1693820262142_IMG_20230904_41800.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e2605b",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externalmg_1693820262139_IMG_20230904_41526.jpg",
    "orientation": "landscape"
  },
  {
```

```
    "status": false,
    "_id": "64f5a554eb1f822256e25ff7",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244205_IMG_20230904_39853.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e2605e",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262145_IMG_20230904_42654.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e26063",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262339_IMG_20230904_37620.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e26067",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_r_1693820262179_IMG20230904131957.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f5a566eb1f822256e26060",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262150_IMG_20230904_43213.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f5a554eb1f822256e25fef",
    "name": "Living Room",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244187_IMG_20230904_36625.jpg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "64f5a554eb1f822256e25ff1",
      "name": "Living Room",
      "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244192_IMG_20230904_37288.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18744",
    "max": "18947"
  },
  "builtUpRateRange": {
    "min": "17041",
    "max": "17225"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "291.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "READYFORCHECKER",
"_id": "64f1f77eeb1f822256e029af",
"ownerName": "Mr. Shivaji Raghunath Patil & Mrs. Archana Shivaji Patil",
"ownerPhoneNo": "9930228836",
"appAddress": "flat no 409 4th floor C wing jindal Resdincy village kasbe panvel ",
"remark": "ssl pinky / vanjana madam ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "09/03/2021",
      "from": {
        "value": "The_Promoter",
        "label": "The Promoter"
      },
      "The_Promoter": "M/s. Jindal Builders And Developers ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Shivaji Raghunath Patil & Mrs. Archana Shivaji Patil"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "262926",
    "path": "cases/64f1f77eeb1f822256e029af/
document_1693579077667_New_Doc_09012023_1712.pdf",
    "fileName": "document_1693579077667_New_Doc_09012023_1712.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "30/10/2020",
      "nameOfApprovingAuthority": {
        "value": "Panvel_Municipal_Corporation",
        "label": "Panvel Muncipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  }
]
```

```
    },
    "Document_No": "2020 / PMC / TP / BP / 1441 / 2020"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693825579525_721207.pdf",
  "path": "cases/64f1f77eeb1f822256e029af/document_1693825579525_721207.pdf",
  "id": "339681",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Sep 04 2023 16:36:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "12/04/2018",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "P52000016028"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693828208204_696919.pdf",
  "path": "cases/64f1f77eeb1f822256e029af/document_1693828208204_696919.pdf",
  "id": "279829",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Sep 04 2023 17:20:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "18/07/2022",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    }
  },
  "Purchaser": "Mr. Shivaji Raghunath Patil & Mrs. Archana Shivaji Patil",
  "number": {
    "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "106"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1693828297758_746857.pdf",
"path": "cases/64f1f77eeb1f822256e029af/document_1693828297758_746857.pdf",
"id": "548000",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Sep 04 2023 17:21:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "20/08/2023",
    "nameOfApprovingAuthority": {
      "value": "MSEDCL",
      "label": "MSEDCL"
    },
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Shivaji Raghunath Patil",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "028511382060"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693828401844_155245.pdf",
  "path": "cases/64f1f77eeb1f822256e029af/document_1693828401844_155245.pdf",
  "id": "941997",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Sep 04 2023 17:23:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003526",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
```

```
{
  "id": "962595",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Fri Sep 01 2023 20:08:54 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mr. Shivaji Raghunath Patil & Mrs. Archana Shivaji Patil",
    "phone": "9930228836",
    "ownershipShare": "",
    "email": "",
    "id": "293848"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "",
    "length1": "5",
    "length2": "5",
    "width": "",
    "width1": "2",
    "width2": "9",
    "totalArea": "14.90",
    "images": [],
    "finalArea": "14.90",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "8",
    "name": "Living Room",
    "length": "15.50",
    "length1": "15",
```

```
"length2": "6",
"width": "9.25",
"width1": "9",
"width2": "3",
"totalArea": "143.37",
"images": [],
"finalArea": "143.37",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "11.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "96.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.75"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "W.C",
"length": "3.67",
"length1": "3",
"length2": "8",
"width": "3.17",
"width1": "3",
"width2": "2",
"totalArea": "11.61",
"images": [],
"extraAreas": [],
"finalArea": "11.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "26.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "6.92",
```

```
"width1": "6",
"width2": "11",
"totalArea": "45.53",
"images": [],
"extraAreas": [],
"finalArea": "45.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "13.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.61"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Terrace",
      "label": "Terrace"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "10",
    "length2": "2",
    "length": "10.17",
    "width1": "6",
    "width2": "11",
```



```
"width": "6.92",
"totalArea": "70.32",
"percentageBeforeTotal": "70.32",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "70.32"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Dry_balcony",
    "label": "Dry Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "4",
  "length": "2.33",
  "width1": "5",
  "width2": "10",
  "width": "5.83",
  "totalArea": "13.61",
  "percentageBeforeTotal": "13.61",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.61"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "27.03",
    "totalAreaDocument": "291",
    "docBuiltpUpPercentage": "10",
    "docFinalBuiltpUp": "320.10",
    "docFinalBuiltpUpSquareMeter": "29.74",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "723312"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64f5b6e4eb1f822256e2cf10",
    "property": "Flat",
    "area": "285",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "5400000",
    "expectedRate": "18947.37",
    "builtUpExpectedRate": "17224.88",
    "image": "cases/64f1f77eeb1f822256e029af/indicator_1693823467206_Image.png",
    "squareMeter": "26.48",
    "id": "836906"
  },
  {
    "printlnReport": true,
    "_id": "64f5b6e4eb1f822256e2cf11",
    "property": "Flat",
    "area": "266",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "4986000",
    "expectedRate": "18744.36",
    "builtUpExpectedRate": "17040.33",
    "image": "cases/64f1f77eeb1f822256e029af/indicator_1693823719008_Image.png",
```

```
"squareMeter": "24.71",
"id": "640302"
},
{
  "printlnReport": true,
  "_id": "64f5b6e4eb1f822256e2cf12",
  "property": "Flat",
  "area": "285",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "5400000",
  "expectedRate": "18947.37",
  "builtUpExpectedRate": "17224.88",
  "image": "cases/64f1f77eeb1f822256e029af/indicator_1693823853146_Image.png",
  "squareMeter": "26.48",
  "id": "345402"
},
{
  "printlnReport": true,
  "_id": "64f5cf64eb1f822256e3480b",
  "id": "4",
  "property": "Flat",
  "area": "309",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "square_yards",
  "expectedPrice": "6500000",
  "expectedRate": "21035.60",
  "builtUpExpectedRate": "17529.67",
  "image": "cases/64f1f77eeb1f822256e029af/indicator_1693831012792_Image.png"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a554eb1f822256e25feb",
    "name": "externalImg_1693820244177_IMG_20230904_3962.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalImg_1693820244177_IMG_20230904_3962.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25fec",
  "name": "externallmg_1693820244179_IMG_20230904_4138.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244179_IMG_20230904_4138.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25fed",
  "name": "externallmg_1693820244181_IMG_20230904_4271.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244181_IMG_20230904_4271.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25fee",
  "name": "externallmg_1693820244183_IMG_20230904_36260.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244183_IMG_20230904_36260.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25fef",
  "name": "externallmg_1693820244187_IMG_20230904_36625.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244187_IMG_20230904_36625.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff0",
  "name": "externallmg_1693820244189_IMG_20230904_36884.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244189_IMG_20230904_36884.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff1",
  "name": "externallmg_1693820244192_IMG_20230904_37288.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244192_IMG_20230904_37288.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff2",
  "name": "externallmg_1693820244194_IMG_20230904_37962.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244194_IMG_20230904_37962.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff3",
  "name": "externallmg_1693820244196_IMG_20230904_38365.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244196_IMG_20230904_38365.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff4",
  "name": "externallmg_1693820244199_IMG_20230904_38681.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244199_IMG_20230904_38681.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff5",
  "name": "externallmg_1693820244201_IMG_20230904_39321.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244201_IMG_20230904_39321.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff6",
  "name": "externallmg_1693820244202_IMG_20230904_39582.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244202_IMG_20230904_39582.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff7",
  "name": "externallmg_1693820244205_IMG_20230904_39853.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244205_IMG_20230904_39853.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff8",
  "name": "externallmg_1693820244206_IMG_20230904_40128.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244206_IMG_20230904_40128.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a554eb1f822256e25ff9",
  "name": "externallmg_1693820244208_IMG_20230904_40440.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820244208_IMG_20230904_40440.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a566eb1f822256e26059",
  "name": "externallmg_1693820262136_IMG_20230904_40733.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262136_IMG_20230904_40733.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2605a",
    "name": "externallmg_1693820262138_IMG_20230904_41262.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262138_IMG_20230904_41262.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2605b",
    "name": "externallmg_1693820262139_IMG_20230904_41526.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262139_IMG_20230904_41526.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2605c",
    "name": "externallmg_1693820262142_IMG_20230904_41800.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262142_IMG_20230904_41800.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2605d",
    "name": "externallmg_1693820262144_IMG_20230904_42313.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262144_IMG_20230904_42313.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2605e",
    "name": "externallmg_1693820262145_IMG_20230904_42654.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externallmg_1693820262145_IMG_20230904_42654.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64f5a566eb1f822256e2605f",
    "name": "externalImg_1693820262147_IMG_20230904_42944.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalImg_1693820262147_IMG_20230904_42944.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e26060",
    "name": "externalImg_1693820262150_IMG_20230904_43213.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalImg_1693820262150_IMG_20230904_43213.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e26061",
    "name": "externalImg_1693820262153_IMG_20230904_43506.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalImg_1693820262153_IMG_20230904_43506.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e26062",
    "name": "externalImg_1693820262322_Screenshot_2023090413215957_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/externalImg_1693820262322_Screensho
t_2023090413215957_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e26063",
    "name": "externalImg_1693820262339_IMG_20230904_37620.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalImg_1693820262339_IMG_20230904_37620.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "64f5a566eb1f822256e26064",
  "name": "externalimg_1693820262341_IMG_20230904_43830.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externalimg_1693820262341_IMG_20230904_43830.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a566eb1f822256e26065",
  "name": "externalimg_r_1693820262218_IMG20230904132004.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262218_IMG20230904132004.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a566eb1f822256e26066",
  "name": "externalimg_r_1693820262243_IMG20230904145932.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262243_IMG20230904145932.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a566eb1f822256e26067",
  "name": "externalimg_r_1693820262179_IMG20230904131957.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262179_IMG20230904131957.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f5a566eb1f822256e26068",
  "name": "externalimg_r_1693820262156_IMG20230904130401.jpg",
  "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262156_IMG20230904130401.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "64f5a566eb1f822256e26069",
    "name": "externalimg_r_1693820262298_IMG20230904145947.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262298_IMG20230904145947.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f5a566eb1f822256e2606a",
    "name": "externalimg_r_1693820262266_IMG20230904145941.jpg",
    "path": "cases/64f1f77eeb1f822256e029af/
externalimg_r_1693820262266_IMG20230904145941.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- patil.xlsx",
    "filename": "1693824758825_Calculation_2_patil.xlsx",
    "path": "cases/64f1f77eeb1f822256e029af/
processingDocuments/1693824758825_Calculation_2_patil.xlsx",
    "size": "16030",
    "createdAt": "Mon Sep 04 2023 16:22:38 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1693824758827_igr1.pdf",
    "path": "cases/64f1f77eeb1f822256e029af/
processingDocuments/1693824758827_igr1.pdf",
    "size": "100293",
    "createdAt": "Mon Sep 04 2023 16:22:38 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1693824758831_reference_report.pdf",
    "path": "cases/64f1f77eeb1f822256e029af/
processingDocuments/1693824758831_reference_report.pdf",
    "size": "2401614",
    "createdAt": "Mon Sep 04 2023 16:22:38 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
```

```
"originalname": "Summary - patil.xlsx",
"filename": "1693824758871_Summary__patil.xlsx",
"path": "cases/64f1f77eeb1f822256e029af/
processingDocuments/1693824758871_Summary__patil.xlsx",
"size": "7802328",
"createdAt": "Mon Sep 04 2023 16:22:38 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"remarks": [],
"createdAt": "2023-09-01T14:38:54.761Z",
"updatedAt": "2023-09-04T12:37:10.541Z",
"__v": 0,
"invoiceId": "64f1f77eeb1f822256e029b8",
"fullAddress": "Residential Flat No. 409, 4th Floor, Wing - C, Jindal Residency , Village
- Panvel, Taluka - Panvel, District - Raigad, Navi Mumbai, PIN - 410 206, State -
Maharashtra, Country - India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Shivaji Raghunath Patil ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930228836",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 291.00",
"flatRate": "19000",
"landOtherRate": "16500",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 3 Passage + W.C +
Bathroom",
"carpetTotal": "363.6600000000001",
"otherCarpetTotal": "83.93",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "83.93",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "492.35",
```

"finalCarpetArea": "447.59",
 "finalSalableArea": "541.58",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 364.00\nTerrace Area in Sq. Ft. = 70.00\nDry Balcony Area in Sq. Ft. = 14.00",
 "finalSaleablePercentage": "",
 "reportGeneratedDate": "Mon Sep 04 2023 17:58:12 GMT+0530 (India Standard Time)",
 "siteVisitDate": "2023-09-04"

Name	Length	Width	Total
Composition :			
Passage	5'5"	2'9"	14.90
Living Room	15'6"	9'3"	143.37
Passage	2'8"	4'5"	11.78
Bedroom	10'9"	9'00"	96.75
W.C	3'8"	3'2"	11.61
Bathroom	6'8"	3'11"	26.11
Kitchen	6'7"	6'11"	45.53
Passage	4'8"	2'11"	13.61
Other Composition :			
Terrace	10'2"	6'11"	70.32
Dry Balcony	2'4"	5'10"	13.61