

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64bb68afa87c525d5c04ab8b",
    "firstName": "Sayali",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6500000",
    "discussWithPerson": "Sayali",
    "expectedFees": 3250,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fd2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddedd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
```

```
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.254172257340276",
  "longitude": "73.14455959140483"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.14455959140483,
```

```
19.254172257340276
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-09-04T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-04T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-04T03:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gauripada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "13",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ekdant, Sawalaram Srushti Complex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bhoirwadi",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```



```
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near RTO",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "34/1",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1/11",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Ceiling",
  "label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Other Residential Building",
    "south": "Wing - B",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
```

```
"depreciationPercentage": "9",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "10457",
"depreciatedBuildingRate": "2457"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "72900",
  "landRate": "20400",
  "igrImage": "cases/64f32fc7eb1f822256e17260/igr_1693896279398_Image.png",
  "squareMeterGuideLineRate": "80190.00",
  "squareFeetGuideLineRate": "7450.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "7117.00",
  "squareFeetGuideLineRate": "7117.00",
  "squareMeterGuideLineRate": "76603.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "13500.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt / Open Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2017",
"fullDate": "1/1/2017"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
}
```

```
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
```

```
"label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "750.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64f32fc7eb1f822256e17260/
routeMap_1693914216136_Image.png",
    "routeLat": "19.254417",
    "routeLng": "73.144556",
    "stationName": "Kalyan",
```



```
"routeDistance": "3.9 KM"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "5ia6zd",
    "name": "5ia6zd",
    "image": "cases/64f32fc7eb1f822256e17260/
routeMap_1693914093017_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6535625.00",
"finalValue": "6535625.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Sep 05 2023 18:09:42 GMT+0530 (India Standard Time)",
  "number": "2302417",
  "dayCount": "11",
  "monthCount": "61",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "5337750.00",
  "selectedBuildUpValue": "750.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64f6af65eb1f822256e37bab",
      "name":
"externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
      "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64f6af76eb1f822256e37c13",
      "name":
"externallmg_1693888374352_WhatsApp_Image_20230905_at_94601_AM.jpeg",
      "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374352_WhatsApp_Image_20230905_at_94601_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64f6af76eb1f822256e37c0a",
      "name":
"externallmg_1693888374331_WhatsApp_Image_20230905_at_94559_AM.jpeg",
      "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374331_WhatsApp_Image_20230905_at_94559_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "status": false,
    "_id": "64f6af76eb1f822256e37c07",
    "name":
"externallmg_1693888374319_WhatsApp_Image_20230905_at_94558_AM_5.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374319_WhatsApp_Image_20230905_at_94558_AM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f6af65eb1f822256e37baa",
    "name":
"externallmg_1693888357700_WhatsApp_Image_20230905_at_94557_AM_1.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357700_WhatsApp_Image_20230905_at_94557_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c03",
    "name":
"externallmg_1693888374306_WhatsApp_Image_20230905_at_94558_AM_1.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374306_WhatsApp_Image_20230905_at_94558_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f6af65eb1f822256e37bab",
    "name":
"externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c04",
    "name":
"externallmg_1693888374309_WhatsApp_Image_20230905_at_94558_AM_2.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374309_WhatsApp_Image_20230905_at_94558_AM_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
}
],
"compositionImages": [
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c0c",
    "name": "Kitchen",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374335_WhatsApp_Image_20230905_at_94601_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c12",
    "name": "Flowered Area",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374348_WhatsApp_Image_20230905_at_94601_AM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c0b",
    "name": "Passage",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374333_WhatsApp_Image_20230905_at_94601_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f6af76eb1f822256e37c10",
    "name": "Passage",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374344_WhatsApp_Image_20230905_at_94601_AM_6.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9564",
    "max": "10949"
  },
  "builtUpRateRange": {
    "min": "7970",
    "max": "9125"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "625.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64f32fc7eb1f822256e17260",
"ownerName": "Mr. Sunil Shankar Kamathe & Mrs. Nayana Sunil Kamathe",
"ownerPhoneNo": "9833400240",
"appAddress": "1302, 13th flr., C wing, \"Ekdant\" sawalaram shrurhti, Gauripada, Kalyan (west) 412301",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "16/07/2019",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s Shree Sai Builders and Developers",
    }
  }
]
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Mr. Sunil Shankar Kamathe & Mrs. Nayana Sunil Kamathe"
},
"isHardCopy": false,
"displayStatus": true,
"id": "637933",
"path": "cases/64f32fc7eb1f822256e17260/
document_1693658973760_New_Doc_20190724_134134.pdf",
"fileName": "document_1693658973760_New_Doc_20190724_134134.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "31/07/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700002398"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693912898396_135793.pdf",
  "path": "cases/64f32fc7eb1f822256e17260/
document_1693912898396_135793.pdf",
  "id": "195637",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Sep 05 2023 16:51:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "27/07/2017",
```

```
"nameOfApprovingAuthority": {
  "value": "Kalyan_Dombivli_Municipal_Corporation",
  "label": "Kalyan Dombivli Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "KDMC / NRV / CC / KV / OCC / 87 / 17"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693912968592_OC.pdf",
"path": "cases/64f32fc7eb1f822256e17260/document_1693912968592_OC.pdf",
"id": "371238",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Tue Sep 05 2023 16:52:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "03/06/2016",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / KV / 2012-2013/148/83"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693913087280_CC.pdf",
"path": "cases/64f32fc7eb1f822256e17260/document_1693913087280_CC.pdf",
"id": "672709",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Tue Sep 05 2023 16:54:47 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003538",
"createdBy": "6410199a140f140ffc59b58c",
```

```
"caseHistory": [
  {
    "id": "546282",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 02 2023 18:21:19 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sunil Shankar Kamathe & Mrs. Nayana Sunil Kamathe",
    "phone": "9833400240",
    "ownershipShare": "",
    "email": "",
    "id": "181117"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Balcony Area",
    "length": "6.00",
    "length1": "6",
    "length2": "0",
    "width": "2.00",
    "width1": "2",
    "width2": "0",
    "totalArea": "12.00",
    "images": [],
    "finalArea": "12.00",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Balcony Area",
    "length": "10.00",
```

```
"length1": "10",
"length2": "0",
"width": "5.00",
"width1": "5",
"width2": "0",
"totalArea": "50.00",
"images": [],
"finalArea": "50.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "0",
  "width": "12.00",
  "width1": "12",
  "width2": "0",
  "totalArea": "132.00",
  "images": [],
  "finalArea": "132.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "32.00",
  "images": [],
  "finalArea": "32.00",
  "extraAreas": []
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "9.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bathroom",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "24.00",
  "images": [],
  "finalArea": "24.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Dry Balcony",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
```

```
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "24.00",
"images": [],
"extraAreas": [],
"finalArea": "24.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Living Room",
  "length": "16.00",
  "length1": "16",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "144.00",
  "images": [],
  "finalArea": "144.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Flowered Area",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "14.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.00"
},
{
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "72.00",
  "images": [],
  "finalArea": "72.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Flowered Area",
  "length": "",
  "length1": "7",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "21.00",
  "images": [],
  "finalArea": "21.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Kitchen",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
```

```
"width2": "0",
"totalArea": "80.00",
"images": [],
"finalArea": "80.00",
"extraAreas": []
}
],
"otherComposition": [
{
"toBeAdded": {
"label": "Carpet",
"value": "Carpet"
},
"name": {
"value": "Cupboard",
"label": "Cupboard"
},
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
},
"id": "0",
"length1": "3",
"length2": "00",
"length": "3.00",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "6.00",
"percentageBeforeTotal": "6.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "6"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
}
```

```

    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "58.06",
    "totalAreaDocument": "625",
    "docBuiltpUpPercentage": "20",
    "docFinalBuiltpUp": "750.00",
    "docFinalBuiltpUpSquareMeter": "69.68",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "316813"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64f6ce62eb1f822256e3c75e",
    "property": "Flat",
    "area": "766",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "11",
    "source": "Index_no.2",
    "expectedPrice": "7326000",
    "expectedRate": "9563.97",
    "builtUpExpectedRate": "7969.97",
    "image": "cases/64f32fc7eb1f822256e17260/
indicator_1693895973472_Image.png",
    "squareMeter": "71.16",
    "id": "272185"
  },
  {
    "printlnReport": true,
    "_id": "64f6ce62eb1f822256e3c75f",
    "property": "Flat",
    "area": "650",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "3",
    "source": "magic_bricks",
    "expectedPrice": "6500000",

```

```
    "expectedRate": "10000.00",
    "builtUpExpectedRate": "8333.33",
    "image": "cases/64f32fc7eb1f822256e17260/
indicator_1693896032623_Image.png",
    "squareMeter": "60.39",
    "id": "796987"
  },
  {
    "printlnReport": true,
    "_id": "64f6ce62eb1f822256e3c760",
    "property": "Flat",
    "area": "685",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "13",
    "source": "magic_bricks",
    "expectedPrice": "7500000",
    "expectedRate": "10948.91",
    "builtUpExpectedRate": "9124.09",
    "image": "cases/64f32fc7eb1f822256e17260/
indicator_1693896088280_Image.png",
    "squareMeter": "63.64",
    "id": "567459"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af65eb1f822256e37baa",
    "name":
"externallmg_1693888357700_WhatsApp_Image_20230905_at_94557_AM_1.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357700_WhatsApp_Image_20230905_at_94557_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af65eb1f822256e37bab",
    "name":
"externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357705_WhatsApp_Image_20230905_at_94557_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af65eb1f822256e37bac",
    "name":
"externallmg_1693888357710_WhatsApp_Image_20230905_at_94557_AM.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888357710_WhatsApp_Image_20230905_at_94557_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c03",
    "name":
"externallmg_1693888374306_WhatsApp_Image_20230905_at_94558_AM_1.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374306_WhatsApp_Image_20230905_at_94558_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c04",
    "name":
"externallmg_1693888374309_WhatsApp_Image_20230905_at_94558_AM_2.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374309_WhatsApp_Image_20230905_at_94558_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c05",
    "name":
"externallmg_1693888374313_WhatsApp_Image_20230905_at_94558_AM_3.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374313_WhatsApp_Image_20230905_at_94558_AM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c06",
```

```
    "name":
"externallmg_1693888374317_WhatsApp_Image_20230905_at_94558_AM_4.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374317_WhatsApp_Image_20230905_at_94558_AM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c07",
  "name":
"externallmg_1693888374319_WhatsApp_Image_20230905_at_94558_AM_5.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374319_WhatsApp_Image_20230905_at_94558_AM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c08",
  "name":
"externallmg_1693888374325_WhatsApp_Image_20230905_at_94558_AM.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374325_WhatsApp_Image_20230905_at_94558_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c09",
  "name":
"externallmg_1693888374329_WhatsApp_Image_20230905_at_94559_AM_1.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374329_WhatsApp_Image_20230905_at_94559_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0a",
  "name":
"externallmg_1693888374331_WhatsApp_Image_20230905_at_94559_AM.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374331_WhatsApp_Image_20230905_at_94559_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0b",
  "name":
"externallmg_1693888374333_WhatsApp_Image_20230905_at_94601_AM_1.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374333_WhatsApp_Image_20230905_at_94601_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0c",
  "name":
"externallmg_1693888374335_WhatsApp_Image_20230905_at_94601_AM_2.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374335_WhatsApp_Image_20230905_at_94601_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0d",
  "name":
"externallmg_1693888374337_WhatsApp_Image_20230905_at_94601_AM_3.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374337_WhatsApp_Image_20230905_at_94601_AM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0e",
  "name":
"externallmg_1693888374340_WhatsApp_Image_20230905_at_94601_AM_4.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374340_WhatsApp_Image_20230905_at_94601_AM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c0f",
  "name":
"externallmg_1693888374342_WhatsApp_Image_20230905_at_94601_AM_5.jpeg",
```

```
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374342_WhatsApp_Image_20230905_at_94601_AM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c10",
    "name":
"externallmg_1693888374344_WhatsApp_Image_20230905_at_94601_AM_6.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374344_WhatsApp_Image_20230905_at_94601_AM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c11",
    "name":
"externallmg_1693888374346_WhatsApp_Image_20230905_at_94601_AM_7.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374346_WhatsApp_Image_20230905_at_94601_AM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c12",
    "name":
"externallmg_1693888374348_WhatsApp_Image_20230905_at_94601_AM_8.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374348_WhatsApp_Image_20230905_at_94601_AM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6af76eb1f822256e37c13",
    "name":
"externallmg_1693888374352_WhatsApp_Image_20230905_at_94601_AM.jpeg",
    "path": "cases/64f32fc7eb1f822256e17260/
externallmg_1693888374352_WhatsApp_Image_20230905_at_94601_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "64f6af76eb1f822256e37c14",
  "name":
"externalImg_1693888374355_WhatsApp_Image_20230905_at_94602_AM_1.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externalImg_1693888374355_WhatsApp_Image_20230905_at_94602_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6af76eb1f822256e37c15",
  "name":
"externalImg_1693888374357_WhatsApp_Image_20230905_at_94602_AM.jpeg",
  "path": "cases/64f32fc7eb1f822256e17260/
externalImg_1693888374357_WhatsApp_Image_20230905_at_94602_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- sunil.xlsx",
    "filename": "1693908416521_Calculation_2_sunil.xlsx",
    "path": "cases/64f32fc7eb1f822256e17260/
processingDocuments/1693908416521_Calculation_2_sunil.xlsx",
    "size": "16056",
    "createdAt": "Tue Sep 05 2023 15:36:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "doc.pdf",
    "filename": "1693908416522_doc.pdf",
    "path": "cases/64f32fc7eb1f822256e17260/
processingDocuments/1693908416522_doc.pdf",
    "size": "971902",
    "createdAt": "Tue Sep 05 2023 15:36:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1693908416546_igr1.pdf",
    "path": "cases/64f32fc7eb1f822256e17260/
processingDocuments/1693908416546_igr1.pdf",
    "size": "101061",
    "createdAt": "Tue Sep 05 2023 15:36:56 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Previous report - 2019.pdf",
  "filename": "1693908416548_Previous_report__2019.pdf",
  "path": "cases/64f32fc7eb1f822256e17260/
processingDocuments/1693908416548_Previous_report__2019.pdf",
  "size": "6229765",
  "createdAt": "Tue Sep 05 2023 15:36:56 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - sunil.xlsx",
  "filename": "1693908416639_Summary__sunil.xlsx",
  "path": "cases/64f32fc7eb1f822256e17260/
processingDocuments/1693908416639_Summary__sunil.xlsx",
  "size": "5198348",
  "createdAt": "Tue Sep 05 2023 15:36:56 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"remarks": [],
"createdAt": "2023-09-02T12:51:19.117Z",
"updatedAt": "2023-09-05T12:43:10.091Z",
"__v": 0,
"invoiceld": "64f32fc7eb1f822256e17266",
"fullAddress": "Residential Flat No. 1302, 13th Floor, Wing - C, Ekdant, Sawalaram
Srushti Complex, Near RTO, Bhoirwadi, Village - Gauripada, Taluka - Kalyan , District -
Thane, Kalyan (West), 421 301, State - Maharashtra, India",
"updatedAtBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Sunil Shankar Kamathe",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833400240",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
```

"finalValuationAreaString": "Carpet Area in Sq. Ft. = 625.00",
 "flatRate": "10700",
 "landOtherRate": "8000",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Balcony Area +
 Passage + WC + Bathroom + Dry Balcony + 2 Flowered Area",
 "carpetTotal": "614",
 "otherCarpetTotal": "6.00",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "6.00",
 "otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "extendOfSiteRemark": "Carpet Area in Sq. Ft. = 515\nCupboard Area / EP Area in
 Sq. Ft. = 44.00\nOpen Terrace Area in Sq. Ft. = 66.00\nTotal Carpet Area in Sq. Ft. =
 625.00\n(Area as per Agreement)",
 "finalBuiltupArea": "682.00",
 "finalCarpetArea": "620.00",
 "finalSalableArea": "750.20",
 "salablePercentage": "10",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 499.00\nBalcony Area in Sq. Ft.
 = 121.00\nTotal Carpet Area in Sq. Ft. = 620.00\n(Area as per Actual site
 measurement)",
 "toBeAdded": "",
 "finalSaleablePercentage": "",
 "reportGeneratedDate": "Tue Sep 05 2023 18:04:33 GMT+0530 (India Standard
 Time)",
 "siteVisitDate": "2023-09-04"

| Name | Length | Width | Total |
|---------------|--------|-------|--------|
| Composition : | | | |
| Balcony Area | 6'0" | 2'0" | 12.00 |
| Balcony Area | 10'0" | 5'0" | 50.00 |
| Bedroom | 11'0" | 12'0" | 132.00 |
| Passage | 8'0" | 4'0" | 32.00 |
| WC | 3'00" | 3'00" | 9.00 |
| Bathroom | 8'0" | 3'0" | 24.00 |
| Dry Balcony | 3'00" | 8'00" | 24.00 |
| Living Room | 16'0" | 9'0" | 144.00 |
| Flowered Area | 2'00" | 7'00" | 14.00 |

| | | | |
|------------------------|-------|-------|-------|
| Bedroom | 8'0" | 9'0" | 72.00 |
| Flowered Area | 7'0" | 3'0" | 21.00 |
| Kitchen | 8'0" | 10'0" | 80.00 |
| Other Composition : | | | |
| Cupboard | 3'00" | 2'00" | 6.00 |