

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64cb4e070faf29427aca4671"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb4e070faf29427aca4673",
    "firstName": "Nitin ",
    "lastName": "Misal",
    "mobileNo": "",
    "workMobileNo": "9421528220",
    "email": "mcc8134@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5265000",
    "discussWithPerson": "Nitin ",
  }
}
```

```
"expectedFees": 2632.5,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64cb4e070faf29427aca4671",
  "name": "MCC MW 2 Goregaon\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "mcc8134@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Rajnigandha Shopping Centre, 1st Floor, Krishna Vatika Marg, Opp.
Gokuldham Temple, Goregaon (E), Mumbai 400063"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "64c777a8a5c3051014f4dd1f",
    "role": "SITEENGINEER",
    "firstName": "Pratik",
    "email": "pratikjain2277@gmail.com",
    "lastName": "Jain",
    "mobileNo": "9619286285",
    "designation": "",
    "shortName": "Pratik",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
```

```
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.279908853339744",
  "longitude": "72.8592359522094"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8592359522094,
    19.279908853339744
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
}
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhaynder",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "B-47",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Thane",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Girnar Shantinagar CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shanti Nagar",
  "label": false
},
}
```

```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Flat No 102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```



```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
```

```
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64f97ae363830d2aa3b48577",
"ownerName": "Kavita Mahendra Kothari",
"ownerPhoneNo": "8169762800",
"appAddress": "Flat No.102 ,1 St floor, Girnar Shantinagar CHS Ltd Bldg no-B-47, S.V
No - 740 (P) , Village- Bhayander Sector No - 1, Shantinagar Mira road East - 401007",
```



```
{
  "name": "Kavita Mahendra Kothari",
  "phone": "8169762800",
  "ownershipShare": "",
  "email": "",
  "id": "387280"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f10",
    "name":
"externallmg_1695011969249_IMG_20230916_173547_copy_1200x1597.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969249_IMG_20230916_173547_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f11",
    "name":
"externallmg_1695011969281_IMG_20230916_173652_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969281_IMG_20230916_173652_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f12",
    "name":
"externallmg_1695011969307_IMG_20230916_180445_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969307_IMG_20230916_180445_copy_1200x900.jpg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f13",
  "name":
"externallmg_1695011969321_IMG_20230916_180504_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969321_IMG_20230916_180504_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f14",
  "name":
"externallmg_1695011969330_IMG_20230916_180505_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969330_IMG_20230916_180505_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f15",
  "name":
"externallmg_1695011969338_IMG_20230916_180533_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969338_IMG_20230916_180533_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f16",
  "name":
"externallmg_1695011969348_IMG_20230916_180535_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969348_IMG_20230916_180535_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f17",
  "name":
"externallmg_1695011969358_IMG_20230916_180856_copy_1200x1600.jpg",
```

```
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969358_IMG_20230916_180856_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f18",
    "name":
"externallmg_1695011969365_IMG_20230916_173606_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969365_IMG_20230916_173606_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f19",
    "name":
"externallmg_1695011969373_IMG_20230916_173607_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969373_IMG_20230916_173607_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f1a",
    "name":
"externallmg_1695011969382_IMG_20230916_173608_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969382_IMG_20230916_173608_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f1b",
    "name":
"externallmg_1695011969393_IMG_20230916_173630_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969393_IMG_20230916_173630_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6507d481a8e9b70221e90f1c",
  "name":
"externallmg_1695011969402_IMG_20230916_173647_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969402_IMG_20230916_173647_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f1d",
  "name":
"externallmg_1695011969413_IMG_20230916_173648_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969413_IMG_20230916_173648_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f1e",
  "name":
"externallmg_1695011969421_IMG_20230916_173802_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969421_IMG_20230916_173802_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f1f",
  "name":
"externallmg_1695011969429_IMG_20230916_173803_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969429_IMG_20230916_173803_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d481a8e9b70221e90f20",
  "name":
"externallmg_1695011969437_IMG_20230916_180029_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011969437_IMG_20230916_180029_copy_1200x900.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f21",
    "name":
"externallmg_1695011969446_IMG_20230916_180032_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/"
externallmg_1695011969446_IMG_20230916_180032_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f22",
    "name":
"externallmg_1695011969457_IMG_20230916_180033_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/"
externallmg_1695011969457_IMG_20230916_180033_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d481a8e9b70221e90f23",
    "name":
"externallmg_1695011969465_IMG_20230916_180037_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/"
externallmg_1695011969465_IMG_20230916_180037_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f69",
    "name":
"externallmg_1695011990351_IMG_20230916_180429_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/"
externallmg_1695011990351_IMG_20230916_180429_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f6a",
```

```
    "name":  
    "externallmg_1695011990373_IMG_20230916_180431_copy_1200x900.jpg",  
    "path": "cases/64f97ae363830d2aa3b48577/  
externallmg_1695011990373_IMG_20230916_180431_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6507d496a8e9b70221e90f6b",  
    "name":  
    "externallmg_1695011990385_IMG_20230916_180441_copy_1200x900.jpg",  
    "path": "cases/64f97ae363830d2aa3b48577/  
externallmg_1695011990385_IMG_20230916_180441_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6507d496a8e9b70221e90f6c",  
    "name":  
    "externallmg_1695011990397_IMG_20230916_180442_copy_1200x900.jpg",  
    "path": "cases/64f97ae363830d2aa3b48577/  
externallmg_1695011990397_IMG_20230916_180442_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6507d496a8e9b70221e90f6d",  
    "name":  
    "externallmg_1695011990406_IMG_20230916_180456_copy_1200x900.jpg",  
    "path": "cases/64f97ae363830d2aa3b48577/  
externallmg_1695011990406_IMG_20230916_180456_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6507d496a8e9b70221e90f6e",  
    "name":  
    "externallmg_1695011990416_IMG_20230916_180457_copy_1200x900.jpg",  
    "path": "cases/64f97ae363830d2aa3b48577/  
externallmg_1695011990416_IMG_20230916_180457_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d496a8e9b70221e90f6f",
  "name":
"externallmg_1695011990426_IMG_20230916_180459_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990426_IMG_20230916_180459_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d496a8e9b70221e90f70",
  "name":
"externallmg_1695011990438_IMG_20230916_180507_copy_1200x900.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990438_IMG_20230916_180507_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d496a8e9b70221e90f71",
  "name":
"externallmg_1695011990448_IMG_20230916_180510_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990448_IMG_20230916_180510_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d496a8e9b70221e90f72",
  "name":
"externallmg_1695011990454_IMG_20230916_180515_copy_1200x1600.jpg",
  "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990454_IMG_20230916_180515_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507d496a8e9b70221e90f73",
  "name":
"externallmg_1695011990461_IMG_20230916_180518_copy_1200x1600.jpg",
```

```
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990461_IMG_20230916_180518_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f74",
    "name":
"externallmg_1695011990467_IMG_20230916_180532_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990467_IMG_20230916_180532_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f75",
    "name":
"externallmg_1695011990478_IMG_20230916_180820_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990478_IMG_20230916_180820_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f76",
    "name":
"externallmg_1695011990482_IMG_20230916_180822_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990482_IMG_20230916_180822_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f77",
    "name":
"externallmg_1695011990491_IMG_20230916_180859_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990491_IMG_20230916_180859_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "6507d496a8e9b70221e90f78",
    "name":
"externallmg_1695011990499_IMG_20230916_180918_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990499_IMG_20230916_180918_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f79",
    "name":
"externallmg_1695011990510_IMG_20230916_194416_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990510_IMG_20230916_194416_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f7a",
    "name":
"externallmg_1695011990520_IMG_20230916_194430_copy_1200x900.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990520_IMG_20230916_194430_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507d496a8e9b70221e90f7b",
    "name":
"externallmg_1695011990534_IMG_20230916_194435_copy_1200x1600.jpg",
    "path": "cases/64f97ae363830d2aa3b48577/
externallmg_1695011990534_IMG_20230916_194435_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-07T07:25:23.691Z",
"updatedAt": "2023-09-18T04:39:50.632Z",
"__v": 0,
"invoiceId": "64f97ae363830d2aa3b48584",
```

"fullAddress": "Residential Flat No. Flat No 102, 1st Floor, Building No B-47, Girnar Shantinagar CHSL, Shanti Nagar, Village - Bhaynder, Mira Road East, Thane, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Kavita Mahendra Kothari",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8169762800"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			