

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645f0853ee6a9735bf7688e8"
    },
    "type": "CREDITOFFICER",
    "_id": "645f0853ee6a9735bf7688ea",
    "firstName": "Rajeevkumar ",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "9827114321",
    "email": "indiranagar.pune@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "3540"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank Of India",
  "displayName": "Bank Of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645f0853ee6a9735bf7688e8",
  "name": "Indira Nagar Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903\t",
  "alternateMobileNo": "",
  "email": "indiranagar.pune@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bungalow No 23, Shree Samartha Kripa, Gurukrinear Rathachakara
Chowk,\nIndira Nagar, Nashik-422 009, State - Maharashtra,Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fc92f7ce84bf289baa53f9",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
```

```
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": "",
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "20.01013929404442",
"longitude": "73.83238746425197"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nandur Dasak",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Upper Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "10A+10B+10C+10D",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bidi Kamgar Colony",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Beside Rukhmini Lawns",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "84/2/B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "10-D",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```



```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64fc17ffa8e9b70221dc8fd7",
"ownerName": "Dimpal Desale",
"ownerPhoneNo": "9657580203",
"fullAddress": " Flat No. 10-D, Upper Ground Floor, Beside Rukhmini Lawns, Plot No.
10A+10B+10C+10D, Bidi Kamgar Colony, Village - Nandur Dasak, Taluka - Nashik ,
District - Nashik, Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
```

```
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694242677853_Dimpal_Desle_Sale_Deed.pdf",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
document_1694242677853_Dimpal_Desle_Sale_Deed.pdf",
  "id": "938736",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Sep 09 2023 12:29:39 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003644",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "210643",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 09 2023 12:30:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Dimpal Desale",
    "phone": "9657580203",
    "ownershipShare": "",
    "email": "",
    "id": "250753"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98a7",
    "name":
"externallmg_1694243362526_WhatsApp_Image_20230909_at_111306_AM_1.jpeg",
```



```
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243362526_WhatsApp_Image_20230909_at_111306_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98a8",
    "name":
"externallmg_1694243362626_WhatsApp_Image_20230909_at_111306_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243362626_WhatsApp_Image_20230909_at_111306_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98a9",
    "name":
"externallmg_1694243362729_WhatsApp_Image_20230909_at_111323_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243362729_WhatsApp_Image_20230909_at_111323_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98aa",
    "name":
"externallmg_1694243362818_WhatsApp_Image_20230909_at_111324_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243362818_WhatsApp_Image_20230909_at_111324_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98ab",
    "name":
"externallmg_1694243362921_WhatsApp_Image_20230909_at_111324_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243362921_WhatsApp_Image_20230909_at_111324_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64fc1a23a8e9b70221dc98ac",
  "name":
"externallmg_1694243363056_WhatsApp_Image_20230909_at_111326_AM_1.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363056_WhatsApp_Image_20230909_at_111326_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a23a8e9b70221dc98ad",
  "name":
"externallmg_1694243363125_WhatsApp_Image_20230909_at_111326_AM_2.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363125_WhatsApp_Image_20230909_at_111326_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a23a8e9b70221dc98ae",
  "name":
"externallmg_1694243363162_WhatsApp_Image_20230909_at_111326_AM.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363162_WhatsApp_Image_20230909_at_111326_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a23a8e9b70221dc98af",
  "name":
"externallmg_1694243363284_WhatsApp_Image_20230909_at_111327_AM_1.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363284_WhatsApp_Image_20230909_at_111327_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a23a8e9b70221dc98b0",
  "name":
"externallmg_1694243363321_WhatsApp_Image_20230909_at_111327_AM_2.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363321_WhatsApp_Image_20230909_at_111327_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b1",
    "name":
"externallmg_1694243363387_WhatsApp_Image_20230909_at_111327_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363387_WhatsApp_Image_20230909_at_111327_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b2",
    "name":
"externallmg_1694243363453_WhatsApp_Image_20230909_at_111328_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363453_WhatsApp_Image_20230909_at_111328_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b3",
    "name":
"externallmg_1694243363538_WhatsApp_Image_20230909_at_111328_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363538_WhatsApp_Image_20230909_at_111328_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b4",
    "name":
"externallmg_1694243363602_WhatsApp_Image_20230909_at_111329_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363602_WhatsApp_Image_20230909_at_111329_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b5",
```

```
    "name":
"externallmg_1694243363669_WhatsApp_Image_20230909_at_111329_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363669_WhatsApp_Image_20230909_at_111329_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a23a8e9b70221dc98b6",
    "name":
"externallmg_1694243363753_WhatsApp_Image_20230909_at_111330_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243363753_WhatsApp_Image_20230909_at_111330_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98f2",
    "name":
"externallmg_1694243372148_WhatsApp_Image_20230909_at_111330_AM_2.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372148_WhatsApp_Image_20230909_at_111330_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98f3",
    "name":
"externallmg_1694243372234_WhatsApp_Image_20230909_at_111330_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372234_WhatsApp_Image_20230909_at_111330_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98f4",
    "name":
"externallmg_1694243372308_WhatsApp_Image_20230909_at_111331_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372308_WhatsApp_Image_20230909_at_111331_AM_1.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98f5",
  "name":
"externallmg_1694243372449_WhatsApp_Image_20230909_at_111331_AM_2.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372449_WhatsApp_Image_20230909_at_111331_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98f6",
  "name":
"externallmg_1694243372485_WhatsApp_Image_20230909_at_111331_AM.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372485_WhatsApp_Image_20230909_at_111331_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98f7",
  "name":
"externallmg_1694243372598_WhatsApp_Image_20230909_at_111332_AM_1.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372598_WhatsApp_Image_20230909_at_111332_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98f8",
  "name":
"externallmg_1694243372647_WhatsApp_Image_20230909_at_111332_AM_2.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372647_WhatsApp_Image_20230909_at_111332_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98f9",
  "name":
"externallmg_1694243372731_WhatsApp_Image_20230909_at_111332_AM.jpeg",
```

```
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372731_WhatsApp_Image_20230909_at_111332_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98fa",
    "name":
"externallmg_1694243372826_WhatsApp_Image_20230909_at_111333_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372826_WhatsApp_Image_20230909_at_111333_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98fb",
    "name":
"externallmg_1694243372873_WhatsApp_Image_20230909_at_111333_AM_2.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372873_WhatsApp_Image_20230909_at_111333_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98fc",
    "name":
"externallmg_1694243372911_WhatsApp_Image_20230909_at_111333_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372911_WhatsApp_Image_20230909_at_111333_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a2da8e9b70221dc98fd",
    "name":
"externallmg_1694243372959_WhatsApp_Image_20230909_at_111334_AM_1.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243372959_WhatsApp_Image_20230909_at_111334_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64fc1a2da8e9b70221dc98fe",
  "name":
"externallmg_1694243373006_WhatsApp_Image_20230909_at_111334_AM.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243373006_WhatsApp_Image_20230909_at_111334_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc98ff",
  "name":
"externallmg_1694243373044_WhatsApp_Image_20230909_at_111335_AM_1.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243373044_WhatsApp_Image_20230909_at_111335_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc9900",
  "name":
"externallmg_1694243373102_WhatsApp_Image_20230909_at_111335_AM_2.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243373102_WhatsApp_Image_20230909_at_111335_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a2da8e9b70221dc9901",
  "name":
"externallmg_1694243373165_WhatsApp_Image_20230909_at_111335_AM.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243373165_WhatsApp_Image_20230909_at_111335_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fc1a36a8e9b70221dc9931",
  "name":
"externallmg_1694243381916_WhatsApp_Image_20230909_at_111336_AM_1.jpeg",
  "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243381916_WhatsApp_Image_20230909_at_111336_AM_1.jpeg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fc1a36a8e9b70221dc9932",
    "name":
"externallmg_1694243382047_WhatsApp_Image_20230909_at_111336_AM.jpeg",
    "path": "cases/64fc17ffa8e9b70221dc8fd7/
externallmg_1694243382047_WhatsApp_Image_20230909_at_111336_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-09T07:00:15.270Z",
"updatedAt": "2023-09-09T07:09:42.203Z",
"__v": 0,
"invoiceId": "64fc17ffa8e9b70221dc8fe6",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Dimpal Desale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9657580203"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			