

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231032",
    "firstName": "Namrata ",
    "email": "racpc.sion@sbi.co.in",
    "mobileNo": "",
    "workMobileNo": "8879237774",
    "lastName": "Salvi"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Namrata ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },
]
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.325279683498646",
  "longitude": "73.20155333129796"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.20155333129796,
```

```
19.325279683498646
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-09-11T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-11T08:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Manda",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Titwala (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Indrayani",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "6, Hissa No. 2 & 3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 605",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Chawl Area",
    "south": "Tulsi Villa Building",
    "east": "Sai Prasad Building"
  },
  "asPerDocumentAgreement": {
    "north": "Details is not available",
    "west": "Details is not available",
    "south": "Details is not available",
    "east": "Details is not available"
  },
  "extraDetailOfProperty": "Details is not available"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": ""
```

```
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Manda",
  "rate": "62400",
  "landRate": "8600",
  "igrImage": "cases/64feda97a8e9b70221de2dfd/igr_1694606816876_Image.png",
  "squareMeterGuideLineRate": "62400.00",
  "squareFeetGuideLineRate": "5797.00"
},
"igrFinalRate": {
  "rate": "62400.00",
  "squareMeterGuideLineRate": "62400.00",
  "squareFeetGuideLineRate": "5797.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "8,000",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "Details is not available",
  "meterCardHolderName": "Details is not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
}
```

```
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "2",
"totalLifeBuilding": "60",
"estimatedAge": "58",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "9",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "645.70",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64feda97a8e9b70221de2dfd/
routeMap_1694605139133_Image.png",
    "routeLat": "19.301774",
    "routeLng": "73.200803",
    "stationName": "Titwala ",
    "routeDistance": "1.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
```



```
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "lhmk3b",
    "name": "lhmk3b",
    "image": "cases/64feda97a8e9b70221de2dfd/
routeMap_1694604968141_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3815500.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "3815500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3743123.00",
  "selectedBuildUpValue": "645.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65018c87a8e9b70221e2366b",
      "name":
"externallmg_1694600327630_WhatsApp_Image_20230913_at_34407_PM_1.jpeg",
      "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327630_WhatsApp_Image_20230913_at_34407_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65018c87a8e9b70221e23660",
      "name": "Living Room",
      "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327604_WhatsApp_Image_20230913_at_34407_PM_7.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65018c87a8e9b70221e23664",
      "name": "Living Room",
      "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327614_WhatsApp_Image_20230913_at_34407_PM_11.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65018c87a8e9b70221e23666",
      "name": "Living Room",
      "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327619_WhatsApp_Image_20230913_at_34407_PM_13.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65018c87a8e9b70221e23663",
      "name": "Living Room",
      "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327611_WhatsApp_Image_20230913_at_34407_PM_10.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65018c87a8e9b70221e23669",
    "name": "Living Room",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327625_WhatsApp_Image_20230913_at_34407_PM_16.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65018c87a8e9b70221e2365e",
    "name": "Living Room",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327599_WhatsApp_Image_20230913_at_34407_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65018c87a8e9b70221e2365b",
    "name": "Living Room",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327591_WhatsApp_Image_20230913_at_34407_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65018c87a8e9b70221e2366b",
    "name": "Living Room",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327630_WhatsApp_Image_20230913_at_34407_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65018c87a8e9b70221e23661",
    "name": "Living Room",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327606_WhatsApp_Image_20230913_at_34407_PM_8.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "6022",
"max": "7837"
},
"builtUpRateRange": {
  "min": "5475",
  "max": "7125"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "587.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64feda97a8e9b70221de2dfd",
"ownerName": "Mr. Chandan Dharmdeo Maurya & Mrs. Sangeeta Chandan Maurya ",
"ownerPhoneNo": "9892755071",
"appAddress": "Flat no. 403, 4th Floor, Indrayani Building, Village - Manda, Kalyan",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
```

```
"documentDate": "23/05/2018",
"from": {
  "value": "Promoter",
  "label": "Promoter"
},
"Promoter": "M/s. Mauli Construction ",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Mr. Chandan Dharmdeo Maurya & Mrs. Sangeeta Chandan
Maurya "
},
"isHardCopy": false,
"displayStatus": true,
"id": "692989",
"path": "cases/64feda97a8e9b70221de2dfd/
document_1694423637232_DocScanner_28Aug2023_210_pm.pdf",
"fileName": "document_1694423637232_DocScanner_28Aug2023_210_pm.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KDMC / NRV / CC/ KV / OCC / 621 / 21"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694601822923_document_1694423665932_31955.pdf",
  "path": "cases/64feda97a8e9b70221de2dfd/
document_1694601822923_document_1694423665932_31955.pdf",
  "id": "178803",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Sep 13 2023 16:13:43 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "17/02/2014",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KDMC / NRV / BP / KV / 2013 - 14 / 180"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694601983175_CC.pdf",
  "path": "cases/64feda97a8e9b70221de2dfd/document_1694601983175_CC.pdf",
  "id": "987666",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Sep 13 2023 16:16:23 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "31/08/2017",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51700010665"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694602029368_document_1694423637232_DocScanner_28Aug2023_210_pm.pdf",
  "path": "cases/64feda97a8e9b70221de2dfd/document_1694602029368_document_1694423637232_DocScanner_28Aug2023_210_pm.pdf",
  "id": "953525",
  "uploadedBy": "62fe044a48a26047e6552796",
```

```
    "createdAt": "Wed Sep 13 2023 16:17:09 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003674",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "612617",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 11 2023 14:45:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Chandan Dharmdeo Maurya & Mrs. Sangeeta Chandan Maurya ",
    "phone": "9892755071",
    "ownershipShare": "",
    "email": "",
    "id": "701765"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "696415",
    "name": "Bedroom",
    "length": "9.17",
    "length1": "9",
    "length2": "2",
    "width": "10.25",
    "width1": "10",
    "width2": "3",
    "totalArea": "93.96",
    "images": [],
    "extraAreas": [],
    "finalArea": "93.96"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "10.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "7",
  "width2": "1",
  "totalArea": "28.33",
  "images": [],
  "finalArea": "28.33",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
```

```
"totalArea": "12.00",
"images": [],
"finalArea": "12.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bathroom",
  "length": "",
  "length1": "5",
  "length2": "3",
  "width": "",
  "width1": "3",
  "width2": "10",
  "totalArea": "20.12",
  "images": [],
  "finalArea": "20.12",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "6.17",
  "length1": "6",
  "length2": "2",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "59.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "59.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "6",
"name": "Living Room",
"length": "11.42",
"length1": "11",
"length2": "5",
"width": "12.17",
"width1": "12",
"width2": "2",
"totalArea": "138.90",
"images": [],
"extraAreas": [],
"finalArea": "138.90"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "73.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "73.50"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "0",
"length1": "7",
"length2": "00",
"length": "7.00",
"width1": "9",
"width2": "2",
"width": "9.17",
"totalArea": "64.17",
"percentageBeforeTotal": "64.17",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "64.17"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "8",
  "length2": "00",
  "length": "8.00",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "16.00",
  "percentageBeforeTotal": "16.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "16"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
}
```



```
"name": {
  "label": "Flower Bed Area",
  "value": "Flower_Bed_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length1": "6",
"length2": "2",
"length": "6.17",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "12.33",
"percentageBeforeTotal": "12.33",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "12.33"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "12",
  "length2": "00",
  "length": "12.00",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "24.00",
  "percentageBeforeTotal": "24.00",
  "images": [],
  "extraAreas": [],
```

```
    "percentage": "100",
    "finalArea": "24"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "54.53",
    "totalAreaDocument": "587",
    "docBultupPercentage": "10",
    "docFinalBultUp": "645.70",
    "docFinalBultUpSquareMeter": "59.99",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "126814"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6501a66da8e9b70221e2c599",
    "property": "Manda Village (Nearby Location)",
    "area": "498",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "1",
    "source": "Index_no.2",
    "expectedPrice": "2999000",
    "expectedRate": "6022.09",
    "bultUpExpectedRate": "5474.63",
    "image": "cases/64feda97a8e9b70221de2dfd/
indicator_1694606630722_Image.png",
    "squareMeter": "46.27",
```

```
"id": "337880"
},
{
  "printlnReport": true,
  "_id": "6501a66da8e9b70221e2c59a",
  "property": "Amrut Siddhi, Titwala",
  "area": "518",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "7",
  "source": "magic_bricks",
  "expectedPrice": "3400000",
  "expectedRate": "6563.71",
  "builtUpExpectedRate": "5967.01",
  "image": "cases/64feda97a8e9b70221de2dfd/
indicator_1694606676407_Image.png",
  "squareMeter": "48.12",
  "id": "433720"
},
{
  "printlnReport": true,
  "_id": "6501a66da8e9b70221e2c59b",
  "property": "Indrayani, Titwala",
  "area": "363",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "2845000",
  "expectedRate": "7837.47",
  "builtUpExpectedRate": "7124.97",
  "image": "cases/64feda97a8e9b70221de2dfd/
indicator_1694606740456_Image.png",
  "squareMeter": "33.72",
  "id": "584840"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65018c87a8e9b70221e2365b",
```

```
    "name":  
    "externallmg_1694600327591_WhatsApp_Image_20230913_at_34407_PM_2.jpeg",  
    "path": "cases/64feda97a8e9b70221de2dfd/  
externallmg_1694600327591_WhatsApp_Image_20230913_at_34407_PM_2.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65018c87a8e9b70221e2365c",  
    "name":  
    "externallmg_1694600327594_WhatsApp_Image_20230913_at_34407_PM_3.jpeg",  
    "path": "cases/64feda97a8e9b70221de2dfd/  
externallmg_1694600327594_WhatsApp_Image_20230913_at_34407_PM_3.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65018c87a8e9b70221e2365d",  
    "name":  
    "externallmg_1694600327596_WhatsApp_Image_20230913_at_34407_PM_4.jpeg",  
    "path": "cases/64feda97a8e9b70221de2dfd/  
externallmg_1694600327596_WhatsApp_Image_20230913_at_34407_PM_4.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65018c87a8e9b70221e2365e",  
    "name":  
    "externallmg_1694600327599_WhatsApp_Image_20230913_at_34407_PM_5.jpeg",  
    "path": "cases/64feda97a8e9b70221de2dfd/  
externallmg_1694600327599_WhatsApp_Image_20230913_at_34407_PM_5.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65018c87a8e9b70221e2365f",  
    "name":  
    "externallmg_1694600327601_WhatsApp_Image_20230913_at_34407_PM_6.jpeg",  
    "path": "cases/64feda97a8e9b70221de2dfd/  
externallmg_1694600327601_WhatsApp_Image_20230913_at_34407_PM_6.jpeg",  
    "orientation": "portrait"  
  },  
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e23660",
  "name":
"externallmg_1694600327604_WhatsApp_Image_20230913_at_34407_PM_7.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327604_WhatsApp_Image_20230913_at_34407_PM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e23661",
  "name":
"externallmg_1694600327606_WhatsApp_Image_20230913_at_34407_PM_8.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327606_WhatsApp_Image_20230913_at_34407_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e23662",
  "name":
"externallmg_1694600327609_WhatsApp_Image_20230913_at_34407_PM_9.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327609_WhatsApp_Image_20230913_at_34407_PM_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e23663",
  "name":
"externallmg_1694600327611_WhatsApp_Image_20230913_at_34407_PM_10.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327611_WhatsApp_Image_20230913_at_34407_PM_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e23664",
  "name":
"externallmg_1694600327614_WhatsApp_Image_20230913_at_34407_PM_11.jpeg",
```

```
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327614_WhatsApp_Image_20230913_at_34407_PM_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65018c87a8e9b70221e23665",
    "name":
"externallmg_1694600327616_WhatsApp_Image_20230913_at_34407_PM_12.jpeg",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327616_WhatsApp_Image_20230913_at_34407_PM_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65018c87a8e9b70221e23666",
    "name":
"externallmg_1694600327619_WhatsApp_Image_20230913_at_34407_PM_13.jpeg",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327619_WhatsApp_Image_20230913_at_34407_PM_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65018c87a8e9b70221e23667",
    "name":
"externallmg_1694600327621_WhatsApp_Image_20230913_at_34407_PM_14.jpeg",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327621_WhatsApp_Image_20230913_at_34407_PM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65018c87a8e9b70221e23668",
    "name":
"externallmg_1694600327623_WhatsApp_Image_20230913_at_34407_PM_15.jpeg",
    "path": "cases/64feda97a8e9b70221de2dfd/
externallmg_1694600327623_WhatsApp_Image_20230913_at_34407_PM_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65018c87a8e9b70221e23669",
  "name":
"externalImg_1694600327625_WhatsApp_Image_20230913_at_34407_PM_16.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externalImg_1694600327625_WhatsApp_Image_20230913_at_34407_PM_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e2366a",
  "name":
"externalImg_1694600327628_WhatsApp_Image_20230913_at_34407_PM_17.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externalImg_1694600327628_WhatsApp_Image_20230913_at_34407_PM_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e2366b",
  "name":
"externalImg_1694600327630_WhatsApp_Image_20230913_at_34407_PM_1.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externalImg_1694600327630_WhatsApp_Image_20230913_at_34407_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65018c87a8e9b70221e2366c",
  "name":
"externalImg_1694600327632_WhatsApp_Image_20230913_at_34407_PM.jpeg",
  "path": "cases/64feda97a8e9b70221de2dfd/
externalImg_1694600327632_WhatsApp_Image_20230913_at_34407_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (1) (1).xlsx",
    "filename": "1694604108902_Calculation_1_1.xlsx",
    "path": "cases/64feda97a8e9b70221de2dfd/
processingDocuments/1694604108902_Calculation_1_1.xlsx",
```

```
"size": "15309",
"createdAt": "Wed Sep 13 2023 16:51:48 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"remarks": [],
"createdAt": "2023-09-11T09:15:03.852Z",
"updatedAt": "2023-09-13T12:47:18.382Z",
"__v": 0,
"invoiceId": "64feda98a8e9b70221de2e14",
"fullAddress": "Residential Flat No. 403, 4th Floor, Indrayani, Village - Manda, Taluka - Kalyan, District - Thane, Titwala (West), PIN - 421 605, State - Maharashtra, India",
"updatedAtBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Deepak Maurya ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Brother in law",
"siteVisitContactNo": "9044235305",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 WC + Bathroom",
"carpetTotal": "436.15999999999997",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "92.50",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "116.50",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "607.93",
"finalCarpetArea": "552.66",
"finalSalableArea": "668.72",
"salablePercentage": "10",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 587.00",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 436.00\nOther Useable Area in S. Ft. = 151.00\nTotal Area Sq. Ft. = 587.00",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 436.00\nBalcony Area in Sq. Ft.
```


= 64.00
 Flower Bed Area in Sq. Ft. = 53.00",
 "buildingServicesRate": "2600.00",
 "flatRate": "6500",
 "landOtherRate": "3900",
 "reportGeneratedDate": "Wed Sep 13 2023 18:07:55 GMT+0530 (India Standard Time)",
 "siteVisitDate": "2023-09-13"
 }

Name	Length	Width	Total
Composition :			
Bedroom	9'2"	10'3"	93.96
Passage	3'00"	3'5"	10.25
WC	4'0"	7'1"	28.33
WC	4'0"	3'0"	12.00
Bathroom	5'3"	3'10"	20.12
Kitchen	6'2"	9'7"	59.10
Living Room	11'5"	12'2"	138.90
Bedroom	9'00"	8'2"	73.50
Other Composition :			
Balcony Area	7'00"	9'2"	64.17
Flower Bed Area	8'00"	2'00"	16.00
Flower Bed Area	6'2"	2'00"	12.33
Flower Bed Area	12'00"	2'00"	24.00