

```
{
  "typeOfReport": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7e7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423119d",
    "firstName": "Akshay Kumar",
    "email": "0_default_akshay.kumar10@sbi.co.in_and_sbi.17879@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-28329367",
    "workMobileNo": "0_DEFAULT_91-7053284426"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
  }
}
```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7e7",
  "branchCode": "000048",
  "type": "BRANCH",
  "name": "MIDC Andheri (East) Branch",
  "email": "sbi.17879@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "STATE BANK OF INDIA- MIDC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
```

```
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.10876097487748",
  "longitude": "72.88077140916953"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ambivali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "22",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Andheri Industrial Premises CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off Veera Desai Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```

```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit 121",
  "label": false
},
"municipalityWardNo": {
```



```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
```

```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "64fff852a8e9b70221df4665",
"ownerName": "M/S Cooldeck Aqua Solution Pvt. Ltd.",
"ownerPhoneNo": "9702477421",
"fullAddress": "Commercial Flat No. Unit 121, 1st Floor, Andheri Industrial Premises
CHSL, Plot No. 22, Off Veera Desai Road, Village - Ambivali, Andheri, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694496809637_cooldeck_indu_unit_121_andheri_1.pdf",
    "path": "cases/64fff852a8e9b70221df4665/
document_1694496809637_cooldeck_indu_unit_121_andheri_1.pdf",
    "id": "794473",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Tue Sep 12 2023 11:03:33 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003694",
```



```
"createdBy": "62691c48afd7d55eddecfda3",
"caseHistory": [
  {
    "id": "284157",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 12 2023 11:04:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/S Cooldeck Aqua Solution Pvt. Ltd.",
    "phone": "9702477421",
    "ownershipShare": "",
    "email": "",
    "id": "142908"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a57f",
    "name": "externalImg_r_1696492394237_IMG20231004144139.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492394237_IMG20231004144139.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a580",
    "name": "externalImg_r_1696492394246_IMG20231004145631.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492394246_IMG20231004145631.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a581",
    "name": "externallmg_r_1696492394249_IMG20231004145647.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492394249_IMG20231004145647.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a582",
    "name": "externallmg_r_1696492394241_IMG20231004144205.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492394241_IMG20231004144205.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a583",
    "name": "externallmg_r_1696492394259_IMG20231004145656.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492394259_IMG20231004145656.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a584",
    "name": "externallmg_r_1696492394254_IMG20231004145648.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492394254_IMG20231004145648.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a585",
    "name": "externallmg_r_1696492394262_IMG20231004145705.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492394262_IMG20231004145705.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "651e6b6a072fba0ce3f3a586",
  "name": "externalimg_r_1696492394256_IMG20231004145654.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394256_IMG20231004145654.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b6a072fba0ce3f3a587",
  "name": "externalimg_r_1696492394265_IMG20231004145709.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394265_IMG20231004145709.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b6a072fba0ce3f3a588",
  "name": "externalimg_r_1696492394269_IMG20231004145732.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394269_IMG20231004145732.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b6a072fba0ce3f3a589",
  "name": "externalimg_r_1696492394267_IMG20231004145720.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394267_IMG20231004145720.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b6a072fba0ce3f3a58a",
  "name": "externalimg_r_1696492394272_IMG20231004145736.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394272_IMG20231004145736.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "651e6b6a072fba0ce3f3a58b",
    "name": "externalimg_r_1696492394273_IMG20231004145747.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394273_IMG20231004145747.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a58c",
    "name": "externalimg_r_1696492394276_IMG20231004150003.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394276_IMG20231004150003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a58d",
    "name": "externalimg_r_1696492394278_IMG20231004150009.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394278_IMG20231004150009.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a58e",
    "name": "externalimg_r_1696492394280_IMG20231004150010.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394280_IMG20231004150010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a58f",
    "name": "externalimg_r_1696492394282_IMG20231004150029.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394282_IMG20231004150029.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a590",
```

```
    "name": "externalimg_r_1696492394284_IMG20231004150039.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394284_IMG20231004150039.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a591",
    "name": "externalimg_r_1696492394286_IMG20231004150042.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394286_IMG20231004150042.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b6a072fba0ce3f3a592",
    "name": "externalimg_r_1696492394288_IMG20231004150046.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492394288_IMG20231004150046.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b2",
    "name": "externalimg_r_1696492412512_IMG20231004150115.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412512_IMG20231004150115.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b3",
    "name": "externalimg_r_1696492412500_IMG20231004150046.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412500_IMG20231004150046.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b4",
    "name": "externalimg_r_1696492412506_IMG20231004150054.jpg",
```

```
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412506_IMG20231004150054.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b5",
    "name": "externallmg_r_1696492412503_IMG20231004150052.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412503_IMG20231004150052.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b6",
    "name": "externallmg_r_1696492412515_IMG20231004150123.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412515_IMG20231004150123.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b7",
    "name": "externallmg_r_1696492412519_IMG20231004150225.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412519_IMG20231004150225.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b8",
    "name": "externallmg_r_1696492412522_IMG20231004152312.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412522_IMG20231004152312.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b7c072fba0ce3f3a5b9",
    "name": "externallmg_r_1696492412525_IMG20231004152319.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412525_IMG20231004152319.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5ba",
  "name": "externallmg_r_1696492412528_IMG20231004152325.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412528_IMG20231004152325.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5bb",
  "name": "externallmg_r_1696492412531_IMG20231004152331.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412531_IMG20231004152331.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5bc",
  "name": "externallmg_r_1696492412534_IMG20231004152333.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412534_IMG20231004152333.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5bd",
  "name": "externallmg_r_1696492412539_IMG20231004152904.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412539_IMG20231004152904.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5be",
  "name": "externallmg_r_1696492412541_IMG20231004152908.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412541_IMG20231004152908.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5bf",
  "name": "externalimg_r_1696492412544_IMG20231004152916.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412544_IMG20231004152916.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5c0",
  "name": "externalimg_r_1696492412546_IMG20231004153003.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412546_IMG20231004153003.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5c1",
  "name": "externalimg_r_1696492412548_IMG20231004153006.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412548_IMG20231004153006.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5c2",
  "name": "externalimg_r_1696492412551_IMG20231004153032.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412551_IMG20231004153032.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5c3",
  "name": "externalimg_r_1696492412554_IMG20231004153131.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externalimg_r_1696492412554_IMG20231004153131.jpg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b7c072fba0ce3f3a5c4",
  "name": "externallmg_r_1696492412557_IMG20231004153200.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492412557_IMG20231004153200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5f9",
  "name": "externallmg_1696492439286_Screenshot_2023100414514382_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/64fff852a8e9b70221df4665/externallmg_1696492439286_Screensho
t_2023100414514382_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5fa",
  "name": "externallmg_r_1696492439261_IMG20231004153240.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439261_IMG20231004153240.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5fb",
  "name": "externallmg_r_1696492439258_IMG20231004153229.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439258_IMG20231004153229.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5fc",
  "name": "externallmg_r_1696492439272_IMG20231004153611.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439272_IMG20231004153611.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5fd",
  "name": "externallmg_r_1696492439267_IMG20231004153521.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439267_IMG20231004153521.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5fe",
  "name": "externallmg_r_1696492439289_IMG20231004145658.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439289_IMG20231004145658.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a5ff",
  "name": "externallmg_r_1696492439277_IMG20231004153614.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439277_IMG20231004153614.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a600",
  "name": "externallmg_r_1696492439292_IMG20231004150102.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439292_IMG20231004150102.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e6b97072fba0ce3f3a601",
  "name": "externallmg_r_1696492439281_IMG20231004153638.jpg",
  "path": "cases/64fff852a8e9b70221df4665/
externallmg_r_1696492439281_IMG20231004153638.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b97072fba0ce3f3a602",
    "name": "externalImg_r_1696492439294_IMG20231004150807.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492439294_IMG20231004150807.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6b97072fba0ce3f3a603",
    "name": "externalImg_r_1696492439295_IMG20231004153239.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492439295_IMG20231004153239.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6bcb072fba0ce3f3a642",
    "name": "externalImg_r_1696492490308_IMG20231005123437.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492490308_IMG20231005123437.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e6bcb072fba0ce3f3a643",
    "name": "externalImg_r_1696492490380_IMG20231005123424.jpg",
    "path": "cases/64fff852a8e9b70221df4665/
externalImg_r_1696492490380_IMG20231005123424.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-12T05:34:10.332Z",
"updatedAt": "2023-10-05T07:54:51.109Z",
"__v": 0,
"invoiceId": "64fff852a8e9b70221df4672",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "",
```

"contactPersonName": "M/S Cooldeck Aqua Solution Pvt. Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9702477421"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			