

```
{
  "typeOfReport": {
    "value": "Commercial_Shop",
    "label": "Commercial Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7e7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423119d",
    "firstName": "Akshay Kumar",
    "email": "0_default_akshay.kumar10@sbi.co.in_and_sbi.17879@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-28329367",
    "workMobileNo": "0_DEFAULT_91-7053284426"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7e7",
  "branchCode": "000048",
  "type": "BRANCH",
  "name": "MIDC Andheri (East) Branch",
  "email": "sbi.17879@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "STATE BANK OF INDIA- MIDC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
```

```
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.14670848908088",
  "longitude": "72.8217041691999"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Monisha CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```

```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop 3",
  "label": false
},
"municipalityWardNo": {
```



```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
```

```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "6500311ba8e9b70221e01f92",
"ownerName": "M/s. Cruise Appliances Pvt. Ltd.",
"ownerPhoneNo": "7045959271",
"fullAddress": "Commercial Commercial Shop No. Shop 3, Basement Floor, Monisha
CHSL, Andheri, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694511346483_cruise_appliance_shop_no_3_2.pdf",
    "path": "cases/6500311ba8e9b70221e01f92/
document_1694511346483_cruise_appliance_shop_no_3_2.pdf",
    "id": "763667",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Tue Sep 12 2023 15:05:50 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003729",
"createdBy": "62691c48afd7d55eddecfda3",
```



```
"caseHistory": [
  {
    "id": "451596",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 12 2023 15:06:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Cruise Applaiques Pvt. Ltd.",
    "phone": "7045959271",
    "ownershipShare": "",
    "email": "",
    "id": "906604"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae17",
    "name": "externalImg_1696564065546_IMG20231005WA0214.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564065546_IMG20231005WA0214.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae18",
    "name": "externalImg_1696564065552_IMG20231005WA0215.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564065552_IMG20231005WA0215.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "651f8361a3807b6a5438ae19",
    "name": "externalimg_1696564065567_IMG20231005WA0216.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalimg_1696564065567_IMG20231005WA0216.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae1a",
    "name": "externalimg_1696564065574_IMG20231005WA0217.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalimg_1696564065574_IMG20231005WA0217.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae1b",
    "name": "externalimg_1696564065580_IMG20231005WA0218.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalimg_1696564065580_IMG20231005WA0218.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae1c",
    "name": "externalimg_1696564065593_IMG20231005WA0219.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalimg_1696564065593_IMG20231005WA0219.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae1d",
    "name": "externalimg_1696564065597_IMG20231005WA0220.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalimg_1696564065597_IMG20231005WA0220.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "651f8361a3807b6a5438ae1e",
    "name": "externallmg_1696564065604_IMG20231005WA0221.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564065604_IMG20231005WA0221.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae1f",
    "name": "externallmg_1696564065610_IMG20231005WA0223.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564065610_IMG20231005WA0223.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae20",
    "name": "externallmg_1696564065617_IMG20231005WA0224.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564065617_IMG20231005WA0224.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae21",
    "name": "externallmg_1696564065620_IMG20231005WA0225.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564065620_IMG20231005WA0225.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8361a3807b6a5438ae22",
    "name": "externallmg_1696564065624_IMG20231005WA0226.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564065624_IMG20231005WA0226.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae8b",
```

```
    "name": "externalImg_1696564089137_IMG20231005WA0230.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564089137_IMG20231005WA0230.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae8c",
    "name": "externalImg_1696564089149_IMG20231005WA0231.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564089149_IMG20231005WA0231.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae8d",
    "name": "externalImg_1696564089157_IMG20231005WA0233.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564089157_IMG20231005WA0233.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae8e",
    "name": "externalImg_1696564089162_IMG20231005WA0234.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564089162_IMG20231005WA0234.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae8f",
    "name": "externalImg_1696564089167_IMG20231005WA0235.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externalImg_1696564089167_IMG20231005WA0235.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae90",
    "name": "externalImg_1696564089172_IMG20231005WA0236.jpg",
```

```
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089172_IMG20231005WA0236.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae91",
    "name": "externallmg_1696564089179_IMG20231005WA0237.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089179_IMG20231005WA0237.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae92",
    "name": "externallmg_1696564089187_IMG20231005WA0238.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089187_IMG20231005WA0238.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae93",
    "name": "externallmg_1696564089193_IMG20231005WA0239.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089193_IMG20231005WA0239.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae94",
    "name": "externallmg_1696564089199_IMG20231005WA0240.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089199_IMG20231005WA0240.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651f8379a3807b6a5438ae95",
    "name": "externallmg_1696564089202_IMG20231005WA0222.jpg",
    "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089202_IMG20231005WA0222.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651f8379a3807b6a5438ae96",
  "name": "externallmg_1696564089207_IMG20231005WA0227.jpg",
  "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089207_IMG20231005WA0227.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651f8379a3807b6a5438ae97",
  "name": "externallmg_1696564089209_IMG20231005WA0228.jpg",
  "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089209_IMG20231005WA0228.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651f8379a3807b6a5438ae98",
  "name": "externallmg_1696564089213_IMG20231005WA0229.jpg",
  "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089213_IMG20231005WA0229.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651f8379a3807b6a5438ae99",
  "name": "externallmg_1696564089215_IMG20231005WA0232.jpg",
  "path": "cases/6500311ba8e9b70221e01f92/
externallmg_1696564089215_IMG20231005WA0232.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651f838aa3807b6a5438aec0",
  "name": "externallmg_r_1696564106192_IMG20231005222458.jpg",
  "path": "cases/6500311ba8e9b70221e01f92/
externallmg_r_1696564106192_IMG20231005222458.jpg",
  "orientation": "portrait"
}
```

```

    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651f838aa3807b6a5438aec1",
      "name": "externalImg_r_1696564106124_IMG20231005222448.jpg",
      "path": "cases/6500311ba8e9b70221e01f92/
externalImg_r_1696564106124_IMG20231005222448.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "remarks": [],
  "createdAt": "2023-09-12T09:36:27.293Z",
  "updatedAt": "2023-10-06T03:48:26.826Z",
  "__v": 0,
  "invoiceId": "6500311ca8e9b70221e01fc3",
  "updatedBy": "6006d4ce5080a310ac1fdcf2",
  "addressForMap": "",
  "caseReferredBy": "",
  "contactPersonName": "M/s. Cruise Applaiques Pvt. Ltd.",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "7045959271"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			