

KACPL/SBI/RK/AH/MG/20-21/MC887

September 26, 2020


VALUATION REPORT IN RESPECT OF INDUSTRIAL PREMISES/

FOR

M/s. Maitri Metals Pvt. Ltd.

PROPERTY ADDRESS

Unit No. 5, Ground Floor, Building No. A-4, Gayatri Complex, Village Val, Anjur Phatta Road, Bhiwandi, District – Thane – 421 302



STATE BANK OF INDIA SME MIDC Andheri (E) Branch, Mumbai.



KACPL/SBI/RK/AH/MG/20-21/MC887

September 26, 2020

To.

State Bank of India,

SME MIDC Andheri Branch,

Plot No. B1, Central Marol Road,

MIDC Andheri (E), Mumbai – 400 093

VALUATION REPORT (IN RESPECT OF INDUSTRIAL PREMISES)

	I. GENERAL	
	1. Purpose for which the valuation is made	To ascertain Market Value of the Unit No. 5, Ground Floor, Building No. A-4, Gayatri Complex, Village Val, Anjur Phatta Road, Bhiwandi, District – Thane – 421 302
- Company	2. a) Date of inspection	September 24, 2020
MARKA STATES ASSESSED.	b) Date on which the valuation is made	September 26, 2020
de la composition de la compos	ii. Registration Receipt No. 6620 and Regindicating purchase price Rs.19,22,300 iii. Index II dated September 30, 2010 indiv. Construction Permission dated July 20, (Note: In Construction Permission it is site inspection it is G+1 floor) Name of the owner(s) and his/their address	gistration No. 06620-2010 dated September 30, 2010 /- and Market Value Rs.19,21,480/- cating area 218.36 sq. mtrt. (Built-up) 2007 issued by Gram Panchayat Val. stated that the said building is G+2 floor, but as per M/s. Maitri Metals Pvt. Ltd.
	(es) with Phone No. (details of share of each owner in case of joint ownership)	Same as property address
	Name of the Seller of the property	-
5.	Brief description of the property	The said Unit is located on ground floor of the building known as Gayatri Complex which is approx. 3 km from Bhiwandi Road railway station.



6	Landina of programs		
	at Place Vo. Sharepy No. 1978 No.	New year No. 3274	
	3.) Descri Mo	Live No. 1	
	vii T.S. No. = 1888agge	Val	
	di Warri Tahuka	Hviwaruli	
	ci Mondal District	Thane	
	Date of issue and validity of layout of approved mapiphan	Approved plan not prov	vided to us
	g) Approved map plan issuing authority	No	
	h) Whether genuineness or authenticity of approved map/plan is verified	No	
	Any other comments by our empaneled valuers on authentic of approved plan	No	
*	Postal address of the property	Unit No. 5, Ground Flo Building No. A-4, Gay Village Val, Anjur Pha District – Thane – 421	atri Complex, tta Road, Bhiwandi,
8.	City / Town	A CONTRACTOR OF THE CONTRACTOR	And a second
	Residential Area	No	
	Industrial Area	Yes	
9.	Classification of the area		
	i). High / Middle / Poor	Middle	
	ii). Urban / Semi Urban / Rural	Semi Urban	
1(Panchayat / Municipality	Gram Panchayat Val	
	Whether covered under any State /Central Govt. enactment's (e.g., Urban Land Ceiling Act) or notified under agency area / scheduled area / cantonment area.	!	cuments shown
1	2. Boundaries of the property		
To a contract of the contract	North		Road
	South		Road
-	East	Buil	Iding No. A-5
	West		Road
	3. Dimensions of the site	A As per the Deed	B Actuals
	North South East West	N. A.	N. A.
	14. Extent of the site	Not applicable	WUMBAI &
_			400016 P

	4	Laterado Compilado & Considerante of	19"11"39 A"N 71"03901 A"F
If one required he terminal since how long?	14	Kyneni of the vive considered for valuation	As identified in Point No. 11 of Part 3 (Industrial Unit)
	香香	If occupied by tenant since how long? Root received per month	Owner Occupied

II. APARTMENT BUILDING

1	Nature of Apartment	Industrial unit
2	Location	
	T.S. No.	Not applicable
	Block No.	Not applicable
	Ward No.	Not applicable
State of the state	Village/ Municipality/ Corporation	Village Val,
	Door No., Street or Road (Pin Code)	Gram Panchayat Val Anjur Phatta Road, Bhiwandi, District – Thane – 421 302
3.	Description of the locality Residential / Industrial/ Mixed	Mixed
4.	Year of construction	Approx. 1996 (As per site information)
5.	Number of floors	Ground + 1 upper floor
6.	Type of structure	RCC framed Structure with brick wall masonry
7.	Number of dwelling units in the Building	Details not provided
8.	Quality of construction	Good
9.	Appearance of the building	Good
10.	Maintenance of the building	Good
11.	Facilities available	
	Lift	N.A.
	Protected water supply	Available
	Underground Sewerage	Available
	Car Parking - Open/Covered	Open space facility is available for the said building
	Is compound wall exiting.	No
	Pavement around the building	Cement concrete

III INDUSTRIAL UNIT

1.	The floor in which the Unit is situated	Ground floor	
2.	Door number of the Unit	Unit No. 5	
3.	Specification of the Unit		LES CONSOLTIA
	Roof	RCC roof	WMBAI CP
manuscriptors		The state of the s	11.001.1000

	amounting Private Limited		
I Flooring			
Donas	Tar		
Windows	M.S. Rolling Shutter		
Fillings	N.A		
	Standard		
Finishing	Standard		
4. House Tax			
Assessment No. Tax paid in the name of	Details not provided		
Tax amount			
1	-		
5. Electricity service connection number Meter Card is in the name of	Details not provided		
6. How is the maintenance of the Unit?	Good		
7. Sale Deed executed in the name of	M/s. Maitri Metals Pvt. Ltd.		
8. What is the undivided area of land as p	per N.A Valuation is only for industrial unit		
sale?	The same of the sa		
9. What is the plinth area of the Unit	N.A Valuation is only for industrial unit 2,350 sq. ft. (Built-up) (As per agreement)		
10. What is the floor space index (App.)?	As per local norms		
11. What is the area of the Unit?	As per agreement/ Index II as per measurements		
Unit No. 5	2,350 sq. ft. (Built-up) 1,828 sq. ft. (Carpet)		
Area calculation for valuation	Carpet Area Built up area in sa. ft. in sq. ft.		
Unit No. 5	in sq. ft. in sq. ft. 1,828 2,194		
Area adopted for valuation	2,194 sq. ft. (Built-up)		
Note: Our valuation report is base Index II or that physically moleonical lower.	d on the area which is identified in the agreement easured by us at the time of inspection, whichever is		
2. Is it Posh/I Class/Medium/ Ordinary	Medium		
3. Is it being used for residential or	Industrial		
industrial purpose?			
. Is it owner occupied or let out?	Owner Occupied		
If tenanted, what is the monthly rent?	N.A.		
If tenanted, what is the monthly rem			

VI. MARKETABILITY

VI.	MARKETABIET	
		Good
1	How is the marketability	
1.	for an extra	Nil
12.	What are the factors favoring for an extra	
1 2.	potential value?	
	potentiai varia	Nil
<u> </u>	Any negative factors observed which	
3.	Any negative factor Value in general	es CONSU
	Any negative factors doser of affect the Market Value in general	

7 (1)

10 A 17

	after analyting the companying cult independent with a company to the accompany to the account.	BL) THEN IN BL & THEN YOUR AIR TO HAVE THEN THE
	Assuming it is a new construction, what is the adopted basic composite rate of the Unit under valuation after comparing with the specifications and other factors with the Unit under comparison (Give details)	Rs.2.500/- per sq. ft. on Built up
-	Break- up for the rate	Personal con-elidade (con-elidade (con-elidade (con-elidade (con-elidade)) e con-elidade (con-elidade) e con-elidade) e con-elidade (con-elidade) e con-elidade (con-elidade) e con-elidade) e con-elidade (con-elidade) e con-elidade (con-elidade) e con-elidade) e con-elidade) e con-elidade (con-elidade) e con-elidade) e con-elidade (con-elidade) e con-elidade) e con-elidade) e con-elidade (con-elidade) e con-elidade (con-elidade) e con-elidade) e con-elidade (con-elidade) e
	Building + Services	Rs.1,200/- per sq. ft.
	i) Land + others	Rs.1,300/- per sq. ft.
	Guideline rate obtained from the Registrar's office - Stamp Duty Ready Reckoner Rate 2020-21 (an evidence thereof to be enclosed)	Details not available.
	Guideline Value (Agreement area)	Built-up Area Unit Rate Total Value Rs. in sq. ft. Rs./sq. ft. Details not available

VI. COMPOSITE RATE ADOPTED AFTER DEPRECIATION

Depreciated Building Rate	Rs. $1,200 - \text{Rs.} 432 = \text{Rs.} 768/- \text{per sq. ft.}$
- 1	Rs. 1,200/- x 2350 sq. ft. = Rs.28,20,000/-
(Insurable Value) Age of the building Life of the building estimated	Approx. 24 Years (As per site information) 36 years depending on the regular preventive maintenance of the building
Depreciation percentage assuming the salvage value as 10%	36.00%
Depreciated Ratio of the building	64.00%
Total Composite rate arrived for valuation	Unit No. 5 – Rs.2,068/- per sq. ft. on Built up area.
l access	Rs.768/- per sq. ft.
	Rs.1,300/- per sq. ft.
Total Composite Rate	Rs.2,068/- per sq. ft. on built-up area. However, we have considered Rs.2,500/- per sq. ft. for valuation purpose
	Age of the building Life of the building estimated Depreciation percentage assuming the salvage value as 10% Depreciated Ratio of the building Total Composite rate arrived for valuation Depreciated Building rate VI(a) Rate for Land & other V(3) ii



DETAILS OF VALUATION

51. No.	Description	The second section of the second section sec	Area in Sq. ft.	Unit Nate	Fatirmated/ Present Value (Rs.)
1.	present value of the Unit finel car parking, if provided)	(Built-up)	2,194	2,500	54,85,000
2.	Wardrobes	hangs der al water to four the set of months and for expellent their region	-		Commence of the Commence of th
3.	Show cases		To the motor control of		
4	Kuchen arrangements				
5.	Superfine finish				
6.	Interior decorations	inn de Carlos e gang salagai nasa rikina Jegarin Carde ya Anno esebasir e new in			
7.	Electricity deposits/ electrical fittings, et	tc.			
8.	Extra collapsible gates / grill works etc.				
9.	Potential value, if any	anne anni hi ilgali a minis agrang mengang mengang kalin land mengang mengang dib			
10.	Others				
	Total.				54,85,

Valuation Methodology

The method adopted for valuation of the industrial premises is Sales Comparison Method in which the sales instances of the similar properties or properties with similar attributes in the same region are traced and the market rates are derived by using the experience and expertise of the valuer. Also, the valuation of the premises is based on the present Market Value of the premises depending on the condition, location and other infrastructural facilities available at and around the said premises. We have considered the valuation on built-up area for the premises, which is an increase of 20% over that of its carpet area.

The Realizable Value of the said industrial premises is considered at 85% of the present Market Value of the said premises, while the Forced Sale Value for the said premises is considered at 75% of its present Market Value.

Remarks:

- ➤ All the civic amenities are available within the proximity of the said building.
- We were not provided with any technical documents of the said building, we request the bank to verify the same at your end.
- ➤ We cannot ascertain any violation in the building as we were not provided with the approved plans of the building.



promise & Combidendaria

As a result of our appraisal and analysis, it is our considered opinion that the value of the above referred Unit No. 5, Ground Floor, Building No. A-4, Gayatri Complex, Village Val, Annu Phatta Road, Bhiwandi, District – Thane – 421 302, in its present prevailing condition with aforesaid specifications is as under:

Market Value (MV)	Rs.54.85,000x-	(Rupees fifty four lakh eighty five thousand only)
Realizable Value (85% of MV).	Rs.46,62,000/-	(Rupees forty six lakh sixty two thousand only)
Distress Sale Value (75% of MV)	Rs.41,14,000/-	(Rupees forty one lakh fourteen thousand only)
Book Value (2010 Year)	Rs.19,22,300/-	(Rupees nineteen lakh twenty two thousand only)

For KAKODE ASSOCIATES CONSULTING PRIVATE LIMITED.

ANIL B. PAI KAKODE

Director & Govt. Approved Value of SAGNEERS &

MAHIM, MUMBAI - 400 016. ASHOK S. AKERKAR

Associate Director & Govt. Approved Valuer

Wealth Tax Regn. No. CAT VII-20 of 1988

CCIT/PNJ/4(3)-Tech/2005-06

Place: Mumbai

Date: September 26, 2020