

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba8e"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942310e8",
    "firstName": "Amol Deshpande",
    "email": "0_default_amol.deshpande@cosmosbank.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9930792452"
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba8e",
  "branchCode": "000021",
  "type": "BRANCH",
  "name": "Veera Desai Road Andheri (West) Branch ",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226762671",
  "alternateMobileNo": "02226762672",
  "address": "Shop no 7, Dhanashree Heights Building No 42, Off Veera Desai Road
Andheri (West) Mumbai 400053",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
```

```
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.30697449968205",
  "longitude": "72.85551944255991"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85551944255991,
    19.30697449968205
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-16T07:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "7",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Avishkar Garden CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Poonam Vihar Complex ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "701",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
}
```

```
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "65015772a8e9b70221e18a03",
"ownerName": "Rekha Anil Virani ",
"ownerPhoneNo": "9819842522",
"appAddress": "Flat ",
"remark": "privious report vastukala ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/65015772a8e9b70221e18a03/document_1694586680069_.1",
    "fileName": "document_1694586680069_.1",
    "displayStatus": false,
    "id": "307483",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Sep 13 2023 12:01:40 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003756",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "597884",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Sep 13 2023 12:02:18 GMT+0530 (India Standard Time)"
  }
],
```



```
"owners": [
  {
    "name": "Rekha Anil Virani ",
    "phone": "9819842522",
    "ownershipShare": "",
    "email": "",
    "id": "428163"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1d7",
    "name":
"externallmg_1695184272799_IMG_20230918_160847_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272799_IMG_20230918_160847_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1d8",
    "name":
"externallmg_1695184272807_IMG_20230918_160850_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272807_IMG_20230918_160850_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1d9",
    "name":
"externallmg_1695184272845_IMG_20230918_160858_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272845_IMG_20230918_160858_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1da",
    "name":
"externallmg_1695184272861_IMG_20230918_160900_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272861_IMG_20230918_160900_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1db",
    "name":
"externallmg_1695184272868_IMG_20230918_160905_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272868_IMG_20230918_160905_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1dc",
    "name":
"externallmg_1695184272874_IMG_20230918_160906_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272874_IMG_20230918_160906_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1dd",
    "name":
"externallmg_1695184272884_IMG_20230918_160909_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184272884_IMG_20230918_160909_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a7591612315172eabe1de",
```

```
    "name":  
    "externallmg_1695184272897_IMG_20230918_160913_copy_900x1200.jpg",  
    "path": "cases/65015772a8e9b70221e18a03/  
externallmg_1695184272897_IMG_20230918_160913_copy_900x1200.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650a7591612315172eabe1df",  
    "name":  
    "externallmg_1695184272908_IMG_20230918_160918_copy_1600x1200.jpg",  
    "path": "cases/65015772a8e9b70221e18a03/  
externallmg_1695184272908_IMG_20230918_160918_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650a7591612315172eabe1e0",  
    "name":  
    "externallmg_1695184272914_IMG_20230918_160919_copy_1600x1200.jpg",  
    "path": "cases/65015772a8e9b70221e18a03/  
externallmg_1695184272914_IMG_20230918_160919_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650a75a2612315172eabe2bd",  
    "name":  
    "externallmg_1695184290558_IMG_20230918_160923_copy_1600x1200.jpg",  
    "path": "cases/65015772a8e9b70221e18a03/  
externallmg_1695184290558_IMG_20230918_160923_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650a75a2612315172eabe2be",  
    "name":  
    "externallmg_1695184290569_IMG_20230918_160932_copy_1600x1200.jpg",  
    "path": "cases/65015772a8e9b70221e18a03/  
externallmg_1695184290569_IMG_20230918_160932_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650a75a2612315172eabe2bf",
  "name":
"externallmg_1695184290589_IMG_20230918_160935_copy_1600x1200.jpg",
  "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290589_IMG_20230918_160935_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650a75a2612315172eabe2c0",
  "name":
"externallmg_1695184290596_IMG_20230918_160936_copy_1600x1200.jpg",
  "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290596_IMG_20230918_160936_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650a75a2612315172eabe2c1",
  "name":
"externallmg_1695184290603_IMG_20230918_161358_copy_900x1200.jpg",
  "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290603_IMG_20230918_161358_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650a75a2612315172eabe2c2",
  "name":
"externallmg_1695184290620_IMG_20230918_161400_copy_900x1200.jpg",
  "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290620_IMG_20230918_161400_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650a75a2612315172eabe2c3",
  "name":
"externallmg_1695184290641_IMG_20230918_161555_copy_900x1200.jpg",
```

```
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290641_IMG_20230918_161555_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2c4",
    "name":
"externallmg_1695184290651_IMG_20230918_161656_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290651_IMG_20230918_161656_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2c5",
    "name":
"externallmg_1695184290656_IMG_20230918_161657_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290656_IMG_20230918_161657_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2c6",
    "name":
"externallmg_1695184290662_IMG_20230918_161701_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290662_IMG_20230918_161701_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2c7",
    "name":
"externallmg_1695184290674_IMG_20230918_161724_copy_901x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290674_IMG_20230918_161724_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "650a75a2612315172eabe2c8",
    "name":
"externallmg_1695184290691_IMG_20230918_161729_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290691_IMG_20230918_161729_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2c9",
    "name":
"externallmg_1695184290709_IMG_20230918_161730_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290709_IMG_20230918_161730_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2ca",
    "name":
"externallmg_1695184290727_IMG_20230918_161745_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290727_IMG_20230918_161745_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2cb",
    "name":
"externallmg_1695184290747_IMG_20230918_161746_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290747_IMG_20230918_161746_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2cc",
    "name":
"externallmg_1695184290770_IMG_20230918_194554_copy_900x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290770_IMG_20230918_194554_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2cd",
    "name":
"externallmg_1695184290818_IMG_20230918_194608_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290818_IMG_20230918_194608_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650a75a2612315172eabe2ce",
    "name":
"externallmg_1695184290828_IMG_20230918_194649_copy_1600x1200.jpg",
    "path": "cases/65015772a8e9b70221e18a03/
externallmg_1695184290828_IMG_20230918_194649_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-13T06:32:18.506Z",
"updatedAt": "2023-09-20T04:31:30.994Z",
"__v": 0,
"invoiceId": "65015773a8e9b70221e18a1a",
"fullAddress": " Flat No. 701, 7th Floor, Wing - B, Avishkar Garden CHSL, Poonam
Vihar Complex , Mira Road East, Thane",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Rekha Anil Virani ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819842522"
}
```

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| <hr/> | | | |
| Composition : | | | |
| <hr/> | | | |
| Other | | | |
| Composition : | | | |
| <hr/> | | | |