

```
{
  "typeOfReport": {
    "label": "Amalgamated Flats",
    "value": "Amalgamated_Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9fb"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418df",
    "email": "nayan.bosamia@cosmosbank.in",
    "firstName": "Nayan Bosamia",
    "mobileNo": "9321889545",
    "workMobileNo": "9321889545",
    "lastName": "Bosamia"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "30000000",
    "discussWithPerson": "Nayan Bosamia",
    "expectedFees": 15000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9fb",
  "branchCode": "000015",
  "type": "BRANCH",
  "name": "Vile Parle (East) Branch",
  "email": "vileparle@cosmosbank.in",
  "mobileNo": "912226191096",
  "alternateMobileNo": "",
  "address": "Pratik Evenue, Ground Floor, Opp. Shivsagar Hotel, Nehru Road, Vile
Parle (East), Mumbai - 400 057, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.120971280770085",
```

```
"longitude": "72.8845666279113"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8845666279113,
    19.120971280770085
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-15",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-15",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Marol",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
```

```
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lok Sarita",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Marol Military Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```

```
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```



```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "714",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
```

```
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```

```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6502a0eaa8e9b70221e36589",
"ownerName": "Bambhaniya Baulal Laxman",
"ownerPhoneNo": "9930201915",
"appAddress": "Flat no - 713/714, 7th floor, bldg - D, Lok sarita co operative housing
society Ltd, marol, Andheri East, military road ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6502a0eaa8e9b70221e36589/
document_1694671237139_CB__713.pdf",
    "fileName": "document_1694671237139_CB__713.pdf",
    "displayStatus": false,
    "id": "552622",
```



```
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Thu Sep 14 2023 11:31:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "path": "cases/6502a0eaa8e9b70221e36589/
document_1694671265691_CB__714.pdf",
  "fileName": "document_1694671265691_CB__714.pdf",
  "displayStatus": false,
  "id": "679463",
  "uploadedBy": "62723addafd7d55eddeddfe4",
  "createdAt": "Thu Sep 14 2023 11:31:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003785",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "170696",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 14 2023 11:28:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bambhaniya Baulal Laxman",
    "phone": "9930201915",
    "ownershipShare": "",
    "email": "",
    "id": "455741"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f803",
  "name": "externallmg_1694782759183_1694782655243_image_0.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782759183_1694782655243_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f804",
  "name": "externallmg_1694782759509_1694782655243_image_1.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782759509_1694782655243_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f805",
  "name": "externallmg_1694782759789_1694782655243_image_2.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782759789_1694782655243_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f806",
  "name": "externallmg_1694782759982_1694782655243_image_3.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782759982_1694782655243_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f807",
  "name": "externallmg_1694782760605_1694782655243_image_4.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782760605_1694782655243_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f808",
    "name": "externallmg_1694782760972_1694782655243_image_5.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782760972_1694782655243_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f809",
    "name": "externallmg_1694782761351_1694782655243_image_6.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782761351_1694782655243_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f80a",
    "name": "externallmg_1694782761552_1694782655243_image_7.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782761552_1694782655243_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f80b",
    "name": "externallmg_1694782761778_1694782655243_image_8.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782761778_1694782655243_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f80c",
    "name": "externallmg_1694782762075_1694782655243_image_9.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782762075_1694782655243_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65045580a8e9b70221e6f80d",
  "name": "externallmg_1694782762610_1694782655243_image_10.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782762610_1694782655243_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f80e",
  "name": "externallmg_1694782805927_1694782701935_image_0.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782805927_1694782701935_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f80f",
  "name": "externallmg_1694782806290_1694782701935_image_1.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782806290_1694782701935_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f810",
  "name": "externallmg_1694782806899_1694782701936_image_2.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782806899_1694782701936_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65045580a8e9b70221e6f811",
  "name": "externallmg_1694782807101_1694782701936_image_3.jpeg",
  "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782807101_1694782701936_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65045580a8e9b70221e6f812",
    "name": "externallmg_1694782807457_1694782701936_image_4.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782807457_1694782701936_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f813",
    "name": "externallmg_1694782807846_1694782701936_image_5.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782807846_1694782701936_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f814",
    "name": "externallmg_1694782808147_1694782701936_image_6.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782808147_1694782701936_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f815",
    "name": "externallmg_1694782808489_1694782701936_image_7.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782808489_1694782701936_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f816",
    "name": "externallmg_1694782808905_1694782701936_image_8.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782808905_1694782701936_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f817",
```

```
    "name": "externallmg_1694782809247_1694782701936_image_9.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782809247_1694782701936_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f818",
    "name": "externallmg_1694782843777_1694782739180_image_0.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782843777_1694782739180_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f819",
    "name": "externallmg_1694782844248_1694782739180_image_1.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782844248_1694782739180_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f81a",
    "name": "externallmg_1694782845102_1694782739180_image_2.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782845102_1694782739180_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65045580a8e9b70221e6f81b",
    "name": "externallmg_1694782845702_1694782739180_image_3.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782845702_1694782739180_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65045580a8e9b70221e6f81c",
    "name": "externallmg_1694782675804_1694782571886_image_0.jpeg",
```

```
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782675804_1694782571886_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65045580a8e9b70221e6f81d",
    "name": "externallmg_1694782676234_1694782571886_image_1.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782676234_1694782571886_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65045580a8e9b70221e6f81e",
    "name": "externallmg_1694782676289_1694782571886_image_2.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694782676289_1694782571886_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6505247ba8e9b70221e71753",
    "name":
"externallmg_1694835835479_WhatsApp_Image_20230915_at_64237_PM_1.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694835835479_WhatsApp_Image_20230915_at_64237_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6505247ba8e9b70221e71754",
    "name":
"externallmg_1694835835486_WhatsApp_Image_20230915_at_64237_PM.jpeg",
    "path": "cases/6502a0eaa8e9b70221e36589/
externallmg_1694835835486_WhatsApp_Image_20230915_at_64237_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6505247ba8e9b70221e71755",
```

```

"name":
"externalImg_1694835835493_WhatsApp_Image_20230915_at_64238_PM_1.jpeg",
"path": "cases/6502a0eaa8e9b70221e36589/
externalImg_1694835835493_WhatsApp_Image_20230915_at_64238_PM_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6505247ba8e9b70221e71756",
"name":
"externalImg_1694835835500_WhatsApp_Image_20230915_at_64238_PM.jpeg",
"path": "cases/6502a0eaa8e9b70221e36589/
externalImg_1694835835500_WhatsApp_Image_20230915_at_64238_PM.jpeg",
"orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-14T05:58:02.041Z",
"updatedAt": "2023-09-16T03:43:55.610Z",
"__v": 0,
"updatedBy": "6006d4ce5080a310ac1fd2c2",
"fullAddress": " Amalgamated Flats No. 714, 7th Floor, Wing - D, Lok Sarita, Marol
Military Road, Village - Marol, Andheri East, Mumbai",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Bambhaniya Baulal Laxman",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930201915"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			