

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "21.129381854370934",
  "longitude": "79.05969252024033"
},
"geo": {
  "type": "Point",
  "coordinates": [
    79.05969252024033,
```

```
21.129381854370934
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-17",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2.5BHK",
  "label": "2.5 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nahur",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "29",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhandup (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Runwal Oakwood Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mulund Goregaon Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Fortis Hospital",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Runwal Greens",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "681/A (Part), 681/A3-A8, 681/B",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "681A/7, 681A/8 & 681A/9",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "2904",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 078",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_with_POP_false_Ceiling",
    "label": "Cement Plastering with POP false Ceiling"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Mulund Goregaon Link Road",
  "west": "Internal Road",
  "south": "Runwal Greens Tower No. 8",
  "east": "Runwal Greens Tower No. 2"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "title": "Boundaries of The Flat",
  "isDisplay": false
},
"extraDetailOfProperty": "",
```

"dateOfIssusApprovePlan": "Copy of Approved Plan Vide No. CE / 469 / BPES / AS dated 28.06.2018 issued by Municipal Corporation of Greater Mumbai. (Downloaded from MCGM site)",

"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No"

},

"compositeRate": {

"remark": "",
"depreciationPercentage": "9",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "27730",
"depreciatedBuildingRate": "2730"

},

"igrRate": {

"propertyName": "Runwal Greens, Nahur",
"rate": "149950",
"landRate": "74970",
"igrImage": "cases/65041feda8e9b70221e60b62/igr_1695362835999_Image.png",
"squareMeterGuideLineRate": "172443.00",
"squareFeetGuideLineRate": "16020.00"

},

"igrFinalRate": {

"depreciationPercentage": "94",
"rate": "15477.00",
"squareFeetGuideLineRate": "15477.00",
"squareMeterGuideLineRate": "166594.00"

},

"outgoingDetail": {

"areaStatusList": {
"value": "Medium",
"label": "Medium"

},

"propertyTypeOfUseList": {

"value": "Residential_Purpose",
"label": "Residential Purpose"

},

"propertyOccupiedByList": {

"value": "Owner_Occupied",
"label": "Owner Occupied"

},

"monthlyRent": "64,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "000074695094 "

```
"meterCardHolderName": "Sushma Nagendra Rao ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2017",
    "fullDate": "1/1/2017"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "54",
"ageOfBuilding": "6",
"noOfBasement": "2",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "36",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1017.50",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
```



```
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/65041feda8e9b70221e60b62/
routeMap_1695376225926_Image.png",
  "routeLat": "19.161611",
  "routeLng": "72.944472",
  "stationName": "Nahur",
  "routeDistance": "1 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "6jqmoa",
    "name": "6jqmoa",
    "image": "cases/65041feda8e9b70221e60b62/
routeMap_1695376107138_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "25650250.00",
"distressValuePercentage": "0",
"realizableValuePercentage": "0",
"bookValue": "0",
"finalValue": "25650250.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "15747848.00",
  "selectedBuildUpValue": "1017.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65068e6ca8e9b70221e8e8fa",
      "name": "externallmg_r_1694928432743_1694928329178_image_0.jpg",
      "path": "cases/65041feda8e9b70221e60b62/externallmg_r_1694928432743_1694928329178_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65068e6ca8e9b70221e8e8fb",
      "name": "externallmg_r_1694928433101_1694928329178_image_2.jpg",
      "path": "cases/65041feda8e9b70221e60b62/externallmg_r_1694928433101_1694928329178_image_2.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65068e6ca8e9b70221e8e8fc",
      "name": "externallmg_r_1694928434155_1694928329178_image_3.jpg",
      "path": "cases/65041feda8e9b70221e60b62/externallmg_r_1694928434155_1694928329178_image_3.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65068e6ca8e9b70221e8e8f9",
```

```
    "name": "externallmg_r_1694928432987_1694928329178_image_1.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928432987_1694928329178_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fa",
    "name": "externallmg_r_1694928432743_1694928329178_image_0.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928432743_1694928329178_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fd",
    "name": "externallmg_r_1694928435070_1694928329178_image_4.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928435070_1694928329178_image_4.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fe",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928436154_1694928329178_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8ff",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928437175_1694928329178_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e900",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928438481_1694928329178_image_7.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e901",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928440267_1694928329178_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e902",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928442172_1694928329178_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e903",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928444652_1694928329178_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e908",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928458322_1694928329178_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65068e6ca8e9b70221e8e906",
    "name": "Living Room",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928452902_1694928329178_image_13.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "27027",
"max": "28680"
},
"builtUpRateRange": {
  "min": "24571",
  "max": "26073"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "925.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65041feda8e9b70221e60b62",
"ownerName": "Mrs. Sushma Nagendra Rao & Mr. Nagendra Ramchandra Rao",
"ownerPhoneNo": "9833202309",
"appAddress": "Flat no. 2904, 29th Floor, Building no. 1, Wing - A, Oakwood, Runwal Greens, Bhandup West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "17/05/2017",
  "from": {
    "value": "Owner",
    "label": "Owner"
  },
  "Owner": "Runwal Homes Private Limited",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mrs. Sushma Nagendra Rao & Mr. Nagendra Ramchandra Rao"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695374964682_document_1694769046832_Racpc_GHatkopar_Sushma_Rao.pdf",
"path": "cases/65041feda8e9b70221e60b62/document_1695374964682_document_1694769046832_Racpc_GHatkopar_Sushma_Rao.pdf",
"id": "824259",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 22 2023 14:59:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/05/2017",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 469 / BPES / AS"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695375075849_1817847.pdf",
  "path": "cases/65041feda8e9b70221e60b62/document_1695375075849_1817847.pdf",
```

```
"id": "104310",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 22 2023 15:01:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/11/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 469 / BPES / AS"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695375234141_2183609_FurtherCC_signed.pdf",
"path": "cases/65041feda8e9b70221e60b62/
document_1695375234141_2183609_FurtherCC_signed.pdf",
"id": "381369",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 22 2023 15:03:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "28/06/2018",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 469 / BPES / AS"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1695375433089_Drawing.pdf",
    "path": "cases/65041feda8e9b70221e60b62/
document_1695375433089_Drawing.pdf",
    "id": "479294",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Fri Sep 22 2023 15:07:13 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f3",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "17/06/2023",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Sushma Nagendra Rao ",
      "number": {
        "value": "Consumer_No",
        "label": "Consumer No"
      },
      "Consumer_No": "000074695094"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1695383358150_document_1694769046832_Racpc_GHatko
par_Sushma_Rao.pdf",
    "path": "cases/65041feda8e9b70221e60b62/document_1695383358150_document
_1694769046832_Racpc_GHatkopar_Sushma_Rao.pdf",
    "id": "466131",
    "uploadedBy": "60f915d3f3dd69653a592199",
    "createdAt": "Fri Sep 22 2023 17:19:18 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "17/06/2023",
      "to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Sushma Nagendra Rao ",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "172"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695383521432_document_1694769046832_Racpc_GHatkopar_Sushma_Rao.pdf",
"path": "cases/65041feda8e9b70221e60b62/document_1695383521432_document_1694769046832_Racpc_GHatkopar_Sushma_Rao.pdf",
"id": "329099",
"uploadedBy": "60f915d3f3dd69653a592199",
"createdAt": "Fri Sep 22 2023 17:22:01 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003834",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "156804",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 15 2023 14:42:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Sushma Nagendra Rao & Mr. Nagendra Ramchandra Rao",
    "phone": "9833202309",
    "ownershipShare": "",
    "email": "",
    "id": "474511"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "612213",
  "name": "Living Room",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "17.75",
  "width1": "17",
  "width2": "9",
  "totalArea": "193.77",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "650d5c31612315172eafb66d",
      "name": "Entrance",
      "extraAreaType": "Add",
      "length": "9.33",
      "length1": "9",
      "length2": "4",
      "width": "3.25",
      "width1": "3",
      "width2": "3",
      "totalArea": "30.33"
    }
  ],
  "finalArea": "224.10000000000002"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "50.87",
```

```
"images": [],
"extraAreas": [],
"finalArea": "50.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "99.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "99.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "72.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
```



```
"name": "Bedroom",
"length": "10.17",
"length1": "10",
"length2": "2",
"width": "14.25",
"width1": "14",
"width2": "3",
"totalArea": "144.87",
"images": [],
"extraAreas": [],
"finalArea": "144.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "105.71",
  "images": [],
  "extraAreas": [],
  "finalArea": "105.71"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "21.40",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "21.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "35.14",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.14"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "35.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.39"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
```

```
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "10",
  "length2": "5",
  "length": "10.42",
  "width1": "5",
  "width2": "5",
  "width": "5.42",
  "totalArea": "56.42",
  "percentageBeforeTotal": "56.42",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "56.42"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "10",
  "length2": "3",
  "length": "10.25",
  "width1": "3",
  "width2": "5",
  "width": "3.42",
  "totalArea": "35.02",
  "percentageBeforeTotal": "35.02",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
```

```
"finalArea": "35.02"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "7",
  "length2": "9",
  "length": "7.75",
  "width1": "1",
  "width2": "9",
  "width": "1.75",
  "totalArea": "13.56",
  "percentageBeforeTotal": "13.56",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.56"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "300575",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "925",
    "squareMeterArea": "85.93",
    "docFinalBuiltUp": "1017.5",
```

```
"docFinalBuiltUpSquareMeter": "94.52300000000001",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"printlnReport": true,
"_id": "650d2f55612315172eaf31d1",
"property": "Runwal Greens, Nahur",
"area": "925",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "37",
"source": "https://www.99acres.com/",
"expectedPrice": "25500000",
"expectedRate": "27567.57",
"builtUpExpectedRate": "25061.43",
"image": "cases/65041feda8e9b70221e60b62/
indicator_1695362051204_Image.png",
"squareMeter": "85.94",
"id": "856726"
},
{
"printlnReport": true,
"_id": "650d2f55612315172eaf31d2",
"property": "Runwal Greens, Nahur",
"area": "925",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "magic_bricks",
"expectedPrice": "26000000",
"expectedRate": "28108.11",
"builtUpExpectedRate": "25552.83",
"image": "cases/65041feda8e9b70221e60b62/
indicator_1695362158073_Image.png",
"squareMeter": "85.94",
"id": "493009"
}
```

```
},
{
  "printlnReport": true,
  "_id": "650d2f55612315172eaf31d3",
  "property": "Runwal Greens, Nahur",
  "area": "925",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "22",
  "source": "magic_bricks",
  "expectedPrice": "25000000",
  "expectedRate": "27027.03",
  "builtUpExpectedRate": "24570.02",
  "image": "cases/65041feda8e9b70221e60b62/
indicator_1695362255291_Image.png",
  "squareMeter": "85.94",
  "id": "634037"
},
{
  "printlnReport": true,
  "_id": "650d2f55612315172eaf31d4",
  "property": "Runwal Greens, Nahur",
  "area": "924",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "12",
  "source": "magic_bricks",
  "expectedPrice": "26500000",
  "expectedRate": "28679.65",
  "builtUpExpectedRate": "26072.41",
  "image": "cases/65041feda8e9b70221e60b62/
indicator_1695362324904_Image.png",
  "squareMeter": "85.84",
  "id": "274195"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8f9",
    "name": "externallmg_r_1694928432987_1694928329178_image_1.jpg",
```

```
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928432987_1694928329178_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fa",
    "name": "externallmg_r_1694928432743_1694928329178_image_0.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928432743_1694928329178_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fb",
    "name": "externallmg_r_1694928433101_1694928329178_image_2.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928433101_1694928329178_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fc",
    "name": "externallmg_r_1694928434155_1694928329178_image_3.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928434155_1694928329178_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fd",
    "name": "externallmg_r_1694928435070_1694928329178_image_4.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928435070_1694928329178_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65068e6ca8e9b70221e8e8fe",
    "name": "externallmg_r_1694928436154_1694928329178_image_5.jpg",
    "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928436154_1694928329178_image_5.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e8ff",
  "name": "externallmg_r_1694928437175_1694928329178_image_6.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928437175_1694928329178_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e900",
  "name": "externallmg_r_1694928438481_1694928329178_image_7.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928438481_1694928329178_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e901",
  "name": "externallmg_r_1694928440267_1694928329178_image_8.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928440267_1694928329178_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e902",
  "name": "externallmg_r_1694928442172_1694928329178_image_9.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928442172_1694928329178_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e903",
  "name": "externallmg_r_1694928444652_1694928329178_image_10.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928444652_1694928329178_image_10.jpg",
  "orientation": "portrait"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e904",
  "name": "externallmg_r_1694928446908_1694928329178_image_11.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928446908_1694928329178_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e905",
  "name": "externallmg_r_1694928449856_1694928329178_image_12.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928449856_1694928329178_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e906",
  "name": "externallmg_r_1694928452902_1694928329178_image_13.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928452902_1694928329178_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e907",
  "name": "externallmg_r_1694928456179_1694928329178_image_15.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928456179_1694928329178_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e908",
  "name": "externallmg_r_1694928458322_1694928329178_image_16.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928458322_1694928329178_image_16.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e909",
  "name": "externallmg_r_1694928454304_1694928329178_image_14.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928454304_1694928329178_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e90a",
  "name": "externallmg_r_1694928460734_1694928329178_image_17.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928460734_1694928329178_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e90b",
  "name": "externallmg_r_1694928462713_1694928329178_image_18.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928462713_1694928329178_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e90c",
  "name": "externallmg_r_1694928464673_1694928329178_image_19.jpg",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928464673_1694928329178_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65068e6ca8e9b70221e8e90d",
  "name": "externallmg_r_1694928163729_1694928060430_image_2.png",
  "path": "cases/65041feda8e9b70221e60b62/
externallmg_r_1694928163729_1694928060430_image_2.png",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65068e6ca8e9b70221e8e90e",
"name": "externalimg_r_1694928161952_1694928060430_image_1.jpg",
"path": "cases/65041feda8e9b70221e60b62/
externalimg_r_1694928161952_1694928060430_image_1.jpg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65068e6ca8e9b70221e8e90f",
"name": "externalimg_r_1694928160452_1694928060430_image_0.jpg",
"path": "cases/65041feda8e9b70221e60b62/
externalimg_r_1694928160452_1694928060430_image_0.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "Calculation (1).xlsx",
"filename": "1695363716664_Calculation_1.xlsx",
"path": "cases/65041feda8e9b70221e60b62/
processingDocuments/1695363716664_Calculation_1.xlsx",
"size": "1084249",
"createdAt": "Fri Sep 22 2023 11:51:56 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"remarks": [],
"createdAt": "2023-09-15T09:12:13.414Z",
"updatedAt": "2023-09-22T11:54:28.643Z",
"__v": 0,
"invoiceId": "65041feea8e9b70221e60b98",
"fullAddress": "Residential Flat No. 2904, 29th Floor, Building No 1, Wing - A, Runwal
Oakwood Co-op. Hsg. Soc. Ltd., Runwal Greens, Near Fortis Hospital, Mulund
Goregaon Link Road, Village - Nahur, Municipality Ward No. S, Taluka - Kurla, District -
Mumbai, Bhandup (West), PIN - 400 078, State - Maharashtra, India",
"updatedAt": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Sushma Nagendra Rao",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```

"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833202309",
"siteVisitDate": "2023-09-17",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 925.00",
"flatRate": "28000",
"landOtherRate": "25000",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + Passage + 2
Toilet",
"carpetTotal": "789.40",
"otherCarpetTotal": "105.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "105.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "983.84",
"finalCarpetArea": "894.40",
"finalSalableArea": "1082.22",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'11"	17'9"	193.77
Dining	9'3"	5'6"	50.87
Kitchen	11'8"	8'6"	99.17
Bedroom	8'1"	9'0"	72.75
Bedroom	10'2"	14'3"	144.87
Bedroom	9'10"	10'9"	105.71

Passage	6'7"	3'3"	21.40
Toilet	7'8"	4'7"	35.14
Toilet	8'2"	4'4"	35.39
Other Composition :			
Balcony Area	10'5"	5'5"	56.42
Balcony Area	10'3"	3'5"	35.02
Balcony Area	7'9"	1'9"	13.56