

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd93aace84bf289baab038",
    "firstName": "Pranjli ",
    "lastName": "Prabhu",
    "mobileNo": "",
    "workMobileNo": "9969957108",
    "email": "pranjli.prabhu@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Pranjli ",
    "expectedFees": 3000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.053789067912522",
  "longitude": "72.87046392086697"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87046392086697,
    19.053789067912522
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kurla - 3",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "17",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1/B",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Sion - Chunabhatti",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Darshan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Swadeshi Mill Road",
  "label": false
},
"street2": {
  "status": false,
```



```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Swadeshi Mill MHADA Sankul",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "477C (P)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1708",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "L",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 022",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sion",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
}
```

```
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Old MHADA Building",
    "west": "Railway Track",
    "south": "Reliance Mall",
    "east": "Swadeshi Mill Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  }
}
```

```
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "The property is constructed by MHADA. MHADA itself is
planning authority.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "18005",
  "depreciatedBuildingRate": "2505"
},
"igrRate": {
  "propertyName": "Kurla",
  "rate": "125170",
  "landRate": "49960",
  "igrImage": "cases/650422b3a8e9b70221e618a6/igr_1695373515591_Image.png",
  "squareMeterGuideLineRate": "137687.00",
  "squareFeetGuideLineRate": "12792.00"
},
"igrFinalRate": {
  "depreciationPercentage": "89",
  "rate": "11895.00",
  "squareFeetGuideLineRate": "11895.00",
  "squareMeterGuideLineRate": "128037.00"
},
"outgoingDetail": {
```

```
"areaStatusList": {
  "value": "Medium",
  "label": "Medium"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "10,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MHADA norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
```

```
"label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
```

```
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "49",
```



```
"ageOfBuilding": "11",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "19",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "12"
},
"finalPlinthArea": {
  "area": "270.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/650422b3a8e9b70221e618a6/
routeMap_1695380575393_Image.png",
    "routeLat": "19.055861",
    "routeLng": "72.872083",
    "stationName": "Chunnabhatti",
    "routeDistance": "550 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "qc3e1",
      "name": "qc3e1",
      "image": "cases/650422b3a8e9b70221e618a6/
routeMap_1695380525852_Image.png"
    }
  ]
}
```

```
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4051125.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "4051125.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Sep 22 2023 17:38:42 GMT+0530 (India Standard Time)",
  "number": "2302676",
  "dayCount": "13",
  "monthCount": "320",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3211650.00",
  "selectedBuildUpValue": "270.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65084f18612315172eabc094",
      "name": "externalimg_1695043345139_1695043233790_image_13.jpeg",
      "path": "cases/650422b3a8e9b70221e618a6/
externalimg_1695043345139_1695043233790_image_13.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "65084f18612315172eabc097",
    "name": "externallmg_1695043347789_1695043233790_image_16.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043347789_1695043233790_image_16.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65084f18612315172eabc092",
    "name": "externallmg_1695043342922_1695043233790_image_11.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043342922_1695043233790_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc090",
    "name": "externallmg_1695043341409_1695043233790_image_9.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043341409_1695043233790_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc096",
    "name": "externallmg_1695043346569_1695043233790_image_15.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043346569_1695043233790_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc094",
    "name": "externallmg_1695043345139_1695043233790_image_13.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043345139_1695043233790_image_13.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": [
  {
    "status": false,
    "_id": "65084f18612315172eabc087",
    "name": "Living Room",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043334872_1695043233790_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc089",
    "name": "Living Room",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043336255_1695043233790_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc08d",
    "name": "Living Room",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043339084_1695043233790_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65084f18612315172eabc08e",
    "name": "Living Room",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043340405_1695043233790_image_7.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17778",
    "max": "22936"
  },
  "builtUpRateRange": {
    "min": "14815",
    "max": "19114"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
```

```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "225.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "650422b3a8e9b70221e618a6",
"ownerName": "Mr. Rajesh Ganpat Jadhav & Mr. Rakesh Ganpat Jadhav",
"ownerPhoneNo": "9702947427",
"appAddress": "Flat no. 1708, 17th Floor, Building no. 1/B, Shiv Darshan CHS,
Chunabhatti, Sion,",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    }
  },
  "inputs": {
    "documentDate": "31/03/2022",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    }
  },
  "Vendor": "Mr. Mukhtarahmed Jan Mohd. Khan",
  "to": {
```

```
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Rajesh Ganpat Jadav & Mr. Rakesh Ganpat Jadhav",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "9859 / 2022"
},
"isHardCopy": false,
"displayStatus": true,
"id": "610938",
"path": "cases/650422b3a8e9b70221e618a6/
document_1694777082633_Sale_Deed_Mhada_1708.pdf",
"fileName": "document_1694777082633_Sale_Deed_Mhada_1708.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "24/08/2012",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 470 / BPES / Govt. / L"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "850513",
  "path": "cases/650422b3a8e9b70221e618a6/
document_1694777108452_102225.pdf",
"fileName": "document_1694777108452_102225.pdf"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
}
```

```
"inputs": {
  "documentDate": "29/10/2013",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Mukhtarahmed Jan Mohd. Khan",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Rajesh Ganpat Jadav & Mr. Rakesh Ganpat Jadhav",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "UPMU / (PNN) / MM / Girni S. No. 56 / Case No. 979 / 1513 / 13"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695379905528_Allot.pdf",
"path": "cases/650422b3a8e9b70221e618a6/document_1695379905528_Allot.pdf",
"id": "447621",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 22 2023 16:21:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "inputs": {
    "documentDate": "29/10/2013",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Housing_and_Area_Development_Board",
      "label": "Mumbai Housing and Area Development Board"
    }
  }
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695379956400_posee.pdf",
"path": "cases/650422b3a8e9b70221e618a6/
document_1695379956400_posee.pdf",
"id": "583618",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 22 2023 16:22:36 GMT+0530 (India Standard Time)"
```

```
}
],
"caseNumber": "003835",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "669120",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 15 2023 14:54:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajesh Ganpat Jadhav & Mr. Rakesh Ganpat Jadhav",
    "phone": "9702947427",
    "ownershipShare": "",
    "email": "",
    "id": "442715"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "330277",
    "name": "Living Room",
    "length": "9.58",
    "length1": "9",
    "length2": "7",
    "width": "7.75",
    "width1": "7",
    "width2": "9",
    "totalArea": "74.27",
    "images": [],
    "extraAreas": [],
    "finalArea": "74.27"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "1",
  "name": "Bedroom",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "60.57",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.57"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
  "totalArea": "53.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "53.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "30.62",
```

```
"images": [],
"extraAreas": [],
"finalArea": "30.62"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"value": "60ae1245aa6d152c1801b2e3",
"label": "Sale Deed"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"docFinalBuiltUp": "270",
"docFinalBuiltUpSquareMeter": "25.08",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"printlnReport": true,
"_id": "650d5cd1612315172eafb96f",
"property": "Swadeshi MHADA Sankul, Sion",
"area": "225",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Nobroker.com",
"expectedPrice": "4300000",
"expectedRate": "19111.11",
"builtUpExpectedRate": "15925.93",
"image": "cases/650422b3a8e9b70221e618a6/
indicator_1695369358482_Image.png",
```

```
"squareMeter": "20.90",
"id": "385167"
},
{
  "printlnReport": true,
  "_id": "650d5cd1612315172eafb970",
  "property": "Swadeshi MHADA Sankul, Sion",
  "area": "225",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "4000000",
  "expectedRate": "17777.78",
  "builtUpExpectedRate": "14814.81",
  "image": "cases/650422b3a8e9b70221e618a6/
indicator_1695369488872_Image.png",
  "squareMeter": "20.90",
  "id": "170374"
},
{
  "printlnReport": true,
  "_id": "650d5cd1612315172eafb971",
  "property": "Swadeshi Sankul, Sion",
  "area": "545",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "12500000",
  "expectedRate": "22935.78",
  "builtUpExpectedRate": "19113.15",
  "image": "cases/650422b3a8e9b70221e618a6/
indicator_1695374308744_Image.png",
  "squareMeter": "50.63",
  "id": "395632"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "65084f18612315172eabc087",
    "name": "externallmg_1695043334872_1695043233790_image_0.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043334872_1695043233790_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc088",
    "name": "externallmg_1695043335683_1695043233790_image_1.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043335683_1695043233790_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc089",
    "name": "externallmg_1695043336255_1695043233790_image_2.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043336255_1695043233790_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08a",
    "name": "externallmg_1695043337255_1695043233790_image_3.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043337255_1695043233790_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08b",
    "name": "externallmg_1695043337392_1695043233790_image_4.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043337392_1695043233790_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08c",
```

```
    "name": "externallmg_1695043337900_1695043233790_image_5.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043337900_1695043233790_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08d",
    "name": "externallmg_1695043339084_1695043233790_image_6.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043339084_1695043233790_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08e",
    "name": "externallmg_1695043340405_1695043233790_image_7.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043340405_1695043233790_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc08f",
    "name": "externallmg_1695043340812_1695043233790_image_8.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043340812_1695043233790_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc090",
    "name": "externallmg_1695043341409_1695043233790_image_9.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043341409_1695043233790_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc091",
    "name": "externallmg_1695043342570_1695043233790_image_10.jpeg",
```

```
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043342570_1695043233790_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc092",
    "name": "externallmg_1695043342922_1695043233790_image_11.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043342922_1695043233790_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc093",
    "name": "externallmg_1695043344432_1695043233790_image_12.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043344432_1695043233790_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc094",
    "name": "externallmg_1695043345139_1695043233790_image_13.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043345139_1695043233790_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc095",
    "name": "externallmg_1695043345952_1695043233790_image_14.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043345952_1695043233790_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65084f18612315172eabc096",
    "name": "externallmg_1695043346569_1695043233790_image_15.jpeg",
    "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043346569_1695043233790_image_15.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65084f18612315172eabc097",
  "name": "externallmg_1695043347789_1695043233790_image_16.jpeg",
  "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043347789_1695043233790_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65084f18612315172eabc098",
  "name": "externallmg_1695043310076_1695043206473_image_0.jpeg",
  "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043310076_1695043206473_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65084f18612315172eabc099",
  "name": "externallmg_1695043311613_1695043206473_image_1.jpeg",
  "path": "cases/650422b3a8e9b70221e618a6/
externallmg_1695043311613_1695043206473_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (1).xlsx",
    "filename": "1695374579195_Calculation_1.xlsx",
    "path": "cases/650422b3a8e9b70221e618a6/
processingDocuments/1695374579195_Calculation_1.xlsx",
    "size": "613815",
    "createdAt": "Fri Sep 22 2023 14:52:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [],
"createdAt": "2023-09-15T09:24:03.708Z",
"updatedAt": "2023-09-22T12:11:02.273Z",
"__v": 0,
```

"invoiceId": "650422b4a8e9b70221e618bd",  
 "fullAddress": "Residential Flat No. 1708, 17th Floor, Building No 1/B, Shiv Darshan Co-op. Hsg. Soc. Ltd., Swadeshi Mill MHADA Sankul, Swadeshi Mill Road, Village - Kurla - 3, Municipality Ward No. L, Sion, District - Mumbai, Sion - Chunabhatti, PIN - 400 022, State - Maharashtra, India",  
 "updatedBy": "60f915d3f3dd69653a592199",  
 "addressForMap": "",  
 "caseReferredBy": "60b7177d2ffdf65bcd65882a",  
 "contactPersonName": "Mr. Rajesh Ganpat Jadav",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "siteVisitContactNo": "9702947427",  
 "siteVisitDate": "2023-09-18",  
 "buildingServicesRate": "3000",  
 "finalAreaType": "Carpet Area",  
 "finalAsPerArea": "Sale Deed",  
 "finalBuiltUpPercentage": "20",  
 "finalCarpetConvertToBuiltUpPer": "20",  
 "finalMeasurementType": "Sq. Ft.",  
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 225.00",  
 "flatRate": "18500",  
 "landOtherRate": "15500",  
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet",  
 "carpetTotal": "219.13",  
 "otherCarpetTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "241.04",  
 "finalCarpetArea": "219.13",  
 "finalSalableArea": "265.15",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "",  
 "finalSaleablePercentage": "0"

Name	Length	Width	Total
Composition :			
Living Room	9'7"	7'9"	74.27
Bedroom	8'2"	7'5"	60.57

Kitchen	9'4"	5'9"	53.67
Toilet	3'6"	8'9"	30.62
Other Composition :			