

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3200000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 1600,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "627219d6afd7d55eddedd283",
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c8cdd2a5c3051014f62c65",
"role": "SITEENGINEER",
"firstName": "Bhavesh",
"email": "freelancevaluer@gmail.com",
"lastName": "Shelar",
"mobileNo": "9272696074",
"designation": "",
"shortName": "BSS",
"workWithDocumentMaker": "",
"profilePhoto": "users/64c8cdd2a5c3051014f62c65/profilePhoto_1690881490040_3
25961526_225125063269350_5532229620043102208_n.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER + RATE VERFIER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": "",
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.41874322949438",
  "longitude": "72.83287389520036"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83287389520036,
    19.41874322949438
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-16T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-16T03:00:00.000Z",
      "remark": ""
    }
  ]
}
```

```
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"compositionFlatType": {
"value": "1BHK",
"label": "1 BHK"
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
"status": true,
"name": "Village",
"key": "village",
"value": "Achole",
"label": true
},
"floorNo": {
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
"status": true,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "Type A",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Star Residency \"B\" in Star Residency Bldg B & B2 Co-Op. Hsg. Soc. Ltd.",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Star Residency Complex",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Evershine City",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "272",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "Vasai Road (East)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters",
    "label": "Teak Wood Door Frame With Flush Shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
```

```
"label": "CIDCO"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Regal Plaza Building",
  "west": "Bungalow / Star Residency 'A' Wing",
  "south": "Internal Road",
  "east": "Garden Area"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "5000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Yes",
"constructionWorkStatus": {
  "value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "40",
"ageOfBuilding": "20",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
```

```
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "495.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65050b71a8e9b70221e70fea/
routeMap_1695470418814_Image.png",
    "routeLat": "19.407861",
    "routeLng": "72.834306",
    "stationName": "Vasai Road",
    "routeDistance": "4.3KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "71pzl9",
      "name": "71pzl9",
      "image": "cases/65050b71a8e9b70221e70fea/
routeMap_1695470190844_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```



```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "495.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "650e863b0c1bfd1d9fddce1d",
      "name": "externalimg_1695450683458_IMG20230921WA0028.jpg",
      "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683458_IMG20230921WA0028.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddcebb",
    "name": "externallmg_1695450702532_IMG20230921WA0031.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702532_IMG20230921WA0031.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce1f",
    "name": "externallmg_1695450683470_IMG20230921WA0030.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683470_IMG20230921WA0030.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce21",
    "name": "externallmg_1695450683477_IMG20230921WA0034.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683477_IMG20230921WA0034.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddcebc",
    "name": "externallmg_1695450702536_IMG20230921WA0032.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702536_IMG20230921WA0032.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceba",
    "name": "externallmg_1695450702530_IMG20230921WA0027.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702530_IMG20230921WA0027.jpg",
```

```
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce1a",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683449_IMG20230921WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb1",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702513_IMG20230921WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceaf",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702507_IMG20230921WA0014.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb3",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702516_IMG20230921WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb4",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702519_IMG20230921WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "650e864e0c1bfd1d9fddceb6",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702522_IMG20230921WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb8",
    "name": "Living Room",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702526_IMG20230921WA0025.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "495.00",
```



```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "65050b71a8e9b70221e70fea",
"ownerName": "Mr. Mehul Gunvantrai Malkan & Mrs. Neelam Mehul Malkan",
"ownerPhoneNo": "9321482026",
"appAddress": "flat b/01 type a i star residency b star residency bldg b & b2 cha star
residency complex evershine city achole vasai east",
"remark": "loan AMT 25.6 lack",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "12/09/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Roohi Ignatious Binoy Vadakkethala",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Mehul Gunvantrai Malkan & Mrs. Neelam Mehul Malkan"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "832428",
    "path": "cases/65050b71a8e9b70221e70fea/
document_1694829358846_mehul_malkan.pdf",
    "fileName": "document_1694829358846_mehul_malkan.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "07/01/2003",
      "nameOfApprovingAuthority": {
        "value": "CIDCO",
```

```
    "label": "CIDCO"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "CIDCO / VVSR / POC / BP / ZCC-20 / E / 4059"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695474673256_Occupancy_Certificate.pdf",
"path": "cases/65050b71a8e9b70221e70fea/
document_1695474673256_Occupancy_Certificate.pdf",
"id": "990451",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Sat Sep 23 2023 18:41:13 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003864",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "596868",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 16 2023 07:27:05 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Mehul Gunvantrai Malkan & Mrs. Neelam Mehul Malkan",
    "phone": "9321482026",
    "ownershipShare": "",
    "email": "",
    "id": "398029"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "id": "690581",
```

```
"name": "Living Room",
"length": "7.75",
"length1": "7",
"length2": "9",
"width": "17.83",
"width1": "17",
"width2": "10",
"totalArea": "138.21",
"images": [],
"extraAreas": [],
"finalArea": "138.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "34.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "34.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "",
  "length1": "9",
  "length2": "9",
  "width": "",
  "width1": "7",
  "width2": "4",
  "totalArea": "71.50",
  "images": [],
  "finalArea": "71.50",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "8.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "30.03",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.03"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.17",
```

```
"length1": "9",
"length2": "2",
"width": "13.00",
"width1": "13",
"width2": "00",
"totalArea": "119.17",
"images": [],
"extraAreas": [],
"finalArea": "119.17"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "385912",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "495",
  "squareMeterArea": "45.99",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltpPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce16",
  "name": "externalImg_1695450683438_IMG20230921WA0004.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalImg_1695450683438_IMG20230921WA0004.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce17",
  "name": "externalimg_1695450683441_IMG20230921WA0005.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683441_IMG20230921WA0005.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce18",
  "name": "externalimg_1695450683444_IMG20230921WA0006.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683444_IMG20230921WA0006.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce19",
  "name": "externalimg_1695450683447_IMG20230921WA0009.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683447_IMG20230921WA0009.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1a",
  "name": "externalimg_1695450683449_IMG20230921WA0011.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683449_IMG20230921WA0011.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1b",
  "name": "externalimg_1695450683452_IMG20230921WA0018.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683452_IMG20230921WA0018.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1c",
  "name": "externallmg_1695450683454_IMG20230921WA0020.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683454_IMG20230921WA0020.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1d",
  "name": "externallmg_1695450683458_IMG20230921WA0028.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683458_IMG20230921WA0028.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1e",
  "name": "externallmg_1695450683463_IMG20230921WA0029.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683463_IMG20230921WA0029.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce1f",
  "name": "externallmg_1695450683470_IMG20230921WA0030.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683470_IMG20230921WA0030.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e863b0c1bfd1d9fddce20",
  "name": "externallmg_1695450683474_IMG20230921WA0033.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683474_IMG20230921WA0033.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce21",
    "name": "externallmg_1695450683477_IMG20230921WA0034.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683477_IMG20230921WA0034.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce22",
    "name": "externallmg_1695450683481_IMG20230921WA0035.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450683481_IMG20230921WA0035.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce23",
    "name": "externallmg_1695450683486_Screenshot_20230922001817479_cnwpsm
office_eng.png",
    "path": "cases/65050b71a8e9b70221e70fea/externallmg_1695450683486_Screens
hot_20230922001817479_cnwpsmoffice_eng.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce24",
    "name": "externallmg_1695450683491_Screenshot_20230922001821439_cnwpsm
office_eng.png",
    "path": "cases/65050b71a8e9b70221e70fea/externallmg_1695450683491_Screens
hot_20230922001821439_cnwpsmoffice_eng.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce25",
    "name": "externallmg_1695450683496_Screenshot_20230922001826445_cnwpsm
office_eng.png",
    "path": "cases/65050b71a8e9b70221e70fea/externallmg_1695450683496_Screens
hot_20230922001826445_cnwpsmoffice_eng.png",
    "orientation": "portrait"
  }
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce26",
    "name": "externalimg_1695450683499_IMG20230921WA0002.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683499_IMG20230921WA0002.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce27",
    "name": "externalimg_1695450683502_IMG20230921WA0003.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450683502_IMG20230921WA0003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce28",
    "name": "externalimg_r_1695450683369_IMG_20230922_001926.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_r_1695450683369_IMG_20230922_001926.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e863b0c1bfd1d9fddce29",
    "name": "externalimg_r_1695450683400_IMG_20230922_001935.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_r_1695450683400_IMG_20230922_001935.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceaa",
    "name": "externalimg_1695450702491_IMG20230921WA0007.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702491_IMG20230921WA0007.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e864e0c1bfd1d9fddceab",
  "name": "externallmg_1695450702496_IMG20230921WA0008.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702496_IMG20230921WA0008.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e864e0c1bfd1d9fddceac",
  "name": "externallmg_1695450702499_IMG20230921WA0010.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702499_IMG20230921WA0010.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e864e0c1bfd1d9fddcead",
  "name": "externallmg_1695450702502_IMG20230921WA0012.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702502_IMG20230921WA0012.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e864e0c1bfd1d9fddceae",
  "name": "externallmg_1695450702503_IMG20230921WA0013.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702503_IMG20230921WA0013.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e864e0c1bfd1d9fddceaf",
  "name": "externallmg_1695450702507_IMG20230921WA0014.jpg",
  "path": "cases/65050b71a8e9b70221e70fea/
externallmg_1695450702507_IMG20230921WA0014.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb0",
    "name": "externalimg_1695450702510_IMG20230921WA0015.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702510_IMG20230921WA0015.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb1",
    "name": "externalimg_1695450702513_IMG20230921WA0016.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702513_IMG20230921WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb2",
    "name": "externalimg_1695450702515_IMG20230921WA0017.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702515_IMG20230921WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb3",
    "name": "externalimg_1695450702516_IMG20230921WA0019.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702516_IMG20230921WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb4",
    "name": "externalimg_1695450702519_IMG20230921WA0021.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702519_IMG20230921WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb5",
    "name": "externalimg_1695450702521_IMG20230921WA0022.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702521_IMG20230921WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb6",
    "name": "externalimg_1695450702522_IMG20230921WA0023.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702522_IMG20230921WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb7",
    "name": "externalimg_1695450702524_IMG20230921WA0024.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702524_IMG20230921WA0024.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb8",
    "name": "externalimg_1695450702526_IMG20230921WA0025.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702526_IMG20230921WA0025.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddceb9",
    "name": "externalimg_1695450702528_IMG20230921WA0026.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702528_IMG20230921WA0026.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "650e864e0c1bfd1d9fddceba",
    "name": "externalimg_1695450702530_IMG20230921WA0027.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702530_IMG20230921WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddcebb",
    "name": "externalimg_1695450702532_IMG20230921WA0031.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702532_IMG20230921WA0031.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e864e0c1bfd1d9fddcebc",
    "name": "externalimg_1695450702536_IMG20230921WA0032.jpg",
    "path": "cases/65050b71a8e9b70221e70fea/
externalimg_1695450702536_IMG20230921WA0032.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-16T01:57:05.841Z",
"updatedAt": "2023-09-23T13:26:40.435Z",
"__v": 0,
"invoiceId": "65050b71a8e9b70221e70ff2",
"fullAddress": "Residential Flat No. B-001, Ground Floor, Building No Type A, Wing - B,
Star Residency \"B\" in Star Residency Bldg B & B2 Co-Op. Hsg. Soc. Ltd., Star
Residency Complex, Evershine City, Village - Achole, Vasai Road (East), Taluka -
Vasai, District - Palghar, PIN - 401 208, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Guptaji",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9321482026",
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + Passage + Toilet",
 "carpetTotal": "401.95",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "0.00",
 "builtupPercentage": "20",
 "finalBuiltupArea": "482.34",
 "finalCarpetArea": "401.95",
 "finalSalableArea": "482.34",
 "salablePercentage": "0",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "",
 "finalAreaType": "Built Up Area",
 "finalAsPerArea": "Agreement For Sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 495.00"

Name	Length	Width	Total
Composition :			
Living Room	7'9"	17'10"	138.21
Dining	4'7"	7'6"	34.37
Kitchen	9'9"	7'4"	71.50
Passage	2'8"	3'3"	8.67
Toilet	3'10"	7'10"	30.03
Bedroom	9'2"	13'00"	119.17
Other Composition :			