

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ec3372eb1f822256d7a6c0"
    },
    "type": "CREDITOFFICER",
    "_id": "64ec3372eb1f822256d7a6c2",
    "firstName": "Abhimanyu",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8763993948",
    "email": "bmmsro2197@centralbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "52200000",
    "discussWithPerson": "Abhimanyu",
    "expectedFees": 26100,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64ec3372eb1f822256d7a6c0",
  "name": "Goregaon West Branch",
  "branchCode": "",
  "mobileNo": "022 28720068",
  "alternateMobileNo": "",
  "email": "bmmsro2197@centralbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Nirala House. Pt. Dayal Upadhyay Chowk, 36. Jawahar Nahar, Goregaon
West, Mumbai - 400 1004"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.1609269262976",
  "longitude": "72.83554435860717"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83554435860717,
    19.1609269262976
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-17",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pahadi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "24",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Mumbai",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goregaon (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sienna, Fiorenza Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Off. Western Express Highway",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Next to Hub Mall",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Lodha Fiorenza",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "587(P) & 586(P)",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "586/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 063",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
},
```

```
"flooring": {
  "value": "ItalianMarbleFlooring",
  "label": "Italian Marble Flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
  "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
  "label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Ceiling",
  "label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Hub Mall",
    "west": "Nirlon Knowledge Park",
```

```
"south": "Minal Tai Gore Flyover",
"east": "Western Express Highway"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "east": "",
    "south": "",
    "west": ""
  },
  "asPerDocument": {
    "north": "",
    "east": "",
    "south": "",
    "west": ""
  },
  "title": "Boundaries of The Flat",
  "isDisplay": true
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "Rate considered for valuation is including of 2 Car Parking, Interior and Amenities provided in the building.",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "38485",
  "depreciatedBuildingRate": "2685"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "142760",
  "landRate": "63420",
  "igrImage": "cases/65058f2fa8e9b70221e88ae4/igr_1695028465232_Image.png",
  "squareMeterGuideLineRate": "164174.00",
  "squareFeetGuideLineRate": "15252.00"
},
"igrFinalRate": {
  "depreciationPercentage": "93",
```

```
"rate": "14597.00",
"squareFeetGuideLineRate": "14597.00",
"squareMeterGuideLineRate": "157121.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "1,32,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Electricity Bill Consumer No.9000 0080 0131",
  "meterCardHolderName": "Mr. Jitendra Thakare",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Along with Two Car Parking Space bearing No. P4-65A & 65B",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2016",
"fullDate": "1/1/2016"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
```

```
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
```

```
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "2",
"noOfPodium": "6",
"noOfAmenityFloors": "",
"noOfFloors": "39",
"flatFloorNo": "",
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1653.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65058f2fa8e9b70221e88ae4/
routeMap_1695038474876_Image.png",
    "routeLat": "19.154556",
    "routeLng": "72.856306",
    "stationName": "Ram Mandir",
    "routeDistance": "550 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "vh3j6",
```



```
    "name": "vh3j6",
    "image": "cases/65058f2fa8e9b70221e88ae4/
routeMap_1695038398313_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "53032330.00",
  "finalValue": "53032330.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "24137599.00",
  "selectedBuildUpValue": "1653.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6507474ea8e9b70221e8f2b2",
      "name": "externallmg_1694975636585_1694975527402_image_0.jpeg",
      "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975636585_1694975527402_image_0.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b3",
    "name": "externallmg_1694975636697_1694975527402_image_1.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975636697_1694975527402_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b4",
    "name": "externallmg_1694975636792_1694975527402_image_2.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975636792_1694975527402_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b6",
    "name": "externallmg_1694975636857_1694975527402_image_4.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975636857_1694975527402_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c1",
    "name": "externallmg_1694975730733_1694975626579_image_5.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730733_1694975626579_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d1",
    "name": "externallmg_1694975774440_1694975671323_image_12.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774440_1694975671323_image_12.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b8",
    "name": "externallmg_1694975637103_1694975527402_image_6.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637103_1694975527402_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b9",
    "name": "externallmg_1694975637163_1694975527402_image_7.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637163_1694975527402_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b5",
    "name": "externallmg_1694975636841_1694975527402_image_3.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975636841_1694975527402_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2bc",
    "name": "externallmg_1694975730361_1694975626579_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730361_1694975626579_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d0",
    "name": "externallmg_1694975774436_1694975671323_image_11.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774436_1694975671323_image_11.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c3",
```

```
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730755_1694975626579_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c4",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730758_1694975626579_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c9",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774082_1694975671323_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c8",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774068_1694975671323_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cf",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774420_1694975671323_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cb",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774131_1694975671323_image_6.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c6",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975773880_1694975671322_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c5",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975773855_1694975671322_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b7",
    "name": "Living Room",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637086_1694975527402_image_5.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26720",
    "max": "39913"
  },
  "builtUpRateRange": {
    "min": "22267",
    "max": "33261"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1378.00",
"empanelmentNo": [
  "SMRO /CREDIT/2017-18/1311"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "65058f2fa8e9b70221e88ae4",
"ownerName": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
"ownerPhoneNo": "9265220957",
"appAddress": "flat no 2403 b wing sienna lodha fioranza chs opposite Western
express Highway Goregaon east",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "inputs": {
      "documentDate": "18/07/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Ankit Jain & Mrs. Mitanshi Kaushal"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1695035496703_document_1694862564293_MOU_B2403.pdf",
    "path": "cases/65058f2fa8e9b70221e88ae4/
document_1695035496703_document_1694862564293_MOU_B2403.pdf",
```

```
"id": "878127",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Sep 18 2023 16:41:36 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "21/02/2021",
    "to": {
      "value": "Beneficiary",
      "label": "Beneficiary"
    },
    "Beneficiary": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "250"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695035744934_document_1694863045065_47762.pdf",
  "path": "cases/65058f2fa8e9b70221e88ae4/
document_1695035744934_document_1694863045065_47762.pdf",
  "id": "455276",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Sep 18 2023 16:45:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1287aa6d152c1801b415",
    "label": "Index - II"
  },
  "inputs": {
    "documentDate": "09/11/2015",
    "from": {
      "value": "Transferor",
      "label": "Transferor"
    },
    "Transferor": "Lodha Developers Pvt. Ltd.",
    "to": {
      "value": "Transferee",
      "label": "Transferee"
    }
  }
}
```

```
    },
    "Transferee": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695035855600_document_1694863045065_47762.pdf",
  "path": "cases/65058f2fa8e9b70221e88ae4/
document_1695035855600_document_1694863045065_47762.pdf",
  "id": "401962",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Sep 18 2023 16:47:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1254aa6d152c1801b325",
    "label": "Society NOC Letter "
  },
  "inputs": {
    "documentDate": "17/08/2023"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695035912631_document_1694863045065_47762.pdf",
  "path": "cases/65058f2fa8e9b70221e88ae4/
document_1695035912631_document_1694863045065_47762.pdf",
  "id": "933121",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Sep 18 2023 16:48:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "29/04/2016",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    }
  },
  "number": {
    "value": "No",
```

```
    "label": "No"
  },
  "No": "CHE / 8846 / BPWS / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695036027912_OC.pdf",
"path": "cases/65058f2fa8e9b70221e88ae4/document_1695036027912_OC.pdf",
"id": "321832",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Sep 18 2023 16:50:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "10/07/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "23-24 / 07-09 / 0202"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695036076568_document_1694863045065_47762.pdf",
"path": "cases/65058f2fa8e9b70221e88ae4/
document_1695036076568_document_1694863045065_47762.pdf",
"id": "234885",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Sep 18 2023 16:51:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Tata_Power",
      "label": "Tata Power"
    }
  },
  "to": {
```

```
    "value": "Beneficiary",
    "label": "Beneficiary"
  },
  "Beneficiary": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
  "number": {
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": "9000 0080 0131"
},
"isHardCopy": false,
"displayStatus": false,
"fileName":
"document_1695036168039_document_1694862839392_Bill_No_099377906069.pdf",
"path": "cases/65058f2fa8e9b70221e88ae4/
document_1695036168039_document_1694862839392_Bill_No_099377906069.pdf",
"id": "533694",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Sep 18 2023 16:52:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003884",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "314848",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 16 2023 16:49:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Jitendra B. Thakare & Mrs. Nikita J. Thakare",
    "phone": "9265220957",
    "ownershipShare": "",
    "email": "",
    "id": "731025"
  }
],
"proposePurchasers": [
  {
    "name": "Mr. Ankit Jain & Mrs. Mitanshi Kaushal ",
    "phone": "",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
}
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "508840",
    "name": "Living Room",
    "length": "19.58",
    "length1": "19",
    "length2": "7",
    "width": "11.42",
    "width1": "11",
    "width2": "5",
    "totalArea": "223.58",
    "images": [],
    "extraAreas": [],
    "finalArea": "223.58"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "90.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "90.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
```



```
"name": "Bedroom",
"length": "10.67",
"length1": "10",
"length2": "8",
"width": "14.75",
"width1": "14",
"width2": "9",
"totalArea": "157.33",
"images": [],
"extraAreas": [],
"finalArea": "157.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "33.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "39.00",
  "images": [],
  "extraAreas": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65082ddc612315172eab745e",
  "name": "Passage 2",
  "extraAreaType": "Add",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "30.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65082e74612315172eab74af",
  "name": "Passage 3",
  "extraAreaType": "Add",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "33.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65082e90612315172eab74c1",
  "name": "Passage 4",
  "extraAreaType": "Add",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "5.08",
  "width1": "5",
  "width2": "1",
}
```

```
"totalArea": "44.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65082ecd612315172eab7654",
  "name": "Passage / Toilets",
  "extraAreaType": "Add",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65082f3c612315172eab7783",
  "name": "Passage 5",
  "extraAreaType": "Add",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "98.23"
}
],
"finalArea": "257.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
```

```
"length2": "00",
"width": "11.42",
"width1": "11",
"width2": "5",
"totalArea": "159.83",
"images": [],
"extraAreas": [],
"finalArea": "159.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "89.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "14.24",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.24"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "8",
"name": "Toilet",
"length": "7.25",
"length1": "7",
"length2": "3",
"width": "3.25",
"width1": "3",
"width2": "3",
"totalArea": "23.56",
"images": [],
"extraAreas": [],
"finalArea": "23.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "35.14",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.14"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "4.42",
```

```
"width1": "4",
"width2": "5",
"totalArea": "22.45",
"images": [],
"extraAreas": [],
"finalArea": "22.45"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "130.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "130.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "10",
    "length2": "00",
    "length": "10.00",
    "width1": "3",
    "width2": "00",
```

```
"width": "3.00",
"totalArea": "30.00",
"percentageBeforeTotal": "30.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "30"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "14",
  "length2": "4",
  "length": "14.33",
  "width1": "3",
  "width2": "5",
  "width": "3.42",
  "totalArea": "48.97",
  "percentageBeforeTotal": "48.97",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "48.97"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "9",
  "length2": "00",
  "length": "9.00",
  "width1": "3",
  "width2": "00",
  "width": "3.00",
  "totalArea": "27.00",
  "percentageBeforeTotal": "27.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "27"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "710676",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1378",
    "squareMeterArea": "128.02",
    "docFinalBuiltUp": "1653.6",
    "docFinalBuiltUpSquareMeter": "153.62400000000002",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65081557a8e9b70221e9e775",
    "property": "Flat",
```



```
"area": "1460",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "21",
"source": "https://www.99acres.com/",
"expectedPrice": "56000000",
"expectedRate": "38356.16",
"builtUpExpectedRate": "31963.47",
"image": "cases/65058f2fa8e9b70221e88ae4/
indicator_1695027995510_Image.png",
"squareMeter": "135.64",
"id": "518262"
},
{
  "printlnReport": true,
  "_id": "65081557a8e9b70221e9e776",
  "property": "Flat",
  "area": "1378",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "13",
  "source": "https://www.99acres.com/",
  "expectedPrice": "55000000",
  "expectedRate": "39912.92",
  "builtUpExpectedRate": "33260.76",
  "image": "cases/65058f2fa8e9b70221e88ae4/
indicator_1695028042755_Image.png",
  "squareMeter": "128.02",
  "id": "943854"
},
{
  "printlnReport": true,
  "_id": "65081557a8e9b70221e9e777",
  "property": "Flat",
  "area": "1400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "10",
  "source": "https://www.99acres.com/",
  "expectedPrice": "55000000",
```

```
    "expectedRate": "39285.71",
    "builtUpExpectedRate": "32738.10",
    "image": "cases/65058f2fa8e9b70221e88ae4/
indicator_1695028090524_Image.png",
    "squareMeter": "130.06",
    "id": "164532"
  },
  {
    "printlnReport": true,
    "_id": "65081557a8e9b70221e9e778",
    "property": "Flat",
    "area": "1403",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "38",
    "source": "https://www.99acres.com/",
    "expectedPrice": "53600000",
    "expectedRate": "38203.85",
    "builtUpExpectedRate": "31836.54",
    "image": "cases/65058f2fa8e9b70221e88ae4/
indicator_1695028159458_Image.png",
    "squareMeter": "130.34",
    "id": "561528"
  },
  {
    "printlnReport": true,
    "_id": "65081557a8e9b70221e9e779",
    "property": "Flat",
    "area": "1006",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "11",
    "source": "Index_no.2",
    "expectedPrice": "22400000",
    "expectedRate": "22266.40",
    "builtUpExpectedRate": "0.00",
    "image": "cases/65058f2fa8e9b70221e88ae4/
indicator_1695028285398_Image.png",
    "squareMeter": "93.46",
    "id": "381043"
  }
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b2",
    "name": "externalimg_1694975636585_1694975527402_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externalimg_1694975636585_1694975527402_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b3",
    "name": "externalimg_1694975636697_1694975527402_image_1.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externalimg_1694975636697_1694975527402_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b4",
    "name": "externalimg_1694975636792_1694975527402_image_2.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externalimg_1694975636792_1694975527402_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b5",
    "name": "externalimg_1694975636841_1694975527402_image_3.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externalimg_1694975636841_1694975527402_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2b6",
    "name": "externalimg_1694975636857_1694975527402_image_4.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externalimg_1694975636857_1694975527402_image_4.jpeg",
    "orientation": "portrait"
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507474ea8e9b70221e8f2b7",
  "name": "externallmg_1694975637086_1694975527402_image_5.jpeg",
  "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637086_1694975527402_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507474ea8e9b70221e8f2b8",
  "name": "externallmg_1694975637103_1694975527402_image_6.jpeg",
  "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637103_1694975527402_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507474ea8e9b70221e8f2b9",
  "name": "externallmg_1694975637163_1694975527402_image_7.jpeg",
  "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637163_1694975527402_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507474ea8e9b70221e8f2ba",
  "name": "externallmg_1694975637178_1694975527402_image_8.jpeg",
  "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637178_1694975527402_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507474ea8e9b70221e8f2bb",
  "name": "externallmg_1694975637194_1694975527402_image_9.jpeg",
  "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975637194_1694975527402_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2bc",
    "name": "externallmg_1694975730361_1694975626579_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730361_1694975626579_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2bd",
    "name": "externallmg_1694975730390_1694975626579_image_1.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730390_1694975626579_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2be",
    "name": "externallmg_1694975730458_1694975626579_image_2.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730458_1694975626579_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2bf",
    "name": "externallmg_1694975730727_1694975626579_image_3.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730727_1694975626579_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c0",
    "name": "externallmg_1694975730732_1694975626579_image_4.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730732_1694975626579_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c1",
    "name": "externallmg_1694975730733_1694975626579_image_5.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730733_1694975626579_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c2",
    "name": "externallmg_1694975730740_1694975626579_image_6.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730740_1694975626579_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c3",
    "name": "externallmg_1694975730755_1694975626579_image_7.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730755_1694975626579_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c4",
    "name": "externallmg_1694975730758_1694975626579_image_8.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975730758_1694975626579_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c5",
    "name": "externallmg_1694975773855_1694975671322_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975773855_1694975671322_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6507474ea8e9b70221e8f2c6",
    "name": "externallmg_1694975773880_1694975671322_image_1.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975773880_1694975671322_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c7",
    "name": "externallmg_1694975773906_1694975671322_image_2.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975773906_1694975671322_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c8",
    "name": "externallmg_1694975774068_1694975671323_image_3.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774068_1694975671323_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2c9",
    "name": "externallmg_1694975774082_1694975671323_image_4.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774082_1694975671323_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2ca",
    "name": "externallmg_1694975774110_1694975671323_image_5.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774110_1694975671323_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cb",
```

```
    "name": "externallmg_1694975774131_1694975671323_image_6.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774131_1694975671323_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cc",
    "name": "externallmg_1694975774147_1694975671323_image_7.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774147_1694975671323_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cd",
    "name": "externallmg_1694975774161_1694975671323_image_8.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774161_1694975671323_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2ce",
    "name": "externallmg_1694975774416_1694975671323_image_9.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774416_1694975671323_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2cf",
    "name": "externallmg_1694975774420_1694975671323_image_10.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774420_1694975671323_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d0",
    "name": "externallmg_1694975774436_1694975671323_image_11.jpeg",
```



```
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774436_1694975671323_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d1",
    "name": "externallmg_1694975774440_1694975671323_image_12.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975774440_1694975671323_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d2",
    "name": "externallmg_1694975517635_1694975386196_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975517635_1694975386196_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6507474ea8e9b70221e8f2d3",
    "name": "externallmg_1694975517656_1694975414566_image_0.jpeg",
    "path": "cases/65058f2fa8e9b70221e88ae4/
externallmg_1694975517656_1694975414566_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- ankit.xlsx",
    "filename": "1695028619684_Calculation_2_ankit.xlsx",
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028619684_Calculation_2_ankit.xlsx",
    "size": "16039",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1695028619687_igr1.pdf",
```

```
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028619687_igr1.pdf",
    "size": "458732",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1695028619724_igr2.pdf",
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028619724_igr2.pdf",
    "size": "591490",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Part OC (1).pdf",
    "filename": "1695028619773_Part_OC_1.pdf",
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028619773_Part_OC_1.pdf",
    "size": "2318412",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1695028619969_reference_report.pdf",
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028619969_reference_report.pdf",
    "size": "664512",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - Ankit.xlsx",
    "filename": "1695028620054_Summary__Ankit.xlsx",
    "path": "cases/65058f2fa8e9b70221e88ae4/
processingDocuments/1695028620054_Summary__Ankit.xlsx",
    "size": "6197726",
    "createdAt": "Mon Sep 18 2023 14:47:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"remarks": [],
"createdAt": "2023-09-16T11:19:11.996Z",
"updatedAt": "2023-09-20T04:50:19.583Z",
```

```
"__v": 0,
"invoiceId": "65058f31a8e9b70221e88b00",
"fullAddress": "Residential Flat No. 2403, 24th Floor, Wing - B, Sienna, Fiorenza Co-
op. Hsg. Soc. Ltd., Lodha Fiorenza, Next to Hub Mall, Off. Western Express Highway,
Village - Pahadi, Taluka - Borivali, District - Mumbai, Goregaon (East), PIN - 400 063,
State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "64acf498d9a15943959de54c",
"contactPersonName": "Mr. Ankit Jain ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Proposed Purchaser",
"siteVisitContactNo": "8433646880",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Memorandum of Understanding",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1378.00",
"flatRate": "38800",
"landOtherRate": "35800",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 5 Toilet +
Passage",
"carpetTotal": "1236.24",
"otherCarpetTotal": "105.97",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "105.97",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1476.43",
"finalCarpetArea": "1342.21",
"finalSalableArea": "1624.07",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"siteVisitDate": "2023-09-17",
"reportGeneratedDate": "Mon Sep 18 2023 17:47:03 GMT+0530 (India Standard
Time)"
}
```

Name	Length	Width	Total
Composition :			
Living Room	19'7"	11'5"	223.58
Dining	10'00"	9'00"	90.00
Bedroom	10'8"	14'9"	157.33
Toilet	4'7"	7'4"	33.61
Passage	13'00"	3'00"	39.00
Bedroom	14'00"	11'5"	159.83
Kitchen	11'8"	7'8"	89.44
Toilet	3'5"	4'2"	14.24
Toilet	7'3"	3'3"	23.56
Toilet	7'8"	4'7"	35.14
Toilet	5'1"	4'5"	22.45
Bedroom	13'00"	10'00"	130.00
Other Composition :			
Balcony Area	10'00"	3'00"	30.00
Balcony Area	14'4"	3'5"	48.97
Balcony Area	9'00"	3'00"	27.00