

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6363aa704d42487767aeaf99",
    "firstName": "SUNIL BHOSALE",
    "lastName": "BHOSALE",
    "mobileNo": "9004074579",
    "email": "sunil.bhosale@sbi.co.in",
    "workMobileNo": "9004074579"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "SUNIL BHOSALE",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER + RATE VERFIER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
{

```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.176379806561236",
  "longitude": "72.83383986626612"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83383986626612,
    19.176379806561236
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-21T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-21T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-21T08:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malad (South)",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Evershine Grandeur Co-Op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mindspace",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Link Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1406/A/25/9",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 064",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "Malad (West)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Vitrified_Tile_Flooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teal_wood_door_frame_with_flush_shutters",
    "label": "Teal wood door frame with flush shutters"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Vivette Banquet",
"west": "Vibgyor School Road",
"south": "Internal Road",
"east": "Shree Kamdhenu Estate"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"isActive": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.\n\n",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
}
```

```
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "15000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Yes",
"constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2006",
"fullDate": "1/1/2006"
},
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": ""
```

```
"noOfFloors": "10",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1214.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/650be1d0612315172eada230/
routeMap_1695388022586_Image.png",
    "routeLat": "19.176056",
    "routeLng": "72.833694",
    "stationName": "Malad",
    "routeDistance": "2.6KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "zr170h",
      "name": "zr170h",
      "image": "cases/650be1d0612315172eada230/
routeMap_1695387286797_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```



```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "1214.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "650d1af5612315172eae69",
      "name": "externalimg_1695357684975_IMG_20230921_142950.jpg",
      "path": "cases/650be1d0612315172eada230/
externalimg_1695357684975_IMG_20230921_142950.jpg",
```

```
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "650d1ad9612315172eaeedff",
    "name": "externallmg_1695357657307_IMG_20230921_142132.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657307_IMG_20230921_142132.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "650d1ad9612315172eae07",
    "name": "externallmg_1695357657366_IMG_20230921_142911.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657366_IMG_20230921_142911.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1af5612315172eae67",
    "name": "externallmg_1695357684952_IMG_20230921_142946.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357684952_IMG_20230921_142946.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1af5612315172eae69",
    "name": "externallmg_1695357684975_IMG_20230921_142950.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357684975_IMG_20230921_142950.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "650d1ad9612315172eae09",
    "name": "externallmg_r_1695357657350_IMG_20230921_142837.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_r_1695357657350_IMG_20230921_142837.jpg",
```

```
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "650d1ad9612315172eaeedf6",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657254_IMG_20230921_142016.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1ad9612315172eaeedfa",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657284_IMG_20230921_142055.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1ad9612315172eaeedfb",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657288_IMG_20230921_142103.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1ad9612315172eaeedfe",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657301_IMG_20230921_142124.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1ad9612315172eaeeee01",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657322_IMG_20230921_142258.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "650d1ad9612315172eae02",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657327_IMG_20230921_142302.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650d1af5612315172eae06d",
    "name": "Living Room",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357684996_IMG_20230921_142014.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "1012.00",
```



```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "650be1d0612315172eada230",
"ownerName": "Mrs. Hansa Jagdish Somani, Mr. Jagdish Chunilal Somani & Mr. Dhiraj
Jagdish Somani",
"ownerPhoneNo": "9699796991",
"appAddress": "Flat no A-401.4floor,Evershine Grandeur CHS Ltd,Mindspace Off Link
Road Malad West",
"remark": "+91 96997 96991",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/650be1d0612315172eada230/
document_1695277435644_112597.pdf",
    "fileName": "document_1695277435644_112597.pdf",
    "displayStatus": false,
    "id": "720784",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Sep 21 2023 11:54:41 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1695287378765_FORCE_CLOSER_LOD.pdf",
    "path": "cases/650be1d0612315172eada230/
document_1695287378765_FORCE_CLOSER_LOD.pdf",
    "id": "950034",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Sep 21 2023 14:41:14 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695287410144_AGREEMENT_2.pdf",
"path": "cases/650be1d0612315172eada230/
document_1695287410144_AGREEMENT_2.pdf",
"id": "832364",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Thu Sep 21 2023 14:41:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "20/07/2022",
    "from": {
      "value": "Transferor",
      "label": "Transferor"
    },
    "Transferor": "Mr. Satish R. Bhardwaj & Mrs. Promilla Satish Bhardwaj",
    "to": {
      "value": "Transferee",
      "label": "Transferee"
    },
    "Transferee": "Mrs. Hansa Jagdish Somani, Mr. Jagdish Chunilal Somani & Mr.
Dhiraj Jagdish Somani"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "127213",
  "path": "cases/650be1d0612315172eada230/
document_1695287425765_AGREEMENT_3.pdf",
  "fileName": "document_1695287425765_AGREEMENT_3.pdf"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695287472371_66019.pdf",
  "path": "cases/650be1d0612315172eada230/
document_1695287472371_66019.pdf",
  "id": "641704",
```

```
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Thu Sep 21 2023 14:41:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a0aa6d152c1801b483",
    "label": "site Details"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695357782304_Mrs_hansa_jagdish_somani.pdf",
  "path": "cases/650be1d0612315172eada230/
document_1695357782304_Mrs_hansa_jagdish_somani.pdf",
  "id": "344845",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Fri Sep 22 2023 10:13:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "12/04/2006",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CHE / 7312 / BP (WS) / AP"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695447170855_Occupancy_Certificate.pdf",
  "path": "cases/650be1d0612315172eada230/
document_1695447170855_Occupancy_Certificate.pdf",
  "id": "318586",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Sat Sep 23 2023 11:02:50 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003938",
"createdBy": "60af3d172ffdf65bcd6585cd",
```

```
"caseHistory": [
  {
    "id": "306927",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 21 2023 11:55:20 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Hansa Jagdish Somani, Mr. Jagdish Chunilal Somani & Mr. Dhiraj Jagdish Somani",
    "phone": "9699796991",
    "ownershipShare": "",
    "email": "",
    "id": "881855"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "369996",
    "name": "Living Room",
    "length": "22.33",
    "length1": "22",
    "length2": "4",
    "width": "10.33",
    "width1": "10",
    "width2": "4",
    "totalArea": "230.78",
    "images": [],
    "extraAreas": [],
    "finalArea": "230.78"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Dining",
```

```
"length": "8.67",
"length1": "8",
"length2": "8",
"width": "8.42",
"width1": "8",
"width2": "5",
"totalArea": "72.94",
"images": [],
"extraAreas": [],
"finalArea": "72.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "15.75",
  "length1": "15",
  "length2": "9",
  "width": "7.58",
  "width1": "7",
  "width2": "7",
  "totalArea": "119.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "15.83",
  "length1": "15",
  "length2": "10",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "48.82",
  "images": [],
  "finalArea": "48.82",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.83",
  "length1": "11",
  "length2": "10",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "127.21",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "650e6c120c1bfd1d9fdd728d",
      "name": "Bedroom",
      "extraAreaType": "Add",
      "length": "3.92",
      "length1": "3",
      "length2": "11",
      "width": "6.50",
      "width1": "6",
      "width2": "6",
      "totalArea": "25.46"
    }
  ],
  "finalArea": "152.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
```

```
"width": "4.92",
"width1": "4",
"width2": "11",
"totalArea": "38.51",
"images": [],
"extraAreas": [],
"finalArea": "38.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.42",
  "length1": "13",
  "length2": "5",
  "width": "11.58",
  "width1": "11",
  "width2": "7",
  "totalArea": "155.41",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "650e6c9e0c1bfd1d9fdd7361",
      "name": "Bedroom",
      "extraAreaType": "Add",
      "length": "3.25",
      "length1": "3",
      "length2": "3",
      "width": "9.42",
      "width1": "9",
      "width2": "5",
      "totalArea": "30.60"
    }
  ],
  "finalArea": "186.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "39.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "10.79",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "650e6d090c1bfd1d9fdd7478",
      "name": "Passage",
      "extraAreaType": "Add",
      "length": "2.00",
      "length1": "2",
      "length2": "00",
      "width": "3.50",
      "width1": "3",
      "width2": "6",
      "totalArea": "7.00"
    }
  ]
}
```



```
    }
  ],
  "finalArea": "17.79"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "13.33",
  "length1": "13",
  "length2": "4",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "146.67",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "650e6d7a0c1bfd1d9fdd7571",
      "name": "Bedroom",
      "extraAreaType": "Add",
      "length": "3.25",
      "length1": "3",
      "length2": "3",
      "width": "9.25",
      "width1": "9",
      "width2": "3",
      "totalArea": "30.06"
    }
  ],
  "finalArea": "176.73"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
```

```
"length": "5.25",
"length1": "5",
"length2": "3",
"width": "7.67",
"width1": "7",
"width2": "8",
"totalArea": "40.25",
"images": [],
"extraAreas": [],
"finalArea": "40.25"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Store Room",
    "value": "Store_Room"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "4",
  "length2": "4",
  "length": "4.33",
  "width1": "2",
  "width2": "7",
  "width": "2.58",
  "totalArea": "11.19",
  "percentageBeforeTotal": "11.19",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "11.19"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
```

```
    "label": "Store Room",
    "value": "Store_Room"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "5",
  "length2": "10",
  "length": "5.83",
  "width1": "3",
  "width2": "11",
  "width": "3.92",
  "totalArea": "22.85",
  "percentageBeforeTotal": "22.85",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "22.85"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "328986",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1012",
    "squareMeterArea": "94.02",
    "docFinalBuiltUp": "1214.4",
    "docFinalBuiltUpSquareMeter": "112.824",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eaeedf6",
    "name": "externalImg_1695357657254_IMG_20230921_142016.jpg",
    "path": "cases/650be1d0612315172eada230/
externalImg_1695357657254_IMG_20230921_142016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eaeedf7",
    "name": "externalImg_1695357657259_IMG_20230921_142024.jpg",
    "path": "cases/650be1d0612315172eada230/
externalImg_1695357657259_IMG_20230921_142024.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eaeedf8",
    "name": "externalImg_1695357657270_IMG_20230921_142025.jpg",
    "path": "cases/650be1d0612315172eada230/
externalImg_1695357657270_IMG_20230921_142025.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eaeedf9",
    "name": "externalImg_1695357657278_IMG_20230921_142027.jpg",
    "path": "cases/650be1d0612315172eada230/
externalImg_1695357657278_IMG_20230921_142027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eaeedfa",
    "name": "externalImg_1695357657284_IMG_20230921_142055.jpg",
    "path": "cases/650be1d0612315172eada230/
externalImg_1695357657284_IMG_20230921_142055.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650d1ad9612315172eaeedfb",
      "name": "externallmg_1695357657288_IMG_20230921_142103.jpg",
      "path": "cases/650be1d0612315172eada230/
externallmg_1695357657288_IMG_20230921_142103.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650d1ad9612315172eaeedfc",
      "name": "externallmg_1695357657293_IMG_20230921_142105.jpg",
      "path": "cases/650be1d0612315172eada230/
externallmg_1695357657293_IMG_20230921_142105.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650d1ad9612315172eaeedfd",
      "name": "externallmg_1695357657297_IMG_20230921_142112.jpg",
      "path": "cases/650be1d0612315172eada230/
externallmg_1695357657297_IMG_20230921_142112.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650d1ad9612315172eaeedfe",
      "name": "externallmg_1695357657301_IMG_20230921_142124.jpg",
      "path": "cases/650be1d0612315172eada230/
externallmg_1695357657301_IMG_20230921_142124.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650d1ad9612315172eaeedff",
      "name": "externallmg_1695357657307_IMG_20230921_142132.jpg",
      "path": "cases/650be1d0612315172eada230/
externallmg_1695357657307_IMG_20230921_142132.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1ad9612315172eae00",
  "name": "externallmg_1695357657317_IMG_20230921_142136.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357657317_IMG_20230921_142136.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1ad9612315172eae01",
  "name": "externallmg_1695357657322_IMG_20230921_142258.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357657322_IMG_20230921_142258.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1ad9612315172eae02",
  "name": "externallmg_1695357657327_IMG_20230921_142302.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357657327_IMG_20230921_142302.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1ad9612315172eae03",
  "name": "externallmg_1695357657331_IMG_20230921_142728.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357657331_IMG_20230921_142728.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1ad9612315172eae04",
  "name": "externallmg_1695357657337_IMG_20230921_142735.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357657337_IMG_20230921_142735.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eae05",
    "name": "externallmg_1695357657340_IMG_20230921_142738.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657340_IMG_20230921_142738.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eae06",
    "name": "externallmg_1695357657359_IMG_20230921_142909.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657359_IMG_20230921_142909.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eae07",
    "name": "externallmg_1695357657366_IMG_20230921_142911.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_1695357657366_IMG_20230921_142911.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eae08",
    "name": "externallmg_r_1695357657355_IMG_20230921_142840.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_r_1695357657355_IMG_20230921_142840.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1ad9612315172eae09",
    "name": "externallmg_r_1695357657350_IMG_20230921_142837.jpg",
    "path": "cases/650be1d0612315172eada230/
externallmg_r_1695357657350_IMG_20230921_142837.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "650d1af5612315172eae67",
  "name": "externallmg_1695357684952_IMG_20230921_142946.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357684952_IMG_20230921_142946.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1af5612315172eae68",
  "name": "externallmg_1695357684968_IMG_20230921_142948.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357684968_IMG_20230921_142948.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1af5612315172eae69",
  "name": "externallmg_1695357684975_IMG_20230921_142950.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357684975_IMG_20230921_142950.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1af5612315172eae6a",
  "name": "externallmg_1695357684982_IMG_20230921_142958.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357684982_IMG_20230921_142958.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650d1af5612315172eae6b",
  "name": "externallmg_1695357684986_IMG20230921WA0046.jpg",
  "path": "cases/650be1d0612315172eada230/
externallmg_1695357684986_IMG20230921WA0046.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "650d1af5612315172eae6c",
    "name": "externalimg_1695357684989_IMG_20230921_141626.jpg",
    "path": "cases/650be1d0612315172eada230/
externalimg_1695357684989_IMG_20230921_141626.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1af5612315172eae6d",
    "name": "externalimg_1695357684996_IMG_20230921_142014.jpg",
    "path": "cases/650be1d0612315172eada230/
externalimg_1695357684996_IMG_20230921_142014.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650d1af5612315172eae6e",
    "name": "externalimg_r_1695357684988_IMG20230921WA0047.jpg",
    "path": "cases/650be1d0612315172eada230/
externalimg_r_1695357684988_IMG20230921WA0047.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-21T06:25:20.236Z",
"updatedAt": "2023-09-23T05:36:15.006Z",
"__v": 0,
"invoiceId": "650be1d0612315172eada23c",
"fullAddress": "Residential Flat No. A-401, 4th Floor, Wing - A, Evershine Grandeur
Co-Op. Hsg. Soc. Ltd., Mindspace, Off Link Road, Village - Malad (South), Malad
(West), Taluka - Borivali, District - Mumbai Suburban, PIN - 400 064, State -
Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Jagdish Somani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9699796991",
 "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 2 Passage +
 3 Toilet",
 "carpetTotal": "1123.55",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "34.04",
 "builtupPercentage": "20",
 "finalBuiltupArea": "1348.26",
 "finalCarpetArea": "1123.55",
 "finalSalableArea": "1348.26",
 "salablePercentage": "0",
 "toBeAdded": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement For Sale",
 "finalBuiltUpPercentage": "10",
 "finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 1012.00",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "0.00",
 "otherCompositionSaleableTotal": "0.00",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1123.55\nStorage Area in Sq. Ft.
 = 34.04\nTotal Area in Sq. Ft. = 1157.59\n(Area as per actual site measurement)"
 }

Name	Length	Width	Total
Composition :			
Living Room	22'4"	10'4"	230.78
Dining	8'8"	8'5"	72.94
Kitchen	15'9"	7'7"	119.44
Passage	15'10"	3'1"	48.82
Bedroom	11'10"	10'9"	127.21
Toilet	7'10"	4'11"	38.51
Bedroom	13'5"	11'7"	155.41
Toilet	7'8"	5'2"	39.61
Passage	3'1"	3'6"	10.79
Bedroom	13'4"	11'00"	146.67

Toilet	5'3"	7'8"	40.25
<hr/>			
Other Composition :			
<hr/>			
Store Room	4'4"	2'7"	11.19
<hr/>			
Store Room	5'10"	3'11"	22.85
<hr/>			