

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "35.35000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 0.017675,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
  "_id": "5fc78e26625ecd20ec1f88e9",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "firstName": "Vaishali",
  "lastName": "Sarmalkar",
  "shortName": "VS",
  "email": "v.sarmalkar@vastukala.org",
  "designation": "",
  "mobileNo": "9004437379",
  "role": "MAKER+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "1"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.201557376729884",
  "longitude": " 73.20023967557803"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.20023967557803,
```

```
19.201557376729884
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-25",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Morivali",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "04",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ambernath",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Deniz Building",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Panvelkar Aqua Marine Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "201",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421501",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Ambernath (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Ambernath_Municipal_Council",
  "label": "Ambernath Municipal Council"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Anand Upvan",
  "west": "Residential Building",
  "south": "Internal Road",
  "east": "Aqua Marine Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "5737.5",
  "depreciatedBuildingRate": "2237.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "56600",
  "landRate": "11990",
  "igrImage": "cases/650d7beb612315172eb01a92/igr_1695711867663_Image.png",
  "squareMeterGuideLineRate": "56600.00",
  "squareFeetGuideLineRate": "5258.00"
},
"igrFinalRate": {
  "depreciationPercentage": "93",
  "rate": "4968.00",
  "squareFeetGuideLineRate": "4968.00",
  "squareMeterGuideLineRate": "53477.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "8,000.00",
  "assessmentNo": "Property Tax Receipt No. AS5402",
  "taxPaidHolderName": "Mr. Vinod Jaisingh Yadav & Mrs. Rajani Vinod Yadav",
  "taxAmount": "5,369.00",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per AMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2016",
    "fullDate": "1/1/2016"
  },
  "planningArea": {
    "value": "Residential",
```

```
"label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "798.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
}
```



```
    },
    "routeMapImg": "cases/650d7beb612315172eb01a92/
routeMap_1695714549765_Image.png",
    "routeLat": "19.195889",
    "routeLng": "73.201889",
    "stationName": "Ambernath",
    "routeDistance": "2.6 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "jvjde",
      "name": "jvjde",
      "image": "cases/650d7beb612315172eb01a92/
routeMap_1695714485934_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
```

```
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3815770.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "3815770.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "3964464.00",
  "selectedBuildUpValue": "798.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6511446f0c1bfd1d9fe04cf8",
      "name":
"externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
      "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6511447a0c1bfd1d9fe04d36",
      "name":
"externallmg_1695630458571_WhatsApp_Image_20230925_at_12345_PM_1.jpeg",
      "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458571_WhatsApp_Image_20230925_at_12345_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6511446f0c1bfd1d9fe04cf8",
      "name":
"externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
      "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  {
    "status": false,
```

```
    "_id": "6511446f0c1bfd1d9fe04cf9",
    "name":
"externallmg_1695630447799_WhatsApp_Image_20230925_at_12326_PM_2.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447799_WhatsApp_Image_20230925_at_12326_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d2e",
    "name":
"externallmg_1695630458551_WhatsApp_Image_20230925_at_12326_PM_3.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458551_WhatsApp_Image_20230925_at_12326_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d30",
    "name":
"externallmg_1695630458557_WhatsApp_Image_20230925_at_12326_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458557_WhatsApp_Image_20230925_at_12326_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d32",
    "name":
"externallmg_1695630458561_WhatsApp_Image_20230925_at_12327_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458561_WhatsApp_Image_20230925_at_12327_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d2f",
    "name":
"externallmg_1695630458554_WhatsApp_Image_20230925_at_12326_PM_4.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458554_WhatsApp_Image_20230925_at_12326_PM_4.jpeg",
    "orientation": "landscape"
  }
]
```

```
],
"compositionImages": [
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d34",
    "name": "Living Room",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458567_WhatsApp_Image_20230925_at_12328_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d39",
    "name": "Living Room",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458583_WhatsApp_Image_20230925_at_12345_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d3c",
    "name": "Bedroom",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458591_WhatsApp_Image_20230925_at_12346_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d3a",
    "name": "Bedroom",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458586_WhatsApp_Image_20230925_at_12346_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d38",
    "name": "Kitchen",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458581_WhatsApp_Image_20230925_at_12345_PM_3.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "5544",
"max": "6727"
},
"builtUpRateRange": {
  "min": "4621",
  "max": "5607"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "665.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "650d7beb612315172eb01a92",
"ownerName": "Mr. Vinod Jaisingh Yadav & Mrs. Rajani Vinod Yadav",
"ownerPhoneNo": "8879084882",
"appAddress": "flat nk 201 2 nd floor panvelkar Aque mafine chs Ltd Bldg no 4
Ambrnath \n1",
"remark": "code Sharmila madam. Narayan ssl ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "07/07/2021",
  "from": {
    "value": "Seller",
    "label": "Seller"
  },
  "Seller": "Mr. Navin Hiranandani & Mr. Tulsi L. Hiranandani",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Vinod Jaisingh Yadav & Mr. Rajani Vinod Yadav"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695711479713_Vinod_yadav__sbi_Racpc_belapur.pdf",
"path": "cases/650d7beb612315172eb01a92/
document_1695711479713_Vinod_yadav__sbi_Racpc_belapur.pdf",
"id": "813344",
"uploadedBy": "64cde526dc9f3034f3fefa49",
"createdAt": "Tue Sep 26 2023 12:35:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "16/11/2016",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "ANP / NRV / 16-17 / 1089"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695712819804_854329.pdf",
  "path": "cases/650d7beb612315172eb01a92/
document_1695712819804_854329.pdf",
  "id": "985538",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Tue Sep 26 2023 12:50:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/03/2013",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "ANP / NRV / CC / 12-13 / 1286 / 2227 / 996"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695712867102_638140.pdf",
"path": "cases/650d7beb612315172eb01a92/
document_1695712867102_638140.pdf",
"id": "314608",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Tue Sep 26 2023 12:51:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125faa6d152c1801b35b",
    "label": "Property Tax Receipt"
  },
  "inputs": {
    "documentDate": "18/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "AS5402"
},
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1695712909117_724772.pdf",
    "path": "cases/650d7beb612315172eb01a92/
document_1695712909117_724772.pdf",
    "id": "148360",
    "uploadedBy": "60eeaeddf3dd69653a581316",
    "createdAt": "Tue Sep 26 2023 12:51:49 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003977",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "743365",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 22 2023 17:05:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Vinod Jaisingh Yadav & Mrs. Rajani Vinod Yadav",
    "phone": "8879084882",
    "ownershipShare": "",
    "email": "",
    "id": "773444"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "304147",
    "name": "Bedroom",
    "length": "9.00",
    "length1": "9",
    "length2": "00",
    "width": "11.00",
    "width1": "11",
    "width2": "00",
    "totalArea": "99.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "99.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Balcony",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "32.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
```

```
"name": "Passage",
"length": "14.00",
"length1": "14",
"length2": "00",
"width": "3.00",
"width1": "3",
"width2": "00",
"totalArea": "42.00",
"images": [],
"extraAreas": [],
"finalArea": "42.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "14.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "21.33",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "21.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "88.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "88.54"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "120.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Living Room",
  "length": "13.58",
```



```
"length1": "13",
"length2": "7",
"width": "8.67",
"width1": "8",
"width2": "8",
"totalArea": "117.72",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "651285130c1bfd1d9fe2b215",
    "name": "Passage",
    "extraAreaType": "Add",
    "length": "9.08",
    "length1": "9",
    "length2": "1",
    "width": "6.00",
    "width1": "6",
    "width2": "00",
    "totalArea": "54.50"
  }
],
"finalArea": "172.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "25.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.67"
}
],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "114491",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "665",
    "squareMeterArea": "61.78",
    "docFinalBuiltUp": "798",
    "docFinalBuiltUpSquareMeter": "74.136",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "651282880c1bfd1d9fe2a278",
    "property": "Residential Flat",
    "area": "503.50",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "2900000",
    "expectedRate": "5759.68",
    "builtUpExpectedRate": "4799.74",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711665019_Image.jpeg",
    "squareMeter": "46.78",
    "id": "624227"
  },
  {
    "printlnReport": true,
```

```
    "_id": "651282880c1bfd1d9fe2a279",
    "property": "Residential Flat",
    "area": "541.12",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "3000000",
    "expectedRate": "5544.06",
    "builtUpExpectedRate": "4620.08",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711693070_Image.jpeg",
    "squareMeter": "50.27",
    "id": "761169"
  },
  {
    "printlnReport": true,
    "_id": "651282880c1bfd1d9fe2a27a",
    "property": "Residential Flat",
    "area": "503",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3000000",
    "expectedRate": "5964.21",
    "builtUpExpectedRate": "4970.18",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711719482_Image.png",
    "squareMeter": "46.73",
    "id": "196619"
  },
  {
    "printlnReport": true,
    "_id": "651282880c1bfd1d9fe2a27b",
    "property": "Residential Flat",
    "area": "491",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "2800000",
    "expectedRate": "5702.65",
```

```
    "builtUpExpectedRate": "4752.21",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711745397_Image.png",
    "squareMeter": "45.62",
    "id": "804898"
  },
  {
    "printlnReport": true,
    "_id": "651282880c1bfd1d9fe2a27c",
    "property": "Residential Flat",
    "area": "550",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "3700000",
    "expectedRate": "6727.27",
    "builtUpExpectedRate": "5606.06",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711767647_Image.png",
    "squareMeter": "51.10",
    "id": "679306"
  },
  {
    "printlnReport": true,
    "_id": "651282880c1bfd1d9fe2a27d",
    "property": "Residential Flat",
    "area": "482",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "3000000",
    "expectedRate": "6224.07",
    "builtUpExpectedRate": "5186.72",
    "image": "cases/650d7beb612315172eb01a92/
indicator_1695711786461_Image.png",
    "squareMeter": "44.78",
    "id": "497137"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6511446f0c1bfd1d9fe04cf7",
    "name":
"externallmg_1695630447792_WhatsApp_Image_20230925_at_12321_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447792_WhatsApp_Image_20230925_at_12321_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511446f0c1bfd1d9fe04cf8",
    "name":
"externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447795_WhatsApp_Image_20230925_at_12326_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511446f0c1bfd1d9fe04cf9",
    "name":
"externallmg_1695630447799_WhatsApp_Image_20230925_at_12326_PM_2.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630447799_WhatsApp_Image_20230925_at_12326_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d2e",
    "name":
"externallmg_1695630458551_WhatsApp_Image_20230925_at_12326_PM_3.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458551_WhatsApp_Image_20230925_at_12326_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d2f",
    "name":
"externallmg_1695630458554_WhatsApp_Image_20230925_at_12326_PM_4.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458554_WhatsApp_Image_20230925_at_12326_PM_4.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d30",
    "name":
"externallmg_1695630458557_WhatsApp_Image_20230925_at_12326_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458557_WhatsApp_Image_20230925_at_12326_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d31",
    "name":
"externallmg_1695630458560_WhatsApp_Image_20230925_at_12327_PM_1.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458560_WhatsApp_Image_20230925_at_12327_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d32",
    "name":
"externallmg_1695630458561_WhatsApp_Image_20230925_at_12327_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458561_WhatsApp_Image_20230925_at_12327_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d33",
    "name":
"externallmg_1695630458565_WhatsApp_Image_20230925_at_12328_PM_1.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458565_WhatsApp_Image_20230925_at_12328_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d34",
```

```
    "name":
"externallmg_1695630458567_WhatsApp_Image_20230925_at_12328_PM_2.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458567_WhatsApp_Image_20230925_at_12328_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d35",
  "name":
"externallmg_1695630458569_WhatsApp_Image_20230925_at_12328_PM.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458569_WhatsApp_Image_20230925_at_12328_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d36",
  "name":
"externallmg_1695630458571_WhatsApp_Image_20230925_at_12345_PM_1.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458571_WhatsApp_Image_20230925_at_12345_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d37",
  "name":
"externallmg_1695630458573_WhatsApp_Image_20230925_at_12345_PM_2.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458573_WhatsApp_Image_20230925_at_12345_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d38",
  "name":
"externallmg_1695630458581_WhatsApp_Image_20230925_at_12345_PM_3.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458581_WhatsApp_Image_20230925_at_12345_PM_3.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d39",
  "name":
"externallmg_1695630458583_WhatsApp_Image_20230925_at_12345_PM.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458583_WhatsApp_Image_20230925_at_12345_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d3a",
  "name":
"externallmg_1695630458586_WhatsApp_Image_20230925_at_12346_PM_1.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458586_WhatsApp_Image_20230925_at_12346_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d3b",
  "name":
"externallmg_1695630458588_WhatsApp_Image_20230925_at_12346_PM_2.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458588_WhatsApp_Image_20230925_at_12346_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d3c",
  "name":
"externallmg_1695630458591_WhatsApp_Image_20230925_at_12346_PM_3.jpeg",
  "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458591_WhatsApp_Image_20230925_at_12346_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6511447a0c1bfd1d9fe04d3d",
  "name":
"externallmg_1695630458592_WhatsApp_Image_20230925_at_12346_PM_4.jpeg",
```



```
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458592_WhatsApp_Image_20230925_at_12346_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d3e",
    "name":
"externallmg_1695630458594_WhatsApp_Image_20230925_at_12346_PM_5.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458594_WhatsApp_Image_20230925_at_12346_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d3f",
    "name":
"externallmg_1695630458595_WhatsApp_Image_20230925_at_12346_PM_6.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458595_WhatsApp_Image_20230925_at_12346_PM_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6511447a0c1bfd1d9fe04d40",
    "name":
"externallmg_1695630458596_WhatsApp_Image_20230925_at_12346_PM.jpeg",
    "path": "cases/650d7beb612315172eb01a92/
externallmg_1695630458596_WhatsApp_Image_20230925_at_12346_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"externallmg_1695630458592_WhatsApp_Image_20230925_at_12346_PM_4.jpeg",
    "filename": "1695711895325_externallmg_1695630458592_WhatsApp_Image_202
30925_at_12346_PM_4.jpeg",
    "path": "cases/650d7beb612315172eb01a92/processingDocuments/169571189532
5_externallmg_1695630458592_WhatsApp_Image_20230925_at_12346_PM_4.jpeg",
    "size": "68193",
    "createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
  "externallmg_1695630458594_WhatsApp_Image_20230925_at_12346_PM_5.jpeg",
  "filename": "1695711895340_externallmg_1695630458594_WhatsApp_Image_20230925_at_12346_PM_5.jpeg",
  "path": "cases/650d7beb612315172eb01a92/processingDocuments/1695711895340_externallmg_1695630458594_WhatsApp_Image_20230925_at_12346_PM_5.jpeg",
  "size": "59338",
  "createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
  "externallmg_1695630458595_WhatsApp_Image_20230925_at_12346_PM_6.jpeg",
  "filename": "1695711895345_externallmg_1695630458595_WhatsApp_Image_20230925_at_12346_PM_6.jpeg",
  "path": "cases/650d7beb612315172eb01a92/processingDocuments/1695711895345_externallmg_1695630458595_WhatsApp_Image_20230925_at_12346_PM_6.jpeg",
  "size": "44089",
  "createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1695711895347_IGR01.pdf",
  "path": "cases/650d7beb612315172eb01a92/processingDocuments/1695711895347_IGR01.pdf",
  "size": "161073",
  "createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1695711895358_IGR02.pdf",
  "path": "cases/650d7beb612315172eb01a92/processingDocuments/1695711895358_IGR02.pdf",
  "size": "164118",
  "createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1695711895372_IGR03.pdf",
  "path": "cases/650d7beb612315172eb01a92/processingDocuments/1695711895372_IGR03.pdf",
```

```
"size": "153290",
"createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-04.pdf",
"filename": "1695711895377_IGR04.pdf",
"path": "cases/650d7beb612315172eb01a92/
processingDocuments/1695711895377_IGR04.pdf",
"size": "154622",
"createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=Vinod.xlsx",
"filename": "1695711895381_Summary_NewVinod.xlsx",
"path": "cases/650d7beb612315172eb01a92/
processingDocuments/1695711895381_Summary_NewVinod.xlsx",
"size": "2950527",
"createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Vinod yadav sbi Racpc belapur.pdf",
"filename": "1695711895440_Vinod_yadav__sbi_Racpc_belapur.pdf",
"path": "cases/650d7beb612315172eb01a92/
processingDocuments/1695711895440_Vinod_yadav__sbi_Racpc_belapur.pdf",
"size": "20615273",
"createdAt": "Tue Sep 26 2023 12:34:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"remarks": [],
"createdAt": "2023-09-22T11:35:07.641Z",
"updatedAt": "2023-09-26T08:59:36.336Z",
"__v": 0,
"fullAddress": "Residential Flat No. 201, 2nd Floor, Building No 04, Deniz Building,
Panvelkar Aqua Marine Co-op. Hsg. Soc. Ltd., Village - Morivali, Ambernath (West),
Taluka - Ambernath, District - Thane, Ambernath, 421501, State - Maharashtra, India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mrs. Rajani Vinod Yadav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8879084882",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 665.00",
"flatRate": "6000",
"landOtherRate": "3500",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Balcony + Toilet +
Passage + WC + Bathroom",
"carpetTotal": "642.68",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "706.95",
"finalCarpetArea": "642.68",
"finalSalableArea": "777.64",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for
Sale Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area.",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
```

```

"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Tue Sep 26 2023 13:29:48 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-09-25"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	9'00"	11'00"	99.00
Balcony	8'00"	4'1"	32.67
Toilet	6'9"	4'00"	27.00
Passage	14'00"	3'00"	42.00
WC	4'00"	3'6"	14.00
Bathroom	4'00"	5'4"	21.33
Kitchen	10'5"	8'6"	88.54
Bedroom	13'00"	9'3"	120.25
Living Room	13'7"	8'8"	117.72
Balcony	3'6"	7'4"	25.67
Other Composition :			