

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "18000000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 9000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "Binu",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "shortName": "Binu",
  "email": "binu@vastukala.org",
  "designation": "Back Office Team Leader",
  "mobileNo": "9930252906",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.080095993651888",
  "longitude": "72.91738896663374"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91738896663374,
```

```
19.080095993651888
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-25",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ghatkopar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "33",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ghatkopar (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kurla",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pragati Icon",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "A. S. Gawade Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Pant Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "5662 (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 075",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Om Sahyadri Heights",
    "west": "Building No. 32",
    "south": "A. S. Gawade Marg",
    "east": "Shree Gurudatta Mandir Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details is not available",
    "west": "Details is not available",
    "south": "Details is not available",
    "east": "Details is not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details is not available",
      "east": "Details is not available",
      "south": "Details is not available",
      "west": "Details is not available"
    },
    "asPerDocument": {
      "north": "Details is not available",
      "east": "Details is not available",
      "south": "Details is not available",

```

```
    "west": "Details is not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "Details is not available",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential flat",
  "rate": "133620",
  "landRate": "62300",
  "igrImage": "cases/650ffba60c1bfd1d9fdf4293/igr_1695711620338_Image.png",
  "squareMeterGuideLineRate": "140301.00",
  "squareFeetGuideLineRate": "13034.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "133620",
  "squareMeterGuideLineRate": "140301.00",
  "squareFeetGuideLineRate": "13034.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "50000",
```

```
"assessmentNo": "Details is not available",
"taxPaidHolderName": "Details is not available",
"taxAmount": "Details is not available",
"electricityServiceConnectionNo": "Details is not available",
"meterCardHolderName": "Details is not available",
"undividedAreaOfLandAsPerSaleDeed": "Details is not available",
"floorSpaceIndex": "As per MHADA norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
```

```
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
```

```
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "16",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "976.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/650ffba60c1bfd1d9fdf4293/
routeMap_1695717295122_Image.png",
    "routeLat": "19.085500",
    "routeLng": "72.912722",
    "stationName": "Ghatkopar",
    "routeDistance": "650 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "q3z9qx",
      "name": "q3z9qx",
      "image": "cases/650ffba60c1bfd1d9fdf4293/
routeMap_1695717223273_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "21312000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "21312000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Sep 26 2023 15:49:35 GMT+0530 (India Standard Time)",
  "number": "2302724",
  "dayCount": "10",
  "monthCount": "368",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
```

```
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "18",
  "percentage": "40",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "18",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "18",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "18",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "18",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "18",
"percentage": "2.50",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "18",
"percentage": "10.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "18",
"percentage": "1.50",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "85.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12731611.00",
  "selectedBuildUpValue": "976.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "651114060c1bfd1d9fdf9824",
      "name": "externalimg_1695617955410_1695617743275_image_8.jpeg",
      "path": "cases/650ffba60c1bfd1d9fdf4293/
externalimg_1695617955410_1695617743275_image_8.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "651114060c1bfd1d9fdf9829",
      "name": "Living Room",
      "path": "cases/650ffba60c1bfd1d9fdf4293/
externalimg_1695618020804_1695617920237_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9826",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618015491_1695617920237_image_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9827",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618016444_1695617920237_image_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9825",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618013372_1695617920237_image_0.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9828",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618019055_1695617920237_image_3.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9832",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618050988_1695617957152_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "651114060c1bfd1d9fdf9833",
  "name": "Living Room",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618051350_1695617957152_image_5.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651114060c1bfd1d9fdf981d",
    "name": "Living Room",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617928274_1695617743275_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651114060c1bfd1d9fdf9824",
    "name": "Living Room",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617955410_1695617743275_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651114060c1bfd1d9fdf981c",
    "name": "Living Room",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617853410_1695617743275_image_0.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16500",
    "max": "22364"
  },
  "builtUpRateRange": {
    "min": "15000",
    "max": "20332"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "888.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentId": [],
"_id": "650ffba60c1bfd1d9fdf4293",
"ownerName": "Mr. Sandeep Shantaram Hire & Mrs. Sangita Sandeep Hire",
"ownerPhoneNo": "9082911288",
"appAddress": "flat no 604 6 th floor Bldg no 33 pragati lakon pant nagar Gulmohar
Ghatkoper",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Index - II",
      "value": "60ae1287aa6d152c1801b415"
    },
    "inputs": {
      "documentDate": "13/09/2023",
      "amount": "14652000",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Pragati Developers",
      "to": {
        "value": "The_Allottees",
        "label": "The Allottees"
      },
      "The_Allottees": "Mr. Sandeep Shantaram Hire & Mrs. Sangita Sandeep Hire"
    },
    "isHardCopy": false,
```

```
"displayStatus": false,
"id": "814425",
"path": "cases/650ffba60c1bfd1d9fdf4293/
document_1695546237633_Sandeep_hire_1.pdf",
"fileName": "document_1695546237633_Sandeep_hire_1.pdf"
},
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "inputs": {
    "documentDate": "13/09/2023",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s. Pragati Developers",
    "to": {
      "value": "The_Allottees",
      "label": "The Allottees"
    },
    "The_Allottees": "Mr. Sandeep Shantaram Hire & Mrs. Sangita Sandeep Hire"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "850457",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
document_1695615007526_New_Doc_09242023_1630.pdf",
  "fileName": "document_1695615007526_New_Doc_09242023_1630.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "02/09/2020",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51800026241"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"fileName": "document_1695713641470_551786.pdf",
"path": "cases/650ffba60c1bfd1d9dfd4293/document_1695713641470_551786.pdf",
"id": "663716",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Sep 26 2023 13:04:01 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12b3aa6d152c1801b4dc",
    "label": "Further Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/08/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MH / EE / (BP) / GM / MHADA - 1 / 494 / 2022 / FCC / 1 /
Amend"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695713768005_674708.pdf",
  "path": "cases/650ffba60c1bfd1d9dfd4293/document_1695713768005_674708.pdf",
  "id": "401693",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Sep 26 2023 13:06:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "17/06/2020",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "MH / EE / (BP) / GM / MHADA - 1 / 494 / 2022 / FCC / 1 /
Amend "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695713839096_plan.pdf",
  "path": "cases/650ffba60c1bfd1d9dfd4293/document_1695713839096_plan.pdf",
  "id": "929846",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Sep 26 2023 13:07:19 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004003",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "784308",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Sep 24 2023 14:34:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sandeep Shantaram Hire & Mrs. Sangita Sandeep Hire",
    "phone": "9082911288",
    "ownershipShare": "",
    "email": "",
    "id": "942100"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "623732",
    "name": "Living Room",
    "length": "9.42",
    "length1": "9",
    "length2": "5",
    "width": "20.92",
```

```
"width1": "20",
"width2": "11",
"totalArea": "196.96",
"images": [],
"extraAreas": [],
"finalArea": "196.96"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "35.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Dining",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "98.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "98.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "79.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "79.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "26.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
```

```
"totalArea": "99.00",
"images": [],
"extraAreas": [],
"finalArea": "99.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "16.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "",
  "length1": "7",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "28.00",
  "images": [],
  "finalArea": "28.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```



```
"id": "8",
"name": "Toilet",
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "94.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "94.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "100.83",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "100.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "1.08",
  "width1": "1",
  "width2": "1",
  "totalArea": "10.74",
  "images": [],
  "finalArea": "10.74",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Index - II",
      "value": "60ae1287aa6d152c1801b415"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "82.50",
    "totalAreaDocument": "888",
    "docBultupPercentage": "10",
    "docFinalBultUp": "976.80",
    "docFinalBultUpSquareMeter": "90.75",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "752308"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6512823a0c1bfd1d9fe2a137",
    "property": "Residential Flat",
    "area": "888",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "14652000",
    "expectedRate": "16500.00",
    "builtUpExpectedRate": "15000.00",
    "image": "cases/650ffba60c1bfd1d9fdf4293/indicator_1695710835988_Image.png",
    "squareMeter": "82.50",
    "id": "100507"
  },
  {
    "printlnReport": true,
    "_id": "6512823a0c1bfd1d9fe2a138",
    "property": "Residential Flat",
    "area": "626",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "6",
    "source": "Housing.Com",
    "expectedPrice": "14000000",
    "expectedRate": "22364.22",
    "builtUpExpectedRate": "20331.11",
    "image": "cases/650ffba60c1bfd1d9fdf4293/indicator_1695710919075_Image.png",
    "squareMeter": "58.16",
    "id": "305843"
  },
  {
    "printlnReport": true,
    "_id": "6512823a0c1bfd1d9fe2a139",
    "property": "Residential Flat",
    "area": "567",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
```

```
"floor": "22",
"source": "Housing.Com",
"expectedPrice": "9600000",
"expectedRate": "16931.22",
"builtUpExpectedRate": "0.00",
"image": "cases/650ffba60c1bfd1d9fdf4293/indicator_1695711056294_Image.png",
"squareMeter": "52.68",
"id": "599588"
}
],
"externallImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf981c",
  "name": "externallmg_1695617853410_1695617743275_image_0.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617853410_1695617743275_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf981d",
  "name": "externallmg_1695617928274_1695617743275_image_1.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617928274_1695617743275_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf981e",
  "name": "externallmg_1695617931260_1695617743275_image_2.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617931260_1695617743275_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf981f",
  "name": "externallmg_1695617941290_1695617743275_image_3.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617941290_1695617743275_image_3.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9820",
  "name": "externallmg_1695617944045_1695617743275_image_4.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617944045_1695617743275_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9821",
  "name": "externallmg_1695617947864_1695617743275_image_5.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617947864_1695617743275_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9822",
  "name": "externallmg_1695617949900_1695617743275_image_6.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617949900_1695617743275_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9823",
  "name": "externallmg_1695617952929_1695617743275_image_7.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617952929_1695617743275_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9824",
  "name": "externallmg_1695617955410_1695617743275_image_8.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617955410_1695617743275_image_8.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9825",
  "name": "externallmg_1695618013372_1695617920237_image_0.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618013372_1695617920237_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9826",
  "name": "externallmg_1695618015491_1695617920237_image_1.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618015491_1695617920237_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9827",
  "name": "externallmg_1695618016444_1695617920237_image_2.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618016444_1695617920237_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9828",
  "name": "externallmg_1695618019055_1695617920237_image_3.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618019055_1695617920237_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9fdf9829",
  "name": "externallmg_1695618020804_1695617920237_image_4.jpeg",
  "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618020804_1695617920237_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651114060c1bfd1d9dfd982a",
    "name": "externallmg_1695618021583_1695617920237_image_5.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externallmg_1695618021583_1695617920237_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651114060c1bfd1d9dfd982b",
    "name": "externallmg_1695618022763_1695617920237_image_6.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externallmg_1695618022763_1695617920237_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651114060c1bfd1d9dfd982c",
    "name": "externallmg_1695618023429_1695617920237_image_7.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externallmg_1695618023429_1695617920237_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651114060c1bfd1d9dfd982d",
    "name": "externallmg_1695618024283_1695617920237_image_8.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externallmg_1695618024283_1695617920237_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651114060c1bfd1d9dfd982e",
    "name": "externallmg_1695618049213_1695617957152_image_0.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externallmg_1695618049213_1695617957152_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "651114060c1bfd1d9dfd982f",
  "name": "externalimg_1695618049742_1695617957152_image_1.jpeg",
  "path": "cases/650ffba60c1bfd1d9dfd4293/
externalimg_1695618049742_1695617957152_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9dfd9830",
  "name": "externalimg_1695618050068_1695617957152_image_2.jpeg",
  "path": "cases/650ffba60c1bfd1d9dfd4293/
externalimg_1695618050068_1695617957152_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9dfd9831",
  "name": "externalimg_1695618050770_1695617957152_image_3.jpeg",
  "path": "cases/650ffba60c1bfd1d9dfd4293/
externalimg_1695618050770_1695617957152_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9dfd9832",
  "name": "externalimg_1695618050988_1695617957152_image_4.jpeg",
  "path": "cases/650ffba60c1bfd1d9dfd4293/
externalimg_1695618050988_1695617957152_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651114060c1bfd1d9dfd9833",
  "name": "externalimg_1695618051350_1695617957152_image_5.jpeg",
  "path": "cases/650ffba60c1bfd1d9dfd4293/
externalimg_1695618051350_1695617957152_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "651114060c1bfd1d9fdf9834",
    "name": "externallmg_1695618051791_1695617957152_image_6.jpeg",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695618051791_1695617957152_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9fdf9835",
    "name": "externallmg_1695617790620_1695617693836_image_0.jpeg",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617790620_1695617693836_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9fdf9836",
    "name": "externallmg_1695617791646_1695617693836_image_1.jpeg",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617791646_1695617693836_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9fdf9837",
    "name": "externallmg_1695617792005_1695617693836_image_2.jpeg",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617792005_1695617693836_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9fdf9838",
    "name": "externallmg_1695617931615_1695617839469_image_0.jpeg",
    "path": "cases/650ffba60c1bfd1d9fdf4293/
externallmg_1695617931615_1695617839469_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9fdf9839",
```

```
    "name": "externalImg_1695617933185_1695617839469_image_1.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externalImg_1695617933185_1695617839469_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9dfd983a",
    "name": "externalImg_1695617935909_1695617839469_image_2.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externalImg_1695617935909_1695617839469_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9dfd983b",
    "name": "externalImg_1695617936583_1695617839469_image_3.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externalImg_1695617936583_1695617839469_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9dfd983c",
    "name": "externalImg_1695617938004_1695617839469_image_4.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externalImg_1695617938004_1695617839469_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651114060c1bfd1d9dfd983d",
    "name": "externalImg_1695617938648_1695617839469_image_5.jpeg",
    "path": "cases/650ffba60c1bfd1d9dfd4293/
externalImg_1695617938648_1695617839469_image_5.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
    "originalname": "Valuation_Report_Sandeep Shantaram Hire & Mrs. Sangita
Sandeep Hire.pdf",
```

```
"filename": "1695730139446_Valuation_Report_Sandeep_Shantaram_Hire__Mrs_Sangita_Sandeep_Hire.pdf",
"path": "cases/650ffba60c1bfd1d9fdf4293/externalDocuments/1695730139446_Valuation_Report_Sandeep_Shantaram_Hire__Mrs_Sangita_Sandeep_Hire.pdf",
"size": "1165898",
"documentType": {
  "value": "640ece6024088f0f94ee4ea8",
  "label": "Final PDF Report"
},
"createdAt": "Tue Sep 26 2023 17:39:02 GMT+0530 (India Standard Time)",
"uploadedBy": "63f31d626f9c2254a9b39144"
},
],
"processingDocuments": [
  {
    "originalname": "Sandeep S.Hire - flat No. 604 -Calculation sheet.xlsx",
    "filename": "1695710325550_Sandeep_SHire__flat_No_604_Calculation_sheet.xlsx",
    "path": "cases/650ffba60c1bfd1d9fdf4293/processingDocuments/1695710325550_Sandeep_SHire__flat_No_604_Calculation_sheet.xlsx",
    "size": "414456",
    "createdAt": "Tue Sep 26 2023 12:08:45 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "plan.pdf",
    "filename": "1695715607615_plan.pdf",
    "path": "cases/650ffba60c1bfd1d9fdf4293/processingDocuments/1695715607615_plan.pdf",
    "size": "812092",
    "createdAt": "Tue Sep 26 2023 13:36:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"remarks": [],
"createdAt": "2023-09-24T09:04:38.630Z",
"updatedAt": "2023-09-27T10:12:45.999Z",
"__v": 0,
"invoiceId": "650ffba60c1bfd1d9fdf429c",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"fullAddress": "Residential Flat No. 604, 6th Floor, Building No 33, Pragati Icon, A. S. Gawade Marg, Pant Nagar, Village - Ghatkopar, Taluka - Kurla, District - Mumbai Suburban, Ghatkopar (East), PIN - 400 075, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Miss. Priyanka Kantre",
```

```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"siteVisitContactNo": "7710038568",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Index - II",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 888.00",
"flatRate": "24000",
"landOtherRate": "21000",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 4 Passage + Dining +
2 Toilet",
"carpetTotal": "815.4600000000002",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "897.01",
"finalCarpetArea": "815.46",
"finalSalableArea": "1166.11",
"salablePercentage": "30",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"siteVisitDate": "2023-09-25",
"finalSaleablePercentage": ""
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'5"	20'11"	196.96
Passage	7'1"	5'00"	35.42
Dining	11'8"	8'5"	98.19
Kitchen	7'00"	11'5"	79.92
Passage	8'6"	3'2"	26.92
Bedroom	11'00"	9'00"	99.00

Passage	4'00"	4'2"	16.67
Toilet	7'0"	4'0"	28.00
Toilet	7'00"	4'00"	28.00
Bedroom	10'3"	9'3"	94.81
Bedroom	11'00"	9'2"	100.83
Passage	9'11"	1'1"	10.74
Other Composition :			