

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1000000000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 500000,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.18166343047949",
  "longitude": "72.94638526626612"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94638526626612,
```

```
19.18166343047949
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-25",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Mulund",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B-9",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mulund (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kurla",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shri Krishna Dham Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "L.B.S. Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "D",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "240(P), 241(P), 241(3P), 267(P), 268(P)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "36",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 080",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Mahavir Tower",
    "south": "Apoorva Apartment",
    "east": "L.B.S. Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan.",
  "approvePlanVerified": "No",
  "empanelledOfApprovePlan": "N. A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "61.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "20278",
  "depreciatedBuildingRate": "1078"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "173200",
  "landRate": "89150",
  "igrImage": "cases/651171480c1bfd1d9fe13cbd/igr_1695715495858_Image.png",
  "squareMeterGuideLineRate": "147220.00",
  "squareFeetGuideLineRate": "13677.00"
},
"igrFinalRate": {
  "depreciationPercentage": "59",
  "rate": "11465.00",
  "squareFeetGuideLineRate": "11465.00",
  "squareMeterGuideLineRate": "123411.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "22000",
```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "1982",
"fullDate": "1/1/1982"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
```

```
"label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "19",
"ageOfBuilding": "41",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "530.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/651171480c1bfd1d9fe13cbd/
routeMap_1695715635549_Image.png",
    "routeLat": "19.181472",
    "routeLng": "72.946278",
    "stationName": "Mulund",
    "routeDistance": "2.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "474enm",
      "name": "474enm",
      "image": "cases/651171480c1bfd1d9fe13cbd/
routeMap_1695715566923_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "10747340.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "10747340.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Sep 27 2023 11:12:28 GMT+0530 (India Standard Time)",
  "number": "2302735",
  "dayCount": "3",
  "monthCount": "379",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6076450.00",
  "selectedBuildUpValue": "530.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c68d",
      "name": "externalimg_r_1695648417375_1695648314604_image_1.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externalimg_r_1695648417375_1695648314604_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c68a",
      "name": "externalimg_r_1695648415244_1695648314604_image_0.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externalimg_r_1695648415244_1695648314604_image_0.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c68e",
```

```
    "name": "externallmg_r_1695648420992_1695648314604_image_4.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648420992_1695648314604_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68d",
    "name": "externallmg_r_1695648417375_1695648314604_image_1.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648417375_1695648314604_image_1.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68c",
    "name": "externallmg_r_1695648419005_1695648314604_image_2.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648419005_1695648314604_image_2.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c691",
    "name": "Living Room",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648426360_1695648314604_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c690",
    "name": "Living Room",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648424213_1695648314604_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68f",
    "name": "Living Room",
```

```
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648422232_1695648314604_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c694",
    "name": "Living Room",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648428918_1695648314604_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c696",
    "name": "Living Room",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648436100_1695648314604_image_12.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "530.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "ATTACHSIGN",
"paymentId": [],
"_id": "651171480c1bfd1d9fe13cbd",
"ownerName": "Smt. Daksha Pratap Bhanushali",
"ownerPhoneNo": "7506179393",
"appAddress": "flat no 3 rd floor Bldg D B 9 krishna Dham L B S Road mulund ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "03/06/2004",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Shri. Suresh Kumar Jagdipnarayan Singh & Smt. Binu S. Singh",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Smt. Daksha Pratap Bhanushali & Shri. Pratap Ramji Bhanushali"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "813850",
    "path": "cases/651171480c1bfd1d9fe13cbd/
document_1695641867807_Sbi_Racpc_belapur_kadam.pdf",
    "fileName": "document_1695641867807_Sbi_Racpc_belapur_kadam.pdf"
  },
  {
    "documentType": {
```

```
"value": "60ae1250aa6d152c1801b316",
"label": "Part Occupancy Certificate"
},
"inputs": {
  "documentDate": "01/01/1981",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "Not Visible "
},
"isHardCopy": false,
"displayStatus": false,
"fileName":
"document_1695713962125_1695711689195_Part_OC_Shri_Krihnadahm.pdf",
"path": "cases/651171480c1bfd1d9fe13cbd/
document_1695713962125_1695711689195_Part_OC_Shri_Krihnadahm.pdf",
"id": "584207",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Sep 26 2023 13:09:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae128eaa6d152c1801b431",
    "label": "Pan Card"
  },
  "inputs": {
    "remark": "in the name of Sugandha Vijay Kadam",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "AEFPK2096H"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695793750712_sugandhakadam_pan.pdf",
  "path": "cases/651171480c1bfd1d9fe13cbd/
document_1695793750712_sugandhakadam_pan.pdf",
  "id": "811925",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9",
  "createdAt": "Wed Sep 27 2023 11:19:10 GMT+0530 (India Standard Time)"
```

```
},
{
  "documentType": {
    "value": "60ae128eaa6d152c1801b431",
    "label": "Pan Card"
  },
  "inputs": {
    "remark": "in the name of Kadam Tanmay Vijay",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CDKPK2362L"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695793802268_Pan_Card_Tanmay.pdf",
  "path": "cases/651171480c1bfd1d9fe13cbd/
document_1695793802268_Pan_Card_Tanmay.pdf",
  "id": "546908",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9",
  "createdAt": "Wed Sep 27 2023 11:20:02 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004020",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "228550",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 25 2023 17:08:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt. Daksha Pratap Bhanushali",
    "phone": "7506179393",
    "ownershipShare": "",
    "email": "",
    "id": "184653"
  },
  {
    "name": "Shri. Pratap Ramji Bhanushali",
    "phone": "",
    "email": ""
  }
]
```

```
    "ownershipShare": "",
    "id": "721174"
  }
],
"proposePurchasers": [
  {
    "name": "Tanmay Vijay Kadam",
    "phone": "",
    "ownershipShare": "",
    "email": ""
  },
  {
    "name": "Sugandha Vijay Kadam",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "574651",
    "name": "Living Room",
    "length": "17.50",
    "length1": "17",
    "length2": "6",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "164.79",
    "images": [],
    "extraAreas": [],
    "finalArea": "164.79"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "WC",
    "length": "5.25",
```

```
"length1": "5",
"length2": "3",
"width": "2.58",
"width1": "2",
"width2": "7",
"totalArea": "13.56",
"images": [],
"extraAreas": [],
"finalArea": "13.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "17.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "109.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "109.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "12.08",
  "length1": "12",
  "length2": "1",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "85.59",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.59"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.75",
  "length1": "2",
  "length2": "9",
  "width": "15.58",
  "width1": "15",
  "width2": "7",
  "totalArea": "42.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.85"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "249340",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "530",
  "squareMeterArea": "49.24",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65128fa80c1bfd1d9fe2de50",
    "id": "1",
    "property": "Flat",
    "area": "475",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "11500000",
    "expectedRate": "24210.53",
    "builtUpExpectedRate": "20175.44",
    "image": "cases/651171480c1bfd1d9fe13cbd/indicator_1695715240894_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "65128fe80c1bfd1d9fe2df59",
    "id": "2",
    "property": "Flat",
    "area": "430",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "Nobroker.com",
```



```
"expectedPrice": "9500000",
"expectedRate": "22093.02",
"builtUpExpectedRate": "18410.85",
"image": "cases/651171480c1bfd1d9fe13cbd/indicator_1695715303929_Image.png"
},
{
  "printlnReport": true,
  "_id": "651290290c1bfd1d9fe2dfe1",
  "id": "3",
  "property": "Flat",
  "area": "415",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "9000000",
  "expectedRate": "21686.75",
  "builtUpExpectedRate": "9000000",
  "image": "cases/651171480c1bfd1d9fe13cbd/indicator_1695715368940_Image.png"
},
{
  "printlnReport": true,
  "_id": "651290520c1bfd1d9fe2e04d",
  "id": "4",
  "property": "Flat",
  "area": "451",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8600000",
  "expectedRate": "19068.74",
  "builtUpExpectedRate": "8600000",
  "image": "cases/651171480c1bfd1d9fe13cbd/indicator_1695715410447_Image.png"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68a",
    "name": "externallmg_r_1695648415244_1695648314604_image_0.jpg",
```

```
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648415244_1695648314604_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68b",
    "name": "externallmg_r_1695648420232_1695648314604_image_3.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648420232_1695648314604_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68c",
    "name": "externallmg_r_1695648419005_1695648314604_image_2.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648419005_1695648314604_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68d",
    "name": "externallmg_r_1695648417375_1695648314604_image_1.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648417375_1695648314604_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68e",
    "name": "externallmg_r_1695648420992_1695648314604_image_4.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648420992_1695648314604_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65118ac30c1bfd1d9fe1c68f",
    "name": "externallmg_r_1695648422232_1695648314604_image_5.jpg",
    "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648422232_1695648314604_image_5.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65118ac30c1bfd1d9fe1c690",
  "name": "externallmg_r_1695648424213_1695648314604_image_6.jpg",
  "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648424213_1695648314604_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65118ac30c1bfd1d9fe1c691",
  "name": "externallmg_r_1695648426360_1695648314604_image_7.jpg",
  "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648426360_1695648314604_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65118ac30c1bfd1d9fe1c692",
  "name": "externallmg_r_1695648430732_1695648314604_image_9.jpg",
  "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648430732_1695648314604_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65118ac30c1bfd1d9fe1c693",
  "name": "externallmg_r_1695648432281_1695648314604_image_10.jpg",
  "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648432281_1695648314604_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65118ac30c1bfd1d9fe1c694",
  "name": "externallmg_r_1695648428918_1695648314604_image_8.jpg",
  "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648428918_1695648314604_image_8.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c695",
      "name": "externallmg_r_1695648434132_1695648314604_image_11.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648434132_1695648314604_image_11.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c696",
      "name": "externallmg_r_1695648436100_1695648314604_image_12.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648436100_1695648314604_image_12.jpg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c697",
      "name": "externallmg_r_1695648388415_1695648293929_image_2.png",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648388415_1695648293929_image_2.png",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c698",
      "name": "externallmg_r_1695648387284_1695648293929_image_1.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648387284_1695648293929_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65118ac30c1bfd1d9fe1c699",
      "name": "externallmg_r_1695648385685_1695648293929_image_0.jpg",
      "path": "cases/651171480c1bfd1d9fe13cbd/
externallmg_r_1695648385685_1695648293929_image_0.jpg",
      "orientation": "portrait"
    }
  }
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Aadhar Tanmay.pdf",
    "filename": "1695711689173_Aadhar_Tanmay.pdf",
    "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711689173_Aadhar_Tanmay.pdf",
    "size": "306899",
    "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Calculation (2)- binu.xlsx",
    "filename": "1695711689190_Calculation_2_binu.xlsx",
    "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711689190_Calculation_2_binu.xlsx",
    "size": "16049",
    "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Part OC Shri Krihnadahm.pdf",
    "filename": "1695711689195_Part_OC_Shri_Krihnadahm.pdf",
    "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711689195_Part_OC_Shri_Krihnadahm.pdf",
    "size": "387214",
    "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.doc",
    "filename": "1695711689229_reference_report.doc",
    "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711689229_reference_report.doc",
    "size": "9469440",
    "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "sugandhakadam pan.pdf",
    "filename": "1695711690170_sugandhakadam_pan.pdf",
    "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711690170_sugandhakadam_pan.pdf",
    "size": "605052",
    "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - binu.xlsx",
  "filename": "1695711690221_Summary__binu.xlsx",
  "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711690221_Summary__binu.xlsx",
  "size": "3857565",
  "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "sungandhakadamadhar.pdf",
  "filename": "1695711690549_sungandhakadamadhar.pdf",
  "path": "cases/651171480c1bfd1d9fe13cbd/
processingDocuments/1695711690549_sungandhakadamadhar.pdf",
  "size": "563926",
  "createdAt": "Tue Sep 26 2023 12:31:30 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"remarks": [],
"createdAt": "2023-09-25T11:38:48.562Z",
"updatedAt": "2023-09-27T07:48:04.099Z",
"__v": 0,
"invoiceId": "651171480c1bfd1d9fe13ccd",
"fullAddress": "Residential Flat No. 36, 3rd Floor, Building No B-9, Wing - D, Shri
Krishna Dham Co-Op. Hsg. Soc. Ltd., L.B.S. Marg, Village - Mulund, Taluka - Kurla,
District - Mumbai, Mulund (West), PIN - 400 080, State - Maharashtra, India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Kishor Mange ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's relative",
"siteVisitContactNo": "9819856250",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage",
"carpetTotal": "432.85",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
```

```

"finalBuiltupArea": "476.13",
"finalCarpetArea": "432.85",
"finalSalableArea": "523.75",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 530.00",
"buildingServicesRate": "2800",
"flatRate": "22000",
"landOtherRate": "19200",
"siteVisitDate": "2023-09-25"

```

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	17'6"	9'5"	164.79
WC	5'3"	2'7"	13.56
Bathroom	5'3"	3'3"	17.06
Bedroom	12'00"	9'1"	109.00
Kitchen	12'1"	7'1"	85.59
Passage	2'9"	15'7"	42.85
Other Composition :			