

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Market Value",
    "value": "Market_Value"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2105000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 1052.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64535eb5ee347304f2a3005f",
  "role": "DELIVERYPERSON",
  "firstName": "Hemant",
  "email": "hkadam113@gmail.com",
  "lastName": "Kadam",
  "mobileNo": "9819455052",
  "shortName": "Hemant",
  "workWithDocumentMaker": "60b7189d2ffdf65bcd65882b",
  "profilePhoto": "users/64535eb5ee347304f2a3005f/
profilePhoto_1687240220512_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```

    "designation": "",
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {

```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.9763939464808",
  "longitude": "73.10997741497775"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10997741497775,
    18.9763939464808
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-09-25T12:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-25T12:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-27",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Karanjade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Panvel",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "80",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Ashirwad",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "5A",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters",
    "label": "Teak Wood Door Frame With Flush Shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
```

```
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Open Plot",
    "south": "Internal Road",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "9",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "225",
  "depreciatedCostOfConstruction": "9975.00",
  "depreciatedBuildingRate": "2275"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "69000",
  "landRate": "12100",
  "igrImage": "cases/651173790c1bfd1d9fe1580c/igr_1696317903997_Image.png",
  "squareMeterGuideLineRate": "69000.00",
  "squareFeetGuideLineRate": "6410.00"
},
"igrFinalRate": {
  "rate": "6093.00",
  "squareMeterGuideLineRate": "65586.00",
  "squareFeetGuideLineRate": "6093.00",
  "depreciationPercentage": "94"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  }
}
```

```
},
"monthlyRent": "8,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
},
```

```
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
}
```

```
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "472.80",
```



```
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/651173790c1bfd1d9fe1580c/
routeMap_1695980334275_Image.png",
    "routeLat": "18.975997",
    "routeLng": "73.109839",
    "stationName": "Panvel",
    "routeDistance": "4.5KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "0qx22h",
      "name": "0qx22h",
      "image": "cases/651173790c1bfd1d9fe1580c/
routeMap_1695980196104_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
```

```
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3930150.00",
"finalValue": "3930150.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Oct 03 2023 14:18:08 GMT+0530 (India Standard Time)",
  "number": "2302810",
  "dayCount": "7",
  "monthCount": "7",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2880770.00",
"selectedBuildUpValue": "472.80",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65168136e393a05c2412c04a",
"name": "externalImg_r_1695973685441_TimePhoto_20230927_162120.jpg",
"path": "cases/651173790c1bfd1d9fe1580c/
externalImg_r_1695973685441_TimePhoto_20230927_162120.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "6516811fe393a05c2412bee4",
"name": "externalImg_r_1695973663205_TimePhoto_20230927_161234.jpg",
"path": "cases/651173790c1bfd1d9fe1580c/
externalImg_r_1695973663205_TimePhoto_20230927_161234.jpg",
"orientation": "portrait"
}
],
}
```

```
{
  "status": false,
  "_id": "65168136e393a05c2412c04c",
  "name": "externallmg_r_1695973685414_TimePhoto_20230927_162107.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685414_TimePhoto_20230927_162107.jpg",
  "orientation": "portrait"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65168136e393a05c2412c048",
    "name": "externallmg_r_1695973685403_TimePhoto_20230927_162100.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685403_TimePhoto_20230927_162100.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65168136e393a05c2412c04b",
    "name": "externallmg_r_1695973685446_TimePhoto_20230927_162121.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685446_TimePhoto_20230927_162121.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6516811fe393a05c2412bee7",
    "name": "externallmg_r_1695973663215_TimePhoto_20230927_161238.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663215_TimePhoto_20230927_161238.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6516811fe393a05c2412bee8",
    "name": "Living Room",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663223_TimePhoto_20230927_161648.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "6516811fe393a05c2412bee9",
      "name": "Living Room",
      "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663227_TimePhoto_20230927_161653.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65168136e393a05c2412c041",
      "name": "Living Room",
      "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685375_TimePhoto_20230927_161730.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65168136e393a05c2412c042",
      "name": "Living Room",
      "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685383_TimePhoto_20230927_161736.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65168136e393a05c2412c046",
      "name": "Living Room",
      "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685394_TimePhoto_20230927_161952.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65168136e393a05c2412c03d",
      "name": "Living Room",
      "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685372_TimePhoto_20230927_161722.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8444",
```

```
"max": "10417"
},
"builtUpRateRange": {
  "min": "7038",
  "max": "8681"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```



```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "394.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "651173790c1bfd1d9fe1580c",
"ownerName": "Mr. Santosh Nivrutti Jadhav & Mr. Sandeep Nivrutti Jadhav",
"ownerPhoneNo": "9029581819",
"appAddress": "Flat no. 102,1st floor SHIV ASHIRWAD Plot no. 80, 5A Village
Karanjadi Panvel ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },

```

```
"inputs": {
  "documentDate": "06/09/2016",
  "from": {
    "value": "The_Builders",
    "label": "The Builders"
  },
  "The_Builders": "M/s. Shivkrupa Enterprises",
  "to": {
    "value": "The_Purchasers",
    "label": "The Purchasers"
  },
  "The_Purchasers": "Mr. Santosh Nivrutti Jadhav & Mr. Sandeep Nivrutti Jadhav"
},
"isHardCopy": false,
"displayStatus": true,
"id": "185756",
"path": "cases/651173790c1bfd1d9fe1580c/
document_1695642370384_RACPC_Ghatkopar_25__Sandeep_jadhav.pdf",
"fileName":
"document_1695642370384_RACPC_Ghatkopar_25__Sandeep_jadhav.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/06/2016",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / BP-15183 / TPO (NM & K) / 2016 / 0658"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695991084719_Commencement_Certificate.pdf",
  "path": "cases/651173790c1bfd1d9fe1580c/
document_1695991084719_Commencement_Certificate.pdf",
  "id": "287054",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Sep 29 2023 18:08:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
```

```
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/12/2017",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / BP-15183 / TPO (NM & K) / 2016 / 2191"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696319131043_OC__Shiv_Ashirwad.pdf",
  "path": "cases/651173790c1bfd1d9fe1580c/
document_1696319131043_OC__Shiv_Ashirwad.pdf",
  "id": "305874",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Tue Oct 03 2023 13:15:31 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004022",
"createdBy": "64535eb5ee347304f2a3005f",
"caseHistory": [
  {
    "id": "514780",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 25 2023 17:18:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Santosh Nivrutti Jadhav & Mr. Sandeep Nivrutti Jadhav",
    "phone": "9029581819",
    "ownershipShare": "",
    "email": "",
    "id": "448771"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "343516",
  "name": "Living Room",
  "length": "15.83",
  "length1": "15",
  "length2": "10",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "138.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "138.54"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "22.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.17",
  "length1": "6",
  "length2": "2",
```

```
"width": "7.08",
"width1": "7",
"width2": "1",
"totalArea": "43.68",
"images": [],
"extraAreas": [],
"finalArea": "43.68"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "13.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "2.33",
  "length1": "2",
  "length2": "4",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "8.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.75"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "11.58",
  "length1": "11",
  "length2": "7",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "101.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "101.35"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowered Area",
      "value": "Flowered_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "8",
    "length2": "9",
    "length": "8.75",
    "width1": "2",
    "width2": "00",
    "width": "2.00",
    "totalArea": "17.50",
    "percentageBeforeTotal": "17.50",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "17.5"
  }
],
```

```
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "978496",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "394",
    "squareMeterArea": "36.6",
    "docFinalBuiltUp": "472.8",
    "docFinalBuiltUpSquareMeter": "43.92",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "651bc29a2c6c0778ddf26607",
    "property": "Flat",
    "area": "400",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "2",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3800000",
    "expectedRate": "9500.00",
    "builtUpExpectedRate": "7916.67",
    "image": "cases/651173790c1bfd1d9fe1580c/
indicator_1696317506323_Image.png",
    "squareMeter": "37.16",
    "id": "654115"
  },
  {
    "printlnReport": true,
```



```
"_id": "651bc29a2c6c0778ddf26608",
"property": "Flat",
"area": "450",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "5",
"source": "Nobroker.com",
"expectedPrice": "3800000",
"expectedRate": "8444.44",
"builtUpExpectedRate": "7037.04",
"image": "cases/651173790c1bfd1d9fe1580c/
indicator_1696317563789_Image.png",
"squareMeter": "41.81",
"id": "431436"
},
{
  "printlnReport": true,
  "_id": "651bc29a2c6c0778ddf26609",
  "property": "Flat",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "4000000",
  "expectedRate": "10000.00",
  "builtUpExpectedRate": "8333.33",
  "image": "cases/651173790c1bfd1d9fe1580c/
indicator_1696317614379_Image.png",
  "squareMeter": "37.16",
  "id": "835567"
},
{
  "printlnReport": true,
  "_id": "651bc29a2c6c0778ddf2660a",
  "property": "Flat",
  "area": "288",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "4",
  "source": "Index_no.2",
```

```
    "expectedPrice": "3000000",
    "expectedRate": "10416.67",
    "builtUpExpectedRate": "8680.56",
    "image": "cases/651173790c1bfd1d9fe1580c/
indicator_1696317663417_Image.png",
    "squareMeter": "26.76",
    "id": "113408"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee1",
    "name": "externallmg_1695973663128_IMG_20230927_192341.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_1695973663128_IMG_20230927_192341.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee2",
    "name": "externallmg_1695973663163_IMG_20230927_192357.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_1695973663163_IMG_20230927_192357.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee3",
    "name": "externallmg_1695973663190_Screenshot_20230927192012394_comgoo
gleandroidappsmaps.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/externallmg_1695973663190_Screensh
ot_20230927192012394_comgoogleandroidappsmaps.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee4",
    "name": "externallmg_r_1695973663205_TimePhoto_20230927_161234.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663205_TimePhoto_20230927_161234.jpg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee5",
    "name": "externallmg_r_1695973663219_TimePhoto_20230927_161646.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663219_TimePhoto_20230927_161646.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee6",
    "name": "externallmg_r_1695973663209_TimePhoto_20230927_161236.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663209_TimePhoto_20230927_161236.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee7",
    "name": "externallmg_r_1695973663215_TimePhoto_20230927_161238.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663215_TimePhoto_20230927_161238.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee8",
    "name": "externallmg_r_1695973663223_TimePhoto_20230927_161648.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663223_TimePhoto_20230927_161648.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6516811fe393a05c2412bee9",
    "name": "externallmg_r_1695973663227_TimePhoto_20230927_161653.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663227_TimePhoto_20230927_161653.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6516811fe393a05c2412beea",
  "name": "externallmg_r_1695973663231_TimePhoto_20230927_161655.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973663231_TimePhoto_20230927_161655.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c039",
  "name": "externallmg_r_1695973685332_TimePhoto_20230927_161700.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685332_TimePhoto_20230927_161700.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c03a",
  "name": "externallmg_r_1695973685335_TimePhoto_20230927_161701.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685335_TimePhoto_20230927_161701.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c03b",
  "name": "externallmg_r_1695973685344_TimePhoto_20230927_161709.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685344_TimePhoto_20230927_161709.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c03c",
  "name": "externallmg_r_1695973685339_TimePhoto_20230927_161708.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685339_TimePhoto_20230927_161708.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c03d",
    "name": "externallmg_r_1695973685372_TimePhoto_20230927_161722.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685372_TimePhoto_20230927_161722.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c03e",
    "name": "externallmg_r_1695973685350_TimePhoto_20230927_161716.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685350_TimePhoto_20230927_161716.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c03f",
    "name": "externallmg_r_1695973685367_TimePhoto_20230927_161720.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685367_TimePhoto_20230927_161720.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c040",
    "name": "externallmg_r_1695973685359_TimePhoto_20230927_161717.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685359_TimePhoto_20230927_161717.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c041",
    "name": "externallmg_r_1695973685375_TimePhoto_20230927_161730.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685375_TimePhoto_20230927_161730.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65168136e393a05c2412c042",
  "name": "externallmg_r_1695973685383_TimePhoto_20230927_161736.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685383_TimePhoto_20230927_161736.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c043",
  "name": "externallmg_r_1695973685380_TimePhoto_20230927_161731.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685380_TimePhoto_20230927_161731.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c044",
  "name": "externallmg_r_1695973685387_TimePhoto_20230927_161738.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685387_TimePhoto_20230927_161738.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c045",
  "name": "externallmg_r_1695973685391_TimePhoto_20230927_161949.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685391_TimePhoto_20230927_161949.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65168136e393a05c2412c046",
  "name": "externallmg_r_1695973685394_TimePhoto_20230927_161952.jpg",
  "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685394_TimePhoto_20230927_161952.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65168136e393a05c2412c047",
    "name": "externallmg_r_1695973685397_TimePhoto_20230927_162043.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685397_TimePhoto_20230927_162043.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c048",
    "name": "externallmg_r_1695973685403_TimePhoto_20230927_162100.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685403_TimePhoto_20230927_162100.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c049",
    "name": "externallmg_r_1695973685408_TimePhoto_20230927_162101.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685408_TimePhoto_20230927_162101.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c04a",
    "name": "externallmg_r_1695973685441_TimePhoto_20230927_162120.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685441_TimePhoto_20230927_162120.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c04b",
    "name": "externallmg_r_1695973685446_TimePhoto_20230927_162121.jpg",
    "path": "cases/651173790c1bfd1d9fe1580c/
externallmg_r_1695973685446_TimePhoto_20230927_162121.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65168136e393a05c2412c04c",
```

```
"name": "externalImg_r_1695973685414_TimePhoto_20230927_162107.jpg",
"path": "cases/651173790c1bfd1d9fe1580c/
externalImg_r_1695973685414_TimePhoto_20230927_162107.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "6516ac64e393a05c24136f0e",
"note": "Pending of OC",
"taskId": "6511793b0c1bfd1d9fe18f9d",
"createdAt": "2023-09-29T10:52:20.743Z"
}
],
"createdAt": "2023-09-25T11:48:09.181Z",
"updatedAt": "2023-10-03T08:52:07.018Z",
"__v": 0,
"invoiceId": "651173790c1bfd1d9fe15823",
"fullAddress": "Residential Flat No. 102, 1st Floor, Shiv Ashirwad, Plot No. 80, Sector
5A, Village - Karanjade, Navi Mumbai, Taluka - Panvel, District - Raigad, PIN - 410 206,
State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "64535eb5ee347304f2a3005f",
"contactPersonName": "Nivrutti Rama Jadhav ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owners Father",
"siteVisitContactNo": "9869337615",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
Toilet",
```



```
"carpetTotal": "328.26",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "17.50",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "17.50",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "414.91",
"finalCarpetArea": "345.76",
"finalSalableArea": "414.91",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for
Sale Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area.",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 328.26\nFlowerbed Area in Sq.
Ft. = 17.50\nTotal Area in Sq. Ft. = 345.76\n(Area as per actual site measurement)",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 394.00",
"buildingServicesRate": "2500",
"flatRate": "10200",
"landOtherRate": "7700",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"shopDetails": {
  "typeOfShops": {
```

```

    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Tue Oct 03 2023 14:13:05 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-09-27"
}

```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 15'10" | 8'9" | 138.54 |
| Passage | 7'10" | 2'10" | 22.19 |
| Kitchen | 6'2" | 7'1" | 43.68 |
| Bathroom | 3'9" | 3'8" | 13.75 |
| Toilet | 2'4" | 3'9" | 8.75 |
| Bedroom | 11'7" | 8'9" | 101.35 |
| Other Composition : | | | |
| Flowered Area | 8'9" | 2'00" | 17.50 |