

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4900000",
    "discussWithPerson": "Ravindra sir",
    "expectedFees": 2450,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "_id": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg",
  "firstName": "Nitesh",
  "lastName": "Khedekar",
  "shortName": "NK",
  "email": "nitesh.khedekar@vastukala.org",
  "designation": "",
  "mobileNo": "8369040652",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.03011062089906",
  "longitude": "73.01293785092419"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.01293785092419,
    19.03011062089906
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-03",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-03",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "10500",
  "lumpsumValue": "55000",
  "rateMax": "10500",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nerul",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C-28",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Darshan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "48",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "7",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 706",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. C - 27",
    "west": "Parking & Building No. C - 30",
    "south": "Gaurav High School And Junior College",
    "east": "Ramesh Sankarrao Hebbar Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
```

```
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Dated 20.01.1998
issued by CIDCO",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "37.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "14487.5",
  "depreciatedBuildingRate": "1687.5"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "120400.00",
  "landRate": "47400",
  "igrImage": "cases/6511790c0c1bfd1d9fe18e53/igr_1695708763879_Image.png",
  "squareMeterGuideLineRate": "114380.00",
  "squareFeetGuideLineRate": "10626.00"
},
"igrFinalRate": {
  "depreciationPercentage": "75",
  "rate": "9071.00",
  "squareFeetGuideLineRate": "9071.00",
  "squareMeterGuideLineRate": "97635.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "15000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Mr. Akshay Kinjale",
"maintenanceOfFlat": "Good"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
}
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
}
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
}
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
}
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
}
},
"carParking": "Open Parking",
"constructionWorkStatus": {
"value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1998",
  "fullDate": "1/1/1998"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_Possession_Receipt",
  "label": "As per Possession Receipt"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "25",
"totalLifeBuilding": "60",
"estimatedAge": "35",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
```



```
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "375.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6511790c0c1bfd1d9fe18e53/
routeMap_1696398789730_Image.png",
    "routeLat": "19.012510",
    "routeLng": "73.017718",
    "stationName": "Seawoods - Darave",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "bk4pd7",
      "name": "bk4pd7",
      "image": "cases/6511790c0c1bfd1d9fe18e53/
routeMap_1696398694223_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```

```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5433000.00",
"finalValue": "5433000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Oct 04 2023 11:48:14 GMT+0530 (India Standard Time)",
  "number": "2302828",
  "dayCount": "3",
  "monthCount": "25",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3401625.00",
  "selectedBuildUpValue": "375.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "651b8ab92c6c0778ddf198a9",
      "name": "externalimg_1696303797622_1696303707879_image_5.jpeg",
      "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303797622_1696303707879_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
```

```
    "_id": "651b8ab92c6c0778ddf198c1",
    "name": "externalimg_1696303775752_1696303683546_image_13.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303775752_1696303683546_image_13.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198c0",
    "name": "externalimg_1696303774576_1696303683546_image_12.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303774576_1696303683546_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b9",
    "name": "externalimg_1696303774262_1696303683546_image_5.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303774262_1696303683546_image_5.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198bb",
    "name": "externalimg_1696303774368_1696303683546_image_7.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303774368_1696303683546_image_7.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198a5",
    "name": "Living Room",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externalimg_1696303796583_1696303707879_image_1.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "651b8ab92c6c0778ddf198a8",
    "name": "Living Room",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797597_1696303707879_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198ac",
    "name": "Living Room",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797842_1696303707879_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198ae",
    "name": "Living Room",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797867_1696303707879_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651b8ab92c6c0778ddf198ad",
    "name": "Living Room",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797843_1696303707879_image_9.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "15556",
    "max": "17846"
  },
  "builtUpRateRange": {
    "min": "13691",
    "max": "15556"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "375.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6511790c0c1bfd1d9fe18e53",
"ownerName": "Miss. Shreya Rajendra Desai & Mr. Rajendra Gajanan Desai",
"ownerPhoneNo": "9867332136",
"appAddress": "flat no p7 Bldg c wing 28 dhib Darshan chs Ltd Sector no 48 Nerul
\n",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "16/09/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Smt. Pramila Nitin Waghmare",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      }
    }
  }
]
```

```
    },
    "purchaser": "Miss. Shreya Rajendra Desai & Mr. Rajendra Gajanan Desai"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "874985",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
document_1695643012326_Rabendra_Desai_sbi_Racpc_belapur.pdf",
  "fileName": "document_1695643012326_Rabendra_Desai_sbi_Racpc_belapur.pdf"
},
{
  "documentType": {
    "value": "60ae1259aa6d152c1801b340",
    "label": "CIDCO Possession Letter & Receipt"
  },
  "inputs": {
    "documentDate": "03/07/1998",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
  },
  "remark": "(in the name of Sahani Harbanslal Isherdas)"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695715179390_104858.pdf",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
document_1695715179390_104858.pdf",
  "id": "167513",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Tue Sep 26 2023 13:29:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "20/01/1998",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  }
}
```

```
    },
    "Document_No": "N.A."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695715287655_228249.pdf",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
document_1695715287655_228249.pdf",
  "id": "621133",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Tue Sep 26 2023 13:31:27 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004026",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "613079",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 25 2023 17:41:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Miss. Shreya Rajendra Desai & Mr. Rajendra Gajanan Desai",
    "phone": "9867332136",
    "ownershipShare": "",
    "email": "",
    "id": "475387"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "250874",
    "name": "Living Room",
    "length": "8.58",
    "length1": "8",
    "length2": "7",
    "width": "12.67",
```

```
"width1": "12",
"width2": "8",
"totalArea": "108.72",
"images": [],
"extraAreas": [],
"finalArea": "108.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "21.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "7.17",
  "width1": "7",
  "width2": "2",
  "totalArea": "45.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "75.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "75.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
```

```
"totalArea": "16.00",
"images": [],
"extraAreas": [],
"finalArea": "16.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "9.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "34.84",
    "totalAreaDocument": "375.00",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "601490"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "651276760c1bfd1d9fe25e87",
  "property": "1 BHK Flat In Sagar Kinara Housing Society, Nerul, Navi Mumbai",
  "area": "350.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "5750000.00",
  "expectedRate": "16428.57",
  "builtUpExpectedRate": "13690.48",
  "image": "cases/6511790c0c1bfd1d9fe18e53/
indicator_1695708008307_Image.png",
  "squareMeter": "32.52",
  "id": "606521"
},
{
  "printlnReport": true,
  "_id": "651276760c1bfd1d9fe25e88",
  "property": "1 BHK Flat In Sai Sangam CHSL, Sector 48, Nerul, Navi Mumbai",
  "area": "450.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "7000000.00",
  "expectedRate": "15555.56",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6511790c0c1bfd1d9fe18e53/
indicator_1695708210294_Image.png",
  "squareMeter": "41.81",
  "id": "210110"
},
{
  "printlnReport": true,
  "_id": "651276760c1bfd1d9fe25e89",
  "property": "1BHK Flat for Sale in sagar kinara, Sector 48 Seawoods, Navi Mumbai",
  "area": "325.00",
  "builtUpPercentage": "20",
```



```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "5800000.00",
"expectedRate": "17846.15",
"builtUpExpectedRate": "14871.79",
"image": "cases/6511790c0c1bfd1d9fe18e53/
indicator_1695708533210_Image.png",
"squareMeter": "30.19",
"id": "161312"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651b8ab92c6c0778ddf198a4",
"name": "externalImg_1696303796517_1696303707879_image_0.jpeg",
"path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303796517_1696303707879_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651b8ab92c6c0778ddf198a5",
"name": "externalImg_1696303796583_1696303707879_image_1.jpeg",
"path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303796583_1696303707879_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651b8ab92c6c0778ddf198a6",
"name": "externalImg_1696303796613_1696303707879_image_2.jpeg",
"path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303796613_1696303707879_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651b8ab92c6c0778ddf198a7",
"name": "externalImg_1696303796997_1696303707879_image_3.jpeg",
```

```
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303796997_1696303707879_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198a8",
    "name": "externallmg_1696303797597_1696303707879_image_4.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797597_1696303707879_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198a9",
    "name": "externallmg_1696303797622_1696303707879_image_5.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797622_1696303707879_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198aa",
    "name": "externallmg_1696303797687_1696303707879_image_6.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797687_1696303707879_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198ab",
    "name": "externallmg_1696303797772_1696303707879_image_7.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797772_1696303707879_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198ac",
    "name": "externallmg_1696303797842_1696303707879_image_8.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797842_1696303707879_image_8.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198ad",
  "name": "externallmg_1696303797843_1696303707879_image_9.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797843_1696303707879_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198ae",
  "name": "externallmg_1696303797867_1696303707879_image_10.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797867_1696303707879_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198af",
  "name": "externallmg_1696303797887_1696303707879_image_11.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797887_1696303707879_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198b0",
  "name": "externallmg_1696303797922_1696303707879_image_12.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303797922_1696303707879_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198b1",
  "name": "externallmg_1696303799407_1696303707879_image_13.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303799407_1696303707879_image_13.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b2",
    "name": "externallmg_1696303799488_1696303707879_image_14.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303799488_1696303707879_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b3",
    "name": "externallmg_1696303799557_1696303707879_image_15.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303799557_1696303707879_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b4",
    "name": "externallmg_1696303773244_1696303683546_image_0.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303773244_1696303683546_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b5",
    "name": "externallmg_1696303773338_1696303683546_image_1.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303773338_1696303683546_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198b6",
    "name": "externallmg_1696303773362_1696303683546_image_2.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303773362_1696303683546_image_2.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198b7",
  "name": "externallmg_1696303773669_1696303683546_image_3.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303773669_1696303683546_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198b8",
  "name": "externallmg_1696303774242_1696303683546_image_4.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774242_1696303683546_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198b9",
  "name": "externallmg_1696303774262_1696303683546_image_5.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774262_1696303683546_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198ba",
  "name": "externallmg_1696303774312_1696303683546_image_6.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774312_1696303683546_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198bb",
  "name": "externallmg_1696303774368_1696303683546_image_7.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774368_1696303683546_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198bc",
    "name": "externallmg_1696303774573_1696303683546_image_8.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774573_1696303683546_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198bd",
    "name": "externallmg_1696303774573_1696303683546_image_9.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774573_1696303683546_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198be",
    "name": "externallmg_1696303774574_1696303683546_image_10.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774574_1696303683546_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198bf",
    "name": "externallmg_1696303774575_1696303683546_image_11.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774575_1696303683546_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651b8ab92c6c0778ddf198c0",
    "name": "externallmg_1696303774576_1696303683546_image_12.jpeg",
    "path": "cases/6511790c0c1bfd1d9fe18e53/
externallmg_1696303774576_1696303683546_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "651b8ab92c6c0778ddf198c1",
  "name": "externalImg_1696303775752_1696303683546_image_13.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303775752_1696303683546_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198c2",
  "name": "externalImg_1696303775782_1696303683546_image_14.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303775782_1696303683546_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651b8ab92c6c0778ddf198c3",
  "name": "externalImg_1696303775813_1696303683547_image_15.jpeg",
  "path": "cases/6511790c0c1bfd1d9fe18e53/
externalImg_1696303775813_1696303683547_image_15.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-25T12:11:56.103Z",
"updatedAt": "2023-10-04T06:22:24.005Z",
"__v": 0,
"invoiceId": "6511790c0c1bfd1d9fe18e5e",
"fullAddress": "Residential Flat No. 7, 1st Floor, Building No C-28, Shiv Darshan Co-
op. Hsg. Soc. Ltd., Sector 48, Village - Nerul, Taluka - Thane, District - Thane, Navi
Mumbai, PIN Code - 400 706, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Rajendra Desai ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

```
"siteVisitContactNo": "9867332136",
"buildingServicesRate": "2700.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 375.00",
"flatRate": "15500.00",
"landOtherRate": "12800",
"builtupPercentage": "20",
"carpetTotal": "271.44",
"extendOfSiteRemark": "",
"finalBuiltupArea": "344.93",
"finalCarpetArea": "287.44",
"finalSalableArea": "379.42",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + Toilet +
Bathroom",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
```



```
"value": ""
},
"roadFacing": false,
"mall": false
}
}
```

Name	Length	Width	Total
Composition :			
Living Room	8'7"	12'8"	108.72
Passage	3'00"	7'00"	21.00
Kitchen	6'4"	7'2"	45.39
Bedroom	8'00"	9'5"	75.33
Toilet	3'00"	4'00"	12.00
Bathroom	4'00"	4'00"	16.00
Passage	3'00"	3'00"	9.00
Other Composition :			